NOTICE OF CANCELLATION

INCH-POUND

AN804G
NOTICE 1
22 April 1999

MILITARY SPECIFICATION SHEET

# TEE, FLARED TUBE WITH BULKHEAD ON RUN

AN804G, dated 11 April 1994, is hereby cancelled. Future acquisitions for this item should refer to Society of Automotive Engineers (SAE) Aerospace Standard (AS) AS1033, "Tee, Standard and Reducer, Bulkhead on Run, Flared Tube."

Table 1 provides a detailed cross-reference of cancelled AN804 Part or Identifying Numbers (PINs) and replacement AS1033 PINs. The use of "AS" parts is preferable, but "AN" parts may be used for a period of three years from the date of this notice to deplete existing stock. Users are cautioned to evaluate replacements for their particular application.

(DoD activities may obtain copies of SAE AS1033 from the DoDSSP, Standardization Document Order Desk, 700 Robbins Avenue, Building 4D, Philadelphia, PA 19111-5094. The private sector and other Government agencies may purchase copies from the Society of Automotive Engineers International, 400 Commonwealth Drive, Warrendale, PA 15096-0001.)

Custodians:
Army - AV
Navy - AS
Air Force – 99
DLA - CC

Preparing activity:
DLA - CC

(Project 4730-0413)

Review activity:
Air Force - 82



AMSC N/A FSC 4730

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:16Z
Check the source to verify that this is the current version before use.

TABLE 1 - Cross-Reference Data

| Cancelled AN PIN | Tube Size | Replacement AS PIN |
|---|---|---|
| AN804-2 | .125 | AS1033-020202 |
| AN804D2 | .125 | AS1033D020202 |
| AN804J2 | .125 | AS1033J020202 |
| AN804K2 | .125 | AS1033K020202 |
| AN804R2 | .125 | 1/ |
| AN804T2 | .125 | AS1033T020202 |
| AN804W2 | .125 | AS1033W020202 |
| AN804-3 | .188 | AS1033-030303 |
| AN804D3 | .188 | AS1033D030303 |
| AN804J3 | .188 | AS1033J030303 |
| AN804K3 | .188 | AS1033K030303 |
| AN804R3 | .188 | 1/ |
| AN804T3 | .188 | AS1033T030303 |
| AN804W3 | .188 | AS1033W030303 |
| AN804-4 | .250 | AS1033-040404 |
| AN804D4 | .250 | AS1033D040404 |
| AN804J4 | .250 | AS1033J040404 |
| AN804K4 | .250 | AS1033K040404 |
| AN804R4 | .250 | 1/ |
| AN804T4 | .250 | AS1033T040404 |
| AN804W4 | .250 | AS1033W040404 |
| AN804-5 | .312 | AS1033-050505 |
| AN804D5 | .312 | AS1033D050505 |
| AN804J5 | .312 | AS1033J050505 |
| AN804K5 | .312 | AS1033K050505 |
| AN804R5 | .312 | 1/ |
| AN804T5 | .312 | AS1033T050505 |
| AN804W5 | .312 | AS1033W050505 |
| AN804-6 | .375 | AS1033-060606 |
| AN804D6 | .375 | AS1033D060606 |
| AN804J6 | .375 | AS1033J060606 |
| AN804K6 | .375 | AS1033K060606 |
| AN804R6 | .375 | 1/ |
| AN804T6 | .375 | AS1033T060606 |
| AN804W6 | .375 | AS1033W060606 |

| Cancelled AN PIN | Tube Size | Replacement AS PIN |
|---|---|---|
| AN804-8 | .500 | AS1033-080808 |
| AN804D8 | .500 | AS1033D080808 |
| AN804J8 | .500 | AS1033J080808 |
| AN804K8 | .500 | AS1033K080808 |
| AN804R8 | .500 | 1/ |
| AN804T8 | .500 | AS1033T080808 |
| AN804W8 | .500 | AS1033W080808 |
| AN804-10 | .625 | AS1033-101010 |
| AN804D10 | .625 | AS1033D101010 |
| AN804J10 | .625 | AS1033J101010 |
| AN804K10 | .625 | AS1033K101010 |
| AN804R10 | .625 | 1/ |
| AN804T10 | .625 | AS1033T101010 |
| AN804W10 | .625 | AS1033W101010 |
| AN804-12 | .750 | AS1033-121212 |
| AN804D12 | .750 | AS1033D121212 |
| AN804J12 | .750 | AS1033J121212 |
| AN804K12 | .750 | AS1033K121212 |
| AN804R12 | .750 | 1/ |
| AN804T12 | .750 | AS1033T121212 |
| AN804W12 | .750 | AS1033W121212 |
| AN804-16 | 1.000 | AS1033-161616 |
| AN804D16 | 1.000 | AS1033D161616 |
| AN804J16 | 1.000 | AS1033J161616 |
| AN804K16 | 1.000 | AS1033K161616 |
| AN804R16 | 1.000 | 1/ |
| AN804T16 | 1.000 | AS1033T161616 |
| AN804W16 | 1.000 | AS1033W161616 |
| AN804-20 | 1.250 | AS1033-202020 |
| AN804D20 | 1.250 | AS1033D202020 |
| AN804J20 | 1.250 | AS1033J202020 |
| AN804K20 | 1.250 | AS1033K202020 |
| AN804R20 | 1.250 | 1/ |
| AN804T20 | 1.250 | AS1033T202020 |
| AN804W20 | 1.250 | AS1033W202020 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:16Z
Check the source to verify that this is the current version before use.

TABLE 1 - Cross-Reference Data (Continued)

| Cancelled AN PIN | Tube Size | Replacement AS PIN |
|---|---|---|
| AN804-24 | 1.500 | AS1033-242424 |
| AN804D24 | 1.500 | AS1033D242424 |
| AN804J24 | 1.500 | AS1033J242424 |
| AN804K24 | 1.500 | AS1033K242424 |
| AN804R24 | 1.500 | 1/ |
| AN804T24 | 1.500 | AS1033T242424 |
| AN804W24 | 1.500 | AS1033W242424 |
| AN804-28 | 1.750 | Not available |
| AN804D28 | 1.750 | Not available |
| AN804J28 | 1.750 | Not available |
| AN804K28 | 1.750 | Not available |
| AN804R28 | 1.750 | Not available |
| AN804T28 | 1.750 | Not available |
| AN804W28 | 1.750 | Not available |

| Cancelled AN PIN | Tube Size | Replacement AS PIN |
|---|---|---|
| AN804-32 | 2.000 | AS1033-323232 |
| AN804D32 | 2.000 | AS1033D323232 |
| AN804J32 | 2.000 | AS1033J323232 |
| AN804K32 | 2.000 | AS1033K323232 |
| AN804R32 | 2.000 | 1/ |
| AN804T32 | 2.000 | AS1033T323232 |
| AN804W32 | 2.000 | AS1033W323232 |

1/ SAE Committee G-3 is taking action to add R code material (type 321 corrosion resistant steel) and delete S code material (type 347 corrosion resistant steel).



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:16Z
Check the source to verify that this is the current version before use.