NOTICE OF CANCELLATION

INCH-POUND

MS24388H
NOTICE 2
1 December 2010
SUPERSEDING
NOTICE 1
22 April 1999

MILITARY STANDARD

# TEE, FLARED TUBE, INTERNAL THREAD ON SIDE, PRECISION TYPE

MS24388H, dated 16 April 1982, is hereby cancelled. Future acquisitions for this item should refer to SAE-AS1031, " Fitting, Tee, Standard and Reducer, Bulkhead on Run, Internal Port on Side, Flared".

(Copies of these documents are available from SAE International, 400 Commonwealth Drive, Warrendale, PA 15096-0001, Tel: 877-606-7323 (inside USA and Canada) or 724-776-4970 (outside USA), www.sae.org.)

Reason for NOTICE 2: SAE inactivated Part or Identifying Number (PIN) with material code letter D for replacement parts and for new design to use code letter W. This is because code letter W is stronger in tensile strength than code letter D. This is based on the previous PA's revision, as a result of lessons learned. Plus to add back material code letter S for replacement parts and for new design to use code letter R. The code letter R is better for applications requiring higher temperature.

Table l provides a detailed cross-reference of cancelled MS24388H PINs and replacement SAE-AS1031 PINs.

CAUTION: The supersession information is valid as of the date of this notice and may be superseded by subsequent revisions of the superseding document.

## CONCLUDING MATERIAL

Custodians:
Army - AV
Navy - AS
Air Force – 99
DLA - CC

Preparing activity:
DLA - CC

(Project 4730-2010-033)

Review activities:
Army – AR, AT
Navy – MC, SA
Air Force – 11, 71

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.daps.dla.mil.

AMSC N/A

FSC 4730

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:53Z
Check the source to verify that this is the current version before use.

TABLE I. MS24388H to SAE-AS1031, cross-reference data.

| Cancelled AN PIN | Tube Size | Replacement AS PIN | New Design | Cancelled AN PIN | Tube Size | Replacement AS PIN | New Design |
|---|---|---|---|---|---|---|---|
| MS24388-2 | .125 | AS1031-020202 | | MS24388-8 | .500 | AS1031-080808 | |
| MS24388D2 | .125 | AS1031 D020202 | AS1031 W020202 | MS24388D8 | .500 | AS1031 D080808 | AS1031 W080808 |
| MS24388J2 | .125 | AS1031 J020202 | | MS24388J8 | .500 | AS1031 J080808 | |
| MS24388K2 | .125 | AS1031 K020202 | | MS24388K8 | .500 | AS1031 K080808 | |
| MS24388S2 | .125 | AS1031 S020202 | AS1031 R020202 | MS24388S8 | .500 | AS1031S 080808 | AS1031 R080808 |
| MS24388T2 | .125 | AS1031 T020202 | | MS24388T8 | .500 | AS1031 T080808 | |
| MS24388W2 | .125 | AS1031 W020202 | | MS24388W8 | .500 | AS1031 W080808 | |
| MS24388-3 | .188 | AS1031-030303 | | MS24388-10 | .625 | AS1031-101010 | |
| MS24388D3 | .188 | AS1031 D030303 | AS1031 W030303 | MS24388D10 | .625 | AS1031 D101010 | AS1031 W101010 |
| MS24388J3 | .188 | AS1031 J030303 | | MS24388J10 | .625 | AS1031 J101010 | |
| MS24388K3 | .188 | AS1031 K030303 | | MS24388K10 | .625 | AS1031 K101010 | |
| MS24388S3 | .188 | AS1031 S030303 | AS1031 R030303 | MS24388S10 | .625 | AS1031 S101010 | AS1031 R101010 |
| MS24388T3 | .188 | AS1031 T030303 | | MS24388T10 | .625 | AS1031 T101010 | |
| MS24388W3 | .188 | AS1031 W030303 | | MS24388W10 | .625 | AS1031 W101010 | |
| MS24388-4 | .250 | AS1031-040404 | | MS243888-12 | .750 | AS1031-121212 | |
| MS24388D4 | .250 | AS1031 D040404 | AS1031 W040404 | MS24388D12 | .750 | AS1031 D121212 | AS1031 W121212 |
| MS24388J4 | .250 | AS1031 J040404 | | MS24388J12 | .750 | AS1031 J121212 | |
| MS24388K4 | .250 | AS1031 K040404 | | MS24388K12 | .750 | AS1031 K121212 | |
| MS24388S4 | .250 | AS1031 S040404 | AS1031 R040404 | MS24388S12 | .750 | AS1031 S121212 | AS1031 R121212 |
| MS24388T4 | .250 | AS1031 T040404 | | MS24388T12 | .750 | AS1031 T121212 | |
| MS24388W4 | .250 | AS1031 W040404 | | MS24388W12 | .750 | AS1031 W121212 | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:53Z
Check the source to verify that this is the current version before use.

TABLE I. MS24388H to SAE-AS1031, cross-reference data- Continued.

| Cancelled AN PIN | Tube Size | Replacement AS PIN | New Design | Cancelled AN PIN | Tube Size | Replacement AS PIN | New Design |
|---|---|---|---|---|---|---|---|
| MS24388-5 | .312 | AS1031-050505 | | MS24388-16 | 1.000 | AS1031-161616 | |
| MS24388D5 | .312 | AS1031 D050505 | AS1031 W050505 | MS24388D16 | 1.000 | AS1031 D161616 | AS1031 W161616 |
| MS24388J5 | .312 | AS1031 J050505 | | MS24388J16 | 1.000 | AS1031 J161616 | |
| MS24388K5 | .312 | AS1031 K050505 | | MS24388K16 | 1.000 | AS1031 K161616 | |
| MS24388S5 | .312 | AS1031 S050505 | AS1031 R050505 | MS24388S16 | 1.000 | AS1031 S161616 | AS1031 R161616 |
| MS24388T5 | .312 | AS1031 T050505 | | MS24388T16 | 1.000 | AS1031 T161616 | |
| MS24388W5 | .312 | AS1031 W050505 | | MS24388W16 | 1.000 | AS1031 W161616 | |
| MS24388-6 | .375 | AS1031-060606 | | MS24388-20 | 1.250 | AS1031-202020 | |
| MS24388D6 | .375 | AS1031 D060606 | AS1031 W060606 | MS24388D20 | 1.250 | AS1031 D202020 | AS1031 W202020 |
| MS24388J6 | .375 | AS1031 J060606 | | MS24388J20 | 1.250 | AS1031 J202020 | |
| MS24388K6 | .375 | AS1031 K060606 | | MS24388K20 | 1.250 | AS1031K 202020 | |
| MS24388S6 | .375 | AS1031 S060606 | AS1031 R060606 | MS24388S20 | 1.250 | AS1031 S202020 | AS1031 R202020 |
| MS24388T6 | .375 | AS1031 T060606 | | MS24388T20 | 1.250 | AS1031 T202020 | |
| MS24388W6 | .375 | AS1031 W060606 | | MS24388W20 | 1.250 | AS1031 W202020 | |



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:53Z
Check the source to verify that this is the current version before use.