NOTICE OF CANCELLATION

INCH-POUND

MS24398 Rev. H
NOTICE 2
23 February 2001

MILITARY STANDARD

ADAPTER, STRAIGHT, TUBE TO BOSS, PRECISION TYPE

MS24398 Rev. H, dated 10 February 1984, is hereby cancelled. Future acquisitions for this item should refer to the Society of Automotive Engineers (SAE) Aerospace Standard, AS5173, “Fitting, Bushing, Port, Reducer”.

Table I provides a detailed cross-reference of cancelled MS24398 Part or Identifying Numbers (PINs) and replacement AS5173 PINs. The use of AS5173 parts is preferable, but MS parts may be used for a period of three years from the date of this notice to deplete existing stock. Users are cautioned to evaluate replacements for their particular application.

(Copies of SAE AS5173 may be purchased from SAE International, 400 Commonwealth Drive, Warrendale, PA 15096.)

Custodians:
Air Force - 99
Army - AV
Navy - AS
DLA - CC

Review activities:
Army - AT
Air Force – 70, 71
Navy - MC, SA

Preparing activity:
DLA - CC

(Project 4730-2170)

AMSC N/A

FSC 4730

DISTRIBUTION STATEMENT A Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:53Z
Check the source to verify that this is the current version before use.

Table I. Cross-Reference Data

Cancelled MS PIN	Replacement AS PIN	Cancelled MS PIN	Replacement AS PIN 1/
MS24398-3-2	AS5173-0302	MS24398-6-5	AS5173-0605
MS24398D3-2	AS5173D0302	MS24398D6-5	AS5173D0605
MS24398J3-2	AS5173J0302	MS24398J6-5	AS5173J0605
MS24398K3-2	AS5173K0302	MS24398K6-5	AS5173K0605
MS24398S3-2	AS5173R0302	MS24398S6-5	AS5173R0605
MS24398T3-2	AS5173T0302	MS24398T6-5	AS5173T0605
MS24398W3-2	AS5173W0302	MS24398W6-5	AS5173W0605
MS24398-4-2	AS5173-0402	MS24398-8-4	AS5173-0804
MS24398D4-2	AS5173D0402	MS24398D8-4	AS5173D0804
MS24398J4-2	AS5173J0402	MS24398J8-4	AS5173J0804
MS24398K4-2	AS5173K0402	MS24398K8-4	AS5173K0804
MS24398S4-2	AS5173R0402	MS24398S8-4	AS5173R0804
MS24398T4-2	AS5173T0402	MS24398T8-4	AS5173T0804
MS24398W4-2	AS5173W0402	MS24398W8-4	AS5173W0804
MS24398-4-3	AS5173-0403	MS24398-8-5	AS5173-0805
MS24398D4-3	AS5173D0403	MS24398D8-5	AS5173D0805
MS24398J4-3	AS5173J0403	MS24398J8-5	AS5173J0805
MS24398K4-3	AS5173K0403	MS24398K8-5	AS5173K0805
MS24398S4-3	AS5173R0403	MS24398S8-5	AS5173R0805
MS24398T4-3	AS5173T0403	MS24398T8-5	AS5173T0805
MS24398W4-3	AS5173W0403	MS24398W8-5	AS5173W0805
MS24398-5-4	AS5173-0504	MS24398-8-6	AS5173-0806
MS24398D5-4	AS5173D0504	MS24398D8-6	AS5173D0806
MS24398J5-4	AS5173J0504	MS24398J8-6	AS5173J0806
MS24398K5-4	AS5173K0504	MS24398K8-6	AS5173K0806
MS24398S5-4	AS5173R0504	MS24398S8-6	AS5173R0806
MS24398T5-4	AS5173T0504	MS24398T8-6	AS5173T0806
MS24398W5-4	AS5173W0504	MS24398X8-6	AS5173W0806
MS24398-6-4	AS5173-0604	MS24398-10-4	AS5173-1004
MS24398D6-4	AS5173D0604	MS24398D10-4	AS5173D1004
MS24398J6-4	AS5173J0604	MS24398J10-4	AS5173J1004
MS24398K6-4	AS5173K0604	MS24398K10-4	AS5173K1004
MS24398S6-4	AS5173R0604	MS24398S10-4	AS5173R1004
MS24398T6-4	AS5173T0604	MS24398T10-4	AS5173T1004
MS24398W6-4	AS5173W0604	MS24398W10-4	AS5173W1004

1/ The SAE replacement part is a functional equivalent of the military part except that some sizes require longer lengths to eliminate military part failures. An adjustment of the length of the mating tube may be required for ease of installation.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:53Z
Check the source to verify that this is the current version before use.

Table I. Cross-Reference Data (Continued)

Cancelled MS PIN	Replacement AS PIN 1/	Cancelled MS PIN	Replacement AS PIN 1/
MS24398-10-5	AS5173-1005	MS24398-12-10	AS5173-1210
MS24398D10-5	AS5173D1005	MS24398D12-10	AS5173D1210
MS24398J10-5	AS5173J1005	MS24398J12-10	AS5173J1210
MS24398K10-5	AS5173K1005	MS24398K12-10	AS5173K1210
MS24398S10-5	AS5173R1005	MS24398S12-10	AS5173R1210
MS24398T10-5	AS5173T1005	MS24398T12-10	AS5173T1210
MS24398W10-5	AS5173W1005	MS24398W12-10	AS5173W1210
MS24398-10-6	AS5173-1006	MS24398-16-6	AS5173-1606
MS24398D10-6	AS5173D1006	MS24398D16-6	AS5173D1606
MS24398J10-6	AS5173J1006	MS24398J16-6	AS5173J1606
MS24398K10-6	AS5173K1006	MS24398K16-6	AS5173K1606
MS24398S10-6	AS5173R1006	MS24398S16-6	AS5173R1606
MS24398T10-6	AS5173T1006	MS24398T16-6	AS5173T1606
MS24398W10-6	AS5173W1006	MS24398W16-6	AS5173W1606
MS24398-10-8	AS5173-1008	MS24398-16-8	AS5173-1608
MS24398D10-8	AS5173D1008	MS24398D16-8	AS5173D1608
MS24398J10-8	AS5173J1008	MS24398J16-8	AS5173J1608
MS24398K10-8	AS5173K1008	MS24398K16-8	AS5173K1608
MS24398S10-8	AS5173R1008	MS24398S16-8	AS5173R1608
MS24398T10-8	AS5173T1008	MS24398T16-8	AS5173T1608
MS24398W10-8	AS5173W1008	MS24398W16-8	AS5173W1608
MS24398-12-6	AS5173-1206	MS24398-16-10	AS5173-1610
MS24398D12-6	AS5173D1206	MS24398D16-10	AS5173D1610
MS24398J12-6	AS5173J1206	MS24398J16-10	AS5173J1610
MS24398K12-6	AS5173K1206	MS24398K16-10	AS5173K1610
MS24398S12-6	AS5173R1206	MS24398S16-10	AS5173R1610
MS24398T12-6	AS5173T1206	MS24398T16-10	AS5173T1610
MS24398W12-6	AS5173W1206	MS24398W16-10	AS5173W1610
MS24398-12-8	AS5173-1208	MS24398-16-12	AS5173-1612
MS24398D12-8	AS5173D1208	MS24398D16-12	AS5173D1612
MS24398J12-8	AS5173J1208	MS24398J16-12	AS5173J1612
MS24398K12-8	AS5173K1208	MS24398K16-12	AS5173K1612
MS24398S12-8	AS5173R1208	MS24398S16-12	AS5173R1612
MS24398T12-8	AS5173T1208	MS24398T16-12	AS5173T1612
MS24398W12-8	AS5173W1208	MS24398W16-12	AS5173W1612

1/ The SAE replacement part is a functional equivalent of the military part except that some require longer lengths to eliminate military part failures. An adjustment of the length of the mating tube may be required for ease of installation.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:53Z
Check the source to verify that this is the current version before use.

Table I. Cross-Reference Data (Continued)

Cancelled MS PIN	Replacement AS PIN 1/	Cancelled MS PIN	Replacement AS PIN 1/
MS24398-20-8	AS5173-2008	MS24398-20-12	AS5173-2012
MS24398D20-8	AS5173D2008	MS24398D20-12	AS5173D2012
MS24398J20-8	AS5173J2008	MS24398J20-12	AS5173J2012
MS24398K20-8	AS5173K2008	MS24398K20-12	AS5173K2012
MS24398S20-8	AS5173R2008	MS24398S20-12	AS5173R2012
MS24398T20-8	AS5173T2008	MS24398T20-12	AS5173T2012
MS24398W20-8	AS5173W2008	MS24398W20-12	AS5173W2012
MS24398-20-10	AS5173-2010	MS24398-20-16	AS5173-2016
MS24398D20-10	AS5173D2010	MS24398D20-16	AS5173D2016
MS24398J20-10	AS5173J2010	MS24398J20-16	AS5173J2016
MS24398K20-10	AS5173K2010	MS24398K20-16	AS5173K2016
MS24398S20-10	AS5173R2010	MS24398S20-16	AS5173R2016
MS24398T20-10	AS5173T2010	MS24398T20-16	AS5173T2016
MS24398W20-10	AS5173W2010	MS24398W20-16	AS5173W2016

1/ The SAE replacement part is a functional equivalent of the military part except that some sizes require longer lengths to eliminate military part failures. An adjustment of the length of the mating tube may be required for ease of installation.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:53Z
Check the source to verify that this is the current version before use.