NOTICE OF CANCELLATION

INCH-POUND

MS24399F
NOTICE 1
28 September 1999

MILITARY STANDARD

REDUCER, TUBE, PRECISION TYPE

MS24399F, dated 20 July 1984, is hereby cancelled. Future acquisitions for this item should refer to Society of Automotive Engineers (SAE) Aerospace Standard (AS) AS5174, "Fitting, Union and Reducer, Flared."

Table 1 provides a detailed cross-reference of cancelled MS24399 Part or Identifying Numbers (PINs) and replacement AS5174 PINs. The use of "AS" parts is preferable, but "MS" parts may be used for a period of three years from the date of this notice to deplete existing stock. Users are cautioned to evaluate replacements for their particular application.

(DoD activities may obtain copies of SAE AS5174 from the DoDSSP, Standardization Document Order Desk, 700 Robbins Avenue, Building 4D, Philadelphia, PA 19111-5094. The private sector and other Government agencies may purchase copies from the Society of Automotive Engineers International, 400 Commonwealth Drive, Warrendale, PA 15096-0001.)

Custodians:
Army - AV
Navy - AS
Air Force - 99
DLA - CC

Review activity:
Air Force - 82

Preparing activity:
DLA - CC

(Project 4730-0828)

AMSC N/A FSC 4730

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:53Z
Check the source to verify that this is the current version before use.

TABLE 1 - Cross-Reference Data

Cancelled AN PIN	Tube Size	Replacement AS PIN
MS24399-1	.188	AS5174-0302
MS24399D1	.188	AS5174D0302
MS24399J1	.188	AS5174J0302
MS24399K1	.188	AS5174K0302
MS24399S1	.188	AS5174R0302
MS24399T1	.188	AS5174T0302
MS24399W1	.188	AS5174W0302
MS24399-2	.250	AS5174-0402
MS24399D2	.250	AS5174D0402
MS24399J2	.250	AS5174J0402
MS24399K2	.250	AS5174K0402
MS24399S2	.250	AS5174R0402
MS24399T2	.250	AS5174T0402
MS24399W2	.250	AS5174W0402
MS24399-3	.250	AS5174-0403
MS24399D3	.250	AS5174D0403
MS24399J3	.250	AS5174J0403
MS24399K3	.250	AS5174K0403
MS24399S3	.250	AS5174R0403
MS24399T3	.250	AS5174T0403
MS24399W3	.250	AS5174W0403
MS24399-4	.312	AS5174-0504
MS24399D4	.312	AS5174D0504
MS24399J4	.312	AS5174J0504
MS24399K4	.312	AS5174K0504
MS24399S4	.312	AS5174R0504
MS24399T4	.312	AS5174T0504
MS24399W4	.312	AS5174W0504
MS24399-5	.375	AS5174-0602
MS24399D5	.375	AS5174D0602
MS24399J5	.375	AS5174J0602
MS24399K5	.375	AS5174K0602
MS24399S5	.375	AS5174R0602
MS24399T5	.375	AS5174T0602
MS24399W5	.375	AS5174W0602

Cancelled AN PIN	Tube Size	Replacement AS PIN
MS24399-6	.375	AS5174-0603
MS24399D6	.375	AS5174D0603
MS24399J6	.375	AS5174J0603
MS24399K6	.375	AS5174K0603
MS24399S6	.375	AS5174R0603
MS24399T6	.375	AS5174T0603
MS24399W6	.375	AS5174W0603
MS24399-7	.375	AS5174-0604
MS24399D7	.375	AS5174D0604
MS24399J7	.375	AS5174J0604
MS24399K7	.375	AS5174K0604
MS24399S7	.375	AS5174R0604
MS24399T7	.375	AS5174T0604
MS24399W7	.375	AS5174W0604
MS24399-8	.375	AS5174-0605
MS24399D8	.375	AS5174D0605
MS24399J8	.375	AS5174J0605
MS24399K8	.375	AS5174K0605
MS24399S8	.375	AS5174R0605
MS24399T8	.375	AS5174T0605
MS24399W8	.375	AS5174W0605
MS24399-9	.500	AS5174-0802
MS24399D9	.500	AS5174D0802
MS24399J9	.500	AS5174J0802
MS24399K9	.500	AS5174K0802
MS24399S9	.500	AS5174R0802
MS24399T9	.500	AS5174T0802
MS24399W9	.500	AS5174W0802
MS24399-10	.500	AS5174-0803
MS24399D10	.500	AS5174D0803
MS24399J10	.500	AS5174J0803
MS24399K10	.500	AS5174K0803
MS24399S10	.500	AS5174R0803
MS24399T10	.500	AS5174T0803
MS24399W10	.500	AS5174W0803

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:53Z
Check the source to verify that this is the current version before use.

TABLE 1 - Cross-Reference Data (Continued)

Cancelled AN PIN	Tube Size	Replacement AS PIN
MS24399-11	.500	AS5174-0804
MS24399D11	.500	AS5174D0804
MS24399J11	.500	AS5174J0804
MS24399K11	.500	AS5174K0804
MS24399S11	.500	AS5174R0804
MS24399T11	.500	AS5174T0804
MS24399W11	.500	AS5174W0804
MS24399-12	.500	AS5174-0805
MS24399D12	.500	AS5174D0805
MS24399J12	.500	AS5174J0805
MS24399K12	.500	AS5174K0805
MS24399S12	.500	AS5174R0805
MS24399T12	.500	AS5174T0805
MS24399W12	.500	AS5174W0805
MS24399-13	.500	AS5174-0806
MS24399D13	.500	AS5174D0806
MS24399J13	.500	AS5174J0806
MS24399K13	.500	AS5174K0806
MS24399S13	.500	AS5174R0806
MS24399T13	.500	AS5174T0806
MS24399W13	.500	AS5174W0806
MS24399-14	.625	AS5174-1004
MS24399D14	.625	AS5174D1004
MS24399J14	.625	AS5174J1004
MS24399K14	.625	AS5174K1004
MS24399S14	.625	AS5174R1004
MS24399T14	.625	AS5174T1004
MS24399W14	.625	AS5174W1004
MS24399-15	.625	AS5174-1006
MS24399D15	.625	AS5174D1006
MS24399J15	.625	AS5174J1006
MS24399K15	.625	AS5174K1006
MS24399S15	.625	AS5174R1006
MS24399T15	.625	AS5174T1006
MS24399W15	.625	AS5174W1006

Cancelled AN PIN	Tube Size	Replacement AS PIN
MS24399-16	.625	AS5174-1008
MS24399D16	.625	AS5174D1008
MS24399J16	.625	AS5174J1008
MS24399K16	.625	AS5174K1008
MS24399S16	.625	AS5174R1008
MS24399T16	.625	AS5174T1008
MS24399W16	.625	AS5174W1008
MS24399-17	.750	AS5174-1204
MS24399D17	.750	AS5174D1204
MS24399J17	.750	AS5174J1204
MS24399K17	.750	AS5174K1204
MS24399S17	.750	AS5174R1204
MS24399T17	.750	AS5174T1204
MS24399W17	.750	AS5174W1204
MS24399-18	.750	AS5174-1205
MS24399D18	.750	AS5174D1205
MS24399J18	.750	AS5174J1205
MS24399K18	.750	AS5174K1205
MS24399S18	.750	AS5174R1205
MS24399T18	.750	AS5174T1205
MS24399W18	.750	AS5174W1205
MS24399-19	.750	AS5174-1206
MS24399D19	.750	AS5174D1206
MS24399J19	.750	AS5174J1206
MS24399K19	.750	AS5174K1206
MS24399S19	.750	AS5174R1206
MS24399T19	.750	AS5174T1206
MS24399W19	.750	AS5174W1206
MS24399-20	.750	AS5174-1208
MS24399D20	.750	AS5174D1208
MS24399J20	.750	AS5174J1208
MS24399K20	.750	AS5174K1208
MS24399S20	.750	AS5174R1208
MS24399T20	.750	AS5174T1208
MS24399W20	.750	AS5174W1208

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:53Z
Check the source to verify that this is the current version before use.

TABLE 1 - Cross-Reference Data (Continued)

Cancelled AN PIN	Tube Size	Replacement AS PIN
MS24399-21	.750	AS5174-1210
MS24399D21	.750	AS5174D1210
MS24399J21	.750	AS5174J1210
MS24399K21	.750	AS5174K1210
MS24399S21	.750	AS5174R1210
MS24399T21	.750	AS5174T1210
MS24399W21	.750	AS5174W1210
MS24399-22	1.000	AS5174-1604
MS24399D22	1.000	AS5174D1604
MS24399J22	1.000	AS5174J1604
MS24399K22	1.000	AS5174K1604
MS24399S22	1.000	AS5174R1604
MS24399T22	1.000	AS5174T1604
MS24399W22	1.000	AS5174W1604
MS24399-23	1.000	AS5174-1610
MS24399D23	1.000	AS5174D1610
MS24399J23	1.000	AS5174J1610
MS24399K23	1.000	AS5174K1610
MS24399S23	1.000	AS5174R1610
MS24399T23	1.000	AS5174T1610
MS24399W23	1.000	AS5174W1610
MS24399-24	1.000	AS5174-1612
MS24399D24	1.000	AS5174D1612
MS24399J24	1.000	AS5174J1612
MS24399K24	1.000	AS5174K1612
MS24399S24	1.000	AS5174R1612
MS24399T24	1.000	AS5174T1612
MS24399W24	1.000	AS5174W1612
MS24399-25	1.250	AS5174-2004
MS24399D25	1.250	AS5174D2004
MS24399J25	1.250	AS5174J2004
MS24399K25	1.250	AS5174K2004
MS24399S25	1.250	AS5174R2004
MS24399T25	1.250	AS5174T2004
MS24399W25	1.250	AS5174W2004

Cancelled AN PIN	Tube Size	Replacement AS PIN
MS24399-26	1.250	AS5174-2012
MS24399D26	1.250	AS5174D2012
MS24399J26	1.250	AS5174J2012
MS24399K26	1.250	AS5174K2012
MS24399S26	1.250	AS5174R2012
MS24399T26	1.250	AS5174T2012
MS24399W26	1.250	AS5174W2012
MS24399-27	1.250	AS5174-2016
MS24399D27	1.250	AS5174D2016
MS24399J27	1.250	AS5174J2016
MS24399K27	1.250	AS5174K2016
MS24399S27	1.250	AS5174R2016
MS24399T27	1.250	AS5174T2016
MS24399W27	1.250	AS5174W2016
MS24399-28	1.500	AS5174-2416
MS24399D28	1.500	AS5174D2416
MS24399J28	1.500	AS5174J2416
MS24399K28	1.500	AS5174K2416
MS24399S28	1.500	AS5174R2416
MS24399T28	1.500	AS5174T2416
MS24399W28	1.500	AS5174W2416
MS24399-29	1.500	AS5174-2420
MS24399D29	1.500	AS5174D2420
MS24399J29	1.500	AS5174J2420
MS24399K29	1.500	AS5174K2420
MS24399S29	1.500	AS5174R2420
MS24399T29	1.500	AS5174T2420
MS24399W29	1.500	AS5174W2420
MS24399-30	1.000	AS5174-1608
MS24399D30	1.000	AS5174D1608
MS24399J30	1.000	AS5174J1608
MS24399K30	1.000	AS5174K1608
MS24399S30	1.000	AS5174R1608
MS24399T30	1.000	AS5174T1608
MS24399W30	1.000	AS5174W1608

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T14:53Z
Check the source to verify that this is the current version before use.