**NOTICE OF INACTIVATION FOR NEW DESIGN**

**NOT-MEASUREMENT SENSITIVE**

**MIL-DTL-11484/65E**
**NOTICE 1**
**20 January 1999**

**MILITARY SPECIFICATION**

**LAPEL BUTTON, ANTARCTICA SERVICE MEDAL**

MIL-DTL-11484/65E, dated 27 September 1996, is inactive for new design and is no longer used, except for replacement purposes.

**Custodians:**
Army - IH
Navy - NU
Air Force - 45

**Preparing activity:**
Army - IH

**Review activities:**
Navy - CG, MC
Air Force - 32, 82, 99
DLA - CT

**AMSC N/A** **FSC 8455**

**DISTRIBUTION STATEMENT A**: Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T16:26Z
Check the source to verify that this is the current version before use.