MILITARY SPECIFICATION

TELEPHONE SET, TA-840( )/U

This amendment forms a part of MIL-T-28721B(EC) dated 1 November 1973.

Page 1

2.1: Under specification, delete "MIL-I-45208."

Page 3

Add the following:

# "3.10.1.2 Handset"

# Change existing paragraph "3.10.1.2" to "3.10.1.2.1".

Add the following new paragraph:

# "3.10.1.2.2 Multi-conductor wire. Multi-conductor wire shall be used between the diaphragm and the amplifier assembly. The diaphragm shall be adequately secured to prevent wire flex during normal operational usage of the microphone.

Page 8

Under 3.14 , delete "3.13.1" and substitute "3.14.1."

Page 9

# Delete "3.15.1 (b)".

# Delete "3.15.1 (c)" and substitute:

#/ CHANGES FROM PREVIOUS ISSUE. THE OUTSIDE MARGINS OF THIS DOCUMENT HAVE BEEN MARKED "#" TO INDICATE WHERE CHANGES (DELETIONS, ADDITIONS, AND SO FORTH) FROM THE PREVIOUS ISSUE HAVE BEEN MADE. THIS HAS BEEN DONE AS A CONVENIENCE ONLY AND THE GOVERNMENT ASSUMES NO LIABILITY WHATSOEVER FOR ANY INACCURACIES IN THESE NOTATIONS. BIDDERS AND CONTRACTORS ARE CAUTIONED TO EVALUATE THE REQUIREMENTS OF THIS DOCUMENT BASED ON THE ENTIRE CONTENT AS WRITTEN IRRESPECTIVE OF THE MARGINAL NOTATIONS AND RELATIONSHIP TO THE LAST PREVIOUS ISSUE.



Source: https://assist.dla.mil -- Downloaded: 2026-10-20T13:49Z
Check the source to verify that this is the current version before use.

"3.15.1 (c) Tests CS03, CS04, CS05, CS08, RE04 and RS04 shall not apply".

Delete "4.1.1" and renumber "4.1.2" and "4.1.3" accordingly.

Preparing activity:
NAVY-EC
(Project 5805-N162)



Source: https://assist.dla.mil -- Downloaded: 2026-10-20T13:49Z
Check the source to verify that this is the current version before use.