INCH-POUND

MIL-T-41810K
14 May 1990
SUPERSEDING
MIL-T-41810J
30 June 1988

MILITARY SPECIFICATION

TENT, GENERAL PURPOSE, SMALL

This specification is approved for use by all Departments and Agencies of the Department of defense.

1. SCOPE

1.1 Scope. This document covers a six-sided pyramidal tent having the following dimensions. Length of side 8 feet 9 inches; eave height 5 feet; and height at peak 10 feet 6 inches. The tent is equipped with a liner, tent pins and poles and a cover. Both front and rear entrances are provided with a lacing flap arrangement to permit a vestibule attachment or the erection of two tents in tandem.

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Specifications, standards, and handbooks. The following specifications, standards, and handbooks form a part of this document to the extent specified herein. Unless otherwise specified, the issues of these documents shall be those listed in the issue of the Department of Defense Index of Specifications and Standards (DODISS) and supplement thereto, cited in the solicitation (see 6.2).

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be used in improving this document should be addressed to: U.S. Army Natick Research, Development, and Engineering Center, Natick, MA 01760-5014 by using the Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

AMSC N/A

FSC 8340

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

SPECIFICATIONS

FEDERAL

A-A-203	-	Paper, Kraft, Untreated
A-A-883	-	Tape, Pressure-Sensitive Adhesive Masking
L-S-125	-	Screening, Insect, Nonmetallic
T-C-571	-	Cords, Cotton: General and Special Purposes, Sash and Venetian Blind
T-T-871	-	Twine, Cotton, Wrapping
T-T-911	-	Twine, Fibrous, Jute
V-F-106	-	Fastener, Slide, Interlocking
V-T-285	-	Thread, Polyester
QQ-W-321	-	Wire, Copper Alloy
TT-P-595	-	Preservative Coating, Canvas
CCC-C-429	-	Cloth, Osnaburg, Cotton
CCC-C-467	-	Cloth, Burlap, Jute (or Kenaf)
DDD-L-20	-	Label: for Clothing, Equipage and Tentage, (General Use)
PPP-B-601	-	Boxes, Wood, Cleated-Plywood
PPP-B-636	-	Boxes, Shipping, Fiberboard
PPP-B-1055	-	Barrier Material, Waterproofed, Flexible
PPP-T-97	-	Tape, Packaging/Industrial, Filament Reinforced

MILITARY

MIL-F-495	-	Finish, Chemical, Black, for Copper Alloys
MIL-C-496	-	Clips, End, Strap
MIL-P-500	-	Plates, Tent, Peak and Ridge
MIL-P-501	-	Pins, Tent, Metal
MIL-W-530	-	Webbing, Textile, Cotton, General Purpose, Natural or in Colors
MIL-H-1608	-	Hooks, Tent
MIL-L-1709	-	Lines, Tent
MIL-S-1734	-	Slips, Tent Line
MIL-R-2327	-	Rings, Connecting, Round
MIL-C-2399	-	Cement, Liquid, Tent Patching
MIL-R-3390	-	Rings, Dee
MIL-L-11075	-	Loops, Strap Fastener
MIL-G-16491	-	Grommet, Metallic, General Specification For
MIL-L-35078	-	Loads, Unit: Preparation of Semiperishable Subsistence Items; Clothing, Personal Equipment and Equipage; General Specification for
MIL-P-40148	-	Poles, Tent, Telescopic, Adjustable, Aluminum
MIL-S-43002	-	Shield, Stovepipe, Tent, Nonmetallic
MIL-C-43256	-	Cord, Polyester, Solid Braid
MIL-C-43285	-	Cloth, Coated (Chloroprene Base Coated, Chlorosulphonated Polyethylene Top Coated)

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

MIL-T-43333 - Tent Liner, General Purpose, Small and Arctic, 10 Man
MIL-T-43566 - Tape, Textile, Cotton or Polyester, General Purpose, Natural or in Colors
MIL-C-43627 - Cloth, Duck, Cotton, Plied Yarns, Fire, Water, Weather and Mildew Resistant Treated, Lightdry Finish
MIL-W-43638 - Webbing, Textile, Woven, for Tent Framing
MIL-S-43770/10 - Snap Hooks, Cast Body, Fixed Loop Eye W/O Roller, Flat Spring Closure, Wide Mouth
MIL-C-44103 - Cloth, Duck, Polyester, Fire, Water and Weather Resistant

STANDARDS

FEDERAL

FED-STD-751 - Stitches, Seams, and Stitchings

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-129 - Marking for Shipment and Storage
MIL-STD-147 - Palletized Unit Loads
MIL-STD-731 - Quality of Wood Members for Containers and Pallets

(Unless otherwise indicated, copies of federal and military specifications, standards, and handbooks are available from the Standardization Documents Order Desk, Bldg. 4D, 700 Robbins Avenue, Philadelphia, PA 19111-5094.)

2.1.2 Other Government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this document to the extent specified herein. Unless otherwise specified, the issues are those cited in the solicitation.

U.S. DEPARTMENT OF THE ARMY

Field Manual (FM) 10-16-General Repair of Tents, Canvas and Webbing

(Copies are available from the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.)

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

DRAWINGS

U.S. ARMY NATICK RESEARCH, DEVELOPMENT, AND ENGINEERING CENTER

5-4-772	-	Tent, General Purpose, Small: Illustration and Details
5-4-773	-	Assembly and Details
5-4-774	-	Views and Details
5-4-775	-	Front and Rear Details
5-4-776	-	Assembled Front, Rear and Details
5-4-777	-	Side Details and Sections
5-4-778	-	Ventilator and Details
5-4-779	-	Screen Door and Details
5-4-783	-	Cover
5-4-784	-	Flap Details
5-4-785	-	Vestibule and Details
5-4-786	-	Erection Instructions
5-4-787	-	Maintenance, Striking and Folding Instructions

(Copies of drawings are available from the U.S. Army Natick Research, Development, and Engineering Center, ATTN: STRNC-EMSS, Natick, MA 01760-5014.)

2.2 Non-government publications. The following documents form a part of this specification to the extent specified herein. Unless otherwise specified, the issues of the documents which are DOD adopted are those listed in the issue of the DODISS specified in the solicitation. Unless otherwise specified, the issues of documents not listed in the DODISS are the issues of the documents cited in the solicitation (see 6.2).

AMERICAN SOCIETY FOR TESTING AND MATERIALS (ASTM)

D 2016	-	Standard Test Method for Moisture Content of Wood
D 3951	-	Standard Practice for Commercial Packaging

Applications for copies should be addressed to the American Society for Testing and Materials, 1916 Race Street, Philadelphia, PA 19103-1187.)

(Non-Government standards and other publications are normally available from the organizations that prepare or distribute the documents. These documents also may be available in or through libraries or other informational services.)

2.3 Order of precedence. In the event of a conflict between the text of this document and the references cited herein, the text of this document takes precedence. Nothing in this document, however, supersedes applicable laws and regulations unless a specific exemption has been obtained.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

3. REQUIREMENTS

3.1 First article. When specified (see 6.2), a sample shall be subjected to first article inspection (see 6.3) in accordance with 4.3.

3.2 Materials and components. Materials and components shall be as specified herein and as specified in drawings (see 2.1.2). It is encouraged that recycled material be used when practical as long as it meets the requirements of this specification.

3.2.1 Cloth, duck, polyester. The cloth for the tent body, tent peak caps, and vestibule body shall conform to MIL-C-44103. The color shall be Camouflage Green 483.

3.2.2 Cloth, duck, cotton. The cloth for all vestibule reinforcements, and tent reinforcements: A through E, peak reinforcements, roof top reinforcements, reinforcement bands, stove pipe opening reinforcements, inner ply of the cover ventilators shall conform to MIL-C-43627. The color of the cotton duck shall be Olive Drab 7.

3.2.3 Cloth, duck, coated. The cloth for the ground skirts of tents and vestibules shall conform to type I, class 3 of MIL-C-43285. The color of the face and back shall be Camouflage Green 483.

3.2.4 Shield, stovepipe. The stovepipe shield shall conform to MIL-S-43002.

3.2.5 Screening, nonmetallic. The screening shall conform to type II, class 2 or type III, class 1 or 2 of L-S-125.

3.2.6 Tape, cotton. The tape shall be 1/2-inch, 3/4-inch, 1 inch, 1 1/2-inch, and 2-inch widths, Olive Drab 7 conforming to type I, class 4 of MIL-T-43566.

3.2.7 Webbing, cotton. The webbing shall be type IIb, class 4, 1-inch width and type III, class 4, 5/8-inch and 1-1/2 inch widths of MIL-W-530 and the color shall be Olive Drab 7.

3.2.8 Webbing, low elongation. Low elongation webbing shall conform to type I of MIL-W-43638.

3.2.9 Thread, polyester. The thread shall conform to type I, class 1, subclass B of V-T-285 as indicated in table I.

The thread for all stitching shall match Olive Drab S-1 (C.A. 66022). The dyed thread shall show fastness to weathering equal to or better than the standard shade sample (see 6.4). If no standard shade sample is available, the thread shall show "good" fastness to weathering.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

TABLE I. Thread sizes

Location	Size
For all stitching on tent, vestibule, and cover, except zig-zag stitching, bartacking, and stitching indicated by "Z" on drawings	Size F for needle and size E for bobbin
For zig-zag stitching and bartacking	Size E
For stitching indicated by "Z" on drawings	Size F for needle and size E for looper

3.2.10 Lines, tent.

3.2.10.1 Footstops. Footstops shall be as shown on Drawing 5-4-774 and shall be made of cord conforming to type I, class 3, size 7 of T-C-571.

3.2.10.2 Lines, tent, yellow. The corner eave tent lines shall conform to type LII, shade Yellow 24 of MIL-L-1709, except that the length shall be 15 feet 6 inches (see 6.4).

3.2.10.3 Lines, tent, natural. The natural color tent lines shall conform to type LII (intermediate eave line), type LIII (corner roof line), and type LIV (door and vestibule eave line) of MIL-L-1709, except that the lengths shall be 15 feet 6 inches, 24 feet, and 24 feet 6 inches, respectively.

3.2.10.4 Cord, polyester. Ventilator lines, beckets, and toggle loops shall be 1/8-inch diameter cord conforming to MIL-C-43256.

3.2.11 Drip cap stiffener. The drip cap stiffener shall be made of cord specified in 3.2.10.1.

3.2.12 Toggles.

3.2.12.1 Toggles, wood. The wood toggles shall be of the design and dimensions shown on Drawing 5-4-776. They shall be fabricated from uniformly dried, straight grained lumber, and shall contain not more than 15 percent moisture when tested as specified in 4.4.1.1. Toggles shall be free from knots, shakes, checks, splits, or splintery surface. Any of the following woods may be used:

Hickory	Pecan
Red or white oak	Rock elm
Beech	Hard maple
Birch	Ash

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

3.2.12.2 Toggles, metal. The metal toggles shall be of the design and dimensions shown on Drawing 5-4-774 and shall be fabricated from brass wire conforming to alloy No. 270, half-hard temper of QQ-W-321. The toggles shall be given a black chemical finish conforming to MIL-F-495.

3.2.13 Slips, tent line. The tent line slips shall conform to type II of MIL-S-1734.

3.2.14 Fasteners, slide, interlocking. The slide fasteners shall conform to size H, wire stirrup pull of V-F-106. Slide fastener chain shall be fabricated of brass or polyester coil. The slider for the brass chain shall be brass and the slider for the polyester coil shall be die cast zinc alloy. The slide fastener tape shall be dyed to match Olive Drab shade 5 (CA 66519) and be water repellent and mildew-resistant. (Tapes made of 100 percent polyester need not be tested for mildew resistance.) The color of the tape after treatment will be considered acceptable. The tape shall show good fastness to weathering. Alternatively, the slide fastener chain shall be polyester continuous monofilament in a ladder or coil type configuration. Color of the chain shall be Olive Drab or natural finish brass and the sliders shall be brass.

3.2.15 Rings, dee. The dee rings shall conform to class 1 or 2, configuration K, 1-inch by 3/4-inch, or MIL-R-3390.

3.2.16 Rings, connecting, round. The tent rings shall conform to class 2 or 5, size 2 of MIL-R-2327.

3.2.17 Plate, peak. The peak plate shall conform to type XVIII of MIL-P-500.

3.2.18 Snap hooks. The snap hooks shall conform to MIL-S-43770/10.

3.2.19 Grommets, metallic. The grommets shall conform to type III, class 3, size Nos. 1, 2 and 4 of MIL-G-16491.

3.2.20 Clips, end. The end clips shall conform to type I, class 1 or 2, size 1-inch of MIL-C-496.

3.2.21 Loops, strap fastener. The strap fastener loops shall conform to type III, style B of MIL-L-11075.

3.2.22 Hooks, tent. The tent hooks used at the peak plate shall conform to type I, size 1-inch of MIL-H-1608.

3.2.23 Pins, tent, metal. When required the tent pins shall be type I, conforming to MIL-P-501.

3.2.24 Poles, tent, telescopic. When required the aluminum adjustable, telescopic poles shall conform to MIL-P-40148.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

3.2.25 Liner, tent. When required the tent liner shall conform to MIL-T-43333.

3.3 Construction. The construction shall conform in all respects to the drawings listed in section 2 and as specified herein.

3.3.1 Stitching, machine.

3.3.1.1 Types of stitching. All stitching types, except bartacking, shall conform to FED-STD-751 as indicated in table II.

TABLE II. Stitching types

Location	Type	Number of stitches per inch
For all stitching except zig-zag stitching and stitching indicated by "Z" on drawings and alternatively for attachment of slide fasteners	301	5 to 7
For zig-zag stitching	304	10 to 16
For stitching indicated by "Z" on drawings and alternatively for attachment of slide fasteners	401	5 to 7 (chain portion of stitching shall not appear on outside of tent, vestibule, screen, or tent cover)
For bartacking		Bartack 1/2 (± 1/16) inch long with 1/8 ± 1/32 inch bight and shall contain 28 stitches

3.3.1.2 Type 301 stitching. Ends of all stitching shall be backstitched or overstitched 1/2 inch minimum except when caught in other stitching or turned under in a hem. Thread tension shall be maintained so that there will be no loose stitching resulting in puckering of material sewn. The lock shall be embedded in the material sewn.

3.3.1.3 Repairs of type 301 stitching. Repairs of type 301 stitching shall be as follows:

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

a. When thread breaks or bobbin run-outs occur during sewing, the stitching shall be repaired by restarting the stitching a minimum of 1 inch behind the end of the stitching. 1/

b. Thread breaks or two or more consecutive skipped or run-off stitches noted during inspection of the item (in-process or end item) shall be repaired by overstitching. The stitching shall start a minimum of 1 inch before the defective area (1/2 inch on box, box and cross, and W-W stitching) and continue a minimum of 1 inch beyond the defective area onto the existing stitching. Loose or excessively tight stitching shall be repaired by removing the defective stitching, without damaging the materials, and restitching in the required manner. 1/

1/ When making the above repairs, the ends of the stitching are not required to be backstitched.

3.3.1.4 Type 401 stitching. Thread tension shall be maintained so that there will be no loose stitching. Both ends of seams or stitching produced with a 401 stitch type, when not turned under a hem or held down by other stitching, shall have a 3/4 to 1-inch chain extending beyond each end. The looper (under thread) shall always be on the inside of the tent or cover. All repairs shall be made in accordance with 3.3.1.3a or 3.3.1.3b. Repairs may be made using a 301 stitch type.

3.3.1.5 Type 304 stitching. For type 304 stitching, thread tension shall be maintained so that there will be no loose or excessively tight stitching. Repairs shall be in accordance with 3.3.1.3a or 3.3.1.3b except that the stitching shall over stitch the defective stitching area a minimum of three stitches onto the existing stitching.

3.3.1.6 Automatic stitching. Automatic stitching machines may be used to perform any of the required stitch patterns provided the requirements for the stitch pattern, stitches per inch, size and type of thread are met, and at least three or more tying, overlapping or backstitches are used to secure the ends of stitching.

3.3.1.7 Thread ends. All thread ends that are visible on the finished item shall be trimmed to a length of not more than 1/4-inch.

3.3.1.8 Stitching margins. Unless otherwise specified, all stitch margins shall be 1/8, +1/16 -0 inch.

3.3.1.9 Bartacking. Bartacking shall be free of thread breaks or loose stitching.

3.3.1.10 Lubrication of thread. The addition of any lubricant to the polyester sewing thread prior to or during the sewing operation is prohibited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

3.3.2 Attachment of slide fasteners. Care shall be taken to trim all thread ıds and maintain specified distances between the edges of fabric attached to ıide fastener tape so that there will be no interference with the operation of ıe slider.

3.3.3 Attachment of wood toggles. Wood toggles shall be attached as ıllustrated on Drawing 5-4-776.

3.3.4 Setting of grommets. Holes punched to receive the grommets shall be ıaller than the outside diameter of the grommet barrel so that the barrel must ₹ forced through the hole. The grommets shall be securely clinched without ıtting the materials. The roll of the grommet shall not contain splits.

3.3.5 Setting of end clips. The webbing shall be inserted the full depth of ıe clips. The clips shall be securely attached without cutting the webbing, ıd the webbing shall be flat at the point of entrance.

3.3.6 Repairs. All necessary repairs shall be effected in accordance with ıe Department of the Army Field Manual FM 10-16 (see 2.1.2), except that hand- ₹wn patches or cemented patches other than as specified herein will not be ₹ceptable. Cemented patches on holes, cuts, or tears not more than 1-inch in ıameter or length, using cement specified in MIL-C-2399, shall be permitted. A ıximum of three cemented patches per tent shall be allowed without prior ıthorization by the contracting officer. All other repairs shall require ₹ntracting officer authorization. Repairs required as a result of failure of ıe wicking test shall be performed by treating with a compound conforming to ₹pe I, class 1 of TT-P-595 prior to retesting (see 6.6).

3.3.7 Wicking of sewing thread. There shall be no dripping of water through ₹e tent stitching when the tent is tested as specified in 4.5.1. The cup test ₹ intended to insure that non-wicking thread has been utilized and that no ıbrication has been added to the polyester thread prior to or during the sewing ₹eration.

3.3.8 Splicing of cloth. There shall be no splicing of roof, wall or tent ₹ver panels. Splicing of reinforcements and sod cloth sections will be ₹rmitted and, if performed, shall conform to the following requirements:

a. Eight feet or less in length - One splice permitted;
More than 8 feet but not more than 12 feet in length - Two splices permitted;
More than 12 feet in length - Three splices permitted.

b. The shortest length of any spliced piece shall be not less than 2 feet.

c. Pieces shall be joined as shown on Drawing 5-4-777, section MM.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

3.3.9 Splicing of beckets. Splicing will be permitted in the tent doorways and if performed, shall conform to Drawing 5-4-773 with a minimum distance of five feet between splices. No splice shall be in any portion of the loop.

3.3.10 Splicing of webbing. There shall be no splicing of webbing in any portion of the roof section of the tent. Splicing of webbing will be permitted in the liner and other areas, and if performed, shall conform to Drawing 5-4-777. One splice per gore is permitted. A minimum distance between splices shall be 5 feet.

3.3.11 Replacement of defective components. During the spreading, cutting and manufacturing process, components of the tent having material defects or damages that are classified as defects in 4.4.3 shall be removed from production and replaced with non-defective and properly matched components.

3.3.12 Fusing of ends of synthetic cord, webbing and tape. All ends of synthetic cord, webbing, and tape shall be fused. The apparatus used to fuse the ends shall be capable of providing sufficient heat to provide a smooth edge with the cut ends of the cord, webbing and tape yarns all fused together. Fusing of the ends shall be accomplished prior to being assembled for stitching.

3.4 Marking. All marking shall conform to DDD-L-20.

3.4.1 Special marking. The letters "US" on the tent and the tent cover, instructions on the door, and nomenclature on the tent cover shall conform to type IV, class 9 in the size characters and in the locations shown on the drawings. Class 9 markings shall be clearly legible after subjection to accelerated weathering.

3.4.2 Identification label. Identification labels shall conform to type VI, class 6 and shall be 3-1/2 inches by 5-1/2 inches minimum, and a blank space of at least 1-1/4 inches shall be provided on the bottom of the label for the Department of Defense inspector's stamp. Identification labels shall be stitched to the tent, vestibule, and tent cover in the locations shown on the drawings.

3.4.3 Erection instructions and care and maintenance instructions labels. Labels of erection instructions and care and maintenance instructions shall conform to type VI, class 7 and shall be stitched to the tent and the tent cover in the locations shown on the drawings. The labels shall be proportionate copies of Drawings 5-4-786 and 5-4-787 reproduced from a glossy print of the applicable drawing furnished by the contracting officer (see 6.5). The size of the labels shall be 15 inches, $\pm$ 1/4 inch in the longer dimension, with a minimum 1/2-inch margin outside of the borderline on all sides.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

3.5 Workmanship. Cloth components shall be clean and free of holes, cuts, tears or cloth defects such as multiple floats or broken or missing yarns. Webbing and tapes shall not have frayed or scalloped edges, and rope components shall be free of cuts or breaks. Metal components shall be free of burrs, sharp edges or corroded areas and shall not be broken or malformed. The tent shall conform to the quality of product established by this specification and the occurrence of defects shall not exceed the applicable acceptable quality levels.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements (examinations and tests) as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in this specification where such inspections are deemed necessary to ensure supplies and services conform to prescribed requirements.

4.1.1 Responsibility for compliance. All items shall meet all requirements of sections 3 and 5. The inspection set forth in this specification shall become a part of the contractor's overall inspection system or quality program. The absence of any inspection requirements in the specification shall not relieve the contractor of the responsibility of ensuring that all products or supplies submitted to the Government for acceptance comply with all requirements of the contract. Sampling inspection, as part of manufacturing operations, is an acceptable practice to ascertain conformance to requirements, however, this does not authorize submission of known defective material, either indicated or actual, nor does it commit the Government to accept defective material.

4.1.2 Responsibility for dimensional requirements. Unless otherwise specified in the contract or purchase order, the contractor is responsible for ensuring that all specified dimensions have been met. When dimensions cannot be examined on the end item, inspection shall be made at any point, or at all points in the manufacturing process necessary to ensure compliance with all dimensional requirements.

4.2 Classification of inspections. The inspection requirements specified herein are classified as follows:

a. First article inspection (see 4.3).
b. Quality conformance inspection (see 4.4).

4.3 First article inspection. When a first article is required (see 3.1 and 6.2), it shall be examined for defects specified in 4.4.3 and 4.4.4 and tested for the characteristics specified in 4.4.5. Any nonconformance shall be cause for the rejection of the first article.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection. Unless otherwise specified, sampling for inspection shall be performed in accordance with MIL-STD-105.

4.4.1 Component and material inspection. In accordance with 4.1, components and materials shall be inspected in accordance with all the requirements of referenced documents unless otherwise excluded, amended, modified, or qualified in this specification or applicable purchase document.

4.4.1.1 Wood toggle moisture content testing. The wood toggles shall be tested for conformance to the moisture content requirements in 3.2.12.1. The moisture content shall be determined in accordance with the oven-drying or the electronic meter method referenced in ASTM D 2016. The results shall be reported to the nearest 0.1 percent for each toggle tested. The lot size shall be expressed in units of toggles. The sample unit shall be one toggle. The inspection level shall be S-1 and the acceptable quality level (AQL), expressed in terms of defects per hundred units, shall be 4.0.

4.4.2 In-process inspection. Inspection shall be made of the following operations or assemblies to establish conformance to specified requirements. Whenever nonconformance is noted, correction shall be made to the items affected and to the operation. Items which cannot be corrected shall be removed from production.

a. There is no lubrication to the polyester thread (see 3.3.1.10).
b. Holes punched to receive grommets conform to 3.3.4

4.4.3 End item visual examination.

4.4.3.1 Tent with vestibule and cover. The end item shall be examined for the applicable defects listed in table III. The lot size shall be expressed in units of tents with vestibules and covers. The sample unit shall be one tent with vestibule and cover. The inspection level shall be I and the AQL, expressed in terms of defects per hundred units, shall be 25 for major defects, 100 for major and minor A combined defects and 250 for total (major, minor A and minor B combined) defects.

4.4.3.2 Vestibule only or cover only. The end item shall be examined for the applicable defects listed in table III. The lot size shall be expressed in units of vestibules or covers. The sample unit shall be one vestibule or cover. The inspection level shall be I and the AQL, expressed in terms of defects per hundred units, shall be 15 for major defects, 40 for major and minor A combined defects and 150 for total (major, minor A and minor B combined) defects.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

TABLE III. End item visual defects

Examine	Defect	Classification Major	Minor A	Minor B
Fabric	Cut, tear, or hole:			
	-greater than 1/8 inch in length or diameter:			
	-on roof	101		
	-on walls, sod cloth, or cover		201	
	-more than 5 holes not greater than 1/8 inch:			
	-on roof		202	
	-on walls, sod cloth, or cover			301
	Broken or missing yarn: multiple floats clearly visible at normal inspection distance (approximately 3 feet)		203	
Screening	Cut or tear:			
	-more than 2 inches in length	102		
	-more than 1/4 inch but not more than 2 inches in length		204	
Webbing, tie tapes	Edge frayed, scalloped, cut, torn or caught in stitches			302
Hardware	Broken	103		
	Malformed:			
	-fails to perform intended function	104		
	-but will perform intended function		205	
	Corroded area			303
	Burr or sharp edge that may cause injury in handling or damage to fabric	105		
Grommets	Improperly set; two or more teeth exposed (except where grommet is set as specified but is in an area of unequal thickness that prevents uniform clinching)		206	
	Clinched loosely, allowing grommet to rotate in hole		207	

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

TABLE III. End item visual defects - Continued

Examine	Defect	Classification Major	Minor A	Minor B
Grommets (cont'd)	Clinched excessively tight, cutting fabric:			
	-on tent	106		
	-on cover		208	
	Insecurely clinched on tent or vestibule (i.e., grommet or washer may become disengaged)	107		
	Roll of grommet contains splits			304
Tent hooks	Hook not securely closed, allowing connecting hardware to become disengaged		209	
	Set with hook portion facing roof			305
Snap hooks	Reversed (i.e. set with spring tongue facing roof in lieu of interior of tent in a downward position)		210	
End clips	Not securely clinched, webbing not flat at point of insertion			306
	Clinched excessively tight cutting webbing		211	
Toggles, wood	Any knots, shakes, or checks			307
	Any splits or splintery surfaces		212	
Rope components	Any cut or any break:			
	-on guy line		213	
	-on footstop			308
	Eye splice omitted		214	
	Eye splice not as specified			309
	Any free end not finished as specified			310
Tent pins	Not type specified	108		
Tent poles	Not type specified	109		

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

TABLE III. End item visual defects - Continued

Examine	Defects	Classification Major	Minor A	Minor B
Tent liner	Missing (when required)	110		
Seams and stitching	Open seam on stitch type 301:			
	-for more than 1/4-inch but not more than 1-inch			311
	-for more than 1-inch		215	
	Open seam on stitch type 401:			
	-one row of stitching open for 1-inch or less on tent, vesitibule or cover:			312
	-one row of stitching open for more than 1-inch:			
	-on roof		216	
	-on wall or cover			313
	-both rows of stitching open (not necessarily at same location):			
	-on roof	111		
	-on wall or cover		217	
NOTE:	A seam shall be classified as open when one or more stitches joining a seam are broken, or when two or more consecutive skipped or runoff stitches occur. On double-stitched seams, a seam shall be classified as open when either one or both sides of a seam are open.			
	Raw edges caught in stitching:			
	-more than 1-inch but not more than 3-inches		218	
	-more than 3-inches	112		

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

TABLE III. End item visual defects - Continued

Examine	Defect	Classification Major	Minor A	Minor B
Seams and stitching (cont'd)	Thread breaks:			
	-overstitched less than 1-inch on stitch type 401			314
	-overstitched fewer than 3 stitches on stitch type 301			315
	-overstitched less than 3 stitches on stitch type 304			316
	NOTE: Thread breaks not overstitched shall be classified as open seams.			
	Skipped stitches overstitched less than 1-inch on stitch type 401 or 301; less than 3 stitches on type 304 (when two or more skipped stitches occur consecutively)			317
	NOTE: Skipped stitches not overstitched shall be classified as open seam.			
	Needle chew resulting in cut, tear or hole (see Cut, tear or hole under Fabric examination)			
	One or more required rows of stitching omitted (except on boxstitching and "W" stitching)	113		
Boxstitching	Incomplete:			
	-one row or more of stitching omitted			318
	-two or more rows of stitching omitted		219	
	Any boxstitching less than specified length by more than 1/8-inch			319

Source: https://assist.dla.mil -- Downloaded: 202610-21T19:43Z
Check the source to verify that this is the current version before use.

TABLE III. End item visual defects - Continued

Examine	Defect	Classification Major	Minor A	Minor B
"W" stitching	Incomplete:			
	-one row of stitching omitted		220	
	-two or more rows of stitching omitted	114		
	Any "W" stitching less than specified length by more than 1-inch			320
Bartacking	Any bartacking less than specified length by more than 1/8-inch			321
Stitching ends	Overstitched less than 1/2-inch on stitch type 301 (except where ends are held down by other stitching, where ends are turned under in a hem, or where stitching is performed automatically)		221	
	Secured with less than 3 tying, overlapping, or backstitches when automatic stitching is performed		222	
	Secured with less than 1/4-inch of backstitching, overstitching, or an increased number of stitches per inch at the end of stitch type 304			322
Seams	Seam pleated:			
	-on roof		223	
	-at eave or on wall			323
Seam type	Wrong seam type	115		
Stitch type	Wrong stitch type	116		
Stitch tension	Loose for more than 6-inches, resulting in an exposed bobbin or top thread		224	
	Tight for more than 6-inches, as evidenced by puckering on fabric		225	

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

TABLE III. End item visual defects - Continued

Examine	Defect	Classification Major	Minor A	Minor B
Seams and stitching (cont'd)				
Stitches per inch	Less than minimum specified (except panel joining seams):			
	-one stitch			324
	-two or more stitches		226	
	Less than minimum specified on panel joining seams		227	
	More than maximum specified:			
	-one stitch			325
	-two or more stitches		228	
	NOTE: Variation in the number of stitches per inch, caused by the operator speeding up the machine and pulling the fabric in order to sew over heavy places or heavy seams or in turning corners, shall be classified as follows: a. Within the minor "B" defect classification - no defect b. Within the minor "A" defect classification - minor "B" defect			
Stitching gage	Not as specified		229	

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

TABLE III. End item visual defects - Continued

Examine	Defect	Classification Major	Minor A	Minor B
Seams and stitching (cont'd)				
Stitching margin	Larger than specified:			
	-for more than 2-inches but not more than 4-inches in length			326
	-for more than 4-inches in length		230	
	Less than specified:			
	-for more than 2-inches but not more than 4-inches in length			327
	-for more than 4-inches in length		231	
Stitching indicated by "Z" on drawings	Chain portion of stitching shows on outside of tent, vestibule, or cover		232	
Mends, darns or patches	Repairs not in accordance with Department of the Army Field Manual FM 10-16 or not authorized by the contracting officer (see 3.3.6)	117		
Components and assembly	Any component missing	118		
	Any component part not fabricated of applicable referenced material		233	
Hems	Constructed with partial turnunder when double turnunder is required		234	
	Twisted or pleated			328

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

TABLE III. End item visual defects - Continued

Examine	Defect	Classification Major	Minor A	Minor B
Seams and stitching (cont'd)				
Reinforcements	Improperly applied causing excessive fullness on reinforcement or reinforced part			329
	Splicing of reinforcement bands -more splices than permitted		235	
	-spliced piece less than 2 feet in length		236	
	-splicing not as indicated on applicable drawings		237	
Binding	Improperly or loosely applied, ends not finished as specified			330
Slide fasteners	Slider jams or fails to interlock chain	119		
	Any tape improperly assembled causing failure of chain to effect a smooth and secure closure	120		
	Wrong length	121		
	Width not as specified	122		
	Puckering of tape	123		
	Broken or missing scoops	124		
	Thong omitted	125		
	NOTE: The inspector shall pull slide fasteners three or four times to an open and closed position to determine proper function and effectiveness of each fastener.			

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

TABLE III. End item visual defects - Continued

Examine	Defect	Classification Major	Minor A	Minor B
Construction detail				
Tent line lugs	Any lug stitched through roof only instead of through reinforcement webbing and roof reinforcement	126		
	Any part of lug single ply construction		238	
	Piece "B" improperly set, causing fullness on tent or distortion of corners		239	
Doorway flaps	Left edge flap not stitched through door opening tape reinforcement		240	
	Top end of flap not stitched through wall, eave band, and tape reinforcement		241	
	Facing improperly applied, causing fullness on flap			331
Toggle loops	Loops not securely stitched to flap		242	
	End of loops exposed (i.e. not turned under or not caught in stitching attaching flap to wall)			332
Toggles	Toggle held in place with a single turn of rope around groove, or double turn not overhand knotted			333
Beckets	Cord not continuous			334
	Any becket loose (i.e. not caught in stitching on either side)		243	
	Not continuous or spliced within 6-inches of grommet			335
	Not spliced as specified			336
	More than two splices per connecting lug		244	
	Spliced cord less than 5 feet in length		245	

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

TABLE III. End item visual defects - Continued

Examine	Defect	Classification Major	Minor A	Minor B
Construction detail (cont'd)				
Beckets (cont'd)	Splice not centered between beckets			337
	Splice not made as indicated on Drawing 5-4-773		246	
Vent flaps	Top of flaps not overlapped	127		
	Misplaced (i.e. not stitched through vent opening reinforcement)		247	
Stovepipe shield	Set to roof with oval opening in a horizontal position instead of vertical	128		
	Exposed stitching or needle holes			338
Peak assembly	Webbing engaging snaps out of alignment with peak plate holes resulting in distortion or stress on the fabric	129		
Peak cap	Improperly applied (i.e. irregular in circumference or pleated)			339
Splicing of webbing	Splicing (when necessary) not made as indicated on Drawing 5-4-777			340
	More than one splice per gore on seams joining tent panels		248	
Cloth splicing	Splice in roof wall, or tent cover panels	130		
	Number of splices per reinforcement or sod cloth section more than specified		249	
	Spliced pieces not joined as shown on Drawing 5-4-777			341
General	Any other construction detail not performed as specified		250	

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

TABLE III. End item visual defects - Continued

Examine	Defect	Classification Major	Minor A	Minor B
Labels	Omitted, incorrect, illegible or misplaced: -care and maintenance, or erection instruction	251		
	-identification			342
Markings: "U.S." and identification	Omitted, incorrect, illegible, or misplaced			343
Cleanness	Grease or oil stains			344
	Thread ends not trimmed to 1/4-inch or less (except in slide fastener area)			345
	Thread ends not trimmed to 1/4-inch or less in slide fastener area	252		

4.4.4 End item dimensional examination.

4.4.4.1 Tent with vestibule and cover. The end items shall be examined to determine compliance with the applicable dimensions specified in table IV. Any nonconformance shall be considered a defect. The lot size shall be expressed in units of tents with vestibules and covers. The sample unit shall be one tent with vestibule and cover. The inspection level shall be S-3 and the AQL, expressed in terms of defects per hundred units, shall be 2.5 for major defects, 15 for major and minor A combined defects, and 40 for total (major, minor A and minor B combined) defects.

4.4.4.2 Vestibule only or cover only. The end items shall be examined to determine compliance with the applicable dimensions specified in table IV. Any nonconformance shall be considered a defect. The lot size shall be expressed in units of vestibules or covers. The sample unit shall be one vestibule or cover. The inspection level shall be S-3 and the AQL, expressed in terms of defects per hundred units, shall be 10 for major defects, 25 for major and minor A combined defects, and 100 for total (major, minor A and minor B combined) defects.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

TABLE IV. End item dimensional defects

Examine	Defect	Classification Major	Minor A	Minor B
Overall dimensions of tent or vestibule	Smaller than specified dimensions less applicable minus tolerance indicated on drawings	101		
	Larger than specified dimensions and applicable plus tolerance indicated on drawings			301
Tent cover ventilator opening dimensions	Smaller than specified dimensions less applicable minus tolerance indicated on drawing, but not smaller than the specified dimensions less twice the applicable minus tolerance			302
	Smaller than specified dimensions less twice the applicable minus tolerance indicated on drawings		201	
	Larger than specified dimensions and applicable plus tolerance indicated on drawings			303
Location dimensions (unless otherwise specified)	Not within specified tolerance: -not exceeding twice the applicable tolerance			304
	-exceeding twice the applicable tolerance		202	
Webbing, tie tapes	Finished length less than specified by more than 1-inch			305
	Turnunder at ends of webbing engaging hardware less than specified: -by more than 1-inch but not more than 1-1/2 inches		203	
	-by more than 1-1/2 inches	102		
	Distance between splices on webbing less than 5 feet			306

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

TABLE IV. End item dimensional defects - Continued

Examine	Defect	Classification Major	Minor A	Minor B
Grommets	Set beyond specified location by more than 1/2-inch			307
Rope components, tent lines	Eye on footstop or line less than specified by more than 1/2-inch			308
	Finished length of guy line less than specified:			
	-by more than 12-inches	103		
	-by more than 4-inches but not more than 12-inches		204	
	-by not more than 4-inches			309
Lug, connecting	End set above or below specified location by more than 1/2-inch			310
Beckets	Misplaced:			
	-by more than 1/4-inch but not more than 1/2-inch			311
	-by more than 1/2-inch		205	
	Length of loop more or less than specified by 1/2-inch or more		206	
Toggle loops	Free end of loop extending less than 3/4-inch beyond edge of flap			312
Metal toggle chapes	Misplaced:			
	-by more than 1/4-inch but not more than 1/2-inch			313
	-by more than 1/2-inch		207	
Hems	Hems required to finish less than 3/4-inch in width, less than specified; hems required to finish more than 3/4-inch in width, less than specified by more than 1/4-inch			314

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

TABLE IV. End item dimensional defects - Continued

Examine	Defect	Classification Major	Minor A	Minor B
Reinforcements	Finished dimensions less than specified by more than 1/2-inch			315
Tent line lugs	Loop portion of piece "A" less than 3/4-inch		208	
Snow cloths (tent and vestibule)	Less than specified width by more than 1-inch			316
Doorway flaps	Bottom end of flap uneven with breakline of wall by more than 1/4-inch; outer edge or end of facing uneven with edge or end of flap by more than 1/4-inch			317
Peak of wall	Peak of wall halves joined to roof with edges of door opening less than 7/8-inch apart, failing to provide clearance for top of slide fastener		209	
Ventilator opening	Misplaced by more than 1/2-inch			318
Stovepipe opening	Misplaced by more than 1/2-inch			319
Rings and ring chapes	Misplaced: -by more than 1/4-inch but not more than 1/2-inch			320
	-by more than 1/2-inch		210	
Cover flaps	Center line of flaps set off center of body by more than 3/4-inch			321

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

4.4.5 End item testing. The completely fabricated end items (tent with/without vestibule or vestibule only) shall be tested as specified in 4.5.1 for conformance to the wicking requirements specified in 3.3.7. The lot size shall be expressed in units of end items. The sample size shall be the number of end items indicated by inspection level S-3. Any test failure shall be cause for rejection of the lot.

4.4.6 Packaging examination. The fully packaged end items shall be examined for the defects listed below. The lot size shall be expressed in units of shipping containers. The sample unit shall be one shipping container fully packaged. The inspection level shall be S-2 and the AQL, expressed in terms of defects per hundred units, shall be 2.5.

Examine	Defect
Marking	Omitted; incorrect; illegible; of improper size, location, sequence, or method of application
Materials	Any component missing, damaged, or not as specified
Workmanship	Inadequate application of components, such as: incomplete sealing or closure of flap, improper taping, loose strapping or inadequate stapling Bulged or distorted container
Content	Number per container is more or less than required.

4.4.7 Palletization examination. The fully packaged and palletized end items shall be examined for the defects listed below. The lot size shall be expressed in units of palletized unit loads. The sample unit shall be one palletized unit load, fully packaged. The inspection level shall be S-1 and the AQL, expressed in terms of defects per hundred units, shall be 6.5.

Examine	Defect
Finished dimensions	Length, width, or height exceeds specified maximum requirements
Palletization	Pallet pattern not as specified Interlocking of loads not as specified Load not bonded as specified
Weight	Exceeds maximum load limits
Marking	Omitted; incorrect; illegible; of improper size, location, sequence, or method of application

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

4.5 Methods of inspection.

4.5.1 Wicking of sewing thread (cup test). The tent and vestibule shall each be tested in three areas as follows: at the peak, at a ridge or on a joining seam abutting the peak or ridge; at an intersection of a horizontal and vertical seam such as at an intersection of a side wall and roof; and on a roof panel seam. The seamed section of the test fabric shall be suspended in the center of a 6 ± 1/8 inch diameter hoop and shall form a depression with the seam fabric in the hoop to a depth of 1 ± 1/4 inch. Slowly pour 500 mL of water at 77° ± 4°F into the cupped area (depression) and observe the under surface of the fabric for water penetration. Any wicking of water in any test area along the sewing thread, identified by a discoloration or darkening of the thread within 5 minutes after water is poured, shall constitute a test failure. Water leakage through the needle holes or between the plies of the lapped seamed fabric shall not be considered a failure.

5. PACKAGING

5.1 Preservation. Preservation shall be level A or Commercial, as specified (see 6.2).

5.1.1 Level A preservation.

5.1.1.1 Tent, with vestibule. Each tent shall have all slide fasteners closed. The six sides shall be folded in accordion pleats extending from the peak to the bottom of the side wall and laid one upon another. All lines shall be placed within the folds and on top of the tent. The tent shall be folded in half the width to approximately 30 inches. The tent shall then be folded in half the length by bringing the peak down to the outer edge of the sod or snow cloth. The length shall be folded in half again so that the completely folded tent approximates 30 by 44 inches. Care shall be taken during the folding operation to expel entrapped air. The vestibule, with slide fasteners closed, shall be neatly and compactly folded to dimensions equal to or slightly less than the length and width dimensions of the folded tent. The completely folded tent and vestibule shall be placed within the cover and the cover securely closed with the cover straps. All cover corners shall be closed and the flaps neatly folded within the bundle.

5.1.1.2 Tent without vestibule. Each tent shall have all slide fasteners closed. The six sides shall be folded in accordion pleats extending from the peak to the bottom of the side wall and laid one upon another. All lines shall be placed within the folds and on top of the tent. The tent shall be folded in half the width to approximately 30 inches. The tent shall then be folded in half the length by bringing the peak down to the outer edge of the sod or snow cloth. The length shall be folded in half again so that the completely folded tent approximates 30 by 44 inches. Care shall be taken during the folding operation to expel entrapped air. The completely folded tent shall be placed within the cover and the cover securely closed with the cover straps. All cover corners shall be closed and the flaps folded within the bundle.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

5.1.1.3 Vestibule. Each vestibule, with slide fasteners closed, shall be smoothly folded flat to measure approximately 30 by 22 inches. All lines shall be placed within the folds and on top. Care shall be taken during the folding operation to expel entrapped air. Five vestibules of one type only shall be neatly stacked in a bundle and completely wrapped with waterproofed kraft wrapping paper conforming to class B-1 or B-2 or PPP-B-1055. The wrapped bundle shall be cross-taped with minimum 1-inch wide tape conforming to type III of PPP-T-97.

5.1.1.4 Tent covers. Each cover, when procurred separately, shall be compactly folded so that the identification markings are visible. The folded cover shall measure approximately 20 by 14 inches. All straps shall be placed within the folds. Five folded covers shall be stacked and cross-tied with cotton tape or twine.

5.1.1.5 Tent liner. Each tent liner (see 3.2.25), with slide fasteners closed, shall be smoothly folded flat to measure approximately 30 by 44 inches. Care shall be taken during the folding operations to expel entrapped air. Five folded liners shall be stacked and cross-tied with cotton tape or twine.

5.1.1.6 Tent, with tent pins, tent poles, and liner. Each tent and liner shall be folded as specified in 5.1.1.2 and 5.1.1.5, respectively. Twenty-nine tent pins, one 10-foot tent pole, and eight 7-foot tent poles (see 3.2.23 and 3.2.24) shall be secured in compact bundles with the poles reduced to their shortest length. Each bundle shall be completely wrapped with 50-pound basis weight kraft paper conforming to A-A-203 and wrapped securely with minimum 1-inch wide tape conforming to A-A-883. The tent, tent liner, tent pins, and tent poles shall then be placed within the cover and the cover securely closed with the cover straps. All cover corners shall be closed and the flaps folded within the bundles.

5.1.2 Commercial preservation. Each tent with vestibule; tent without vestibules; tent with tent pins, tent poles, and liner; vestibules only; or tent covers only shall be preserved in accordance with ASTM D 3951.

5.2 Packing. Packing shall be level A, B, or Commercial, as specified (see 6.2).

5.2.1 Level A packing.

5.2.1.1 Tent with vestibule and cover; tent with cover; tent and cover, tent pins and poles and liner; or vestibule only. Four tents with vestibules; four tents without vestibules; four tents with tent pins, tent poles, and liners; or twenty vestibules, when procured separately (see 6.2), preserved as specified in 5.1, shall be respectively packed in a snug-fitting cleated-plywood container conforming to overseas type, type 3 load of PPP-B-601. Each container shall be provided with skids as specified in PPP-B-601. Each shipping container shall be closed and reinforced with flat steel strapping in accordance with the appendix of PPP-B-601.

Source: https://assist.dla.mil -- Downloaded: 202610-21T19:43Z
Check the source to verify that this is the currentversion before use.

5.2.1.2 Tent covers. Ten tent covers, when procured separately (see 6.2), preserved as specified in 5.1, shall be packed in a snug-fitting fiberboard shipping container conforming to style RSC-L, grade V2s of PPP-B-636. The inside of each container shall be fitted with a box liner conforming to type CF, class weather-resistant, variety DW, grade V15c of PPP-B-636. Each shipping container shall be closed in accordance with method III, waterproofed in accordance with method V, and reinforced as specified in the appendix of PPP-B-636. Shipping containers shall be arranged in unit loads in accordance with MIL-L-35078 for the type and class of load specified (see 6.2). Strapping shall be limited to nonmetallic strapping, except for type II, class F loads.

5.2.2 Level B packing.

5.2.2.1 Tent with vestibule and cover; tent with cover; tent and cover, tent pins and poles and liner; or vestibule only. One tent with vestibule; one tent without vestibule; one tent with tent pins, tent poles, and liners; five vestibules or ten tent covers, when procured separately (see 6.2), preserved as specified in 5.1, shall be respectively wrapped and sewn in cotton osnaburg cloth conforming to class 2 of CCC-C-429 or burlap cloth conforming to class 3 of CCC-C-467. The wrapping shall be securely hand-sewn with type I or II, 16-ply cotton twine conforming to T-T-871 or type I, size No. 2 jute twine conforming to T-T-911, with approximately one stitch to the inch and every third stitch knotted, or, alternatively, the seams of the warp may be machine sewn. A minimum of 5 inches of wrapping material or tubing shall be gathered together on each of the four corners and securely sewn into ears for handles. However, the polyester thread used in fabricating the end item may be used for effecting the machine sewn closure of the wrapping or tubing. Alternatively, the ten tent covers may be packed in a snug-fitting fiberboard shipping container conforming to style RSC-L, type CF or SF, variety SW, class domestic, grade 275 of PPP-B-636. The inside of each shipping container shall be fitted with a liner conforming to type CF, variety SW, class domestic, grade 275 of PPP-B-636. Each container shall be closed in accordance with method II in the appendix of PPP-B-636.

5.2.3 Commercial packing. Each tent and vestibule with cover; tent with cover; tent and cover with tent pins, tent poles, and liner; vestibule only; or tent covers only, preserved as specified in 5.1, shall be packed in accordance with ASTM D 3951.

5.3 Palletization. When specified (see 6.2), the tents packed as specified in 5.2, shall be palletized on a 4-way entry pallet in accordance with load type Ia or II (as applicable) of MIL-STD-147. Pallet type shall be type I (4-way entry), type IV or type V in accordance with MIL-STD-147. Pallets shall be fabricated from wood groups I, II, III, or IV of MIL-STD-731. Each prepared load shall be bonded with primary and secondary straps in accordance with bonding means C and D or film bonding means F or G. Pallet pattern shall be in accordance with appendix of MIL-STD-147.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

FEDERAL

5.4 Marking. In addition to any special marking required by the contract or purchase order, shipments and palletized unit loads shall be marked in accordance with MIL-STD-129 or ASTM D 3951, as applicable.

5.4.1 Additional marking. The following shall be stenciled or imprinted on each cloth covered bundle and shipping container containing a tent with vestibule; tent without vestibule; or tent with tent pins, tent poles, and liner in characters not less than 3/4-inch high:

"SEE ERECTION INSTRUCTION SEWED TO INSIDE OF TENT COVER"

6. NOTES

(This section contains information of a general or explanatory nature that may be helpful, but is not mandatory.)

6.1 Intended use. The tents are intended for use in temperate and tropical zones as a command post, fire direction center, battalion aid station, or for any general purpose use. A liner is available for use with this tent.

6.2 Acquisition requirements. Acquisition documents must specify the following:

a. Title, number, and date of this specification.
b. Issue of DODISS to be cited in the solicitation, and if required, the specific issue of individual documents referenced (see 2.1.1 and 2.2).
c. When a first article is required (see 3.1, 4.3, and 6.3).
d. Levels of preservation and packing (see 5.1 and 5.2).
e. When tent with vestibule and cover only is required (see 5.2.1.1).
f. When tent with cover only is required (see 5.2.1.1).
g. When vestibule only is required (see 5.2.1.1).
h. When tent cover only is required (see 5.2.1.2).
i. Type and class of unit load required (see 5.2.1).
j. When palletization is required (see 5.3).

6.3 First article. When a first article is required, it shall be inspected and approved under the appropriate provisions of FAR 52.209. The first article should be a preproduction sample. The contracting officer should specify the appropriate type of first article and the number of units to be furnished. The contracting officer should also include specific instructions in acquisition documents regarding arrangements for selection, inspection, and approval of the first article.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

6.4 Standard sample. For access to a standard shade sample of thread and yellow tent line, address the contracting activity issuing the invitation for bids or request for proposal.

6.5 Prints. Glossy prints of drawings of the labels specified in 3.4.3 may be obtained from the contracting activity.

6.6 Seam retreatment. A satisfactory method of applying the textile retreatment compound for the repair of leaking seams is as follows:

a. A suitable volume of compound conforming to type I, class 1 of TT-P-595, shall be thoroughly stirred and diluted with an equal volume of petroleum solvent (Stoddard solvent or equivalent). Thoroughly stir mixture again before use.

b. Prior to application of the compound, the tent must be dry. Special attention must be taken to ensure adequate ventilation and that proper fire preventive measures are taken since the compound is flammable.

c. Two coats of the compound shall be applied to the seams (on the outside of the tent only). A 4-inch wide stiff brush is recommended for use. The first coat shall be air dried for a minimum of 4 hours prior to application of the second coat. Elapsed time between coats may be reduced by providing a supply of hot air to evaporate the solvent more quickly. In this manner, a second coat may be applied as soon as the first coat is dry to the touch. After the application of the second coat, the treated tent shall be allowed to air dry for a period of at least 24 hours.

6.6.1 Seams to be treated. Seams that failed the test specified in 4.5.1 can be treated as follows:

a. Failure at roof panel lap seams - treat all roof panel lap seams.
b. Failure at peak reinforcement - treat all peak reinforcement stitching.
c. Failure at eave - treat all stitching at eave and webbing reinforced roof joining seams.

6.7 International standardization agreements. Certain provisions of this document are the subject of international standardization agreement as cited in NATO, STANAG No. 2882, relative to camouflage requirements for tents, shelters and subsidiary components. When amendment, revision, or cancellation of this document is proposed that will affect or violate the international agreement concerned, the preparing activity will take appropriate reconciliation action through international standardization channels including departmental standardization offices, if required.

6.8 Subject term (key word) listing.

Shelter

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

6.9 Changes from previous issue. Marginal notations are not used in this revision to identify changes with respect to the previous issue due to the extensiveness of the changes.

Custodians:

Army - GL
Air Force - 99

Review activities:

Air Force - 82
DLA - CT

User activity:

Air Force - 45

Preparing activity:

Army - GL

(Project 8340-0529)

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T19:43Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS

1. The preparing activity must complete blocks 1, 2, 3, and 8. In block 1, both the document number and revision letter should be given.
2. The submitter of this form must complete blocks 4, 5, 6, and 7.
3. The preparing activity must provide a reply within 30 days from receipt of the form.

NOTE: This form may not be used to request copies of documents, nor to request waivers, or clarification of requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

I RECOMMEND A CHANGE:	1. DOCUMENT NUMBER	2. DOCUMENT DATE (YYMMDD)
	MIL-T-41810K	90/05/14

3. DOCUMENT TITLE

TENT, GENERAL PURPOSE, SMALL

4. NATURE OF CHANGE *(Identify paragraph number and include proposed rewrite, if possible. Attach extra sheets as needed.)*

5. REASON FOR RECOMMENDATION

6. SUBMITTER

a. NAME (Last, First, Middle Initial)	b. ORGANIZATION	
c. ADDRESS (Include Zip Code)	d. TELEPHONE (Include Area Code) (1) Commercial (2) AUTOVON (If applicable)	7. DATE SUBMITTED (YYMMDD)

8. PREPARING ACTIVITY

a. NAME	b. TELEPHONE (Include Area Code) (1) Commercial	(2) AUTOVON
U.S. Army Natick RD&E Center	508-651-5221	256-5221
c. ADDRESS (Include Zip Code) Commander, U.S. Army Natick RD&E Center ATTN: STRNC-ES Natick, MA 01760-5014	IF YOU DO NOT RECEIVE A REPLY WITHIN 45 DAYS, CONTACT: Defense Quality and Standardization Office 5203 Leesburg Pike, Suite 1403, Falls Church, VA 22041-3466 Telephone (703) 756-2340 AUTOVON 289-2340	

Source: https://assist.dla.mil -- Downloaded: 2026-01-21T19:43Z
Check the source to verify that this is the current version before use.