MIL-M-60544B(MU)
AMENDMENT 1
15 October 1969

MILITARY SPECIFICATION

MOUNTS, TELESCOPE: M148 AND XM164

This amendment forms a part of Military Specification MIL-M-60544B(MU), dated 13 January 1969.

Paragraph 3.10.3: Delete and substitute

"3.10.3 Boresight locks.- With the locking screws set, using a 20 pound-inch maximum torque, there shall be no rotation of the AZ and EL boresight movements, in either direction, when torques of 20 pound-in minimum are applied to each movement."

Paragraph 4.3.2.3, TABLE II: Delete "105. Locking screws 3.10.3, 4.6.7" and substitute "105. Boresight locks 3.10.3, 4.6.7".

Paragraph 4.6.7: Delete and substitute

"4.6.7 Boresight locks.- A torque wrench capable of applying the specified torques to the locking screws and boresight movements, together with a standard type driver bit that properly fits the screw slot of the locking screws and boresight movements, shall be utilized for performing these tests. The mount shall be positioned as in 4.6.1 with the aligning telescope secured in the dovetail. The telescope reticle shall be aligned to a reference point on the target. Set the AZ and EL locking screws as specified in 3.10.3. Apply, in a clockwise direction, the minimum specified torque to the AZ boresight movement, then observe for any change of the reticle position with respect to the target image reference point. Then apply, in a counterclockwise direction, the minimum specified torque to the AZ boresight movement, and again observe for any change in the reticle position. Repeat this test procedure on the EL boresight movement. To conform to the requirements of 3.10.3 there shall be no visible displacement or movement of the telescope reticle pattern with respect to the target image reference point.

Custodian:

Army - MU

Preparing activity:

Army - MU

Project No. 1240-A193

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:42Z
Check the source to verify that this is the current version before use.