MIL-F-50780(MU)
AMENDMENT 1
14 December 1972

MILITARY SPECIFICATION

FUZE, MT, M565 ASSEMBLY (ALTERNATE)

This amendment forms a part of Military Specification MIL-F-50780(MU) dated 16 June 1972.

Paragraph 3.4.2, line 4, delete "180 plus 5 feet" and substitute "150 plus 5 feet".

Paragraph 3.4.3, add "Table I" above "Fuze Setting".

Add Paragraph 3.4.7:

"3.4.7 High and Low Temperature Conditioning.-For the high and low temperature firings only the fuze shall be temperature conditioned. The elapsed time for the conditioning chamber to the firing in the weapon shall not exceed five (5) minutes. Reconditioning is not permitted".

Paragraph 3.5.1, delete the word "porosity".

Paragraph 4.2, line 7, after "20", delete"D.A.M."and substitute "Delay Arming Mechanism (D.A.M.)", line 8 after 4.4.13.1 add "(see 6.8)".

Paragraph 4.2.3.2, delete "(3)" and substitute "(2)".

Paragraph 4.2.1, delete "450" and substitute "425".

Paragraph 4.2.6, under "Test Method" for 4.4.13.1 add "(see 6.8)".

Paragraph 4.2.6, under "Quantity" for "Time-to-Burst (Ambient Temperature)", delete "5" and substitute "20".

Paragraph 4.3.2.11 after MAJOR, add "AQL = 1.0%" and delete MAJOR characteristic "101".

Paragraph 4.3.2.15, delete drawing letter "D" and substitute "F".
Add MAJOR characteristic 108 and 109.

"108.	Profile of external surface, incorrect	Gage
109.	Threads damaged	Visual".

Paragraph 4.3.2.16, in heading, delete "(Faze)" and substitute "(Fuze)".
Add MAJOR characteristic 108.

"108.	Profile of external surface, incorrect	Gage"

FSC 1390

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:37Z
Check the source to verify that this is the current version before use.

Paragraph 4.3.2.27, for CRITICAL characteristic 3, delete "Riming" and substitute "Timing".

Paragraph 4.3.2.33, line 1, after the word "Periodic" add "(at least once during each 8 hours shift)".

Paragraph 4.3.2.33, f., delete drawing number "F10523008" and substitute "F11743960".

Paragraph 4.3.2.33, h., delete "(3)" in its entirety.

Add new paragraphs 4.3.2.34, 4.3.2.35, 4.3.2.36, 4.3.2.37 and 4.3.2.38.

"4.3.2.34 Pallet Assembly, Drawing D11743962 covering a detail of Drawing F11738602.

CRITICAL

None defined

MAJOR AQL = 1.0%

101.	Broken, deformed, or bent assembly	Visual
102.	Balance, staff inadequately staked or seated	Visual
103.	Metal defective	Visual

4.3.2.35 Wheel and Pinion Escapement Drawing D11743967 covering a detail of Drawing F11738602.

CRITICAL

None defined

MAJOR AQL = 1.0%

101.	Circular runout of escape wheel and pinion	Gage
102.	Perpendicularity of escape wheel and pinion, incorrect	Gage
103.	Broken or missing teeth	Visual

4.3.2.36 No. 1 Gear and Pinion Assembly, Drawing D10523167 covering a detail of Drawing F11738602.

CRITICAL

None defined.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:37Z
Check the source to verify that this is the current version before use.

4.3.2.36 (Cont'd)

MAJOR AQL = 1.0%

101.	Circular runout of gear and pinion	Gage
102.	Perpendicularity of gear and pinion, incorrect	Gage
103.	Broken or missing teeth	Visual

4.3.2.37 Rotor Assembly, Drawing D10551356 covering a detail of drawing F11738602.

CRITICAL

None defined

MAJOR AQL = 1.0%

101.	Circular runout of rotor assembly	Gage
102.	Perpendicularity of rotor assembly, incorrect	Gage
103.	Broken or missing teeth, improper assembly	Visual

4.3.2.38 Escape Wheel, Drawing C8595539 covering a detail of Drawing F11738602.

CRITICAL

None defined

MAJOR AQL = 1.0%

101.	Escape wheel profile, incorrect	Gage"

Paragraph 4.3.3.1, delete drawing numbers "D10523171" and substitute "C8595539", "B10523175" and substitute "B11743965" and "C10520951" and substitute "C10520664".

Delete "Arbor, escapement D10534857".

Paragraph 4.3.3.4.1, delete drawings numbers "D10523170" and substitute "D11743967" and "D10523174" and substitute "D11743962".

Paragraph 4.3.3.4.2, delete "Escapement Gear and Pinion Assembly C10521112".

Delete paragraphs, 4.3.3.11, 4.4.11 and 4.4.11.1 in their entirety.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:37Z
Check the source to verify that this is the current version before use.

Paragraph 4.3.3.13, line 1, delete "Sixty (60)" and substitute "Forty (40)" and after the word "fuzes" add "plus 20 D.A.M.'s".

Paragraph 4.4.10.1, line 3, delete "lower cap" and substitute "head".

Paragraph 4.4.13.1, line 2, after "subassemblies" add "(see 6.8)".

Custodian:

Army - MU

Preparing activity:

Army - MU(FA)

Project No. 1390-A116

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:37Z
Check the source to verify that this is the current version before use.