MILITARY SPECIFICATION

SHELL, TEST (INERT) 155MM, T5106E2 AND E3 ASSEMBLE

This amendment forms a part of Military Specification MIL-P-50291 (MU), dated 27 April 1970, and is mandatory for use by the Activities of Army Munitions Command.

Page 1 -(a) SPECIFICATIONS. Delete: "MILITARY, MIL-B-20202-Blanks, Rotating Band for Projectile and MIL-B-20295-Blanks, Centrifugal Cast, Rotating Band."
(b) STANDARDS, MILITARY. Delete: "BFBX3-589942-Pin, Straight, Precision. Add: "MS16555-60-Pin, Straight, Headless".

Page 2 -(a) DRAWINGS, ORDNANCE CORPS. Delete: "75-14-41-Band, Rotating Gilding Metal" and substitute "9216409-Blank Rotating Band".
(b) Para. 3.5. Delete: "(see dwgs 9233010 and 75-14-41)" and substitute "(see dwgs 9233007, 9233010 and 9216409)".
(c) Delete para. 3.5.1.

Page 4 -Add Para. "3.9 Interference fit (see dwg 9233006) An interference fit of .0005 to .0010 shall be maintained on all pins in the rear joint assembly when processed as specified in 4.4.6. An interference fit of .0008 to .0012 shall be maintained on all pins in the forward joint when processed as specified in 4.4.6. The interference fit specified for the middle pins shall be maintained when processed as specified in 4.4.6. Maximum hole diameter for pins in front or rear joints shall be .3900. Each oversized hole and pin shall be numbered with the same number by stamping with rubber stamp.

Page 8 -Paragraph 4.3.2.1.1. Add Major defects: "107 Length from left face to rotating band groove.....Gage and 108 Length from band groove to small outside diameter (dwg 9233007 only).....Gage".

Page 9 - Paragraph 4.3.2.1.2. Delete Major defect 107. Add Major defect "126 No gap between rotating band and edges of band seat .....Visual".

Page 10-Paragraph 4.3.2.1.4. Delete Major defects 107 and 108.

Page 11-Paragraph 4.3.2.1.4. Add Major defect: 131 No gap between rotating band and edges of band seat.....Visual.

FSC 1190

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:20Z
Check the source to verify that this is the current version before use.

Page 13-Paragraph 4.3.2.1.9: Add Major defect "110. Interference fit (see 3.9).....Gage.

Page 14-(a) Paragraph 4.3.2.1.10 Major Defect 101. Delete "BFBX3-589942" and substitute: MS16555-60".

(b) Add Paragraph 4.3.2.1.12

"4.3.2.1.12 Blank rotating band (see dwg 9216409) covering a detail of dwgs 9233007 and 9233010.

Categories	Characteristics	Method of Inspection
Critical:	None defined	
Major		
101.	Length	*Measure
102.	Inside diameter	*Measure
103.	Outside diameter	*Measure
104.	Material (see 3.1)	Visual

*Measure with suitable scale

Minor: None defined"

Page 15-(a) Delete Para. 4.3.3.1.1.

(b) Delete Para. 4.3.3.3.2.

Page 16-(a) Delete Para. 4.4.1.1.

(b) Para. 4.4.1.2. Delete "dwg 9233006" and substitute "dwg 9233010" in line 22.

Page 17-Para. 4.4.2.2. Delete "Charpy or tensile (see 4.3.3.2.2 and 4.3.3.3.2)". and substitute "Charpy (see 4.3.3.2.2). In 6th and 7th lines delete: "methods 211.1 or 222.1, as applicable" and substitute "method 222.1."

Page 18-(a) Para. 4.4.2.3. Delete "4.3.3.3" and substitute "4.3.3.3.3".

(b) Add Para. 4.4.6 Interference fit (see 3.9). When oversized pin holes are used in the assembly select an oversized pin for the oversized hole. Measure the selected pin diameter to the nearest .0001 inch. Subtract the pin diameter from the hole diameter to determine the interference fit which shall comply with 3.9. The maximum hole diameter shall be .3900 inch when specified on dwg. All other hole dimensions and pin dimensions shall comply with drawing requirements. Mark the oversize pin and hole with a numbered rubber stamp to assure selective assembly.

Custodian
Army - MU

Preparing Activity
Army - MU
Project No 1190-A057

☆ U.S. GOVERNMENT PRINTING OFFICE: 1971-714-158/2550

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:20Z
Check the source to verify that this is the current version before use.