INCH-POUND
MIL-C-60315B (AR)
AMENDMENT 2
12 March 1993
SUPERSEDING
AMENDMENT 1
12 March 1992

MILITARY SPECIFICATION

CHARGE, PROPELLING, M67 FOR 105MM HOWITZER
LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-C-60315B (AR) dated 9 September, 1991, and is approved for use within the US Army Armament Munitions and Chemical Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 3

* Add paragraph:

"3.6 First article test. This specification contains provisions for the submission of a first article sample. This is a one time qualification test for a new contractor to load, assemble, and pack M67 propelling charges. Test samples shall be withdrawn from the first lot of propelling charges produced by the contractor. Charges will be tested in accordance with all the requirements of this specification and with Table III (See 6.9). Until the first article sample has been found to be acceptable, the contractor is in no way authorized by the Government to initiate production of a second lot unless otherwise directed by the contracting officer."

PAGE 4

* 4.2, Classification of inspection: Delete in its entirety and substitute the following:

"4.2 Classification of inspection. The following types of inspection shall be conducted on this item:

a. First Article Inspection.
b. Quality Conformance Inspection."

* 4.3.1b: Add the following:

"An entire lot of multi-perforated propellant shall be utilized in the formation of one lot of propelling charges unless otherwise directed by the contracting officer."



AMSC N/A

FSC 1315

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.

PAGE 8

4.3.2.3 Charge, assembly: Delete in its entirety and substitute new paragraph as included.

PAGE 11

4.3.3.3 Charge, propelling, assembly weight: Delete in its entirety.

PAGE 14

* Add paragraph:

"6.9 First article test. The first article test is one time qualification test for a new contractor to load, assemble and pack acceptable M67 propelling charges. Once a contractor has demonstrated the ability to load, assemble and pack the propelling charges, the first article test may be waived by the contracting officer. The following test program shall be used for the first article test:

TABLE III
First Article Test

| Test Phase | Temp (Deg F) | No. Control Rounds | No. Test Rounds | TECOM TOP |
|---|---|---|---|---|
| Propellant checkout | 70 | | 10 | TOP-4-2-504 |
| | 145 | | 10 | TOP-4-2-504 |
| | -60 | | 10 | TOP-4-2-504 |
| Sequential Environmental | 145 | 15 | 60 | TOP-4-2-504 |
| | -60 | 15 | 60 | TOP-4-2-504" |



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

# CLASSIFICATION OF CHARACTERISTICS

MIL-C-60315B (AR)
AMENDMENT 2

| PARAGRAPH | TITLE | SHEET | DRAWING NUMBER |
|---|---|---|---|
| 4.3.2.3 | Charge, Assembly | 1 OF 1 | 9205472 or 9288695 |
| | | | NEXT HIGHER ASSEMBLY |

| CLASSIFICATION | EXAMINATION OR TEST | CONFORMANCE CRITERIA | REQUIREMENT PARAGRAPH | INSPECTION METHOD REFERENCE |
|---|---|---|---|---|
| Critical | | | | |
| 1 | Missing or incorrect increments or incorrect propelling charge assembly weight. | 100 % 1/ | 3.2 | Scale |
| Major | | | | |
| 101 | Incorrect sequence of increments. | 100 % | 3.2 | Visual |
| 102 | Assembly damaged to the extent that propellant can escape. | 100 % | 3.2 | Visual |
| Minor | | | | |
| 201 | Increments insecurely tied at junctions. | Table II | 3.2 | Visual |
| 202 | Ties loose, broken or insecurely tied. | Table II | 3.2 | Visual |
| 203 | Marking missing or unidentifiable. | Table II | 3.2 | Visual |
| 204 | Evidence of poor workmanship. | Table II | 3.5 | Visual |

NOTES:

1/ The defect shall be classed critical when the weight is in excess of 3 times that specified in 3.4. Major when the weight is in excess of that in 3.4 but not greater than 3 times. Compliance with 3.4 shall be determined by using the average weight of the empty bag assembly. If the defect is determined to be due to an incorrect propelling charge assembly weight, remove increment 5 by raising it off the scale without breaking the cord and replace it with a weight representing the average weight of increment 5. If the weight is incorrect, reject the charge. If the weight is correct and it can be determined that the off weight of increment 5 is caused by the lead foil (tare weight of bag) the charge shall be considered acceptable.



Source: (https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.

NOTE: The margins of this amendment are marked with an asterisk or vertical line to indicate where changes (additions, modification, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1315-AE71)



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:28Z
Check the source to verify that this is the current version before use.