ADMINISTRATIVE NOTICE

INCH-POUND

MIL-DTL-28837/2C
NOTICE 1
18 August 2006

DETAIL SPECIFICATION

MIXER STAGES, RADIO FREQUENCY DOUBLE BALANCED, SOLDER LEADS

The FSC for MIL-DTL-28837/2C has changed to 5895 from 5985.

Custodians:
Army - CR
Navy - EC
Air Force - 11
DLA - CC

Preparing activity:
DLA - CC

Review activities:
Army - AR, MI
Navy - AS, CG, MC, OS
Air Force - 19, 99

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at http://assist.daps.dla.mil.

AMSC N/A

FSC 5895

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T19:23Z
Check the source to verify that this is the current version before use.