MIL-C-48394 (PA)
AMENDMENT 1
7 April 1976

MILITARY SPECIFICATION

CARTRIDGE, 81MM, SMOKE, WP, M375A3

ASSEMBLING, MARKING AND PACKING

This Amendment forms a part of Military Specification MIL-C-48394 (PA), dated 6 November 1975.

2.1, line 6: Specification "MIL-C-48156", delete "Cartridge, Ignition, XM299, LAP", and substitute "Cartridge, Ignition, M299, LAP".

2.1, Line 14: Delete "9230175 - Container.....in Jungle Wrap" and substitute "9276596 - Container, Ammunition, Fiber, M252A5 for 81MM Mortar Ammunition".

2.1, Add the following after last line on page:

9287603 - Packing and Marking for Container, Fiber, M252A5, Ammunition for 81MM Mortar Ammunition in Jungle Wrap".

PAGE 3

4.2.2, Examination, add the following after the last sentence of the paragraph:

"The contractor may elect to perform 100% inspection with automated equipment or impose mandatory process controls on automated operations in lieu of conducting sampling inspection for defects listed in this specification. In such cases, calibration plans shall be submitted to the Technical Agency (see 6.5) for approval for each automatic inspection station and process control plans must be submitted for approval for each of the automated operations. The plans shall identify; (1) the frequency (production interval) for validating equipment functioning, (2) the defect standards and (3) a description of material control procedures to be imposed on product passing through each automated station during the production interval between validations. Under these provisions final acceptance will be withheld from material produced during a production interval until satisfactory validation of each of the automated stations so controlled. In the event of a validation failure of any station, the material processed through such station since the last acceptable validation shall be placed in a rejected status pending corrective action".

FSC: 1315

Source: https://assist.dla.mil -- Downloaded: 20261O-22T19:24Z
Check the source to verify that this is the current version before use.

PAGE 4

4.2.2.1, Change number in drawing number box from "8835263" to "8885263".

PAGE 5

4.2.2.2 Delete "Major A" and substitute "Major", Delete "9294735" in Next Higher Assembly Block.

PAGE 6

4.2.2.3 Delete "Major A" and substitute "Major", Delete "9294735" in Next Higher Assembly Block.

PAGE 7

4.2.2.4, line 2: Delete "Critical 1. Ignition cartridge head not fully seated.....Visual" and add "Critical 1. Depth of ignition cartridge from fin end below minimum...100%....3.2...Gage CD".

4.2.2.4, line 7: Delete "5. Fin assembly cracked, damaged or distorted... 100%...3.2..Visual" and Add "5. Fin blade distorted...100%...3.2..Gage" and "6 Cracks in fin housing...100%...3.2...Visual (4 power magnification)".

4.2.2.4 above Major A add the following "Special a...WARNING label(s) missing...100% 3.2....Visual".

4.2.2.4 Delete "Major A" and substitute "Major", Delete 9294735" in Next Higher Assembly Block".

PAGE 8

4.2.2.4 Delete "Major A" and add "Major", Delete "9294735" in Next Higher Assembly Block.

4.2.2.4, line 14 from top of page: Delete "202. Pettman cement does not cover....Visual" in its entirety and substitute "Minor: 202. Pettman cement (or alternate) improperly applied (applicable to the fuze, fin and ignition cartridge)....0.65%....3.2....Visual".

PAGE 9

4.2.2.4, line 2: Delete this line in its entirety.

4.2.2.4 Delete "9294735" in Next Higher Assembly Block.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:24Z
Check the source to verify that this is the current version before use.

PAGE 10

4.2.2.5 Drawing Number: Delete "9230175" and add "9276596".

4.2.2.5 Next Higher Assembly: Delete "9230175" and add "9287603".

4.2.2.5, add the following above Minor, "Critical 1. Propelling charge supports missing...100%...3.2...Visual".

PAGE 11

4.2.2.6 Drawing Number: Delete "9230175" and add "9287603".

4.2.2.6 Next Higher Assembly: Delete "9230175" and add "9287601".

4.2.2.6 Delete "Major A" and substitute "Major".

PAGE 12

4.2.2.7 Drawing Number: Delete "9230175" and add "9287603".

4.2.2.7 Next Higher Assembly: Delete "9230175" and add "9287601".

4.2.2.7 Delete "Major B" and add "Major".

4.2.2.7 In category column: Delete "131 and 132" and substitute "101 and 102" respectively.

4.2.2.7 Following line 7: add "203...Kraft paper missing or not properly assembled...0.65%.....3.2....Visual".

PAGE 13

4.2.2.8, line 2: Delete "Boards split or separated" and substitute "Boards split or separated exposing container".

4.2.2.8, change number in Next Higher Assembly Block from "9278234" to "9287601".

Change page numbers "14, 15, 16 and 17" to "15, 16, 17 and 18" respectively.

Add the table on the following page as page number 14.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:24Z
Check the source to verify that this is the current version before use.