MIL-T-81978(AS)

Amendment 2
1 December 1976
SUPERSEDING
Amendment 1
9 July 1975

MILITARY SPECIFICATION

TEST SET, MISSION RECORDER AN/USM-387

This amendment forms a part of Military Specification MIL-T-81978(AS), 6 August 1974, and has been approved by the Naval Air Systems Command, Department of the Navy.

Page 1

*Title, Line 2: Delete "AN/USM-387" and substitute "AN/USM-387B".

*1.2, Line 6: Delete "OQ-184/USM-387" and substitute "OQ-184A/USM-387".

1.2, Line 7: Delete "MT-4628/USM-387" and substitute MT-4628A/USM-387".

Page 3

Following MIL-STD-794 entry: Add "MS3102 Connector, Receptacle, Electric, Box Mounting, Solder Contacts, AN Type".

Page 5

3.3.1 Line 3: Delete "460" and substitute "472".

Page 6

3.3.7.2 following 2A3J7 entry: Add "3A2P1 MS3106F-20-4P 115 VAC, 400 Hz Power Input".

3.3.7.2 last entry: Delete "W8P1MS3106F-20-4P 115 VAC, 400 Hz Power Input".

FSC 5841

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T06:33Z
Check the source to verify that this is the current version before use.

Page 17

*3.6.2.1: Delete entirely and substitute "Horizontal Sweep input - The typical Horizontal Sweep input signal is as shown by Waveform A, Figure 6 or 7, depending upon recorded scan. The signal voltage shall not exceed plus or minus 1.3 volts."

*3.6.2.2: Delete entirely and substitute "Vertical Sweep input - The typical Vertical Sweep input signal is as shown in Waveform B, Figure 6 or 7, depending upon recorded scan. The signal voltage shall not exceed plus or minus 1.3 volts."

Page 21

3.6.4.1 Line 2: Delete "7M111P14M," and substitute "7M111P14M* (or an approved equivalent),".

Bottom Left of Page: Add "*Thomas Electronics, Inc. Part Number"

Page 24

*3.7.2, Line 1: Delete "OQ-184/USM-387" and substitute "OQ-184A/USM-387"

*3.7.2(1): Delete "IP-1172/USM-387" and substitute "IP-1172A/USM-387"

*3.7.2(3): Delete "SG-1062/USM-387" and substitute "SG-1062A/USM-387"

*3.7.2.1, Line 1: Delete "IP-1172/USM-387" and substitute "IP-1172A/USM-387"

Page 25

*Delete Figure 9 and replace with modified Figure 9 contained herein.

Page 28

*3.7.2.3, Line 1: Delete "SG-1062/USM-387" and substitute "SG-1062A/USM-387"

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T06:33Z
Check the source to verify that this is the current version before use.




FIG. 8 AN/USM-387B CABLING DIAGRAM

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T06:33Z
Check the source to verify that this is the current version before use.

Page 30

3.7.2.3.6, Line 1, Delete "Electrical connections-" and substitute "Electrical Connections-".

Page 32

3.7.3, Line 1: Delete "MT-4628/USM-387" and substitute "MT-4628A/USM-387".

3.7.3.1, Line 3: Add "The Test Stand shall also house the Transformer Assembly (3A2), which isolates the 400 Hz power source ground from the 60 Hz power source ground."

3.7.3.2, Line 2: Delete "27" and substitute "39".

"The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in those notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment."

Custodians:

Navy - AS

Preparing Activity:

Navy - AS

Project No. 5841-N038

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T06:33Z
Check the source to verify that this is the current version before use.