NOTICE OF GROUP CANCELLATION

INCH-POUND

MIL-C-81659B
NOTICE 1
1 June 2007

MILITARY SPECIFICATION

CONNECTORS, ELECTRICAL, RECTANGULAR, CRIMP CONTACTS, GENERAL SPECIFICATION FOR

MIL-C-81659B and the following specification sheets associated with MIL-C-81659B are hereby canceled:

| Document | Date | Cancellation Notice No. | Replacement | DoD Project No. |
|---|---|---|---|---|
| MIL-C-81659B | 02-Aug-1976 | 1 | SAE-AS81659 | 5935-2005-066 |
| MIL-C-81659/9B | 16-Dec-1971 | 2 | SAE-AS81659/9 | 5935-2005-067 |
| MIL-C-81659/29B | 02-Aug-1976 | 1 | SAE-AS81659/29 | 5935-2005-068 |
| MIL-C-81659/31B | 02-Aug-1976 | 1 | SAE-AS81659/31 | 5935-2005-069 |
| MIL-C-81659/33B | 02-Aug-1976 | 1 | SAE-AS81659/33 | 5935-2005-070 |
| MIL-C-81659/35B | 02-Aug-1976 | 1 | SAE-AS81659/35 | 5935-2005-071 |
| MIL-C-81659/37B | 02-Aug-1976 | 1 | SAE-AS81659/37 | 5935-2005-072 |
| MIL-C-81659/39B | 02-Aug-1976 | 1 | SAE-AS81659/39 | 5935-2005-073 |
| MIL-C-81659/41B | 02-Aug-1976 | 1 | SAE-AS81659/41 | 5935-2005-074 |
| MIL-C-81659/43B | 02-Aug-1976 | 1 | SAE-AS81659/43 | 5935-2005-075 |
| MIL-C-81659/53A | 16-Dec-1971 | 3 | SAE-AS81659/53 | 5935-2005-076 |
| MIL-C-81659/56A | 16-Dec-1971 | 2 | SAE-AS81659/56 | 5935-2005-077 |
| MIL-C-81659/57A | 16-Dec-1971 | 2 | SAE-AS81659/57 | 5935-2005-078 |
| MIL-C-81659/58A | 16-Dec-1971 | 2 | SAE-AS81659/58 | 5935-2005-079 |
| MIL-C-81659/61 | 02-Aug-1976 | 1 | SAE-AS81659/61 | 5935-2005-080 |
| MIL-C-81659/62 | 02-Aug-1976 | 1 | SAE-AS81659/62 | 5935-2005-081 |
| MIL-C-81659/63 | 02-Aug-1976 | 1 | SAE-AS81659/63 | 5935-2005-082 |
| MIL-C-81659/64 | 02-Aug-1976 | 1 | SAE-AS81659/64 | 5935-2005-083 |
| MIL-C-81659/65 | 02-Aug-1976 | 1 | SAE-AS81659/65 | 5935-2005-084 |
| MIL-C-81659/66 | 02-Aug-1976 | 1 | SAE-AS81659/66 | 5935-2005-085 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T05:52Z
Check the source to verify that this is the current version before use.

| Document | Date | Cancellation Notice No. | Replacement | DoD Project No. |
|---|---|---|---|---|
| MIL-C-81659/67 | 02-Aug-1976 | 1 | SAE-AS81659/67 | 5935-2005-086 |
| MIL-C-81659/68 | 02-Aug-1976 | 1 | SAE-AS81659/68 | 5935-2005-087 |
| MIL-C-81659/69 | 02-Aug-1976 | 1 | SAE-AS81659/69 | 5935-2005-088 |
| MIL-C-81659/70 | 02-Aug-1976 | 1 | SAE-AS81659/70 | 5935-2005-089 |
| MIL-C-81659/71 | 02-Aug-1976 | 1 | SAE-AS81659/71 | 5935-2005-090 |
| MIL-C-81659/72 | 02-Aug-1976 | 1 | SAE-AS81659/72 | 5935-2005-091 |

CAUTION: The supersession information is valid as of the date of this notice and may be superseded by subsequent revisions of the superseding document.

(Copies of this document are available from SAE International, 400 Commonwealth Drive, Warrendale, PA 15096-0001 or www.sae.org.)

Custodians:
Army - CR
Navy - AS
Air Force - 11
DLA - CC

Preparing activity:
Navy - AS

(Project 5935-2005-066)

Review activities:
Navy - EC, OS
Air Force - 99

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at http://assist.daps.dla.mil.



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T05:52Z
Check the source to verify that this is the current version before use.