ADOPTION NOTICE

ASTM-D1683, "Failure in Sewn Seams of Woven Apparel Fabrics", was adopted on 03-OCT-1994 for use by the Department of Defense (DoD). Proposed changes by DoD activities must be submitted to the DoD Adopting Activity: Commander, Defense Supply Center Philadelphia, ATTN: DSCP-FMBS, 700 Robbins Avenue, Philadelphia, PA 19111-5096. Copies of this document may be purchased from the ASTM International, 100 Barr Harbor Drive, West Conshohocken, Pennsylvania 19428-2959. http://www.astm.org/

Custodians:
Army - GL
Navy - NU
Air Force - 99
DLA - CT

Adopting Activity:
DLA - CT

NOTE: The activities above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at http://assist.daps.dla.mil.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T15:27Z
Check the source to verify that this is the current version before use.