MIL-M-50901 (AR)
Amendment 1
17 September 1981

MILITARY SPECIFICATION

MINE, ANTI-PERSONNEL, M26
PRIMER AND DELAY ASSEMBLY FOR

This amendment forms a part of Military Specification MIL-M-50901 (MU), dated 22 Feb 1971 and is approved by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

* Add the following preamble underneath the title:

"This specification is approved by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense."

PAGE 5

4.2.2.1: Delete in its entirety and substitute the following:

"4.2.2.1 Firing of primer and delay assembly at ambient temperature (see Dwg. 8840311). One hundred and twenty-five (125) primer and delay assemblies shall be subjected to this test. If two or more assemblies fail to function, or, after functioning, have the cup protruding through the crimp which secures the cup in the shell case, the lot shall be rejected. Rejection shall be as specified in 4.2.3."

4.2.2.2: Delete last sentence and substitute the following:

"Rejection shall be as specified in 4.2.3 except for the water imnmersion test which shall be for engineering informational purposes only."

PAGE 8

4.3.2.3: Add major defects as follows:

"107. Depth of largest inside diameter Gage 03007"
"108. Radius at bottom of primer cavity Gage 03008"

FSC: 1345

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:43Z
Check the source to verify that this is the current version before use.

PAGE 8

4.3.2.3: Delete Minor Category in its entirety and substitute the following:

"Minor	AQL 1.50 percent		
201.	Largest outside diameter	Gage	03009
202.	Length of flange	Gage	03010
203.	Diameter of hole in primer cavity	Gage	03011
204.	Evidence of poor workmanship (see 3.4)"	Visual	03012

PAGE 9

4.3.2.5: Delete Major Categories 103. and 106. and substitute the following:

"103.	Crimp of shell case holding retaining ring missing or incomplete	Visual	05003
106.	Retaining ring missing	Visual	05006"

PAGE 12

4.3.2.12: Add as follows:

"4.3.2.12 Ring, retaining (see Dwg. B-9272316).

Categories	Defects	Method of Inspection	Code No.
Critical: None defined			
Major	AQL 0.40 Percent		
101.	Diameter of wire	Gage	21001
102.	Outside diameter, min.	Gage	21002
Minor:	AQL 1.00 Percent		
201.	Gap, max.	Gage	21003
202.	Evidence of poor workmanship (see 3.4)"	Visual	21004

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project No.: 1345-A186

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:43Z
Check the source to verify that this is the current version before use.