NOTICE OF GROUP CANCELLATION

INCH-POUND

MIL-C-85049A
NOTICE 1
19 June 2003

MILITARY SPECIFICATION

CONNECTOR ACCESSORIES, ELECTRICAL, GENERAL SPECIFICATION FOR

MIL-C-85049A, the following specification sheets associated with MIL-C-85049, and current amendments and notices are hereby canceled:

| Document | Date | Cancellation Notice No. | DoD Project No. | Replacement |
|---|---|---|---|---|
| MIL-C-85049A | 30-Aug-90 | 1 | 5935-4264 | SAE-AS85049 |
| MIL-C-85049/1A | 30-Nov-90 | 1 | 5935-4264-001 | SAE-AS85049/1 |
| MIL-C-85049/2A | 30-Nov-90 | 1 | 5935-4264-002 | SAE-AS85049/2 |
| MIL-C-85049/3A | 28-Jun-88 | 1 | 5935-4264-003 | SAE-AS85049/3 |
| MIL-C-85049/4A | 28-Jun-88 | 1 | 5935-4264-004 | SAE-AS85049/4 |
| MIL-C-85049/5B | 24-Nov-92 | 1 | 5935-4264-005 | SAE-AS85049/5 |
| MIL-C-85049/6A | 30-Nov-90 | 1 | 5935-4264-006 | SAE-AS85049/6 |
| MIL-C-85049/7A | 30-Nov-90 | 1 | 5935-4264-007 | SAE-AS85049/7 |
| MIL-C-85049/8A | 30-Nov-90 | 1 | 5935-4264-008 | SAE-AS85049/8 |
| MIL-C-85049/9A | 30-Nov-90 | 1 | 5935-4264-009 | SAE-AS85049/9 |
| MIL-C-85049/10A | 30-Nov-90 | 1 | 5935-4264-010 | SAE-AS85049/10 |
| MIL-C-85049/11A | 30-Nov-90 | 1 | 5935-4264-011 | SAE-AS85049/11 |
| MIL-C-85049/14 | 21-Nov-86 | 2 | 5935-4264-012 | SAE-AS85049/14 |
| MIL-C-85049/15 | 21-Nov-86 | 2 | 5935-4264-013 | SAE-AS85049/15 |
| MIL-C-85049/16 | 21-Nov-86 | 2 | 5935-4264-014 | SAE-AS85049/16 |
| MIL-C-85049/17 | 16-Jan-80 | 3 | 5935-4264-015 | SAE-AS85049/17 |
| MIL-C-85049/18B | 1-Oct-84 | 2 | 5935-4264-016 | SAE-AS85049/18 |
| MIL-C-85049/19A | 4-Mar-83 | 2 | 5935-4264-017 | SAE-AS85049/19 |
| MIL-C-85049/20A | 4-Mar-83 | 2 | 5935-4264-018 | SAE-AS85049/20 |
| MIL-C-85049/21A | 4-Mar-83 | 2 | 5935-4264-019 | SAE-AS85049/21 |
| MIL-C-85049/23A | 30-Nov-90 | 1 | 5935-4264-020 | SAE-AS85049/23 |
| MIL-C-85049/24A | 30-Nov-90 | 1 | 5935-4264-021 | SAE-AS85049/24 |



DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T10:12Z
Check the source to verify that this is the current version before use.

| Document | Date | Cancellation Notice No. | DoD Project No. | Replacement |
|---|---|---|---|---|
| MIL-C-85049/25A | 30-Nov-90 | 1 | 5935-4264-022 | SAE-AS85049/25 |
| MIL-C-85049/26A | 30-Nov-90 | 1 | 5935-4264-023 | SAE-AS85049/26 |
| MIL-C-85049/27A | 21-Nov-86 | 2 | 5935-4264-024 | SAE-AS85049/27 |
| MIL-C-85049/28B | 1-Mar-82 | 2 | 5935-4264-025 | SAE-AS85049/28 |
| MIL-C-85049/29 | 16-Jan-80 | 3 | 5935-4264-026 | SAE-AS85049/29 |
| MIL-C-85049/30A | 21-Nov-86 | 2 | 5935-4264-027 | SAE-AS85049/30 |
| MIL-C-85049/31B | 30-Nov-90 | 1 | 5935-4264-028 | SAE-AS85049/31 |
| MIL-C-85049/32A | 21-Nov-86 | 2 | 5935-4264-029 | SAE-AS85049/32 |
| MIL-C-85049/33A | 21-Nov-86 | 2 | 5935-4264-030 | SAE-AS85049/33 |
| MIL-C-85049/34A | 30-Nov-90 | 1 | 5935-4264-031 | SAE-AS85049/34 |
| MIL-C-85049/36 | 16-Jan-80 | 3 | 5935-4264-032 | SAE-AS85049/36 |
| MIL-C-85049/37A | 21-Nov-86 | 2 | 5935-4264-033 | SAE-AS85049/37 |
| MIL-C-85049/38C | 19-Dec-89 | 1 | 5935-4264-034 | SAE-AS85049/38 |
| MIL-C-85049/39C | 19-Dec-89 | 1 | 5935-4264-035 | SAE-AS85049/39 |
| MIL-C-85049/41A | 30-Nov-90 | 1 | 5935-4264-036 | SAE-AS85049/41 |
| MIL-C-85049/42A | 30-Nov-90 | 1 | 5935-4264-037 | SAE-AS85049/42 |
| MIL-C-85049/43A | 30-Nov-90 | 1 | 5935-4264-038 | SAE-AS85049/43 |
| MIL-C-85049/44A | 21-Nov-86 | 2 | 5935-4264-039 | SAE-AS85049/44 |
| MIL-C-85049/45A | 5-Mar-83 | 2 | 5935-4264-040 | SAE-AS85049/45 |
| MIL-C-85049/46B | 5-Mar-83 | 2 | 5935-4264-041 | SAE-AS85049/46 |
| MIL-C-85049/47B | 12-Sep-88 | 1 | 5935-4264-042 | SAE-AS85049/47 |
| MIL-C-85049/48B | 11-Sep-91 | 1 | 5935-4264-043 | SAE-AS85049/48 |
| MIL-C-85049/49C | 6-Sep-90 | 1 | 5935-4264-044 | SAE-AS85049/49 |
| MIL-C-85049/50B | 11-Sep-91 | 1 | 5935-4264-045 | SAE-AS85049/50 |
| MIL-C-85049/51C | 30-Nov-90 | 1 | 5935-4264-046 | SAE-AS85049/51 |
| MIL-C-85049/52C | 30-Nov-90 | 1 | 5935-4264-047 | SAE-AS85049/52 |
| MIL-C-85049/53A | 30-Nov-90 | 1 | 5935-4264-048 | SAE-AS85049/53 |
| MIL-C-85049/54A | 30-Nov-90 | 1 | 5935-4264-049 | SAE-AS85049/54 |
| MIL-C-85049/55B | 30-Nov-90 | 1 | 5935-4264-050 | SAE-AS85049/55 |
| MIL-C-85049/56A | 26-Jan-87 | 2 | 5935-4264-051 | SAE-AS85049/56 |
| MIL-C-85049/57A | 26-Jan-87 | 2 | 5935-4264-052 | SAE-AS85049/57 |
| MIL-C-85049/58A | 21-Nov-86 | 2 | 5935-4264-053 | SAE-AS85049/58 |
| MIL-C-85049/59A | 28-June-88 | 1 | 5935-4264-054 | SAE-AS85049/59 |
| MIL-C-85049/60A | 30-Nov-90 | 1 | 5935-4264-055 | SAE-AS85049/60 |
| MIL-C-85049/61A | 21-Nov-86 | 2 | 5935-4264-056 | SAE-AS85049/61 |
| MIL-C-85049/62A | 26-Jan-87 | 2 | 5935-4264-057 | SAE-AS85049/62 |
| MIL-C-85049/63A | 26-Jan-87 | 2 | 5935-4264-058 | SAE-AS85049/63 |



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T10:12Z
Check the source to verify that this is the current version before use.

| Document | Date | Cancellation Notice No. | DoD Project No. | Replacement |
|---|---|---|---|---|
| MIL-C-85049/64B | 19-Dec-89 | 1 | 5935-4264-059 | SAE-AS85049/64 |
| MIL-C-85049/65B | 19-Dec-89 | 1 | 5935-4264-060 | SAE-AS85049/65 |
| MIL-C-85049/69B | 1-Oct-84 | 2 | 5935-4264-061 | SAE-AS85049/69 |
| MIL-C-85049/74A | 21-Nov-86 | 2 | 5935-4264-062 | SAE-AS85049/74 |
| MIL-C-85049/75A | 21-Nov-86 | 2 | 5935-4264-063 | SAE-AS85049/75 |
| MIL-C-85049/76 | 28-Aug-89 | 1 | 5935-4264-064 | SAE-AS85049/76 |
| MIL-C-85049/77 | 28-Aug-89 | 1 | 5935-4264-065 | SAE-AS85049/77 |
| MIL-C-85049/78 | 28-Aug-89 | 1 | 5935-4264-066 | SAE-AS85049/78 |
| MIL-C-85049/79 | 28-Aug-89 | 1 | 5935-4264-067 | SAE-AS85049/79 |
| MIL-C-85049/80 | 22-Sep-89 | 1 | 5935-4264-068 | SAE-AS85049/80 |
| MIL-C-85049/81 | 22-Sep-89 | 1 | 5935-4264-069 | SAE-AS85049/81 |
| MIL-C-85049/82 | 18-Aug-92 | 1 | 5935-4264-070 | SAE-AS85049/82 |
| MIL-C-85049/83 | 18-Aug-92 | 1 | 5935-4264-071 | SAE-AS85049/83 |
| MIL-C-85049/84 | 18-Aug-92 | 1 | 5935-4264-072 | SAE-AS85049/84 |
| MIL-C-85049/85 | 18-Aug-92 | 1 | 5935-4264-073 | SAE-AS85049/85 |
| MIL-C-85049/86 | 18-Aug-92 | 1 | 5935-4264-074 | SAE-AS85049/86 |
| MIL-C-85049/87 | 18-Aug-92 | 1 | 5935-4264-075 | SAE-AS85049/87 |
| MIL-C-85049/88 | 18-Aug-92 | 1 | 5935-4264-076 | SAE-AS85049/88 |
| MIL-C-85049/89 | 18-Aug-92 | 1 | 5935-4264-077 | SAE-AS85049/89 |
| MIL-C-85049/90 | 18-Aug-92 | 1 | 5935-4264-078 | SAE-AS85049/90 |
| MIL-C-85049/91 | 28-Jan-93 | 1 | 5935-4264-079 | SAE-AS85049/91 |
| MIL-C-85049/92 | 28-Jan-93 | 1 | 5935-4264-080 | SAE-AS85049/92 |
| MIL-C-85049/93 | 18-Feb-93 | 1 | 5935-4264-081 | SAE-AS85049/93 |
| MIL-C-85049/94 | 8-Oct-93 | 1 | 5935-4264-082 | SAE-AS85049/94 |
| MIL-C-85049/95 | 8-Oct-93 | 1 | 5935-4264-083 | SAE-AS85049/95 |
| MIL-C-85049/96 | 8-Oct-93 | 1 | 5935-4264-084 | SAE-AS85049/96 |

CAUTION: The supersession information is valid as of the date of this notice and may be superseded by subsequent revisions of the superseding document.

(Application for copies of SAE - Aerospace Standards should be addressed to SAE, 400 Commonwealth Drive, Warrendale, PA 15096-0001.)



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T10:12Z
Check the source to verify that this is the current version before use.

CONCLUDING MATERIAL

Custodians:
Army - CR
Navy - AS
Air Force - 11
DLA - CC

Review activities:
Army - AR, MI
Navy - EC, SH
Air Force - 99

Preparing activity:
Navy - AS

(Project 5935-4264)



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T10:12Z
Check the source to verify that this is the current version before use.