INCH-POUND

MIL-C-60395C (AR)
AMENDMENT 2
14 June 1991
SUPERSEDING
AMENDMENT 1
18 July 1986

MILITARY SPECIFICATION

CHARGE, PROPELLING, 155MM, M4A2,
LOADING, ASSEMBLING AND PACKING

This amendment forms a part of Military Specification MIL-C-60395C (AR) dated 16 June 1983, and is approved for use by the US Army Armament, Munitions and Chemical Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 2

2.1.2: Delete "9331258 - Packing and Marking for Container, Ammo, Metal PA 95: for Charge, Propelling, 155MM, M4A2" and substitute "7548187 - Packing and Marking of Metal Containers for Propelling Charges, Assembly and Details".

* 2.1.2: Add the following new drawings:

"12913754	- Packing and Marking for Container, Ammo, Metal: PA128 for Charge, Propelling, 155MM, M4A2 (alternate)
19-48-4231/53	- Unitization Procedure for Ammunition and Components Packed in Cylindrical Metal or Plastic Containers on 4-Way Entry Metal Pallets"

PAGE 6

TABLE II: Delete "Dwg 9331258" and substitute "Dwg 7548187".

* TABLE II: Delete "Dwg 7548187" and substitute "Dwg 7548187/12913754".

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:35Z
Check the source to verify that this is the current version before use.

PAGE 8

4.4.1: Delete "BPI" and substitute "SPI".

PAGE 12

4.4.2.4:

Critical defect 1: Delete in its entirety.

Major defect 101: Delete "BPI" and substitute "SPI".

PAGE 14

4.4.2.6:

Critical defect 1: Delete in its entirety.

Critical defect 2: Delete in its entirety.

Add Major defect 204: "Marking missing, misleading, unidentifiable or incorrect lot number...0.65%...3.2...Visual".

PAGE 16

4.4.2.8:

Add Minor defect 204: "Marking missing, misleading, unidentifiable or incorrect lot number...0.65%...3.2...Visual".

PAGE 17

4.4.2.9:

Critical defect 1: Delete "BPI" and substitute "SPI".

Add Critical defect 2: "Igniter charge assembly missing...100%...3.2...Visual".

PAGE 18

4.4.2.10:

Drawing Number: Delete "9331258" and substitute "7548187".

* Drawing number: Delete "7548187" and substitute "7548187/12913754".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:35Z
Check the source to verify that this is the current version before use.

Add Major defect 101: "Charge cannot be removed by hand . . . (a) . . . 3.2 . . . 4.5.7".

Minor defect 202: Delete in its entirety.

Notes: Add the following: "(a) One sample from every eight hours production".

PAGE 19

4.4.2.11: Delete "9331258" and substitute "7548187".

* 4.4.2.11: Delete "7548187" and substitute "7548187/12913754".

PAGE 20

4.5.2: Delete "BPI" and substitute "SPI".

4.5.2.1: Delete "BPI" and substitute "SPI".

PAGE 21

4.5.2.2: Delete "BPI" and substitute "SPI" in four places.

PAGE 22

4.5.6: Delete "BPI" and substitute "SPI".

Add the following paragraph:

"4.5.7 Charge removal from container. Each sample shall be tested for removal of the propelling charge from the container by hand. The charge may be pulled out by the straps or the container may be inverted and the charge either pulled out or slid out. Any charges that cannot be removed from the container using the above method shall be cause for rejection of the production represented by the sample."

* Delete paragraph 5.2.1 and add new paragraph 5.2.1:

"5.2.1 Level A. The propelling charges shall be packed, sealed and tested in accordance with specified requirements of drawings 7548187/12913754".

* Delete paragraph 5.3 and add new paragraph 5.3:

Source: https://assist.dla.mil -- Downloaded: 202610-23T00:35Z
Check the source to verify that this is the currentversion before use.