MILITARY SPECIFICATION

WARHEAD, HE, M18A1
PARTS FOR

This amendment forms a part of Military Specification MIL-W-50275A(MU), dated 15 October 1972.

Page 3

3.7, delete and substitute:

"3.7 Assembly force of base of the nose cap connector to the ogive. The base (see dwg. 9278721) shall assemble to a fixture representing the nominal opening in the ogive and cross section form of the opening. The base shall not break or crack during assembly and shall be capable of being removed without breaking or cracking and shall withstand disassembly force of 2 pounds minimum."

3.8, delete first sentence and substitute: "The fuze end of the flexible cable assembly shall assemble to a base connector assembly (9251979) with a force of five (5) pounds minimum and twenty-five (25) pounds maximum."

Page 9

4.3.2.5, Category Major: Delete "AQL 1.00 Percent" and substitute "AQL 0.65 Percent".

Page 10

4.3.2.6, Category Major: Delete "AQL 1.00 Percent" and substitute "AQL 0.65 Percent".

4.3.2.7, Category Major: Delete "AQL 1.00 Percent" and substitute "AQL 0.65 Percent".

FSC 1340

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:19Z
Check the source to verify that this is the current version before use.

4.3.2.8, delete and substitute:

"4.3.2.8 Liner (see dwg. 9220009 covering a detail of dwg. 9242585).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined.		
Major:	AQL 0.25%		
101	Runout of shoulder to center axis	Gage	08001
102	Outside diameter below shoulder	Gage	08002
103	Runout of O.D. below shoulder	Gage	08003
Major:	AQL 1.50%		
104	Distance to datum point B	Gage	08004
105	Distance to datum point A	Gage	08005
106	Thickness and variation at other than apex or base sections of cone	Gage	08006
107	Thickness of base flange	Gage	08007
108	Straightness of cone surface	Gage	08008
109	Outside diameter of flange	Gage	08009
110	Surface finish of central portion of cone	Gage	08010
111	Surface finish of outside diameter above flange	Gage	08011
112	Sharp edge present in wire slot	Visual/Tactile	08012
113	Depth from base of wire slot	Gage	08013
114	Depth from flange of wire slot	Gage	08014
115	Thickness of cone at base	Gage	08015
116	Component split, scarred, pitted or dented	Visual	08016
117	Total length of liner	Gage	08017
118	Width of wire slot	Gage	08018
Minor:	AQL 1.5%		
201	Thickness of cone at apex	Gage	08019
202	Radii improper	Visual	08020
203	Evidence of poor workmanship	Visual	08021"

4.3.2.10, Category Major: Delete "AQL 1.00 Percent" and substitute "AQL 0.65 Percent".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:19Z
Check the source to verify that this is the current version before use.