MILITARY SPECIFICATION

HOWITZER, LIGHT, TOWED, 105MM: M102

This amendment forms a part of Military Specification MIL-H-45586A, dated 10 March 1975, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 2

2.1 Under "STANDARDS" - change "MIL-STD-930" to "MIL-STD-130"

Under "PUBLICATIONS" - Delete the following:

"IEL 8428300 - Inspection Equipment List Howitzer, Light, Towed, 105MM: M102"

Substitute the following

"QEDL8428300 - Quality Engineering Data List, Howitzer, Light, Towed, 105MM: M102"

PAGE 6

3.3.1.5 Delete in its entirety and substitute the following paragraphs:

"3.3.1.5 Foamed oil and contaminated oil.

3.3.1.5.1 Foamed oil.-After exercising the recoil mechanism 25 cycles by mechanical gymnastication, or after the 4 rounds of proof-firing, oil withdrawn slowly from the recoil mechanism into a straight sided glass beaker shall be in accordance with the following: Within the first minute after withdrawal, the oil shall be five percent or less foam by volume; when exposed to the atmosphere for 15 minutes the aeration bubbles shall disappear. Testing shall be as specified in 4.5.3.2 and 4.5.3.5.

FSC: 1015

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T03:28Z
Check the source to verify that this is the current version before use.

3.3.1.5.2 Contaminated oil.-Within one to five minutes, after exercising the recoil mechanism 25 cycles by mechanical gymnastication, or after the 4 rounds of proof-firing, a minimum of two ounces of oil shall be removed from the purge hole in the recuperator cylinder into a straight sided glass beaker. Metallic particles allowable in the oil sample shall not exceed 400 micron in size. Testing shall be as specified in 4.5.3.2."

PAGE 9

3.3.4.2 Delete the third sentence: "Variable in trammel markings..." in its entirety.

PAGE 10

3.3.5 Delete the second sentence: "The trammel marking..." in its entirety.

PAGE 14

4.5.3.2 Delete in its entirety and substitute the following:

"4.5.3.2 Recoil mechanism and gymnastication testing.-Each completely assembled recoil mechanism shall be mechanically gymnasticated and tested for the performance characteristics of 3.3.1 and 3.3.1.1 thru 3.3.1.6 using the test method specified in 4.6.1 and 4.6.1.1 thru 4.6.1.6 respectively. Failure of the recoil mechanism to meet the requirements shall be cause for rejection. When five consecutive recoil mechanisms have passed the contaminated oil test (see 4.6.16) on each order, the frequency of testing for contaminated oil can be reduced to one randomly selected from each 25 produced. If a rejection occurs, revert back to original testing procedure."

PAGE 16

4.5.5.1 Delete "List of Inspection Equipment IEL8428300" and substitute: "Quality Engineering Data List QEDL8428300."

4.6.1.5 Delete "also, the oil withdrawn shall be inspected for contaminated oil." And the last sentence in its entirety. Add: "(see 3.3.1.5.1)" after the words "15 minutes."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T03:28Z
Check the source to verify that this is the current version before use.

4.6.1.6 Add the following paragraph:

"4.6.1.6 Contaminated oil test.-Within one to five minutes after the recoil mechanism has been mechanically gymnasticated, or after proof-firing, drain two ounces of oil from the purge hole of the recuperator cylinder. The largest metallic particle allowable in the oil sample shall not exceed 400 micron in size (see 3.3.1.5.2)."

PAGE 20

*4.6.3.4 Change paragraph 3.3.3.1.2 in the last line to paragraph 3.3.3.3.

*4.6.3.5.b Change paragraph 3.3.3.1.4 in line 3 to 3.3.3.5 and change paragraph 3.3.3.1.3 in line 5 to 3.3.3.4.

PAGE 21

4.6.4 Delete in its entirety and substitute the following paragraph:

"4.6.4 Proof-firing test.-Proof firing of carriage shall consist of firing both standard rounds and specific pressure rounds of ammunition. Proof-firing shall be performed by the Government (see 6.2). The carriage shall be proof-fired in accordance with Table III of 3.3.4.2, or in accordance with Table II of 3.3.4.1 in event proof-firing is accomplished simultaneously with the recoil mechanism. Visual examination for cracks, weld failures, deformation and other forms of damage shall be conducted on each unit at the conclusion of the firing program.

4.6.5 Delete in its entirety and substitute the following paragraph:

"4.6.5 Road test.-The completed carriage (less dummy round) shall be coupled to a vehicle equipped with standard pintle to determine compliance with the requirements specified in 3.3.5. Visual examination for cracks, weld failures, deformations and other forms of damage shall be conducted.

PAGE 22

5.1 In line 1 after word "complete" add the word "howitzer".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T03:28Z
Check the source to verify that this is the current version before use.

5.2 First sentence delete: "Shall" and substitute: "A complete howitzer shall...".

NOTE: The margins of this amendment are marked with an asterisk to indicate where changes from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
ARMY-AR
NAVY-MC

Preparing Activity:
ARMY-AR

Project Number: 1015-A274

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T03:28Z
Check the source to verify that this is the current version before use.