INCH-POUND

MIL-C-14750B (AR)
AMENDMENT 3
03 April 1995

SUPERSEDING
AMENDMENT 2
8 December 1992

MILITARY SPECIFICATION

CARTRIDGE, 60MM, HE, M49A4
LOADING, ASSEMBLING AND PACKING

This amendment forms a part of MIL-C-14750B (AR), dated 18 June 1989, and is approved for use by the U.S. Army Armament Research, Development and Engineering Center, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 9

* 4.4.2, Delete in its entirety and substitute:

"4.4.2 Examination. See MIL-A-48078.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Test Tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

b. Tool control dimensions. Dimensions marked tool control shall be inspected as follows: select and gage one cartridge from each press in operation every two hours or fraction thereof and whenever tooling is changed. Prior to any tooling change, the last fin assembly canted by the old tooling shall be gaged for the requirements of the applicable drawing. All cartridges produced prior to periodic inspection shall be rejected and screened whenever a defective tool control dimension is found and corrective action must be taken."

AMSC N/A **FSC 1310**

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:41Z
Check the source to verify that this is the current version before use.

PAGE 13

* 4.4.2.4, Critical Defect 3, Delete in its entirety.

Major 102, Delete and substitute:

"102 Propellant sheets damaged ... 100% ... 3.2 ...Visual".

Major 105, Delete in its entirety.

Major 110 and 111, Add as follows:

"110 Fuze not fully seated ... 0.40% ... 3.2 ... Visual
111 Fin and fin extension not fully seated ... 0.40% ... 3.2 ... Visual".

* Major 112 and 113, Add as follows:

"112 Fin blade(s) canted in improper direction ... 0.40% ... 3.2 ... Visual".
113 Height of fin blade cant ... 0.40% ... 3.2 ... Gage".

Minor 203, Delete in its entirety and substitute:

"203 Evidence of poor workmanship ... 0.65% ... 3.10 ... Visual".

PAGE 18

* 4.4.2.7, Minor Defect 201, Delete in its entirety.

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (modifications, additions, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in this notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1310-0563)

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:41Z
Check the source to verify that this is the current version before use.