MIL-C-14762A(AR)
6 June 1978
SUPERSEDING
MIL-C-14762(PA)
21 May 68

MILITARY SPECIFICATION

CONTAINER SHIPPING AND STORAGE: M467

This specification is approved for use by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification covers special requirements not included on the drawings, and provides the quality assurance provisions for the fabrication of parts, assembling, and the preparation for delivery for one type of container used to store and ship the M454 and M455 projectiles and designated as Container Shipping and Storage M467.

2. APPLICABLE DOCUMENTS

2.1 The following documents, of the issue in effect on date of invitation for bids or request for proposals, form a part of this specification to the extent specified herein:

SPECIFICATIONS (see 6.5)

FEDERAL

MMM-A-189 - Adhesive, Bonding Vulcanized Synthetic Rubber to Steel.
QQ-P-416 - Plating, Cadmium (Electrodeposited).
QQ-Z-325 - Zinc Plating (Electrodeposited).
RR-C-271 - Chain, Weldless.
TT-C-490 - Cleaning Methods and Pretreatment of Ferrous Surfaces for Organic Coatings.

Beneficial comments (recommendations, additions, deletions), and any pertinent data which may be of use in improving this document, should be addressed to: Commander, US Army Armament Research and Development Command, ATTN: DRDAR-QAN-Q, Dover, New Jersey 07801, by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426), appearing at the end of this document, or by letter.

FSC-NUOR

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

MILITARY

MIL-A-8623 - Adhesive, Epoxy Resin, Metal to Metal Structural Bonding.
MIL-C-22443 - Containers, Modular, Metal, General Specification for.
MIL-I-8835 - Indicator, Humidity, Card Chemically, Impregnated.
MIL-I-26860 - Indicator, Humidity, Plug, Color Change.
MIL-N-24129/2 - Nut Self Locking, Plastic Insert, Hexagon, Regular Height, 250°F for Grade 8 Steel, Bolting.
MIL-T-5021 - Tests: Aircraft and Missile Welding Operator's Qualification.
MIL-W-6858 - Welding Aluminum, Magnesium Non Hardening Steels or Alloys, and Titanium, Spot, Seams and Stitch.
MIL-W-8604 - Welding of Aluminum Alloys: Process for

PUBLICATIONS

ASTM-E8-66 - Methods of Tension Testing of Metallic Materials.

STANDARDS (see 6.5)

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-1168 - Lot Numbering of Ammunition
MIL-STD-1169 - Packaging, Packing and Marking for Shipment of Inert Ammunition Components
MS-15795 - Washer, Flat
MS-16535 - Rivet, Tubular
MS-16997 - Screw, Cap, Socket Head, Hex.
MS-20470 - Rivet, Solid
MS-21209 - Insert, Screw, Thread
MS-25043 - Cap
MS-27183 - Washer, Flat
MS-33537 - Insert Dim. for Coarse Fine Thread Helicoil
MS-35338 - Washer, Lock
MS-35340 - Washer, Lock
MS-35649 - Nut, Plain, Hex.
MS-35650 - Nut, Plain, Hex.
MS-35690 - Nut, Plain, Hex.
MS-90725 - Screw, Cap, Hex. Hd.
MS-90727 - Screw, Cap, Hex. Hd.
MS-90728 - Screw, Cap, Hex. Hd.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

DRAWINGS (see 6.5)

US Army Armament Research and Development Command
Product and Packaging Drawings

8791666 - Indicator, Humidity, Plug
8791671 - Nut, Plain, Hexagon
8791672 - Plate, Indicator
8791673 - Ring, Externally Threaded
8791682 - Housing, Card, Humidity, Indicator
8850104 - Container Shipping and Storage: M467
8850105 - Clamp Assembly, Front
8850106 - Clamp Assembly, Rear
8850108 - Cradle Assembly, Rear
8850110 - Container Frame Assembly
8850114 - Cushioning Material, Packaging, Bottom
8850116 - Partition
8850119 - Mount, Resilient
8850120 - Tubing
8850121 - Web, Belt
8850122 - Strap, Webbing
8850127 - Pad, Cushioning
8850131 - Dessicant Wrap
8850132 - Divider Cradle
8850133 - Divider Cradle
8850134 - Support Cradle Front
8850137 - Divider, Clamp
8850138 - Brace, Clamp
8850139 - Divider, Clamp
8850140 - Support
8850147 - Support, Clamp Front
8850151 - Screw, Shoulder
8850152 - Washer, Thrust
8850154 - Ring
8850155 - Washer-Screw, Socket Head
8850160 - Bracket, Angle
8850165 - Mount, Resilient
8850166 - Cradle Assembly, Front
8850167 - Bracket, Mount
8853791 - Vent Assembly
8853795 - Plug
8859012 - Finishing Requirements for Ferrous Metal Containers
8875823 - Skid Retainer
8880591 - Pad, Cushioning
8880592 - Bracket
8880595 - Clip
8880596 - Bracket Assembly
9204479 - Runner, Wood
9204480 - Bracket, Skid
9206889 - Preparation and Bonding of Non-Structural Rubber Parts to Metal

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

9321236 - Commercial Packaging and Marking
AA-38-409 - Dummy Projectile
ET-8850104 - Equipment Tabulation

(Copies of specifications, standards, drawings, and publications required by contractors in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

3. REQUIREMENTS

3.1 Materials. The contractor shall furnish objective evidence (see 6.2) that the material used to fabricate any part complies with the specifications listed on the applicable drawing.

3.2 Assembly. The container shall comply with all requirements specified on Drawing (dwg.) 8850104, with all requirements specified herein, and with the requirements of applicable specifications to the extent specified on the drawing and herein.

3.3 First article testing. Requirements for the submission of first article samples by the contractor shall be as specified in the contract (see 4.2).

3.4 Performance characteristics. Each container shall be tested as specified in 4.4.1 utilizing a dummy projectile supplied by the procuring agency (see dwg AA-38-409). The rear cradle shall be capable of rotating the projectile in a vertical position without any indication of binding. The dummy projectile shall fit snugly into position so that there is no evidence of looseness, play or the possibility that the projectile will shift in position in any test specified herein. The projectile shall not cut or damage rubber after being clamped in position with a torque of 200 inch-pounds on each clamping screw.

3.5 Pressure

3.5.1 Pressure, container. Each container shall withstand an internal pressure of 1.70 ± .15 pounds per square inch gage (psig) for a period of 30 minutes, minimum (min) with a maximum pressure loss of 0.15 p.s.i.g. when tested as specified in 4.4.2.1.

3.5.2 Pressure relief valve. Each pressure relief valve shall open when subjected to a pressure or vacuum within the range of 1.10 to 1.70 p.s.i.g. The pressure relief valve shall be closed when subjected to a pressure or vacuum of 1.00 - .15 p.s.i.g. The pressure relief valve shall be tested as specified in 4.4.2.2.

3.5.3 Pressure relief valve after assembly in container. Each pressure relief valve shall be tested after assembly in the container in accordance with 4.4.2.3. The valve shall operate freely in both directions without any indication of sticking or binding.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

3.6 Pull. The top rail and side panel of the container shall withstand a pull of 2000 ± 50 pounds without showing evidence of cracking or breaking of the epoxy band at the extrusion joint when tested as specified in 4.4.3.

3.7 Hoisting. Each container shall be capable of being lifted free from the ground or other support by lifting provisions provided without visible permanent distortion of the hoisting grapples or container when loaded with 450 pounds weight and tested as specified in 4.4.4.

3.8 Vibration. The container, loaded with a dummy projectile supplied by the procuring agency (see dwg AA-38-409) shall withstand vibration without cracking, splitting, loosening of parts, or projectile or other damage which would impair use when tested as specified in 4.4.5. Upon completion of this test the container shall comply with 3.4 and 3.5.

3.9 Drop and impact. The container, loaded with a dummy projectile supplied by procuring agency (see dwg AA-38-409) shall withstand the progressive drop and impact tests without evidence of cracks, splits, weld failure, loosening of parts or projectile, or other damage which would impair use when tested as specified in 4.4.6. Upon completion of each test the container shall comply with 3.4 and 3.5.

3.10 Welding. Welds shall be reasonably smooth and free of craters. They shall exhibit characteristics of fusion penetration and soundness of weld deposit representative of good welding practice. They shall be free of irregularities which indicate lack of skill on the part of the operator. All welds shall be tested in accordance with 4.4.7.

3.10.1 Fusion. Fusion welding shall be in accordance with MIL-W-8604 and shall be performed by operators who are currently certified in accordance with MIL-T-5021 Class A welders.

3.10.2 Spot welds. Spot welds shall be high commercial standards with shear strength and metallurgy equivalent to that defined in MIL-W-6858, Class 13, except that welds for primary structural loads shall be Class A.

3.11 Serialization. The contractor may assign serial numbers for internal control purposes at his discretion. The finish or any dimension of the item shall not be altered or damaged by the application of the serial number. The material used for marking shall not be subject to corrosion, fungus, flaking, or other similar adverse action which could prevent proper functioning of the item. The contractor may select any number suitable for his purpose.

3.12 Workmanship.

3.12.1 Plastic and metal characteristics. All components shall be free from cracks, splits, cold flow, shrinkage, cold shuts, inclusions, porosity, or any similar characteristic.

3.12.2 Threads. Threads shall be full and undamaged for the entire minimum length or depth as required on the applicable drawing.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

3.12.3 Burrs. Parts shall be free from burrs.

3.12.4 Foreign matter. Parts shall be free from chips, dirt, grease, rust, corrosion, or any embedded foreign material.

3.12.5 Cleaning. The cleaning method shall not be injurious to any of the parts, nor shall the parts be contaminated by the cleaning agents.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specifed herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

4.2 First article inspection.

4.2.1 Quantity to be submitted (see 6.4). The contractor shall submit 3 complete assemblies (see dwg 8850104); 3 sub-assemblies (see dwgs 8791666, 8850105, 8850106, 8850108, 8850110, 8850112, 8850117, 8850155, 8850166, 8853791, 8880596, 8880598, and 8880599); and 3 of each part; for first article testing to the testing facility designated in the invitation for bids or request for proposal.

4.2.2 Inspection and testing to be performed. The first article inspection sample shall be subjected to the inspections and tests specified in table I. Tests need not be conducted in the order specified in table I.

Table I
First article inspection and tests

Examination or Test	Contractor's Inspection before Submission	Destructive	Non-Destructive	Assembly	Sub-Assembly	Part
1. Classification of characteristics (see 4.3.2.1)	X		X	X	X	X
2. Performance characteristics (see 3.4)	X		X	X		
3. Pressure (see 3.5)	X		X	X		
4. Pull (see 3.6)		X			X	
5. Hoisting (see 3.7)	X		X	X		

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

Table I (cont'd)

Examination or Test	Contractor's Inspection before Submission	Destructive	Non-Destructive	Assembly	Sub-Assembly	Part
6. Vibration (see 3.8)	X		X	X		
7. Drop and impact (see 3.9)		X		X		
8. Humidity indicator (see 4.3.3.6)	X		X		X	
9. Humidity cards (see 4.3.3.7)	X		X			X
10 Tensile (see 4.3.3.8)	X		X			X
11 Paint Adhesion (see 4.3.3.9)	X		X	X	X	X

4.2.3 Inspection equipment. The inspection and testing specified in 4.2.2 shall be accomplished by using the gages and test equipment specified in 4.3.4.1.

4.2.4 Rejection. If any item fails to comply with any of the applicable requirements, the first article sample shall be rejected.

4.3 Product acceptance inspection.

4.3.1 Lot formation. A lot shall consist of parts and assemblies produced by one manufacturer in one unchanged process, in accordance with the same drawing, same drawing revision, same specification and same specification revision. Drawing, specification and process changes not affecting safety, performance, storage, or interchangeability, as determined by the Government, shall not necessitate changing the lot interfix number. The criteria and procedures for the assignment of lot numbers shall be in accordance with MIL-STD-1168.

4.3.1.1 Inspection lot. An inspection lot shall be the quantity of parts, subassemblies, or assemblies from the same lot, which are submitted to inspection for Government acceptance.

4.3.2 Product inspection examination. Critical characteristics shall require 100 percent inspection of all items in the inspection lot. A sample shall be selected at random from each inspection lot in accordance with the applicable major or minor characteristic table and inspected for all characteristics in the applicable classification. Any characteristic in the sample found to be defective shall reject the inspection lot. Sequence for the inspection of characteristics in each classification need not be followed as long as all characteristic inspections are performed.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

Major characteristic table II

Lot size	Sample size 100% inspection
1- 25	25
26- 30	26
31- 35	27
36- 40	28
41- 45	29
46- 50	30
51- 55	31
56- 60	32
61- 65	33
66- 70	34
71- 75	35
76- 85	36
86- 95	37
96- 110	38
111- 130	39
131- 156	40
157- 190	41
191- 240	42
241- 340	43
341- 520	44
521-1120	45
1121 and over	

Minor characteristic table III

Lot size	Sample size 100% inspection
1- 25	16
26- 35	17
36- 45	18
46- 55	19
56- 65	20
66- 100	21
101- 200	22
201 and over	

4.3.2.1 Classification of characteristics. Critical, major, and minor characteristics are defined in MIL-STD-105. Inspection shall be conducted as follows:

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-14762A(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.3.2.1.1	Bracket (Before Painting)		8880592
			NEXT HIGHER ASSEMBLY 8880596

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Location of 4 small holes		Table II		Gage
102.	Diameter of 4 small holes		Table II		Gage
103.	Location of 3 large holes		Table II		Gage
104.	Diameter of 3 large holes		Table II		Gage
105.	Length between bottom of top bend and bottom of bottom bend		Table II		Gage
106.	Height of top bend		Table II		Gage
107.	Material		100%	3.1	Visual
108.	Cleaning and primer application (see dwg 8859012)		Table II		Visual/Manual
Minor:					
201.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.3.2.1.2	Bracket				8880592
					NEXT HIGHER ASSEMBLY
					8880596
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE / INSPECTION METHOD
Critical:	None defined				
Major:					
101.	No finish on surfaces to be bonded		Table II		Visual
Minor:					
201.	No paint missing including bare spot		Table III		Visual
202.	Serialization		Table III	3.11	Visual
203.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-14762A(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.3.2.1.3	Clip (before painting)	1 OF 1	8880595
			NEXT HIGHER ASSEMBLY 8880596

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Location of 2 holes		Table II		Gage
102.	Diameter of 2 holes		Table II		Gage
103.	Length and width, min.		Table II		Gage
104.	Material		100%	3.1	Visual
105.	Cleaning and primer application (see dwg 8859012)		Table II		Visual/Manual
Minor:					
201.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8880595 / NEXT HIGHER ASSEMBLY 8880596
4.3.2.1.4	Clip				
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:	None defined				
Minor:					
201.	No paint missing including bare spot		Table III		Visual
202.	Serialization		Table III	3.11	Visual
203.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8880591
4.3.2.1.5	Pad, cushioning				NEXT HIGHER ASSEMBLY 8880596
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Location of 2 holes if applicable (see dwg note 3)		Table II		**Measure
102.	Diameter of 2 holes if applicable (see dwg note 3)		Table II		**Measure
103.	No tear, split or crack		Table II		Visual
104.	Material		100%	3.1	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

**Measure with suitable scale.

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.3.2.1.6	Cap				MS 25043-10C
					NEXT HIGHER ASSEMBLY
					8853792
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OP 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Objective evidence available for part in accordance with MS25043		100%	6.2	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.3.2.1.7	Plug		8853795
			NEXT HIGHER ASSEMBLY
			8853791

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR DEC%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Small diameter of groove in right face of flange, max.		Table II		Gage
102.	Major diameter of thread, max.		Table II		Gage
103.	Inside diameter in right face of flange, min.		Table II		Gage
104.	Depth of groove in right face of flange, max.		Table II		Gage
105.	Width across flats of hex, max.		Table II		Gage
106.	Material		100%	3.1	Visual
107.	Objective evidence available for protective finish in accordance with dwg 8853795		100%	6.2	Visual
Minor:					
201.	Chamfer present		Table III		Visual
202.	Serialization		Table III	3.11	Visual
203.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-14762A(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.3.2.1.8	Divider, cradle		8850133
			NEXT HIGHER ASSEMBLY 8850166

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE INSPECTION
Critical:	None defined				
Major:					
101.	Total width		Table II		Gage
102.	Material		100%	3.1	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-14762A(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.3.2.1.9	Support cradle front		8850134
			NEXT HIGHER ASSEMBLY
			8850166 and 8850108

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Radius of outside		Table II		Gage
102.	Width		Table II		Gage
103.	Depth		Table II		Gage
104.	Material		100%	3.1	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.3.2.1.10	Pad, cushioning		8850127
			NEXT HIGHER ASSEMBLY 8850166

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Thickness		Table II		Gage
102.	Material		100%	3.1	Visual
103.	No tear, split, crack		Table II		Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.3.2.1.11	Insert screw thread				MS 21209C6-15
					NEXT HIGHER ASSEMBLY
					8850166 and 8850108
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Objective evidence available for part in accordance with MS2109		100%	6.2	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850166
4.3.2.1.12	Cradle assembly, front (before painting and bonding of rubber strip)				NEXT HIGHER ASSEMBLY 8850104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Width of formed opening		Table II		Gage
102.	Total depth to bottom of divider		Table II		Gage
103.	Location of hole in sides		Table II		Gage
104.	Diameter of hole in sides		Table II		Gage
105.	Total length		Table II		Gage
106.	Pitch diameter of 2 threaded holes in accordance with MS 35337		Table II		Gage
107.	Minor diameter of 2 threaded holes, max. in accordance with MS 35337		Table II		Gage
108.	Location of 2 threaded holes		Table II		Gage
109.	Welding		Table II	3.11	Visual
110.	Taper of inside surface (see dwg 8850134)		Table II		Gage
111.	Left thickness (see dwg 8850134)		Table II		Gage
112.	Cleaning and primer application (see dwg 8859012)		Table II		Visual/Manual
Minor:					
201.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-14762A(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.3.2.1.13	Cradle assembly, front		8850166
			NEXT HIGHER ASSEMBLY 8850104

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Location of rubber strip		Table II		Gage
102.	Rubber strip bonded in accordance with dwg 9206889		Table II		Visual/Manual
103.	Rubber properly trimmed		Table II		Visual
104.	Objective evidence available for adhesive in accordance with MMM-A-189		100%	6.2	Visual
105.	No paint on rubber strip		Table II		Visual
Minor:					
201.	No paint missing including bare spot		Table III		Visual
202.	Serialization		Table III	3.11	Visual
203.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.3.2.1.14	Divider, clamp		8850137
			NEXT HIGHER ASSEMBLY 8850105

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Diameter of hole		Table II		Gage
102.	Radius of center bend		Table II		Gage
103.	Width		Table II		Gage
104.	Material		Table II	3.1	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-14762A(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.3.2.1.15	Support, clamp front		8850147
			NEXT HIGHER ASSEMBLY 8850105

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Radius of outside		Table II		Gage
102.	Width		Table II		Gage
103.	Material		100%	3.1	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.3.2.1.16	Brace, clamp	1 OF 1	8850138
			NEXT HIGHER ASSEMBLY: 8850105

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Radius of center curved section		Table II		Gage
102.	Material		100%	3.1	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-14762A(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.3.2.1.17	Chain safety, weldless		RR-C-27
			NEXT HIGHER ASSEMBLY
			8850105 and 8850106

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Objective evidence available for part in accordance with RR-C-27		100%	6.2	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850105
4.3.2.1.18	Clamp assembly, front (before painting and assembly of rubber strip)				NEXT HIGHER ASSEMBLY 8850104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Distance between 2 holes and slots		Table II		Gage
102.	Diameter of 2 holes, min.		Table II		Gage
103.	Width of slot		Table II		Gage
104.	Length of hole and slot		Table II		Gage
105.	Rivet flush or below flush before assembly of pad		Table II		Visual/Manual
106.	Taper (see dwg 8850147)		Table II		Gage
107.	Thickness at left of taper (see dwg 8850147)		Table II		Gage
108.	Location of slotted holes		Table II		Gage
109.	Welding		Table II	3.10	Visual/Manual
110.	Surfaces smooth designated on dwg		Table II		Manual
111.	Cleaning and primer application (see dwg 8859012)		Table II		Visual/Manual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850105
4.3.2.1.19	Clamp assembly, front				NEXT HIGHER ASSEMBLY 8850104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Rubber strip bonded in accordance with dwg 9206889		Table II		Visual/Manual
102.	No paint on rubber strip		Table II		Visual
103.	Objective evidence available for adhesive in accordance with MMM-A-189		100%	6.2	Visual
Minor:					
201.	No paint missing including bare spot		Table III		Visual
202.	Serialization		Table III	3.11	Visual
203.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850132
4.3.2.1.20	Divider cradle				NEXT HIGHER ASSEMBLY 8850108
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Width		Table II		Gage
102.	Material		100%	3.1	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850108
4.3.2.1.21	Cradle assembly, rear (before painting and bonding rubber parts)				NEXT HIGHER ASSEMBLY 8850104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Width of center opening		Table II		Gage
102.	Depth to bottom of divider		Table II		Gage
103.	Location of 2 threaded holes		Table II		Gage
104.	Pitch diameter of 2 threaded holes in accordance with MS35337		Table II		Gage
105.	Minor diameter of 2 threaded holes, max. in accordance with MS 35337		Table II		Gage
106.	Location of 2 side holes		Table II		Gage
107.	Diameter of 2 side holes		Table II		Gage
108.	Welding		Table II	3.10	Visual
109.	Mounting surfaces not ground smooth		Table II		Visual/Manual
110.	Cleaning and primer application (see dwg 8859012)		Table II		Visual/Manual
Minor:					
201.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850108
4.3.2.1.22	Cradle assembly, rear				NEXT HIGHER ASSEMBLY 8850104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE / INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Location of rubber strip in curved section		Table II		Gage
102.	Location of rubber strip left end		Table II		Gage
103.	Rubber strip bonded in accordance with dwg 9206899		Table II		Visual/Manual
104.	Objective evidence available for adhesive in accordance with MMM-A-189		100%	6.2	Visual
105.	No paint on rubber parts		Table II		Visual
Minor:					
201.	No paint missing including bare spot		Table III		Visual
202.	Serialization		Table III	3.11	Visual
203.	Workmanship		Table III	3.12	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.3.2.1.23	Divider clamp		8850139
			NEXT HIGHER ASSEMBLY 8850106

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Diameter of hole		Table II		Gage
102.	Radius of center bend		Table II		Gage
103.	Width		Table II		Gage
104.	Material		100%	3.1	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850106
4.3.2.1.24	Clamp assembly, rear (before painting and assembly of rubber part)				NEXT HIGHER ASSEMBLY 8850104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Distance between 2 mounting holes		Table II		Gage
102.	Diameter of 2 mounting holes, min.		Table II		Gage
103.	Width of slot on 2 mounting holes		Table II		Gage
104.	Total length mounting hole and slot		Table II		Gage
105.	Location of mounting holes		Table II		Gage
106.	Welding		Table II	3.10	Visual/Manual
107.	Surfaces indicated ground smooth		Table II		Visual/Manual
108.	Cleaning and primer application (see dwg 8859012)		Table II		Visual/Manual
Minor:					
201.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850106
4.3.2.1.25	Clamp assembly, rear				NEXT HIGHER ASSEMBLY 8850104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Rivet head not flush or below flush before assembly of pad		Table II		Visual/Manual
102.	Rivet loose		Table II		Manual
103.	Location of rubber part		Table II		Gage
104.	Rubber part bonded in accordance with dwg 9206899		Table II		Visual/Manual
105.	Objective evidence available for adhesive in accordance with MMM-A-189		100%	6.2	Visual
106.	Paint on rubber parts		Table II		Visual
Minor:					
201.	No paint missing including bare spot		Table III		Visual
202.	Serialization		Table III	3.11	Visual
203.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8791682
4.3.2.1.26	Housing, card humidity indicator				NEXT HIGHER ASSEMBLY 8791666
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Width of gasket groove in outside flange, min.		Table II		Gage
102.	Depth of gasket groove in outside flange, max.		Table II		Gage
103.	Small diameter of gasket groove in outside flange		Table II		Gage
104.	Width of inside groove, min.		Table II		Gage
105.	Depth of inside groove, max.		Table II		Gage
106.	Small diameter of inside groove		Table II		Gage
107.	Minor diameter of inside thread, min.		Table II		Gage
108.	Material		Table II	3.1	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850116
4.3.2.1.27	Partition				NEXT HIGHER ASSEMBLY 8850110
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Width		Table II		**Measure
102.	Length		Table II		**Measure
103.	Location of 6 holes		Table II		Gage
104.	Diameter of 6 holes, min.		Table II		Gage
105.	Material		Table II	3.1	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:
**Measure with suitable scale.

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.3.2.1.28	Desiccant wrap	1 OF 1	8850131
			NEXT HIGHER ASSEMBLY: 8850110

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Length of formed section		Table II		Gage
102.	Total depth		Table II		Gage
103.	Width of formed section		Table II		Gage
104.	Material		100%	3.1	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850167
4.3.2.1.29	Bracket, mount (part no. 8850167-2)				NEXT HIGHER ASSEMBLY 8850110
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Location of 4 holes		Table II		Gage
102.	Diameter of 4 holes		Table II		Gage
103.	Total height of formed section		Table II		Gage
104.	Material		100%	3.1	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850167 / NEXT HIGHER ASSEMBLY 8850110
4.3.2.1.30	Bracket, mount (part no. 8850167-1)				
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Location of 4 mounting holes		Table II		Gage
102.	Diameter of 4 mounting holes		Table II		Gage
103.	Total height of formed section		Table II		Gage
104.	Diameter of small hole		Table II		Gage
105.	Material		100%	3.1	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850140
4.3.2.1.31	Support				NEXT HIGHER ASSEMBLY 8850110
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Location of 4 holes		Table II		Gage
102.	Diameter of 4 holes		Table II		Gage
103.	Radius of top contour		Table II		**Measure
104.	Length from top contour to bottom		Table II		**Measure
105.	Material		100%	3.1	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual

NOTES:

**Measure with suitable scale

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8875823
4.3.2.1.32	Skid retainer				NEXT HIGHER ASSEMBLY 8850110
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Width between bottom channels		Table II		Gage
102.	Depth between bottom channels		Table II		Gage
103.	Location of holes at each end		Table II		Gage
104.	Diameter of holes		Table II		Gage
105.	Material		100%	3.1	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER 8850110
4.3.2.1.33	Container frame assembly (before painting)				NEXT HIGHER ASSEMBLY 8850104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Diameter of large hole left end		Table II		Gage
102.	Distance across hole at flat		Table II		Gage
103.	Diameter of small hole left end		Table II		Gage
104.	Diameter of hole front side		Table II		Gage
105.	Location of left bracket mounts		Table II		Gage
106.	Location of right bracket mounts		Table II		Gage
107.	Location of support		Table II		Gage
108.	Location of partition		Table II		Gage
109.	Proper rivet assembly		Table II		Visual
110.	Spot welds		Table II	3.10	Visual
111.	Location of desiccant wrap		Table II		Visual
112.	Location of 4 tie down rings and brackets		Table II		Visual
113.	Location of 4 stiffeners		Table II		Visual
114.	Location of 2 hoisting grapples		Table II		Visual
115.	Location of 8 latch assemblies		Table II		Visual
116.	Primer not present on surface areas where cushions, gasket, and rubber pad are to be bonded		Table II		Visual
117.	Location of 4 handles		Table II		Visual
118.	Welding on 4 tie down rings		Table II	3.10	Visual
119.	Number of rivets on skid retainer assembly		Table II		Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 8850110 / NEXT HIGHER ASSEMBLY 8850104
4.3.2.1.33	Container frame assembly (before painting)				
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major:					
120.	Outside diameter of 4 tie down rings after welding (see dwg 8850154)		Table II		Gage
121.	Epoxy present skid retainer assembly		Table II		Visual
122.	Objective evidence available for epoxy in accordance with MIL-A-8623		100%	6.2	Visual
123.	Objective evidence available for container in accordance with MIL-C-22443		100%	6.2	Visual
124.	Cleaning and primer application (see dwg 8859012)		Table II		Visual/Manual
125.	Proper application of sealer		Table II		Visual
Minor:					
201.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850110
4.3.2.1.34	Container frame assembly				NEXT HIGHER ASSEMBLY 8850104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Paint not present on areas to be bonded defined on dwg.		Table II		Visual
Minor:					
201.	No paint missing including bare spot except where defined on dwg.		Table III		Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.3.2.1.35	Mount, Resilient				8850165 and 8850119
					NEXT HIGHER ASSEMBLY 8850104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OF 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Objective evidence available for part in accordance with applicable drawing		100%	6.2	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.3.2.1.36	Strap, webbing		8850122
			NEXT HIGHER ASSEMBLY 8850104

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Objective evidence available for part in accordance with dwg 8850122		100%	6.2	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.3.2.1.37	Strap, webbing	1 OF 1	8850121
			NEXT HIGHER ASSEMBLY: 8850104

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Objective evidence available for part in accordance with dwg 8850121		100%	6.2	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.3.2.1.38	Screw, shoulder		8850151
			NEXT HIGHER ASSEMBLY 8850104

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Outside diameter		Table II		Gage
102.	Pitch diameter of thread		Table II		Gage
103.	Major diameter of thread, min.		Table II		Gage
104.	Material		100%	3.1, 4.3.3.8	Visual
105.	Objective evidence available for protective finish in accordance with dwg 8850151		100%	6.2	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850152 / NEXT HIGHER ASSEMBLY 8850104
4.3.2.1.39	Washer, thrust				
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE / INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Inside diameter, min.		Table II		Gage
102.	Material		100%	3.1	Visual
103.	Objective evidence available for protective finish in accordance with dwg 8850152		100%	6.2	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-14762A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850155
4.3.2.1.40	Washer, screw, socket head				NEXT HIGHER ASSEMBLY 8850104
CATEGORY	EXAMINATION OR TEST	NO OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Objective evidence available for washer in accordance with MS27183		100%	6.2	Visual
102.	Objective evidence available for screw, cap, socket head in accordance with MS16997		100%	6.2	Visual
103.	Perpendicularity of washer with screw thread		Table II		Gage
104.	Welding		Table II	3.10	Visual
105.	Protective finish missing including bare spot		Table II		Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARMA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.3.2.1.41	Tubing		8850120
			NEXT HIGHER ASSEMBLY 8850104

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Cracks, splits, holes		Table II		Visual
102.	Length		Table II		**Measure
103.	Material		100%	3.1	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:
**Measure with suitable scale

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850160
4.3.2.1.42	Bracket, angle				NEXT HIGHER ASSEMBLY 8850104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Location of holes		Table II		Gage
102.	Diameter of holes		Table II		Gage
103.	Total thickness including bend		Table II		**Measure
104.	Material		100%	3.1	Visual
105.	Objective evidence available for protective finish in accordance with dwg 8850160		100%	6.2	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual

NOTES:

**Measure with suitable scale

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9204480
4.3.2.1.43	Bracket, skid				NEXT HIGHER ASSEMBLY 8850104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Location of 3 holes		Table II		Gage
102.	Diameter of 3 holes		Table II		Gage
103.	Diameter of large hole		Table II		Gage
104.	Width between channels		Table II		Gage
105.	Location of large hole		Table II		Gage
106.	Material		100%	3.1	Visual
107.	Cleaning and primer application (see dwg 8859012)		Table II		Visual
Minor:					
201.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9204480
4.3.2.1.44	Bracket, skid				NEXT HIGHER ASSEMBLY 8850104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:	None defined				
Minor:					
201.	No paint missing including bare spot		Table III		Visual
202.	Serialization		Table III	3.11	Visual
203.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9204479
4.3.2.1.45	Runner, wood				NEXT HIGHER ASSEMBLY 8850104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Diameter of holes		Table II		Gage
102.	Steps on bottom present		Table II		Visual
103.	No splits, checks or cracks thru bolt holes or adjacent laminations		Table II		Visual
104.	Material		100%	3.1	Visual
105.	Direction of laminations		Table II		Visual
106.	Length from full depth of slots to left face		Table II		Gage
Minor:					
201.	No lacquer missing including bare spot		Table III		Visual
202.	Marking		Table III		Visual
203.	Serialization		Table III	3.11	Visual
204.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.3.2.1.46	See Below				See Title
					NEXT HIGHER ASSEMBLY
					8850104 and 8853791
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Washer, flat (see MS-15795-204 and MS-27183-14) Washer, lock, (see MS-35340-43 and MS-35338-46), Washer, lock, split (see MS-35338-40, MS-35338-48), Rivet, solid (see MS-20470-AD4-6), nut, plain, hex, (see MS-35649-42, MS-35650-102, and MS-35690-608), Rivet, tubular (see MS-16535-82), Nut, self-locking, plastic insert, hexagon, regular height for grade 8 steel bolting (see MIL-N-24129/2); Screw, machine (see MS-90727-108, MS-90725-76, MS-90725-78 and MS-90728-59)				
Critical:	None defined				
Major:					
101.	Objective evidence available for part in accordance wiht applicable specification		100%	6.2	Visual
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8850114
4.3.2.1.47	Cushioning material, packaging bottom				NEXT HIGHER ASSEMBLY 8850104
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Inside diameter		Table II		**Measure
102.	Total length		Table II		**Measure
103.	Distance from bottom of cavity to left face		Table II		**Measure
Minor:					
201.	Serialization		Table III	3.11	Visual
202.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

**Measure with suitable scale

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
4.3.2.1.48	Container shipping and storage: M467				8850104
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:					
1.	No foreign matter in rubber pads or no sharp edges which could scratch, nick or gouge the projectile in assembly		100%		Visual/Manual
Major:					
101.	Torque on cradle assembly mounting screws		Table II		Gage
102.	Proper assembly of humidity indicator		Table II		Visual/Manual
103.	Humidity indicator plug torque, min.		Table II		Gage
104.	Bonding of top and bottom cushions (see dwg 9206889)		Table II		Visual/Manual
105.	Proper assembly of vent assembly		Table II		Visual/Manual
106.	Vent assembly torque, min.		Table II		Gage
107.	Proper assembly of relief valve		Table II		Visual/Manual
108.	Relief valve torque, min.		Table II		Gage
109.	Proper assembly of rear cradle		Table II		Visual/Manual
110.	Proper assembly of forward cradle		Table II		Visual/Manual
111.	Bonding of rubber parts (see dwg 9206889)		Table II		Visual/Manual
112.	Location of desiccant wrap		Table II		Visual
113.	Proper installation of bracket assembly		Table II		Visual/Manual
114.	Proper assembly of 4 skids		Table II		Visual/Manual
115.	Rear cradle rotates freely		Table II	3.4	Manual
116.	No parts missing		Table II		Visual
117.	Functioning of 8 latches		Table II		Manual
118.	Spot welding		Table II	3.10.2	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.3.2.1.48	Container shipping and storage: M467				8850104
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major:					
119.	All screws, nuts, bolts or assembly tight		Table II		Manual
120.	Functioning of belt buckles		Table II		Visual/Manual
121.	Strap undamaged and properly assembled		Table II		Visual
122.	Torque on skid nuts		Table II		Gage
Minor:					
201.	No paint missing including bare spot		Table III		Visual
202.	Workmanship		Table III	3.12	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.3.2.1.49	Container packaging and marking for shipment				see section 5
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical:	None defined				
Major:					
101.	Container correctly packaged		Table II	5.1, 5.2	Visual/Manual
102.	Container package marked correctly		Table II	5.3	Visual
Minor:					
201.	Workmanship		Table III	3.12	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

4.3.3 Inspection testing. The contractor shall perform all the tests specified in this paragraph. Tests do not have to be performed in the order specified.

Test	Test Classification
a. Performance characteristics	Major
b. Pressure	Major
c. Pull	Major
d. Hoisting	Major
e. Vibration	Major
f. Humidity indicator	Major
g. Humidity cards	Major
h. Tensile	Major
i. Paint adhesion	Minor

Test "c" is considered destructive when sample parts are used as samples and parts so tested shall not be returned to the lot. The destruction samples are over and above the deliverable quantity of the items required by the contract.

4.3.3.1 Performance characteristics (see 3.4). Each container shall be subjected to this test (see 4.4.1). If any container fails to comply with 3.4, it shall be rejected and removed from the lot.

4.3.3.2 Pressure (see 3.5). Each container and relief valve shall be tested as specified in 4.4.2. If any container or relief valve fails to comply with 3.5, the container or relief valve (as applicable) shall be rejected and removed from the lot.

4.3.3.3 Pull (see 3.6). A sample specimen selected at random from each lot of bonded parts shall be subjected to this test (see 4.4.3). If the sample fails to comply with 3.6, the lot of binded parts shall be rejected.

4.3.3.4 Hoisting (see 3.7). Each container shall be subjected to this test (see 4.4.4). If any container fails to comply with the 3.7, it shall be classified defective and removed from the lot.

4.3.3.5 Vibration (see 3.8). One container of every 50 or less containers produced shall be tested as specified in 4.4.5. If the container fails to comply with 3.8, the lot of containers shall be rejected.

4.3.3.6 Humidity indicator (see dwg 8791666). This test is required when the humidity indicator plug is procured as a complete unit. The lot of humidity indicator plugs shall be tested in accordance with MIL-I-26860 using an AQL of 2.5% level II for sample sizes selected from MIL-STD-105. If the sample tested fails to comply with MIL-I-26860 and MIL-STD-105, the lot of parts shall be rejected.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

4.3.3.7 Humidity cards (see dwg 8875803). This test is required for each lot of humidity indicator cards when contractor makes the humidity indicator plugs. Each lot of humidity indicator cards shall be tested in accordance with MIL-I-8835 with the limitations listed on the drawing. If the samples tested do not comply with the specification requirements the lot of humidity indicator cards shall be rejected.

4.3.3.8 Tensile test (see dwg 8850151). A sample test specimen selected at random from each lot of material shall be prepared and tested in accordance with ASTM-E8-66. If the sample fails to comply with drawing requirements, the lot of material shall be rejected.

4.3.3.9 Paint adhesion (see dwgs 8880592, 8880595, 8850104, 8850166, 8850105, 8850106, 8850108, 8850110, 9204480 and 8880596). Each part or assembly shall be tested for paint adhesion as specified in 4.2.6 TT-C-490. Any part or assembly which fails to comply with the requirements for paint adhesion in 3.7 TT-C-409 shall be classified defective and removed from the lot.

4.3.4 Acceptance inspection equipment.

4.3.4.1 Critical and major characteristics and tests. Inspection and testing shall be performed with the acceptance inspection equipment, operating instructions, and calibration instructions specified on the Equipment Lists (EL). EL's for assemblies are listed on the Equipment Tabulation, ET-8850104. When either of the conditions listed below exist, the contractor shall design required equipment or specify suitable commercial equipment. The contractor shall obtain approval of such designs, operating instructions, and special calibration instructions as specified in 6.3 prior to use on the contract.

a. Any deviation from equipment or procedures specified on the EL is desired.
b. The code "CD" is listed in the "Part or Identifying Number" column on the EL.

4.3.4.2 Minor characteristics and tests. Acceptance inspection equipment for minor characteristics is not specified on EL's. The acceptance inspection equipment, operating instructions and calibration instructions used by the contractor for minor classification inspection shall be approved by the Government representative authorized by the procuring agency.

4.4 Test methods. The tolerances specified herein are absolute with no allowance for test equipment inaccuracy. The tolerances used by the manufacturer shall be equal to the absolute tolerances less the accuracy tolerances of the test equipment used.

4.4.1 Performance characteristics (see 3.4). Place the dummy projectile in the container and secure rear clamp with torque 200 ± 10 inch pounds on each clamping screw. Tilt projectile to vertical position and comply with 3.4. Return projectile to horizontal position and assemble forward clamp with 200 ± 10 inch pounds on each clamping screw. Close the

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

cover of the container. Tip the container on right end, then on left end, then on top, and then return to upright condition. After completion of the test the projectile shall comply with 3.4.

4.4.2 Pressure (see 3.5). Pressure test equipment provided shall have minimum graduations of 0.15 pounds per square inch indication.

4.4.2.1 Pressure retention container (see 3.5.1). The container shall be assembled and sealed as if for shipment except that the relief valve opening shall be blocked off. The container shall be pressurized internally to the pressure specified in 3.5.1 and isolated from the pressure source. After 30 minutes minimum the exact pressure reading shall comply with 3.5.1.

4.4.2.2 Pressure relief valve (see 3.5.2). The relief valve shall be subjected to an increasing pressure until the valve opens. The pressure shall then be decreased until the valve closes. The pressure valves for the functioning of the valve shall comply with 3.5.2. The pressure shall be released and a vacuum applied, increasing until the valve opens. The vacuum shall then be decreased until the valve closes. The vacuum valves for the functioning of the valve shall comply with 3.5.2.

4.4.2.3 Pressure relief valve after assembly in container (see 3.5.3). The relief valve shall be tested after assembly in the container by pushing the valve with the finger from the outside of the container. Then push the valve with finger from the inside of the container. The action of the relief valve shall comply with 3.5.3.

4.4.3 Pull test (see 3.6). The sample specimen shall consist of rail, and a Side Panel having a bonded length of 6 + 1/8 inches long and with the panel extending approximately 2 inches from the rail. The bond of this specimen shall be subjected to a pull of 2000 + 50 pounds in an approved tension tester and comply with 3.6.

4.4.4 Hoisting test (see 3.7). The container shall be lifted from the ground or support by two cables of equal length fastened to the hoisting grapples of the container with the cover assembled when the container has been loaded with 450 pounds weight and comply with 3.7.

4.4.5 Vibration (see 3.8). The container, loaded with a dummy projectile, shall withstand vibrations, as specified in Table IV, in each of its three mutually perpendicular axes without evidence of damage that would impair its intended use. Upon completion of this test, the container shall comply with 3.8.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

Table IV

Vibration Schedule

Frequency (c.p.s.)	Sweep time minutes	Double amplitude (inches)	Sweeps (Number)
2-10-2	10 ± .5	0.40 ± 10 percent	1
11-15-11	10 ± .5	0.25 ± 10 percent	1
16-20-16	10 ± .5	0.13 ± 10 percent	1
21-60-21	10 ± .5	0.06 ± 10 percent	1

4.4.6 Drop and impact (see 3.9). The container, loaded with a dummy projectile, shall withstand the following tests at ambient temperature. After each type of drop and impact test; the container shall be visually examined and comply with 3.9.

4.4.6.1 Edgewise drop. The container shall be supported at one end of the base on a block approximately 5 inches in height and placed between the skids. The opposite end of the container shall be raised and allowed to fall freely from heights of 12, 24 and 36 inches onto a concrete or other similarly hard surface. This test shall be applied to each end of the container.

4.4.6.2 Cornerwise drop. The container shall be supported on one corner of its base on a block approximately 5 inches high. The other corner of the same end shall be supported on a block approximately 12 inches high. The opposite end of the container shall be raised and allowed to fall freely onto a concrete or other similarly hard surface from heights of 12, 24, and 36 inches. This test shall also be applied to the diagonally opposite corner of the container.

4.4.6.3 Pendulum impact test. The container shall be freely suspended and shall be swung as a pendulum against a solid, flat and vertical barrier. The container shall be suspended by ropes, chains, or cables. The longitudinal axis of the container shall be perpendicular to the barrier and the end shall rest lightly against it. The container shall be pulled back from the barrier until the center of gravity is raised 18 inches or to the required pendulum angle, so that an impact velocity equal to 10.5 ± 1.5 ft/sec will be attained and then released and allowed to swing freely against the barrier. This test shall be applied to each end of the container.

5. PREPARATION FOR DELIVERY

5.1 Preservation and packaging. Preservation and packaging shall be level A or C as specified (see 6.1).

5.1.1 Level A. The container shall be preserved and packaged in accordance with instructions contained in MIL-STD-1169.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.

5.1.2 Level C. The container shall be preserved and packaged in accordance with instructions contained in Drawing 9321236.

5.2 Packing

5.2.1 Level A. The container shall be packed in accordance with applicable instructions contained in MIL-STD-1169.

5.2.2 Level C. The container shall be packed in accordance with applicable instructions contained in Drawing 9321236.

5.3 Marking.

Level A marking shall be in accordance with MIL-STD-1169.

Level C marking shall be in accordance with drawing 9321236.

6. NOTES

6.1 Ordering data. Procurement documents should specify the following:

a. Title, number, and date of this specification.

b. Type required (see 1.2).

c. Selection of applicable level of packaging and packing required (see 5.1 and 5.2).

6.2 Objective evidence. Records of contractor quality control and inspections which can be verified.

6.3 Acceptance inspection equipment. The contractor shall obtain approval of equipment designs, operating instructions, and calibration instructions from the Commanding Officer, US Army Armament Research and Development Command, ATTN: DRDAR-QAN-Q, Dover, New Jersey 07801.

6.4 Instructions for first article inspection (see 4.2.1). Parts may be used in subassemblies if the examination and tests (see 4.2.2, Table I) are verified by a representative designated by the Government. Subassemblies may be used in final assemblies if the examination or tests (see 4.2.2, Table I) are verified by a representative designated by the Government.

6.5 Drawings and specifications. Drawings and specifications listed in Section 2 of this specification under heading US Army Armament Research and Development Command (ARRADCOM) may also include drawings and specifcations prepared by and identified as Edgewood Arsenal, Frankford Arsenal, Rock Island Arsenal or Picatinny Arsenal drawings. Technical data originally prepared by these activities is now under the cognizance of ARRADCOM.

Custodian:
Army-AR

Preparing activity:
Army-AR

Project No. NUOR-A078

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T04:42Z
Check the source to verify that this is the current version before use.