MIL-S-22128A(OS)
Amendment 2
20 August 1971
Superseding
Amendment 1
24 April 1969

MILITARY SPECIFICATION

SQUIB, ELECTRIC, MARK 2 MODS

This amendment forms a part of Military Specification MIL-S-22128A (WEP) of 20 November 1962 and has been approved by the Naval Ordnance Systems Command, Department of the Navy

By this change, MIL-S-22128A(WEP) is changed to MIL-S-22128A(OS).

Wherever it appears in specification delete "Bureau of Naval Weapons" and substitute "Naval Ordnance Systems Command."

1. Page 1, subtitle: Delete "Cartridge, Impulse, Mark 45 Mod 0".

2. Page 2, paragraph 2.1, under "DRAWINGS": Delete "SK 378738," "SK 378739," and "SK 378942" and associated titles.

3. Page 3, paragraph 2.1, under "PUBLICATIONS." Delete "Technical Memorandum (TM) 1055" and associated title and substitute:

"OD 41571 Special Manufacturing Procedure for Acceptance Testing of Electric Squib Mk 2 Mods 0 and 1.";

also delete the first sentence of the next paragraph.

4. Page 3, paragraph 2.2, delete in its entirety and substitute:

"2.2 Other publications. The following documents form a part of this specification to the extent specified herein. Unless otherwise indicated, the issue in effect on date of invitation for bids shall apply.

Code of Federal Regulations

49 CFR 171-178 Hazardous Materials Regulations, Department of Transportation

MANUALS

Department of Defense

4145.26M DOD Contractor's Safety Manual for Ammunition Explosives and Related Dangerous Material

(Applications for copies of the above publications should be addressed to Superinten-

FSC 1340

Source: https://assist.dla.mil -- Downloaded: 202610-19T11:12Z
Check the source to verify that this is the current version before use.

dent of Documents, Government Printing Office, Washington, D.C 20402.)"

5. Page 4, paragraph 3.3.2: Delete "Dielectric characteristics." and substitute "Insulation resistance."

6. Page 4, paragraph 3.3.3: Delete "1.00 ampere, 24 volts" and substitute "1.00 plus or minus 0.10 ampere".

7. Page 4, paragraph 3.3.5: Delete "the foam polystyrene block. (see SK 378942.)" and substitute "a polystyrene foam block.".

8. Page 5, add new paragraph 3.4 as follows:

"3.4 Safety Precautions, The supplier shall observe the safety precautions of DOD 4145.26M, as applicable."

9. Page 5, paragraph 4.5.1. Delete and substitute:

"4.5.1 Electrical continuity and resistance test. Every squib shall be subjected to an electrical continuity and resistance test in accordance with OD 41571 (test current of less than 10 milliamperes dc). Each squib that does not meet the requirement of 3.3.1 shall be rejected."

10. Page 6, paragraph 4.5.2 Delete and substitute:

"4.5.2 Insulation resistance test. An insulation resistance test shall be conducted in accordance with OD 41571 for verification of conformance to the requirements of 3.3.2. The test potential shall be 500 plus or minus 50 volts dc. The test potential shall be applied for not less than one second. Sampling shall be in accordance with MIL-STD-105, Acceptable Quality Level (AQL) 1.0 percent defective."

11. Page 6, paragraph 4.5.3: Delete first sentence and substitute "The squib shall be tested in accordance with OD 41571 to determine compliance with requirements of 3.3.3".

12. Page 6, paragraph 4.5.4: Delete first sentence and substitute "The firing time test shall be conducted in accordance with OD 41571".

13. Page 6, paragraph 4.5.5. Delete and substitute:

"4.5.5 Output limits test. The squib shall meet the requirements of 3.3.5 when tested in accordance with OD 41571. Sampling shall be in accordance with MIL-STD-105, AQL 1.0 percent defective. In addition, if one or more squibs fail to fire, the lot represented shall be rejected."

14. Pages 9 through 12, delete section 6.4 and Notice.


15. Page 13, Figure 1, "Test 4.5.2": Delete "Dielectric test" and substitute "Insulation resistance test."

16. Page 14, Figure 2, under the test sequence for "Jolt," "Vibration," and "Dielectric":

Source: https://assist.dla.mil -- Downloaded: 2026-10-19T11:12Z
Check the source to verify that this is the current version before use.

Delete "Dielectric" in three places and substitute "Insulation resistance."

Preparing Activity:
NAVY - OS
(Project No. 1340-N311)



Source: https://assist.dla.mil -- Downloaded: 202640-19T11:12Z
Check the source to verify that this is the current version before use.