MIL-F-50968A(PA)
6 December 1976
SUPERSEDING
MIL-F-50968(MU)
31 January 1972

MILITARY SPECIFICATION

FUZE, IMPACT, ATOMIC WEAPON: T53E2

This specification is approved for use by Picatinny Arsenal, Department of the Army, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope.- This specification covers one type of impact fuze; designated Fuze, Impact, Atomic Weapon: T53E2; which produces voltage pulses when subjected to impact shocks. This fuze is a component of the M35 impact fuze set which is used in the Pershing warhead section.

2. APPLICABLE DOCUMENTS

2.1 Issues of documents.- The following documents, of the issue in effect on date of invitation for bids or request for proposal, form a part of this specification to the extent specified herein:

STANDARDS

FEDERAL

FED. STD. No. 356 - Commercial Packaging of Supplies and Equipment.

Beneficial comments (recommendations, additions, deletions), and any pertinent data which may be of use in improving this document, should be addressed to: Commander, Picatinny Arsenal, Dover, NJ 07801, ATTN: SARPA-QA-N-Q by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426), appearing at the end of this document, or by letter.

FSC 1135

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes.

MIL-STD-1460 - Soldering of Electrical Connections and Printed Wiring Assemblies, Procedure for.

DRAWINGS

PICATINNY ARSENAL

8805705 - Fuze, Impact, Atomic Weapon: T53E2.
8805706 - Connector Assembly.
8805713 - Spring, Conical.
8806649 - Body.
8837981 - Cover.
8859018 - Drum, Metal, Shipping, for Fuze, Impact: T53E2 or M1137.

PUBLICATIONS

PICATINNY ARSENAL

ET-8805705 - Inspection Equipment Tabulation.
QAI-PA-1 - Quality Assurance Instructions for Reporting Data on Nuclear Weapons.

Copies of specifications, standards, drawings, and publications required by contractors in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.

3. REQUIREMENTS

3.1 Materials and components.- Materials shall conform to applicable specifications and drawings. Each component shall conform to all dimensions and tests specified on the component drawing. The contractor shall have available verifiable proof (i.e., objective evidence (see 6.2)) that materials and components were fabricated, inspected, and tested under controllable conditions as set forth in the contractor's quality control or inspection procedures.

3.2 Assembly.- The impact fuze shall comply with all requirements specified on drawing (dwg.) 8805705, with all requirements specified herein, and with the requirements of applicable specifications to the extent specified on the drawings and herein.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.

3.3 First article.- When specified, the contractor shall furnish sample impact fuzes for first article inspection and approval (see 4.3 and 6.1).

* 3.4 Capacitance.- The capacitance of the impact fuze shall be as specified in Table I while at a temperature of 77° ± 2°F. In addition, the actual capacitance value in picofarads (pf) for each fuze shall be recorded (see 3.14). If the fuze fails to comply with the capacitance requirement after any environmental test (high temperature, temperature shock, low temperature, humidity, and vibration), the fuze shall be retested after being stabilized at 77° ± 2°F for a period of 24 hours. Testing shall be as specified in 4.5.1.

TABLE I

Limits (pf)	Test Identification Number (see 3.14) 1/
100 - 114	050001

1/ Not required during the following tests: high temperature, temperature shock, low temperature, humidity, and vibration.

* 3.5 Output voltage.- The peak output voltage of the impact fuze, as measured during the initial pulse, shall be as specified in Table II and shall be of positive polarity. The impact pulse applied to the fuze shall be 457 ± 23 gravities (g), peak amplitude, which will result in a maximum duration of the initial pulse of 200 microseconds as measured along the zero-voltage (reference) baseline on the measuring oscilloscope. If the fuze does not comply with the output voltage requirement of Table II, line (a), an alternate impact pulse of 575 ± 25 g shall be applied to the fuze, and the fuze shall be retested using the same test conditions that were used with the initial test. In addition, the minimum output voltage value (out of a total of three values to be measured) shall be recorded only for the acceptable g level (see 3.14). Testing shall be as specified in 4.5.2.

TABLE II

Input Pulse	Peak Voltage	Test Identification Number (see 3.14) 1/
(a) 457 g	3.0 minimum	040001
(b) 575 g	3.0 "	040002

1/ Not required during the following tests: high temperature, temperature shock, low temperature, humidity, and vibration.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.

3.6 Insulation resistance.- The insulation resistance of the impact fuze shall be not less than 1000 megohms. After environmental testing (high temperature, temperature shock, low temperature, and humidity), the insulation resistance of the fuze shall be not less than 500 megohms. There shall be no evidence of insulation breakdown or other damage during this test. Testing shall be as specified in 4.5.3.

* 3.7 Sensitivity.- The sensitivity of the fuze shall be as specified in Table III when subjected to a continuous sinusoidal vibration of 10 g ± 10 percent peak-to-peak amplitude at a frquency of 500 hertz ± 10 percent. In addition, the actual sensitivity value in couloumbs/g, for each fuze, shall be recorded (see 3.14). Testing shall be as specified in 4.5.4.

TABLE III

Sensitivity (couloumbs/g)	Test Identification Number (see 3.14) 1/
1×10^{-10} minimum	070001

1/ Not required during the following tests: high temperature, temperature shock, low temperature, humidity, and vibration.

3.8 High temperature.- The impact fuze shall withstand a high temperature of 160° ± 5°F, for a minimum period of 4 hours, without evidence of deterioration or damage that may impair its intended operation. While at the high temperature (at the end of the high-temperature exposure period), the fuze shall comply with the requirements of 3.5. After this test (at room temperature), the fuze shall comply with the requirements of 3.4, 3.5, 3.6, and 3.7. Testing shall be as specified in 4.5.5.

3.9 Temperature shock.- The impact fuze shall withstand alternate exposures to temperatures of 160° ± 5°F and -65° ± 5°F, for a minimum period of 4 hours at each exposure, without evidence of deterioration or damage that may impair its intended operation. After this test (at room temperature), the fuze shall comply with the requirements of 3.4, 3.5, 3.6, and 3.7. Testing shall be as specified in 4.5.6.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.

3.10 Low temperature.- The impact fuze shall withstand a low temperature of -33° ± 3°F, for a minimum period of 4 hours, without evidence of deterioration or damage that may impair its intended operation. While at the low temperature (at the end of the low-temperature exposure period), the fuze shall comply with the requirements of 3.5. After this test (at room temperature), the fuze shall comply with the requirements of 3.4, 3.5, 3.6, and 3.7. Testing shall be as specified in 4.5.7.

* 3.11 Humidity.- The impact fuze shall withstand a maximum relative humidity of 95 ± 5 percent and a maximum temperature of 130° ± 5°F without evidence of deterioration or damage that may impair its intended operation. After this test (at room temperature), the fuze shall comply with the requirements of 3.4, 3.5, 3.6, and 3.7. Testing shall be as specified in 4.5.8.

* 3.12 Vibration.- The impact fuze shall withstand vibrations as specified in Table IV without evidence of deterioration or damage that may impair its intended operation. During this test, the peak output voltage of the fuze shall not exceed 0.10 volt. After this test, the fuze shall comply with the requirements of 3.4, 3.5, 3.6, and 3.7. Testing shall be as specified in 4.5.9.

TABLE IV

Frequency Range (hertz)	Displacement (D.A.) or Peak g Level (± 10% Tol.)	Minimum Time Period to Cover Freq. Range (minutes)
10-30	0.20 inch	1.75
30-1000	8 g	2.0
1000-2000	10 g	3.75

3.13 Pull test on conical spring.- The conical spring shall be free from embrittlement, after plating, as evidenced by not breaking or cracking when extended to the point of minimum permanent deformation. Testing shall be as specified in 4.5.10.

3.14 Serialization.- A six-letter serial code shall be assigned to each serialized production item. The contractor shall obtain these serial codes by means of a letter addressed to: Commander, Picatinny Arsenal, Dover, New Jersey 07801, Attention: SARPA-QA-N-A. The letter of request shall include: (a) exact nomenclature of the item as specified on the applicable drawing (see dwg. 8805705), (b) contract number or pro-

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.

curement request order number, and (c) number of serial codes required (unused codes must be returned). In addition to the normal inspection records, the contractor shall provide data feedback (see 6.1.2) in conformance with Quality Assurance Instruction QAI-PA-1. The data required to be coded, and the test identification numbers, are specified in 3.4, 3.5, and 3.7.

* 3.15 Soldering.- The connector assembly (dwg. 8805706) shall be soldered in accordance with MIL-STD-1460.

3.16 Workmanship.- All parts and accessories shall be constructed, assembled, and finished in a thoroughly workmanlike manner. Particular attention shall be given to neatness, marking, cleaning, and freedom of the parts from burrs and sharp edges which may affect performance or result in injury during handling. All parts shall be free of chips, dirt, grease, rust, and other foreign material. The cleaning method shall not be injurious to any of the parts, nor shall the parts be contaminated by the cleaning agents.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection.- Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to ensure supplies and services conform to prescribed requirements.

* 4.2 Classification of inspections.- The inspection requirements specified herein are classified as follows:

1. First Article Inspection (see 4.3)
2. Quality Conformance Inspection (see 4.4)

4.3 First article inspection.

* 4.3.1 Submission.- When the contract requires first article inspection, the contractor shall submit the following to the testing facility designated in the invitation for bids or request for proposal: (a) three consecutively produced impact fuzes and (b) three impact fuze bodies (dwg. 8806649)(for defect inspection (see 4.4.2.1.1)).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.

* 4.3.2 Inspection and testing to be performed.- The first article inspection samples shall be inspected, as applicable, for the defects specified in 4.4.2.1.1 and for the defects specified in 4.4.2.1.2 (except defects 104 and 105) using inspection methods contained therein, and for all requirements of Section 3, which are listed in Table V, using the test methods specified in 4.5. Inspection and testing shall be performed with the acceptable inspection equipment specified in 4.4.4. The impact fuzes shall be tested in the order specified in Table V. If any impact fuze, or fuze body, fails to comply with any of the applicable requirements, the first article samples shall be rejected. The Government reserves the right to terminate its inspections upon any failure of the first article samples to comply with the stated requirements. This series of tests is considered destructive.

TABLE V. First article tests.

Test	Requirement paragraph
1. Capacitance	3.4
2. Output voltage	3.5
3. Insulation resistance	3.6
4. Sensitivity	3.7
5. High temperature	3.8
6. Temperature shock	3.9
7. Low temperature	3.10
8. Humidity	3.11
9. Vibration	3.12

4.4 Quality conformance inspection.

4.4.1 Inspection lot.- A lot or batch and its formation, size, and presentation is described in MIL-STD-105, Section 5. Accordingly, a lot shall mean an inspection lot, and a batch shall mean an inspection batch for the purposes of this specification. The manner in which each inspection lot or batch is to be presented and identified by the contractor shall be designated or approved by the Government representative.

4.4.2 Product inspection examination.- A sample shall be selected at random from each inspection lot in accordance with the major defect or the minor defect table as applicable (see Table VI). Any defect found in the sample, selected for the major or minor classification, shall reject the lot. Critical defects shall require 100 percent inspection of all items in the inspection lot. If any critical defect is found in an item, the item shall be removed from the lot. The sequence

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.

of inspections for the classification of defects need not be followed so long as all the defect inspections are performed.

TABLE VI. Inspection lot sampling.

Major Defect Table		Minor Defect Table	
Lot Size	Sample Size	Lot Size	Sample Size
1-30	all	1-30	all
31-45	29	31-45	27
46-60	35	46-60	30
61-75	38	61-75	33
76-95	42	76-95	35
96-130	46	96-130	37
131-180	50	131-180	39
181-250	52	181-250	41
251-400	54	251-400	42
401 and over	56	401 and over	44

4.4.2.1 Classification of defects.- Critical, major, and minor defects are defined in MIL-STD-105.

4.4.2.1.1 Body (see dwg. 8806649). 1/

Categories	Defects	Method of Inspection
Critical:	None defined.	
Major:		
	101. Pitch diameter of tapped hole for cover, max. (3 holes)	Gage
	102. Minor diameter of tapped hole for cover, max. (3 holes)	Gage
	103. Flatness of bottom surface	Gage
	104. Finish of bottom surface	Visual
Minor:		
	201. Evidence of poor workmanship (see 3.16)	Visual

1/ The three impact fuze bodies, submitted as part of the first article samples, shall be used for this inspection during first article testing.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.

* 4.4.2.1.2 Fuze, Impact, Atomic Weapon: T53E2 (see dwg. 8805705).

Categories	Defects	Method of Inspection
Critical:	None defined.	
Major:		
101.	Location of mounting hole (2 holes) (see dwg. 8806649 and 8837981)	Gage
102.	Torque on cover mounting screw, min. (3 screws)	Gage
103.	Ability of connector to engage and disengage with mating receptacle	Manual/Gage
104.	Bonding material missing or improper (between cover and body and between connector assembly and body)(inspect during assembly)	Visual
105.	Soldering of connector assembly improper (inspect during assembly) (see 3.15)	Visual
Minor:		
201.	Weight	Approved weighing device
202.	Connector insert damaged	Visual
203.	Dust cap missing or improper	Visual
204.	Marking missing, improper, or illegible	Visual
205.	Protective finish missing or improper (see dwg. 8806649 and 8837981)	Visual
206.	Evidence of poor workmanship (see 3.16)	Visual

* 4.4.2.1.3 Drum, Metal, Shipping, for Fuze, Impact, T53E2 or M1137 (prior to securing cover)(see dwg. 8859018).

Categories	Defects	Method of Inspection
Critical:	None defined.	
Major:		
101.	Impact fuze improperly wrapped and bagged	Visual/Manual
102.	Cushioning disk (2 places) and cushioning material improperly located or applied	Visual/Manual

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.

Minor:

201. Bag marking missing, improper, or illegible.....Visual

202. Evidence of poor workmanship (see 3.16).....Visual

* 4.4.2.1.4 Drum, Metal, Shipping, for Fuze, Impact, T53E2 or M1137 (see dwg. 8859018).

Categories	Defects	Method of Inspection
Critical:	None defined.	
Major:		
	101. Drum improperly sealed (including metallic seal).....	Visual/Manual
	102. Drum damaged (including punctures, dents, and gouges).....	Visual
Minor:		
	201. Scratch on drum exposing base metal.....	Visual
	202. Marking missing, improper, or illegible.....	Visual
	203. Evidence of poor workmanship (see 3.16).....	Visual

* 4.4.2.1.5 Packaging of Impact Fuzes for Interplant Shipments (see 5.1 and 6.2).

Categories	Defects	Method of Inspection
Critical:	None defined.	
Major:		
	101. Objective evidence available (see 6.2) that impact fuzes were preserved, packaged, packed, and marked in accordance with FED. STD. No. 356 (see 5.1).....	Visual
Minor:	None defined.	

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.

4.4.3 Inspection testing.- The contractor shall perform all of the tests specified in Table VII. The tests on the impact fuze (tests 1 to 6) shall be performed in the listed sequence. Of these tests, No. 7 is considered destructive and samples so tested shall not be returned to the lot.

* TABLE VII. Quality conformance tests.

Test	Test Classification
1. Capacitance	Major
2. Output voltage	Major
3. Insulation resistance	Major
4. Sensitivity	Major
5. High temperature	Major
6. Low temperature	Major
7. Pull test on conical spring	Major
8. Pull test on connector assembly	Minor

* 4.4.3.1 Capacitance (see 3.4), output voltage (see 3.5), Insulation resistance (see 3.6), and sensitivity (see 3.7).- Each impact fuze shall be subjected to these tests (see applicable paragraph in 4.5). If any fuze fails to comply with the applicable requirements, it shall be classified defective and be removed from the lot.

4.4.3.2 High temperature (see 3.8) and low temperature (see 3.10).- Two impact fuzes shall be selected at random from every lot of 100 fuzes produced, or portion thereof, and subjected to these tests (see applicable paragraph in 4.5). If any fuze fails to comply with the applicable requirements, the lot shall be rejected.

4.4.3.3 Pull test on connector assembly (see dwg. 8805706).- Each connector assembly shall be subjected to this test (see 4.5.11). If any connector assembly fails to comply with the pull test requirement of the drawing, it shall be classified defective and be removed from the lot.

4.4.3.4 Pull test on conical spring (see dwg. 8805713 and 3.13).- Ten conical springs shall be selected from each heat-treat lot of springs submitted for acceptance, and they shall be subjected to this test (see 4.5.10). If any spring fails to comply with the applicable requirements, the lot of springs, represented by the samples where the failure occurred, shall be rejected.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.

4.4.4 Acceptance inspection equipment.

4.4.4.1 Major defects and tests.- Inspection and testing shall be performed with the acceptance inspection equipment, operating instructions, and calibration instructions as specified in the Equipment List (EL) listed in the Equipment Tabulation, ET-8805705. When either of the following conditions exists, the contractor shall design required equipment or specify suitable commercial equipment: (a) if any deviation from equipment or procedures, as specified in the EL, is desired or (b) the code "CD" is listed in the "Part or Identifying Number" column in the EL (see 6.1.2). The contractor shall obtain approval of such designs, operating instructions, and special calibration instructions prior to use on the contract (see 6.3).

* 4.4.4.2 Minor defects and tests.- Acceptance inspection equipment for minor defects and tests is not specified in ELs. The acceptance inspection equipment, operating instructions, and calibration instructions used by the contractor for minor classification inspection shall be approved by the Government representative responsible for acceptance inspection.

4.5 Methods of inspection.- The tolerances specified in this specification are absolute with no allowance for test equipment inaccuracy. The tolerances used by the manufacturer shall be equal to the absolute tolerances less the accuracy tolerances of the test equipment used. Unless otherwise specified, the tests shall be conducted at room temperature (77° ± 10°F). NOTE: During environmental tests (see Table V, tests 5 to 8), the impact fuze connector shall be protected by its metal dust cap.

4.5.1 Capacitance. - The capacitance of the impact fuze shall be measured by using a Government-approved capacitance bridge at a frequency of 1000 hertz. The capacitance measurement shall be made between the center terminal and the shell of the connector, and the fuze shall comply with the requirements of 3.4 during this test.

* 4.5.2 Output voltage.- The impact fuze shall be mounted to a Government-approved test fixture with the fuze cover plate in the upper position. Each fuze mounting screw shall be torqued to a value of 25 ± 3 inch-pounds. The output voltage of the fuze shall be measured across a fixed load consisting of a 1000 ohm resistor (± 1 percent) shunted by a 0.1 microfarad capacitor (± 2 percent). A Government-approved, dual-trace oscilloscope shall be used to simultaneously measure the output voltage pulse and the impact shock. The fuze shall

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.

be impacted three times along a vertical axis which is perpendicular to the fuze cover plate. The fuze shall comply with the requirements of 3.5 during this test.

4.5.3 Insulation resistance.- The insulation resistance of the impact fuze shall be measured by using a Government-approved insulation resistance tester at an applied voltage of 1600 ± 100 volts direct current. The measurements shall be made between the center terminal and the shell of the connector assembly with the positive test voltage applied to the center terminal. The test voltage shall be applied instantaneously to the fuze, and the insulation resistance shall be measured after a 10-second application of this test voltage. The fuze shall comply with the requirements of 3.6 during this test.

* 4.5.4 Sensitivity.- The impact fuze shall be mounted to a vibration machine with the fuze cover plate in the upper position. Each fuze mounting screw shall be torqued to a value of 25 ± 3 inch-pounds. The fuze shall be subjected to the vibrations specified in 3.7. The fuze shall be vibrated along a verical axis which is perpendicular to the fuze cover plate. The output of the impact fuze shall be fed directly to a charge amplifier or to a suitable high impedance rms voltmeter (taking into account the system capacitance in converting to couloumbs/g when using the voltmeter). The duration of this test is not significant, but it shall be long enough to ensure obtaining valid measurements. The fuze shall comply with the requirements of 3.7 during this test.

4.5.5 High temperature.- The impact fuze shall be placed into a test chamber, and the temperature of the chamber shall be raised to 160°F. The fuze shall remain at this temperature for a minimum period of 4 hours. At the end of this exposure period, the fuze shall be removed from the test chamber and, within a 3-minute period, it shall be tested for the requirements of 3.5. The fuze shall then be allowed to stabilize at room temperature, and it shall then be tested for the applicable requirements of 3.4, 3.5, 3.6, and 3.7. The fuze shall comply with the requirements of 3.8 during this test.

4.5.6 Temperature shock.- The impact fuze shall be placed into a test chamber having an internal temperature of 160°F, and it shall remain at this temperature for a minimum period of 4 hours. At the end of this test exposure, and within a 3-minute period, the fuze shall be transferred to a test chamber having an internal temperature of -65°F, and it shall remain at this temperature for a minimum period of 4 hours. This high- and low-temperature exposure constitutes one cycle, and the fuze shall be subjected to three such cycles. The duration of exposure at each extreme temperature shall be not

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.

less than that specified and may be extended to overnight exposure to prevent interruption of the transfer sequence. At the completion of the third cycle (at the end of the low-temperature exposure period), the fuze shall be removed from the test chamber and be allowed to stabilize at room temperature. The fuze shall then comply with the requirements of 3.9.

4.5.7 Low temperature.- The impact fuze shall be placed into a test chamber, and the temperature of the chamber shall be lowered to -33°F. The fuze shall remain at this temperature for a minimum period of 4 hours. At the end of this exposure period, the fuze shall be removed from the test chamber and, within a 3-minute period, it shall be tested for the requirements of 3.5. The fuze shall then be allowed to stabilize at room temperature, and it shall then be tested for the applicable requirements of 3.4, 3.5, 3.6, and 3.7. The fuze shall comply with the requirements of 3.10 during this test.

* 4.5.8 Humidity.- The impact fuze shall be subjected to the following humidity test:

(a) The impact fuze shall be placed into a dry oven and conditioned at a temperature of 130°F for a minimum period of 24 hours.

(b) The impact fuze shall be transferred to a humidity chamber having a temperature of 75° ± 5°F and a relative humidity of 50 ± 10 percent. The impact fuze shall remain in this chamber for a minimum period of 24 hours.

(c) The temperature of the chamber shall be gradually raised, within a 2-hour period, to 105° ± 5°F and a relative humidity of 95 percent. The impact fuze shall remain in this chamber for a minimum period of 16 hours.

(d) The temperature of the chamber shall be gradually decreased, within a 2-hour period, to 70° ± 5°F, and the relative humidity shall be maintained at 95 percent. The impact fuze shall remain in this chamber for a minimum period of 4 hours.

(e) Repeat steps (c) and (d) for a total of 10 cycles (240 hours).

(f) At the end of the last cycle of this test, the impact fuze shall be removed from the test chamber, and it shall comply with the requirements of 3.11. NOTE: Accumulated moisture (if any), on the fuze, may be removed by gentle use of dry compressed air.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.

* 4.5.9 Vibration.- The impact fuze shall be mounted to a vibration machine with the fuze cover plate in the upper position. Each fuze mounting screw shall be torqued to a value of 25 ± 3 inch-pounds. The fuze shall be subjected to the vibrations specified in Table IV along a vertical axis which is perpendicular to the fuze cover plate. During this test, the output voltage shall be monitored using the same method (and load) as specified in 4.5.2. The fuze shall compply with the requirements of 3.12 during this test.

4.5.10 Pull test on conical spring.- The conical spring shall be attached to a Government-approved test fixture which will securely clamp approximately one half of the coil at the large end of the spring. The coil at the small end of the spring shall be pulled so that the spring is extended, relaxed, and re-extended to greater lengths until deformation occurs. The spring shall comply with the requirements of 3.13 during this test.

4.5.11 Pull test on connector assembly.- The connector assembly shall be connected to a Government-approved test fixture which will be capable of exerting a pull force (specified on dwg. 8805706) between the receptacle connector and the connecting wafer. The pull force shall be applied for a minimum period of 60 seconds. After this test, the connector assembly shall be inspected for evidence of damage or separation of the two soldered joints.

* 5. PACKAGING

5.1 Impact fuzes for interplant shipments (see 6.2).

5.1.1 Preservation, packaging, packing, and marking.- Preservation, packaging, packing, and marking shall be in accordance with FED. STD. No. 356 or as specified in the contract or purchase order.

5.2 Impact fuzes for spare parts.

5.2.1 Preservation, packaging, and marking.- Preservation, packaging, and marking shall be in accordance with dwg. 8859018.

5.2.2 Packing and marking.- Packing and marking shall be in accordance with FED. STD. No. 356 or as specified in the contract or purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.

6. NOTES

6.1 Ordering data.- Procurement documents should specify the following:

* 6.1.1 Procurement requirements.- (a) Title, number, and date of this specification, (b) whether procurement is for fuzes for spare parts or for interplant shipments (see 6.2), (c) selection of methods of packaging or packing (see 5.1.1 and 5.2.2), and (d) first article sample requirements.

6.1.2 Data requirements.- Data specified in 3.4, 3.5, and 3.7, and contractor engineering documentation specified in 4.4.4.1, will be delivered as identified on a numbered DD Form 1664 when specified on a DD Form 1423 incorporated into the contract.

* 6.2 Definitions.

6.2.1 Objective evidence.- Records of the contractor's quality control and inspections which can be verified.

6.2.2 Interplant shipments.- Shipments from the supply source to a receiving activity for subsequent incorporation into the next assembly during end item production.

6.3 Acceptance inspection equipment.- The contractor shall obtain approval of equipment designs, operating instructions, and calibration instructions from Commander, Picatinny Arsenal, Dover, New Jersey 07801, Attention: SARPA-QA-T.

6.4 Changes from previous issue.- The margins of this specification are marked with asterisks to indicate where major changes (additions, modifications, corrections, deletions) from the previous issue were made. This was done as a convenience only, and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous issue.

Custodian:
Army-PA

(Project 1135-A234)

Preparing activity:
Army-PA

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

OMB Approval
No. 22-R255

INSTRUCTIONS: The purpose of this form is to solicit beneficial comments which will help achieve procurement of suitable products at reasonable cost and minimum delay, or will otherwise enhance use of the document. DoD contractors, government activities, or manufacturers/ vendors who are prospective suppliers of the product are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity.

DOCUMENT IDENTIFIER AND TITLE

MIL-F-50968A(PA) Fuze, Impact, Atomic Weapon: T53E2

NAME OF ORGANIZATION AND ADDRESS	CONTRACT NUMBER
	MATERIAL PROCURED UNDER A ☐ DIRECT GOVERNMENT CONTRACT ☐ SUBCONTRACT

1. HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE?
   A. GIVE PARAGRAPH NUMBER AND WORDING.

   B. RECOMMENDATIONS FOR CORRECTING THE DEFICIENCIES

2. COMMENTS ON ANY DOCUMENT REQUIREMENT CONSIDERED TOO RIGID

3. IS THE DOCUMENT RESTRICTIVE?

   ☐ YES ☐ NO *(If "Yes", in what way?)*

4. REMARKS

SUBMITTED BY *(Printed or typed name and address - Optional)*	TELEPHONE NO.
	DATE

DD FORM 1 JAN 72 1426 REPLACES EDITION OF 1 JAN 66 WHICH MAY BE USED

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:45Z
Check the source to verify that this is the current version before use.