MIL-F-12638A (Ord)
20 November 1961
SUPERSEDING
MIL-F-12638 (Ord)
14 April 1953

MILITARY SPECIFICATION

FUZE, POINT DETONATING M507 LOADING, ASSEMBLING AND PACKING

1. SCOPE

1.1 This specification covers the loading, assembling and packing for one type of fuze designated as Fuze, Point Detonating, M507.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-A-2550 - Ammunition and Special Weapons; General Specification for.
MIL-P-10480 - Plunger, Delay, M1, Loading, Assembling, and Packing.
MIL-I-45208 - Inspection Requirements, General Specification For.
MIL-I-45607 - Inspection Equipment, Supply and Maintenance of.
MIL-D-46432 - Detonator, Stab, M18, Loading, Assembling and Packing.

FSC 1390

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:08Z
Check the source to verify that this is the current version before use.

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes.
MIL-STD-109 - Inspection Terms and Definitions.
MIL-STD-350 - Jolt Test for Use in Production of Fuzes.
MIL-STD-351 - Jumble Test for Use in Production of Fuzes.

DRAWINGS

ORDNANCE CORPS

73-2-345 - Fuze, PD, M507. Assembly.
7548405 - Container, Ammunition, Metal, for Fuzes, MTSQ, M506; PD M507, or MT, M61A2, Assembly, Details, Packing and Marking.
7548406 - Box, Packing, Ammunition, for Fuzes, MTSQ, M506; PD, M507, or MT, M61A2, Assembly, Details, and Packing.
7548407 - Container, Ammunition, Fiber, M296, for Fuze, PD, M507, Assembly, Details, Packing and Marking.
7548408 - Box, Packing, Ammunition, for M507, PD Fuze in Fiber Container, M296, Assembly, Details and Packing.

PUBLICATIONS

ORDNANCE CORPS

ORD-M608-11 - Procedures and Tables for Continuous Sampling by Attributes.
IEL-7151791 - Index of Inspection Equipment Lists.

(Copies of specifications, standards, drawings, and publications required by contractors in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

3. REQUIREMENTS

3.1 Material.-Materials and parts shall be in accordance with applicable drawings and specifications.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:08Z
Check the source to verify that this is the current version before use.

3.2 Fuzes.-The loaded fuzes shall comply with all requirements specified on Drawing (dwg.) 73-2-345, and with all requirements specified in applicable specifications.

3.3 Head assembly torque.-The head assembly shall show no evidence of loosening when subjected to an unscrewing force of not less than 15 nor more than 16 inch-pounds when tested as specified in 4.4.4.

3.4 Jolt and jumble.-The loaded fuze assemblies shall have no explosive elements explode, shall have its interrupter remain in the un-armed position (completely obstruct flash hole), shall not come apart, and shall have no parts broken, deformed or displaced in such a manner as to render the fuze unsafe to handle or dangerous to fire when subjected to the jolt test specified in Standard MIL-STD-350 and the jumble test specified in Standard MIL-STD-351. These tests shall be performed as specified in 4.4.1.

3.5 Functioning.-The fuzes shall comply with the following requirements when tested as specified in 4.4.2.

3.5.1 Superquick phase.

3.5.1.1 Premature burst.-No fuze shall show evidence of premature burst (see 6.2).

3.5.1.2 High order functioning.-No fuze shall fail to cause the projectile to function high order.

3.5.1.3 Reverse functioning.-Not more than one fuze shall show evidence of reverse functioning (see 6.3).

3.5.2 Delay phase.

3.5.2.1 Premature burst.-No fuze shall show evidence of premature burst.

3.5.2.2 High order functioning.-No fuze shall fail to cause the projectile to function high order.

3.5.2.3 Functioning zone.-No fuze shall cause the projectile to function outside a zone of 75 feet, minimum (min.) to 250 feet, maximum (max.) behind the screen.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:08Z
Check the source to verify that this is the current version before use.

3.5.2.4 Reverse functioning.-No fuze shall show evidence of reverse functioning.

3.6 Workmanship.

3.6.1 Finishes.-Moving parts, and surfaces contacting moving parts, shall be free of burrs, slivers, raised metal, cuts, nicks, pits, and scratches.

3.6.2 Foreign matter.-All parts shall be free of chips, scale, dirt, grease, rust, salt deposits, and other foreign material. The cleaning method shall not be injurious to any of the parts nor shall the parts be contaminated by the cleaning agents.

4. QUALITY ASSURANCE PROVISIONS

4.1 General quality assurance provisions.-The supplier is responsible for the performance of all inspection requirements specified herein. Except as otherwise specified, the supplier may utilize his own or any other inspection facilities and services acceptable to the Government. Inspection records of the examinations and tests shall be kept complete and available to the Government as specified in the contract or order. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure that supplies and services conform to prescribed requirements. Reference shall be made to Standard MIL-STD-109 in order to define terms used herein. The provisions of Specification MIL-A-2550 shall apply.

4.1.1 Contractor quality assurance system.-The contractor shall provide and maintain an effective quality assurance system in compliance with the requirements of Specification MIL-I-45208.

4.1.2 Submission of product.-At the time the completed lot of product is submitted to the Government for acceptance, the contractor shall supply the following information accompanied by a certificate which attests that the information provided is correct and applicable to the product being submitted:

a. A statement that the lot complies with all quality assurance provisions of the approved current written description of the system.

b. Number of units of product inspected.

c. Results obtained for all inspection performed.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:08Z
Check the source to verify that this is the current version before use.

d. Drawing, specification number and date, together with an identification and date of changes.

e. Certificates of analyses on all material procured directly by the contractor when such material is controlled by Government specifications referenced in any of the contractual documents.

f. Number of items in the lot.

g. Date submitted.

The certificate shall be signed by a responsible agent of the certifying organization. The initial certificate submitted shall be substantiated by evidence of the agent's authority to bind his principal. Substantiation of the agent's authority will not be required with subsequent certificates unless, during the course of the contract, this authority is vested in another agent of the certifying organization.

4.1.3 Government verification.-Using the contractor's written quality assurance procedure, this detail specification, the applicable drawings and other contractual documents as a guide, the Government inspector shall verify at unscheduled intervals all quality assurance operations performed by the contractor. Verification will be in accordance with Specification MIL-I-45208 and will be performed to the extent necessary to assure compliance with the contractual requirements. Severity of Government inspection of individual characteristics will be directly related to the seriousness of the classification assigned. In no instance will a characteristic classified "critical" be accepted solely on the basis of the contractor's records.

4.2 Initial production.-During initial production, the provisions of 4.3 shall apply and all the examinations and tests therein shall be performed, except that the following tests shall be conducted on the special sample quantities specified beginning with the first lots produced and continuing until two (2) consecutive lots have passed the acceptance criteria prescribed. Thereafter, sampling plans for these tests shall be in accordance with 4.3.3. All initial production samples for these tests shall be selected by the Government inspector.

4.2.1 Jolt and jumble (see 3.4).-Thirty-six (36) loaded fuze assemblies shall be selected from each lot for these tests. If one or more fuze assemblies fail to comply with the requirements specified, the lot shall be rejected. The tests shall be performed as specified in 4.4.1 using equipment in accordance with 4.3.4.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:08Z
Check the source to verify that this is the current version before use.

4.2.2 Functioning (see 3.5).-Sixty (60) loaded fuzes shall be selected from each lot for these tests. The number of fuzes tested at each setting shall be two times the sample sizes specified in Table I. The tests shall be performed as specified in 4.4.2 using equipment in accordance with 4.3.4. Acceptance and rejection shall be in accordance with 4.3.3.2, 4.3.3.2.1 and 4.3.3.2.2.

4.3 Inspection provisions for production.

4.3.1 Lot formation.-A lot shall consist of fuzes loaded and assembled by one manufacturer in one unchanged process, in accordance with the same drawing, same drawing revision, same specification, and same specification revision. Drawing, specification, and process changes not affecting safety, performance, or fit, as determined by the Government, shall not necessitate changing the lot number. Each lot shall contain:

a. Parts and parts assemblies of one interfix lot number from one manufacturer.

b. Delay plunger assemblies of one interfix lot number from one manufacturer.

c. Detonator assemblies of one interfix lot number from one manufacturer.

d. Booster assemblies of one interfix lot number from one manufacturer.

4.3.2 Examination.-Sampling plans and procedures for the following classifications of defects shall be in accordance with Standard MIL-STD-105 except that inspection for critical defects, when listed, shall be 100 percent. Continuous sampling plans in accordance with Handbook ORD-M608-11 may be used if approved by the procuring activity. Also, at the option of the procuring activity, AQL's and sampling plans may be applied to the individual characteristics listed using an AQL of 0.25 percent for each major defect and an AQL of 0.40 percent for each minor defect. Equipment necessary for the performance of the inspection listed shall be in accordance with 4.3.4.

4.3.2.1 Head assembly (see dwg. 73-2-354 covering a detail of dwg. 73-2-345.)

Categories	Defects	Method of inspection
Critical: None defined.		

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:08Z
Check the source to verify that this is the current version before use.

Major:	AQL 0.25 percent	
101.	Detonator missing or inverted (when viewed through detonator retaining screw)	Visual
102.	Detonator cushion missing or not compressed (indicating loose detonator) (when viewed through detonator retaining screw)	Visual
Minor:	AQL 1.5 percent	
201.	Detonator retaining screw stake missing or inadequate	Visual
202.	Detonator retaining screw not fully seated	Visual
203.	Foreign matter on detonator or in any cavity (see 3.6.2)	Visual

4.3.2.2 Assembly, prior to assembling flash tube and booster assembly (see dwg. 73-2-345).

Categories	Defects	Method of inspection
Critical:		
1.	Delay plunger assembly missing or incorrectly positioned (firing pin points toward front of fuze)	Visual
2.	Delay plunger assembly in armed position	Visual
Major:	AQL 0.25 percent	
101.	Foreign matter in flash hole, in booster assembly cavity, or on delay plunger assembly (see 3.6.2)	Visual

Minor: None defined.

4.3.2.3 Assembly, prior to assembly of head assembly (see dwg. 73-2-345).

Categories	Defects	Method of inspection
Critical:		
1.	Interrupter does not completely obstruct flash hole	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:08Z
Check the source to verify that this is the current version before use.

Major:	AQL 0.40 percent	
101.	Nut on flash tube turns when minimum force (inch-pounds) is applied in tightening direction	Manual (see 4.4.3)
102.	Nut missing from flash tube	Visual
103.	Foreign matter in flash tube cavity (see 3.6.2)	Visual
Minor:	**AQL 0.40 percent**	
201.	Nut stake missing	Visual

4.3.2.4 Assembly (see dwg. 73-2-345).

Categories	Defects	Method of inspection
Critical:	None defined.	
Major:	AQL 1.0 percent	
101.	Total length, maximum (max.)	Gage
102.	Length to shoulder above thread, max.	Gage
103.	Ogive partially covers setting sleeve rendering it inaccessible	Visual
104.	Setting sleeve incorrectly positioned	Visual
105.	Body thread damaged	Visual
106.	Booster cup cracked or split	Visual
107.	Firing pin closing disc missing or damaged (punctured, cracked or dented)	Visual
108.	Delay time not specified on body	Visual
Minor:	**AQL 4.0 percent**	
201.	Head assembly turns when min. torque is applied in loosening direction (see 3.3)	Test (see 4.4.4)
202.	Booster assembly turns when min. torque is applied in tightening direction	Test (see 4.4.5)
203.	Wrench slots damaged to extent they will not receive a wrench	Visual-Manual
204.	Crack or puncture at ogive head stake or dimples	Visual
205.	Ogive cracked, dented or deformed	Visual
206.	Protective paint missing from stakes	Visual
207.	Ogive head stake or booster assembly stake missing or inadequate	Visual
208.	Marking misleading or unidentifiable	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:08Z
Check the source to verify that this is the current version before use.

209. Protective coating damaged (ignoring slight scratches)..... Visual
210. Foreign matter (see 3.6.2)..... Visual

4.3.2.5 Carton (sealed) (see dwg. 7548407).

Categories	Defects	Method of inspection
Critical:	None defined.	
Major:	AQL 0.25 percent	
101.	Assembly damaged so that contents are exposed or liable to become exposed.....	Visual
102.	Sealing strip incomplete, badly wrinkled, or not in contact with surface for at least 1/2 inch around entire carton.....	Visual
Minor:	AQL 1.0 percent	
201.	Contents move when carton is shaken....	Manual
202.	Marking misleading or unidentifiable...	Visual

4.3.2.6 Container, metal, sealed (see dwg. 7548405), when applicable (see 5.1.1).

Categories	Defects	Method of inspection
Critical:	None defined.	
Major:	AQL 0.25 percent	
101.	Puncture or deep scratch.....	Visual
102.	Container dented or deformed.....	Visual
Minor:	AQL 1.5 percent	
201.	Contents move when container is tilted (insufficient dunnage).....	Manual
202.	Bare spot on exterior other than slight scratches.....	Visual
203.	Key missing.....	Visual
204.	Marking misleading oruunidentifiable...	Visual

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:08Z
Check the source to verify that this is the current version before use.

4.3.2.7 Box, packing (prior to insertion into box) (see dwg. 7548406 or 7548408, as applicable).

Categories	Defects	Method of inspection
Critical:	None defined.	
Major:	AQL 0.25 percent	
101.	Waterproofness destroyed by separation of heat seal, rip, tear, or puncture	Visual
Minor:	AQL 1.0 percent	
201.	Label missing or peeling (where applicable)	Visual
202.	Marking misleading or unidentifiable	Visual

4.3.2.8 Box, packing (sealed) (see dwg. 7548406 or 7548408, as applicable).

Categories	Defects	Method of inspection
Critical:	None defined.	
Major:	AQL 0.65 percent	
101.	Hardware missing, broken or loose	Visual-Manual
102.	Strapping missing, broken or loose	Visual-Manual
103.	Contents exposed	Visual
104.	Board broken or split	Visual
105.	DOD symbol misleading or unidentifiable	Visual
Minor:	AQL 2.5 percent	
201.	Hardware improperly engaged	Visual-Manual
202.	Handle missing or insecure	Visual-Manual
203.	Contents loose (when box is tilted)	Manual
204.	Strapping improperly assembled	Visual
205.	Marking misleading or unidentifiable	Visual
206.	Car seal missing, unsealed or improperly positioned	Visual

4.3.3 Testing (normal production).-After acceptance of the initial production lots (see 4.2), testing shall be as follows.

4.3.3.1 Jolt and jumble (see 3.4) Critical defect.-Twelve (12) loaded fuzes shall be selected from each lot for these tests. The two tests shall be performed on the same sample. If one or more fuze assemblies fail to comply with the specified requirements, the lot shall be rejected. The tests shall be performed as specified in 4.4.1 using equipment in accordance with 4.3.4.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:08Z
Check the source to verify that this is the current version before use.

4.3.3.2 Functioning (see 3.5) Critical defect if any premature burst occurs; major defect for all others.-Thirty (30) loaded fuze assemblies shall be selected from each lot for these tests. The tests shall be performed as specified in 4.4.2 using equipment in accordance with 4.3.4. The number of samples to be tested in each phase of the test shall be in accordance with Table I. The lot shall be rejected if it fails to comply with any functional requirements specified in 3.5.

4.3.3.2.1 Superquick phase.-If not more than one fuze fails to cause the projectile to function high order, or not more than two fuzes show evidence of reverse functioning, a second sample of forty (40) fuzes, or twice the quantity specified in Table I, shall be tested in this phase. In no instance shall a second sample be tested if a premature burst occurred in the original sample. If, in the combined first and second samples, a premature burst occurs, or two or more fuzes fail to cause the projectile to function high order, or three or more fuzes show evidence of reverse functioning, the lot shall be rejected.

4.3.3.2.2 Delay phase.-If not more than one fuze fails to cause the projectile high order, or not more than one fuze causes the projectile to function outside the zone specified in 3.5.2.3, or not more than one fuze shows evidence of reverse functioning, a second sample of twenty (20) fuzes, or twice the quantity specified in Table I, shall be tested in this phase. In no instance shall a second sample be tested if a premature burst occurred in the original sample. If, in the combined first and second samples, a premature burst occurs, or two or more fuzes fail to cause the projectile to function high order, or two or more fuzes cause the projectile to function outside the zone specified in 3.5.2.3, or if two or more fuzes show evidence of reverse functioning, the lot shall be rejected.
NOTE.-Second samples subjected to functioning tests may be limited to the particular phase in which the lot failed to comply with the specified requirements.

4.3.3.3 Check test for deterioration of detonators (see Military Specification MIL-D-46432) Major defect.-If the total time between original acceptance of any detonator lot and the assembly of that lot into the fuzes exceeds two years, or if the detonators have been subjected to adverse conditions, however brief, at any time since previous tests, the detonator lot shall be subjected to and must satisfactorily pass, the check test for deterioration specified in Military Specification MIL-D-46432 immediately before the detonator lot is assembled into the fuzes. This test shall be performed by the contractor on detonators selected by the Government inspector at the facility assembling

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:08Z
Check the source to verify that this is the current version before use.

the detonators into the fuzes (see 6.4).

4.3.3.4 Check test for deterioration of delay plunger assemblies (see Military Specification MIL-P-10480) Major defect.- If the total time between original acceptance of any delay plunger lot and the assembly of that lot into the fuzes exceeds two years, or if the delay plungers have been subjected to adverse conditions, however brief, at any time since previous tests, the delay plunger lot shall be subjected to and must satisfactorily pass, the check test for deterioration specified in Military Specification MIL-P-10480 immediately before the delay plunger lot is assembled into the fuzes. This test shall be performed by the contractor on delay plungers selected by the Government inspector at the facility assembling the delay plungers into the fuzes (see 6.4).

4.3.4 Inspection equipment.-For the performance of the inspections listed herein, the contractor shall have available and utilize correctly all necessary gages, measuring, and testing equipment identified by Index of Inspection Equipment Lists No. 7151791, or approved equivalents thereto. Designs of equipment developed by the contractor for use in lieu of that specified in the Index of Inspection Equipment Lists shall be documented and submitted to the Government for approval as equivalent (see 6.5). Approval shall be obtained prior to initiation of production. Supply and maintenance of inspection equipment shall be in accordance with Specification MIL-I-45607.

4.4 Test methods and procedures.

4.4.1 Jolt and jumble.-The loaded fuze assemblies shall be subjected to the jolt test in accordance with Standard MIL-STD-350. After completion of the jolt test, the fuzes subjected to the jolt test shall not be disassembled but shall be subjected to the jumble test in accordance with Standard MIL-STD-351. Disassembly and examination of the fuzes shall be accomplished after both jolt and jumble tests have been completed. Examination shall be made to determine compliance with 3.4.

4.4.2 Functioning.-The fuzes shall be assembled into the specified projectile and tested in accordance with Table I, 4.4.2.1 and 4.4.2.2.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:08Z
Check the source to verify that this is the current version before use.

Table I

Phase	Sample Size	Weapon	Muzzle Vel. (1) (ft./sec.)
S.Q	10	Gun, 120MM. A.A., M1	3100
S.Q	10	Gun, 120MM. A.A., M1	3100
Delay	10	Gun, 120MM. A.A., M1	3100

Pressure, max. (psi) 5	Target	Range
38,000	1 inch plywood	400 ft.
38,000	(3) ground imp.	(2) 5000 yds.
38,000	ground imp.	(4) conv.

1 feet per second
2 yards
3 ground impact
4 convenient
5 pounds per square inch

4.4.2.1 Superquick phase.-Twenty (20) fuzes shall be set in the superquick position. Referring to Table I, the fuzes shall be fired as follows:

a. Ten (10) fuzes shall be assembled to Shell, HE, M73 and fired from Gun, 120MM, A.A., M1, with a service charge designed to give a muzzle velocity of 3100 feet per second and a chamber pressure not exceeding 38,000 p.s.i. The fuzes shall be fired for impact against a 1-inch plywood screen placed not less than 400 feet from the muzzle of the gun.

b. Ten (10) remaining fuzes shall be fired as described above, except that impact shall be against firm ground at a range of not less than 5000 yards.

4.4.2.2 Delay phase.-The remaining ten (10) fuzes shall be set in the "Delay" position, assembled, and fired as detailed above, except that, as indicated in Table I, the fuze shall be fired for impact on firm ground at any convenient range to insure impact on the nose of the fuze.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:08Z
Check the source to verify that this is the current version before use.

4.4.3 Flash tube nut torque.-The nut on the flash tube shall be subjected to the minimum force (in inch-pounds), as specified on the applicable drawing, in a tightening direction. Examination shall be made for any evidence of loosening. This test shall be performed prior to staking nut to body.

4.4.4 Head assembly torque.-The head assembly shall be subjected to an unscrewing force of not less than 15 nor more than 16 inch-pounds to determine compliance with 3.3.

4.4.5 Booster assembly torque.-The booster assembly torque test shall be performed using equipment in accordance with 4.3.4 to determine compliance with the requirements specified on the applicable drawing. The test shall be performed prior to staking.

5. PREPARATION FOR DELIVERY

5.1 Preservation and packaging.

5.1.1 Level A.-Packaging for Fuze, M507, shall be in accordance with dwg. 7548405.

5.1.2 Level C.-Packaging for Fuze, M507, shall be in accordance with dwg. 7548407.

5.2 Packing.

5.2.1 Level A.-Packing for Fuze, M507, shall be in accordance with dwg. 7548406.

5.2.2 Level C.-Packing for Fuze, M507, shall be in accordance with dwg. 7548408.

5.3 Marking.-Marking shall be as specified on the applicable packing drawing.

5.4 Data cards.-Data card information shall be as specified in Specification MIL-A-2550.

6. NOTES

6.1 Ordering data.-Procurement documents should specify the title, number, and date of this specification.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:08Z
Check the source to verify that this is the current version before use.

6.2 Premature bursts.-Premature burst is defined as the functioning of the fuze in the weapon bore or in flight before impact.

6.3 Reverse functioning.-Reverse functioning is defined as superquick (SQ) functioning of the fuze when set in the "Delay" position, or delay functioning when set in the "SQ" position.

6.4 Check tests.-The contracting officer will arrange for the contractor to be reimbursed for the expense incurred in the performance of the detonator and delay plunger assembly check tests. The tests shall be conducted at Government expense without cost to the contractors who loaded the detonators and delay plungers or the contractor assembling the detonators and delay plungers into the fuzes, and shall not constitute a basis for rejection against these contractors except where deterioration has occurred as a direct result of carelessness in handling, storage, etc. permitted while the detonator or delay plunger lot was under their jurisdiction.

6.5 Submission of contractor equipment designs.-Documentation of contractor-developed equipment designs shall be submitted in duplicate to Picatinny Arsenal, Dover, New Jersey, ATTN; ORDBB-ND, for approval. This documentation shall identify all standard devices and set-ups etc., as well as special equipment designs.

Notice.-When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use, or sell any patented invention that may in any way be related thereto.

Custodian;
Army-Ordnance Corps

Preparing activity:
Army-Ordnance Corps

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:08Z
Check the source to verify that this is the current version before use.