NOTICE OF VALIDATION

NOT MEASUREMENT SENSITIVE

MIL-DTL-85383A
NOTICE 1
16-Jul-2019

DETAIL SPECIFICATION

Manuals, Technical: Aircraft Structure Repair; Preparation of (Work Package Concept)

MIL-DTL-85383A, dated 26-Nov-1997, has been reviewed and determined to be valid for use in acquisition.

Custodians:
Navy - AS

Preparing Activity:
Navy - AS

NOTE: The activities above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.dla.mil.

AMSC N/A

AREA TMSS

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T10:44Z
Check the source to verify that this is the current version before use.