INCH-POUND

MIL-P-48749D (AR)
AMENDMENT 3
9 December 1992
SUPERSEDING
AMENDMENT 2
28 August 1989

MILITARY SPECIFICATION

PROJECTILE, 155MM, HE: M483A1
LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-P-48749D (AR), dated 27 October 1986, and is approved for use by the U.S. Army Armament, Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 2

2.1.2, Under Product and Packing Drawing, Add the following:

"9395829 - Packing and Marking for Box, Wood for Expulsion Charge Assembly, for M483A1, 155MM Projectile".

PAGE 8

4.4.1g-h, Delete: "from one lot interfix number".

* 4.4.1,h, Add: "All spacers (large and small) used in each production lot shall be only of one type (cored spacers or un-cored spacers)."

PAGE 10

4.4.2.2, Major category, Delete: Major Defect 110.

Major category, Add:

"112	Hole diameter under minimum	0.40%	3.2	Gage".

Minor category, Add:

"202	Hole diameter over maximum	0.65%	3.2	Gage
203	Hole true position	0.65%	3.2	Gage".

DISTIRBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:38Z
Check the source to verify that this is the current version before use.

PAGE 17

4.4.2.9, Critical Defect 2, Delete: "improperly positioned" and substitute: "broken".

Critical category, Add:

"3 Slider lock improperly positioned such that slider would not be restrained 100% 3.2 Visual".

PAGE 18

4.4.2.10, Critical Defect 3, Delete: "cracked, incomplete," and "improperly positioned" and substitute: "broken".

Critical category, Add:

"6 Slider lock improperly positioned such that slider would not be restrained 100% 3.2 Visual".

PAGE 19

4.4.2.11, Major Defect 104, Change: "Sealant" to "Sealing Compound".

PAGE 20

4.4.2.12, Special Defect a., Change: "Gage" to "Gage/4.5.13".

Minor category, Add:

"202 Sealant not present between projectile body and base 0.65% 3.2 Visual".

PAGE 29

4.4.2, Add the included new tables: 4.4.2.21 and 4.4.2.22.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:38Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-P-48749D (AR)
AMENDMENT 3

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.21	Packing and Marking for Box, Fiberboard for Expulsion Chrg Assy for M483A1, 155MM Proj	1	1	9395825
				NEXT HIGHER ASSEMBLY 9395829

CATEGORY	EXAMINATION OR TEST	NO OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Tube missing		0.40%	3.2	Visual
102	Box damaged, exposing content		0.40%	3.2	Visual
103	Partitions missing		0.40%	3.2	Visual
104	Corners not blunted		0.40%	3.2	Visual
105	Barrier bag torn, punctured or heat seal incomplete		0.40%	3.2	Visual
Minor					
201	Contents loose		0.65%	3.2	Manual
202	Barrier bag marking missing, incomplete, or illegible		0.65%	3.2	Visual
203	Wrong type tape		0.65%	3.2	Visual
204	Box marking missing, incomplete, or illegible		0.65%	3.2	Visual

NOTES:

AMSMC Form 1570, 1 Feb 85 — Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: (29a) assist.dla.mil -- Downloaded: 2026-10-22T19:38Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.22	Packing and Marking for Box, Fiberboard for Expulsion Chrg Assy for M483A1, 155MM Proj	1	1	9395829
				NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Box damaged exposing content		0.40%	3.2	Visual
102	Strapping missing (wood box only)		0.40%	3.2	Visual
Minor					
201	Content loose		0.65%	3.2	Manual
202	Marking missing, incomplete, or illegible		0.65%	3.2	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:38Z
Check the source to verify that this is the current version before use.

PAGE 35

4.5.1, line 1, Change: "eight (8) hours of production" to "production interval".

* 4.5.2, Note 1, Delete in its entirety and Substitute:

"Note 1. For the purpose of this test a reject shall be defined as an assembly that leaks to the extent that the M10 propellant becomes wet. To determine the condition of the propellant, each assembly shall be visually examined after leak testing. Those assemblies which exhibit any darkening of the propellant (an indication of wet propellant) shall be cut open so that the darkened propellant can be visually and manually checked for moisture. Only those assemblies containing moisture shall be considered defective."

PAGE 39

Add new paragraph 4.5.13:

"4.5.13 Inspection of gap between projectile body and base. Gap shall be inspected using an approved feeler gage as specified on drawing 9215220. The feeler gage shall be cleaned with a clear dry rag immediately after each inspection such that the gage is free of any base/body gap sealant. No solvent or other substance other than a clean dry rag shall be used to clean the gage. The gap between the projectile body and base shall be inspected within fifteen (15) minutes after the sealant is applied to the shoulder of the base."

5., Delete subparagraphs 5.1, 5.1.1 and 5.2 and substitute new paragraphs 5.1 and 5.2 as follows:

"5.1 Packing and marking projectiles.

5.1.1 Packing-level A. The projectiles shall be palletized in accordance with Dwg. 8837839.

5.1.2 Markings. Markings shall be in accordance with Dwg. 8837839.

5.2 Packing and marking expulsion charge assemblies. Shipping destination shall determine the following requriements for packing and marking.

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:38Z
Check the source to verify that this is the current version before use.

5.2.1 Oversea shipment - qualified level A. Packing of expulsion charge assemblies and markings shall be in accordance with Dwg. 8395829 and applicable notes in drawing.

5.2.2 Domestic shipment - level B. Packing of expulsion charge assemblies and markings shall be in accordance with Dwg. 9395829 and applicable notes in drawing."

The margins of this amendment are marked with an asterisk or vertical line to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notation and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1320-AC47)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:38Z
Check the source to verify that this is the current version before use.