ADMINISTRATIVE NOTICE

INCH-POUND
MIL-HDBK-1599A
NOTICE 2
5 SEP 2006

DEPARTMENT OF DEFENSE
HANDBOOK
BEARINGS, CONTROL SYSTEM COMPONENTS, AND ASSOCIATED HARDWARE USED IN THE DESIGN AND CONSTRUCTION OF AEROSPACE MECHANICAL SYSTEMS AND SUBSYSTEMS

TO ALL HOLDERS OF MIL-HDBK-1599A:

1. THE FOLLOWING PAGE OF MIL-HDBK-1599A, SECTION 601-6 IS INCORRECT AND NEEDS TO BE DELETED:

3.5.1.1 Material and configuration. The material, configuration, and quality shall conform to MIL-T-8878 and MS21251. ~~Steel turnbuckles are not approved for aircraft use.~~
3.5.1.2 Usage. The MS21251 ~~aluminum and brass~~ turnbuckles are approved for primary controls, secondary controls, and auxiliary cable assemblies. The appropriate size turnbuckle shall be used for the applicable size cable as noted on MS21251.
3.5.1.3 Strength. The MS21251 ~~aluminum and brass~~ turnbuckles shall withstand the minimum breaking strength of the appropriate size cable. Size selection shall be on this basis.

2. Presently this document contains a requirement that prohibits the use of steel turnbuckles on aircraft. Recently a galling/chip problem with brass turnbuckles used on aircraft was reported. This problem was resolved by using steel turnbuckle bodies as specified in MIL-DTL-8878, a specification developed exclusively for aircraft control applications. Furthermore, MS21251, which serves as the basic MIL-HDBK-1599 aircraft turnbuckle standard, includes the use of steel materials. Research into this issue indicates that the reason for establishing this part of Requirement 601, paragraph 3.5.1.1 was a corrosion problem with the steel bodies. However, the current specification governing these parts requires the use of cadmium plating on these parts eliminating the corrosion problems that may have existed back when this requirement was generated. An administrative change was the best thing to use to correct this Mil Handbook and a revision is being planned.

3. RETAIN THIS NOTICE AND INSERT BEFORE TABLE OF CONTENTS.

4. Holders of MIL-HDBK-1599A will verify that the above text is deleted from this page indicated above. This notice page will be retained as a check sheet. This issuance, together with appended pages, is a separate publication. Each notice is to be retained by stocking points until the standard is completely revised or canceled.

AMSC N/A FSC 31GP

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:59Z
Check the source to verify that this is the current version before use.

Custodians:
Air Force - 99
Army - AT
Navy - AS

Reviewers:
DLA - GS
Army - AV
Navy - SH

Preparing Activity:
Air Force - 84

Agent Activity:
Air Force - 99

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at http://assist.daps.dla.mil

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:59Z
Check the source to verify that this is the current version before use.