NOTICE OF REACTIVATION

NOT-MEASUREMENT SENSITIVE

MIL-DTL-11589/52E
NOTICE 2
29 June 2001

MILITARY SPECIFICATION

RIBBON, DISTINGUISHED SERVICE MEDAL, ARMY

MIL-DTL-11589/52E, dated 21 January 1999, is hereby reactivated and may be used for either new or existing design acquisition.

Custodians:
Army - IH

Preparing activity:
Army - IH

Review Activities:
DLA - CT

AMSC N/A **FSC 8455**

DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T18:40Z
Check the source to verify that this is the current version before use.