ADMINISTRATIVE NOTICE

INCH-POUND

MIL-D-14951A (AR)
NOTICE 2
03 October 2007

DETAIL SPECIFICATION

DELAY ELEMENT M53
LOADING, ASSEMBLING AND PACKING

This Document was Inactivated for New Design on 10 Jul 96

The Federal Supply Class (FSC) for this document has changed from 1376 to 1390, which is the correct FSC for fuzes and primers.

Custodian:
Army – AR

Preparing Activity:
Army – AR

Comments, suggestions, or questions on this document should be addressed to the Commander, U.S. Army ARDEC, ATTN: AMSRD-AAR-QES-E, Picatinny, NJ 07806-5000 or emailed to ardecstdzn@conus.army.mil. Since contact information can change, you may want to verify the currency of this address information using the ASSIST Online database at http://assist.daps.dla.mil.

AMSC N/A

FSC 1390

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T05:11Z
Check the source to verify that this is the current version before use.