MILITARY SPECIFICATION

BOOSTER, M125A1E3, LOADING AND PACKING

This amendment forms a part of Military Specification MIL-B-60807(MU) dated 16 August 1971.

* Change "M125A1E3" to "M125A1" wherever it appears in the specification.

Paragraph 4.1 delete in its entirety and substitute:

"4.1 Responsibility for inspection - Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements."

Paragraph 4.3.2.4 delete MAJOR characteristic 107. in its entirety

add MAJOR characteristic 111.

"111. Booster cup loosens when on unscrewing torque of 35 inch pounds is applied Gage"

Add paragraph 4.3.2.8

"4.3.2.8 Booster, Pellet Drawing B8595510, covering a detail of Drawing F10520747.

Defect	Method of Inspection
CRITICAL	
None defined	
MAJOR AQL = .40%	
101. Diameter, improper	Gage
102. Width, improper	Gage
103. Weight, improper	Gage"

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:57Z
Check the source to verify that this is the current version before use.

Paragraphs 4.3.3.2 and 4.4.2 delete in their entirety

* The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous issue were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous issue.

Custodian

Army - MU

Preparing activity

Army - MU(FA)

Project No. 1390-A219

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:57Z
Check the source to verify that this is the current version before use.