MILITARY SPECIFICATION

BOOSTER, M125A1E3, LOADING AND PACKING

This amendment forms a part of Military Specification MIL-B-60807(MU) dated 16 August 1967.

Paragraph 4.1 Delete in its entirety and substitute.

"4.1 Responsibility for inspection.-Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements specified herein. Except as otherwise specified in the contract or order, the supplier may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

Paragraph 4.3.2.4 Add MAJOR characteristic 111.

"111. Booster cup loosens when on unscrewing torque of 35 inch pounds is applied - - - - - - - - - - - - - - - Gage"

Custodian

Army - MU

Preparing activity

Army - MU

Project No. 1390-A729

FSC 1390

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:57Z
Check the source to verify that this is the current version before use.