MIL-S-63326(AR)
AMENDMENT 2
15 August 1983

SUPERSEDING
AMENDMENT 1
5 April 1982

MILITARY SPECIFICATION

SAFETY AND ARMING ASSEMBLIES FOR MINES: BLU 91/B AND BLU 92/B

This Amendment forms part of Military Specification MIL-P-63326(AR), dated 11 August 1981, and is approved for use by US Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

2.1, Specification, Federal: Delete "QQ-S-465" and substitute "QQ-S-365".

PAGE 4

* 3.6.2: Delete "partucular" and substitute "particular".

3.8: Delete "... than 0.015 ohm." and substitute "... than 0.15 ohm.".

PAGE 8

* TABLE I: S&A Assembly and Components: Delete "Microminature" and substitute "Microminiature".

PAGE 11

TABLE I, S&A Assembly, Examination for Defects: Delete "4.4.2.45(a)" and substitute "4.4.2.47(a)".

Note (a): Delete "4.4.2.41, 4.4.2.43, been performed" and substitute "4.4.2.41, 4.4.2.43 and 4.4.2.45 have been performed".

* Note (b): Delete "70° ± 10°F" and substitute "Ambient".

FSC 1345

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 12

Note (a): Delete "4.4.2.42 and 4.4.2.41 been performed" and substitute "4.4.2.41, 4.4.2.42 and 4.4.2.44 have been performed".

* Note (b): Delete "70° ± 10°F" and substitute "Ambient".

PAGE 16

4.4.2.2, Borerider:

Add the following Major Category:
"122, Chamfer on tines missing 0.40% 3.2 Visual".

PAGE 22

* 4.4.2.8, Slider Assembly:

Major 106: After staked add "(-1 assy only)".

PAGE 35

* 4.4.2.19, Actuator, Microminiature Piston:

Piston actuator function test: Delete "-60°" and substitute "-65°F".

PAGE 39

4.4.2.23, MDF, PBXN-5 Lead Sheathead:

Major 102: Delete "4.5.10" and substitute "4.5.6".

PAGE 40

* 4.4.2.24, Lower Housing Assembly:

Next Higher Assembly: Delete "9328693" and substitute "9328692".

PAGE 55

4.4.2.32, Pin, Shear Borerider:

Add the following Major Category:
"104, Head thickness, 0.40% 3.2 Gage".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

PAGE 58

* 4.4.2.35, Cup, Centrifugal Lock:

Drawing Number: Delete "9328819" and substitute "9329819".

PAGE 64

* 4.4.2.41, Safe & Arm Assembly (Prior to Assembling Borerider Shear Pin and Lock Plate):

Critical category:

Critical 1: Delete "1/" in its entirety.
Critical 2: Add "1/" after "binding".

Major category:

Major 102: Delete "... missing 0.40% 3.2 Visual/ Manual" and substitute "... missing 1/ 100% 3.2 Visual/Manual".

Notes:

Add the following note:

"1/ Major 102 shall be performed prior to critical 2".

PAGE 66

4.4.2.43, Safe & Arm Assembly (Prior to Assembling Shield and Lock Plate).

Critical category: Delete "none defined" and add new Critical defect as follows:

"1 - Ball lock missing 100% 3.2 Gage".

PAGE 69

* 4.4.2.46, Safe and Arm Assembly:

LAT of S&A ASSEMBLIES, NO. OF SAMPLE UNITS Column: Delete "*".

Transportation vibration, INSPECTION METHOD Column: Delete "4.5.15.3" and substitute "4.5.11.3".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

Continuity - Resistance checks, REQUIREMENT Column: Delete "3.8" and substitute "3.2".

Arming, INSPECTION METHOD column: Delete "4.5.17" and substitute "4.5.13".

Main charge functioning: Add "2/" after "functioning".

SAMPLE SIZE Column: Add "1/" after "SIZE".

+70° + 5°F Column: Delete "+70° + 5°F" and substitute "AMBIENT".

PAGE 70

* 4.4.2.47, Safe & Arm Assembly:

LAT of S&A ASSEMBLIES, NO. OF SAMPLE UNITS Column: Delete "*".

Transportation vibration, INSPECTION METHOD Column: Delete "4.5.15.3" and substitute "4.5.11.3".

Continuity - Resistance checks, REQUIREMENT Column: Delete "3.8" and substitute "3.2".

Main charge functioning: Add "2/" after "functioning".

SAMPLE SIZE Column: Add "1/" after "SIZE".

+70° + 5°F Column: Delete "+70° + 5°F" and substitute "AMBIENT".

PAGE 73

* 4.5.9: Delete "Assemblies subjected to this test shall not be returned to the lot."

PAGE 75

* 4.5.18: Delete "4.5.18" and substitute "4.5.17".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing Activity:
Army-AR

(Project 1345-A291)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:39Z
Check the source to verify that this is the current version before use.