INCH-POUND

MIL-B-43154M
INT. AMENDMENT 1
11 July 1995

MILITARY SPECIFICATION

BOOTS, HOT WEATHER

This interim amendment forms a part of MIL-B-43154M, dated 26 June 1992, and is approved for use by all departments and agencies of the Department of Defense.

Page 3

2.1.1, under "SPECIFICATIONS, MILITARY", Delete: "MIL-I-1821 - Insoles, Footwear (Ventilating Type)".

Page 5

3.3.1.1 Type I., line 2, after "smooth plated", Add: "or hair cell print".

At the end of paragraph, Add the following:

"As an alternate, the inside leather lace row facing piece and the inside leather counterpocket piece may be cut from a/b leather used for the combat boot of MIL-B-44152."

Page 6

3.3.1.4, under "Counters.", line 3, after "follows:" Add the following:

"except that if back part molded is to be employed the counter need neither be formed nor flanged."

AMSC N/A FSC 8430

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

Page 7

3.3.2.1.1, line 5, after "type I", Add the following:

"quarters and gussets"

3.3.2.1.1, line 7, Delete: "for the type II"
line 9, Delete: "as an alternate"
line 10, after "used", Add: "for the type II, collar cover".

Page 8

3.3.2.6, line 2, Delete: "quarter top facing and".
line 3, Delete: "2 inch or" and substitute: "3 inch".
line 4, Delete: "two 1 inch pieces of".
line 6, Delete: "except that the webbing shall be nylon 6.6".

3.3.3, Delete: "Metal", and substitute: "Other materials".

Add as new paragraph:

"3.3.3.1.1 Fiberglass Shank (Alternate). The shank shall consist of glass fibers impregnated with vinyl ester resins and encased in a plastic sleeve or tube. The width of the uncured encased fiberglass resin shall be 1-1/4 (+/-1/32) inch. The shank shall be cured and bonded to the insole and conform to the shape of the last. When fully cured, the shank (glass and resin area) shall be 7/8 (+/-1/16) inch in width. The cured lengths of the shank shall be graded as specified in Table III. The forward end of the shank shall be a 1/2 (+/-1/8) inch taper. The heel end shall be tapered a minimum of 3/8 inch. Testing shall be as specified in 4.4.1."

Page 9

3.3.3.3, line 3, after "boot", Add: "and of sufficient length to securely clinch".

Page 12

Table IV, line 8, after "Tolerance", Add:
New Designation:

"Thickness for Fiberglass Shank 15/32 15/32 15/32 15/32".

Page 13

3.3.7.5 "Collar foam (type II only).", line 1 after "Collar foam", Delete: "(type II only)".

3.3.7.6.1: Delete.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

3.3.7.6.2: Delete.

Add as new paragraph

"3.3.7.6.2 Removable cushion insole (alternate). The low density molded polyurethane heel cup arch support shall be a polyurethane polyester system medium black in color molded directly to a cambrelle top cloth, nicotine in color. The total thickness of the insole (insert) shall be 0.150 to 0.180 inch forward of the instep arch and 0.220 to 0.250 inch elsewhere. Each pair shall be molded on to the top cloth as blokers marked 0,1,2,3,4. Net cut sizes and widths shall be cut form said blockers for placement into product (see 6.6.5). A certificate of compliance shall be submitted and will acceptable for stated requirements. The polyester polyurethane foam shall conform to the properties:

Properties	Requirements
Density shore "00" hardness 55 ± 10....	17 + 2, - 1 lb per/cubic foot
Tensile strength	82 psi (minimum)
Compression set (77 degrees F)	25% @10.6 psi (maximum)
	50% @21.6 psi (maximum)"

3.3.7.6.3, Delete: "Type II - molded cushion insole." and substitute: "Molded cushion insole.".

3.3.7.6.3, under "Type II - molded cushion insole.", line 4, after "support.", Add: "Before thermoforming, the polyethylene shall have a density of 4 pound/cu. ft. (± 10%) and a minimum thickness of 0.200 inch.

3.3.7.6.3, line 5 and 6, Delete: ", and shall include an active organic anti-microbial agent. The top cover shall be perforated."

3.3.7.6.3, line 12, after, "hydrolysis", Add: "1/".

after line 12, Add footnote:

"1/ less than 10 percent after 5 hours exposure to saturated steam at 15 psi."

3.3.7.6.3, line 9 and 10, after "included.", Delete: "The total thickness....0.215 inch elsewhere.", and substitute:

"The total thickness of the insole shall be 0.150 to 0.180 inch forward of the instep arch and 0.220 to 0.250 inch elsewhere."

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

At the end of paragraph, Add the following:

"The cushion insole shall have cambrelle in nicotine color, flame laminated over the polyurethane top cover."

3.4.1, line 3, delete: "ventilating or".
line 5, delete: "top stay".
line 6, after "reinforcements.", Add the following:
"The boots shall have a latex foam padded collar covered with nylon cloth."

3.4.2, line 4, after "outside of the boot", Add: "including the eyelet stays".

3.5, line 3 after "be", Delete: "9-7/8", and substitute: "10-1/2". Line 3 & 4 after "inches" Delete: "for the type I boot.....type II boot".

line 21, after "size", Add: "and/or one full width".
line 25, after "the type I boot.", Add the following:

"The stitched uppers may be sized over/under the last one half size to accommodate variations in leather temper and maintain proper lasting margins. The boots shall have their size markings adjusted accordingly."

Under Table V, line 4, Delete: "Quarter (type I)", and substitute: "Quarter".

line 5, Quarter (type II), delete in its entirety
line 14, Collar cover (type II), Delete: "(type II)".
line 15, Collar foam (type II), Delete: "(type II)".

Under "Component parts", line 21, after "Ankle...widths" Add the following Note:

"Note: The leather for type II component shall be flesh side out with the exception of the counter pockets, which shall be grain side out."

3.7.1.1, under "Cutting leather uppers.", Delete the following:

"The leather for the type II boot components, with the exception of the eyelet stays and inside counterpockets, shall be cut so as to be used flesh out." and substitute:

"The leather for the type II, components shall be flesh side out, with the exception of the counterpockets which shall be grain side out."

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

Page 16

3.7.1.2, after "Cutting fabric upper parts.", Delete the following:

"The quarters shall be cut in the warp or filling direction or on an approximately 15 degree from the warp direction." and substitute:

"The quarters shall be cut in the bias direction approximately 15 degrees from the warp direction."

3.7.1.2, line 4, after "cover", Delete: " for the type II boot".

Page 18

3.7.5.1.1, line 1, after "the", Delete: "2" and substitute: "3".
line 6 through 9, after "inch.", Delete: "When the 1 inch ankle....stitching. Four of the single....edge.".

Page 19

3.7.5.1.3, line 2, after "folded", Delete: "inwards", and substitute: "outwards".

3.7.5.1.5: Delete.

Page 20

3.7.5.1.6, line 1, after "Padded collar", Delete: "(type II only).".

3.7.5.2, line 8, after "out," Delete: "," and Add the following:

"for type I and flesh side out for type II".

3.7.5.2, line 14, Delete: "that shall extend not less than 3/8 inch on the quarter top facing (type I)"
line 17, Delete: "For the type II, one" and substitute: "one".

Page 21

3.7.6.2, line 5, after "quarter." Delete: "The type I....through 14."
line 8, after "The", Delete: "type II".

3.7.7, line 2, 3, Delete: "The quarter shall be....eyelets."

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

3.7.9, under "LASTING.", line 18, after "inch", Delete: "nor more than 3/4 inch." and substitute: "Any excess lasting allowance margin, due to stretchy leather not permitting a proper heel seat bottom closure, shall be trimmed."

Add as new paragraph:

"3.7.9.1 Shank and heel filler attachment (for alternate fiberglass shank only). The alternate fiberglass shank shall be cut to the specified length for the boot size, formed to the last bottom profile securely attached and cured in place. The rear end of the shank shall be positioned in the center of the heel seat. The heel filler, as specified in 3.3.7.1 and Table VII, shall be positioned in the center of the heel seat, covering the rear end of the shank, and securely bonded with one of the adhesives specified in 3.3.7.2."

Add as new paragraph:

"3.7.9.2 Alternative counter assembly. As an alternate, an unmolded counter, well cemented on both sides, shall be assembled in accordance with the counter size schedule (3.3.1.4) so that they fill the counterpockets. When required for fit, one size smaller may be used. The counter and upper shall be formed and flanged using appropriate shaped molds on the back part molding machine. When leather counters are used, the flesh side of the leather counter shall be toward the inside of the boots. The counter shall be turned over the last at the bottom 1/2 + - 1/16 inch. Uppers of the correct size and width shall be assembled to the last in a manner to provide for a wiped-in heel seat of not less than 7/16 inch nor more than 3/4 inch. Although not a requirement, the counter may be seated to the insole with one or two tacks near the back end of the counter flange. If tacks are used, they shall be driven through the outside counterpocket and insole and clinched against the heel seat plate. Steel tacks may be used for lasting operations. Commencing with the conditioning and insertion of the box toe, the remainder of the lasting procedure is as the standard method."

Source: https://assist.dla.mil - Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

3.7.20.1, after paragraph, Add: "the following Note":

"Note: Upon occasion when some insignificant thread ends are noted during inspection (audit) they will not be cause for lot/shipment rejection. In-plant corrective action shall be made on current/future production."

3.7.23: Delete.

Add as new paragraph:

"3.7.23 Molded/Removeable cushion insole. One molded cushion insole as described in 3.3.7.6.3 and one removeable cushion insole (alternate) as described in 3.3.7.6.2 shall be inserted in each boot."

4.4.1 Component and material inspection., under "Lot size" line 3, after: "22,001 and....5, Add the following:

" Component	Requirements Paragraph	
Leather Insole	3.3.1.3	
Counters	3.3.1.4	
Backseam Tape	3.3.2.2	
Vamp Lining	3.3.2.4	1/
Webbing Tape	3.3.2.6	1/
Thread Insole	3.3.6	
Laces	3.3.7.4	
Shank	3.3.3.1	1/
Drainage Eyelets	3.3.3.4.1.1	1/
And Washers Type I	3.3.4.2	1/
Heel Fillers	3.3.7.1	1/
Steel Insole Plate	3.3.3.5	
Type I Thread Upper	3.3.5	

1/ A certificate of compliance shall be submitted and will be acceptable for the stated testing/inspection requirements contained in component specifications. In addition to the certificate of compliance a laboratory test report shall be provided with each component, lot/shipment from each supplier for prime contractor records and verification by the Government, when testing/inspection is deemed necessary on all components covered by a certificate of compliance."

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

Page 31

Table VIII, after the listing of tests for shank, steel, Add the following:

"Testing of components

Components and unit of Product	Characteristic	Specification refer Requirement paragraph	Test method
Fiberglass	Material identification	3.3.3.1	1/
Shank (Alternate)	Width	3.3.3.1	1/"

Page 33

Table VIII. Component test (contd), under "Requirement paragraph", line 28, Add: "3.3.7.6.3".
line 31, Add: "3.3.7.6.3".
line 32, Add: "3.3.7.6.3".
Under "Component", Collar foam (type II only), Delete: "(type II only)".

Pages 33, 34 Table VIII. Component test (contd), under "Component", Delete: "Insole cushion alternate (1 square yard material)" and substitute:

"Molded cushion insole and removable cushion insole (alternate)".

Page 34

Table VIII. Component test (contd), under "Component", Delete in its entirety: "Contoured cushion insole".

Page 35

4.4.2.2, line 3-5, after "4.4.2.2.2." Delete the following:

"The inspection level shall be.....defects."

Page 36

4.4.2.2.1 Examination of uppers after all fittings., under Table IX, Classification, Major, line 26 Delete: "105" and substitute: "*".

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

Page 37

Table X. Boot before last pulling defects, under Bottom of boot, line 8, Add the following:

"Examine	Defect	Classification Major (*)	Minor
Bottom of boot (for uppers with alternate fiber glass shank only)	Shank not properly positioned e.g., end of shank extending beyond ball line	X	
	Shank wrong size or malformed		X
	Shank not fitting contour of boot bottom".	*	

Page 38

4.4.3, under, End item visual examination., line 8, after "defects." Delete the following:

"The inspection level shall be II, and....defects."

Delete Note and substitute:

"Note: appearance defects shall be scored only when the condition is plainly visible from a distance of 3 feet or more and it appreciably affects appearance."

Page 39

Table XII, under Color and finish, "Defect" Delete: "Not specified color" and substitute: "Not within the specified range of color".

"Upper leather", under "Defect" Delete: lines 3 through 6 and substitute:

"any grub or tick damage, scars/scratch brands or bony leather, fat wrinkles, flanky leather, course grain or veins, etc., that appreciably affects appearance/serviceability.

Under "Classification": Asterisk (*) defect" Delete: "107" and substitute: "*".

Page 40

Table XII, under "Examine" for nylon quarter and gusset, under "Defect" Delete: "any quarter not cut on the bias".

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

Page 41

Table XII, "Outersole and heel., under, "Defect", Delete: "Thickness not as specified" and substitute: "Thickness less than specified or more than 1/32 inch greater than specified.", under "Classification, Major", Delete: "119" and substitute: "*".

Page 54

6.6.5, line 4, Delete: "35 Balch Street, Building K, P.O. Box 398, Beverly, Ma. 019115" and substitute: "166 Frobes Road, Braintree, Ma. 02184".

Add as new paragraph:

"6.6.7 Removable cushion insole (alternate). A suggested source for the alternate cushion meeting the requirement of 3.3.7.6.2 is Atlantic Thermoplastics, P.O. Box 457, Blackstone, MA 01504.".

Page 56

Under,"INSTRUCTION TAG (FOR TYPE I)" Item 2, line 5, after "of" Delete: "ventilating", and substitute: "cushion".
Item 5, Delete in its entirety.

Preparing Activity:
DLA - CT

(Project 8430-A442)

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.