MILITARY SPECIFICATION

CLOTH, CARTRIDGE, POLYESTER-VISCOSE RAYON (FOR CARTRIDGE BAGS)

1. SCOPE

1.1 Scope. This specification covers four classes of polyester-viscose rayon cloth.

1.2 Classification. The polyester-viscose rayon cloth shall be of the following classes, as specified in the contract (see 6.1) :

Class 1—Breaking strength 90 pounds per inch min.

Class 2—Breaking strength 125 pounds per inch min.

Class 3—Breaking strength 175 pounds per inch min.

Class 4—Breaking strength 200 pounds per inch min.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposal, form a part of this specification to the extent specified herein.

SPECIFICATIONS

FEDERAL

CCC-T-191 — Textile Test Methods

PPP-B-601 — Boxes, Wood, Cleated-Plywood

MILITARY

MIL-B-107 — Boxes, Wood, Wirebound (Overseas Type)

MIL-L-10547 — Liners, Case, Waterproof

MIL-T-13505 — Thread, Silk, Sewing (For Propellant Bags)

MIL-T-40040 — Thread, Polyester

STANDARDS

FEDERAL

FED-STD-751 — Stitches, Seams, and Stitching

MILITARY

MIL-STD-105 — Sampling Procedures and Tables for Inspection by Attributes

MIL-STD-109 — Inspection Terms and Definitions

MIL-STD-129 — Marking for Shipment and Storage

MIL-STD-1235 — Single and Multilevel Continuous Sampling Procedures and Tables for Inspection by Attributes

(Copies of specifications, standards, drawings and publications required by suppliers in connection

FSC 8305

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer.)

3. REQUIREMENTS

3.1 Material. Polyester-viscose rayon cartridge cloth shall be woven of polyester-viscose rayon yarns that have been spun from a blend of polyester fibers of the polyethylene-terephthalate type and viscose rayon fibers.

3.2 Appearance. The cloth shall be uniform and free of visible imperfections.

3.3 Width. The width shall be as specified in the contract or purchase order (see 6.1), when tested as specified in 4.3.2.

3.4 Chemical properties. The chemical properties shall be as specified in table I.

TABLE I

Properties	Percent		Applicable paragraph
	Minimum	Maximum	
Polyester Fiber content	50.0	60.0	4.3.1
pH of water extract	5.0	9.0	4.3.3
Ash		2.0	4.3.4
Acidity as acetic acid		0.1	4.3.5
Alkalinity as sodium carbonate		0.1	
Ether soluble material		10.0	4.3.6
Sizing Starch		10.0	4.3.1.1

3.5 Physical requirements. The finished cloth shall comply with the requirements specified in table II when tested as specified in the applicable paragraph.

TABLE II *Physical requirements*

Weave	Class 1	Class 2	Class 3	Class 4	Applicable paragraph
	Plain single, one end in a dent	2X1 twill	2X1 twill	2X2 basket	
Weight (Ounce per sq yard)					4.3.7
Min.	4.75	5.75	8.75	10.75	
Max.	5.25	6.25	9.25	11.25	
Thread Count, threads per inches, min.					4.3.8
Warp	35	35	45	50	
Filling	35	35	45	50	

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

TABLE II.—Continued

Weave	Class 1	Class 2	Class 3	Class 4	Applicable paragraph
	Plain single, one end in a dent	2X1 twill	2X1 twill	2X2 basket	
Breaking Strength, pounds per in., min.					4.3.9
Warp	90	125	175	200	
Filling	90	125	175	200	
Slippage value, min.					4.3.10
Warp	60	60	60	60	
Filling	60	60	60	60	
Stretch, percent, max					4.3.11
Warp	10	10	10	10	
Filling	10	10	10	10	

3.6 **Color.** The color of the cloth shall be specified in the contract or purchase order.

3.7 **Workmanship.** The finished cloth shall be uniformly and closely woven and shall be free of defects (dropped threads, knots, etc.) which might affect its serviceability).

4. QUALITY ASSURANCE PROVISIONS

4.1 **General quality assurance provisions.** Unless otherwise specified in the contract or purchase order, the supplier is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified, the supplier may utilize his own or any other inspection facilities and services acceptable to the Government Inspection records of the examinations and tests shall be kept complete and available to the Government as specified in the contract or order. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements. Reference shall be made to MIL–STD–109 in order to define the terms used herein. Inspection shall be performed in accordance with this specification and other specifications referenced in any of the contractual documents.

4.1.1 **Contractor quality assurance system.** If the contractor desires to utilize a quality assurance system, which is at variance with the quality assurance provisions of 4.2 and 4.3 and other documents referenced herein, he shall submit a written description of the system to the contracting officer for approval prior to initiation of product. It shall include a description covering controls for lot formation and identification, inspections to be performed, inspection stations, sampling procedures, methods of inspection, (measuring and testing equipment), and provisions for control and disposition of nonconforming material. The written description will be considered acceptable when, as a minimum, it provides the quality assurance provisions required by the provisions of 4.2 and 4.3 and the other documents referenced herein. The contractor shall not be restricted to the inspection station or the method of inspection listed in this specification provided that an equiva-

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

lent control is included in the approved quality assurance procedure In cases of dispute as to whether certain procedures of the contractor's system provide equal assurance, the comparable procedure of this specification shall apply The contractor shall notify the Government of, and obtain approval for, any changes to the written procedure that effects the degree of assurance required by this specification or other documents referenced herein.

4.1.2 **Submission of product.** At the time the completed lot of product is submitted to the Government for acceptance, the contractor shall supply the following information accompanied by a certificate which attests that the information provided is correct and applicable to the product submitted:

(a) A statement that the lot complies with all quality assurance provisions of the approved current written description of the system.

(b) Quantity of product inspected.

(c) Results obtained for all inspection performed.

(d) Specification number and date, together with an identification and date of changes.

(e) Certificates of analysis on all material procured directly by the contractor when such material is controlled by Government specifications listed in any of the contractual documents.

(f) Quantity of product in the lot.

(g) Date submitted.

The certificate shall be signed by a responsible agent of the certifying organization. The initial certificate submitted shall be substantiated by evidence of the agent's authority to bind his principal. Substantiation of the agent's authority will not be required with subsequent certificates unless, during the course of the contract, this authority is vested in another agent of the certifying organization

4.1.3 **Government verification.** Using the contractor's written quality assurance procedure (see 4.1.1), this detail specification, and other contractual documents as a guide, the Government inspector shall verify all quality assurance operations performed by the contractor. Verification shall be in accordance with a or b as applicable, the decision being the responsibility of the procuring activity. In either case, the inspector shall also ascertain, prior to acceptance, that all quality assurance provisions of other specifications referenced in any of the contractual documents have been complied with Deviations from prescribed or agreed upon procedures discovered by the Government inspector shall be brought to the attention of the supplier. Disposition of the product and remedial action shall be as directed by the Government inspector and, depending on the nature of the deviation, may consist of lot rejection, screening, resampling, reinstruction of the supplier's employees, or other appropriate action:

(a) Verification at the point of manufacture shall be accomplished at scheduled intervals in accordance with 4.1.3.1 and 4.1.3.2.

(b) Verification at the point of delivery shall be in accordance with 4.1.3.2.

4.1.3.1 **Surveillance.** Surveillance shall include, but is not limited to·

(a) Observation of procedures concerning lot formation and identification.

(b) Observation of sampling procedures and application of acceptance criteria.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

(c) Determination that all required examinations and tests are performed in accordance with the prescribed procedures of this specification, or approved equivalents thereto.

(d) Review of procedures for control and disposition of non-conforming material.

4.1.3.2 **Product inspection.** Product inspection shall consist of Government inspection of product which has been previously inspected by the contractor and found to meet the quality assurance provisions of this specification. The inspection by the Government shall be performed in order to determine that the product is of the quality required by this specification and that the contractor's records are reliable.

4.2 **Inspection provisions.**

4.2.1 **Lot formation.** A lot shall consist of one or more batches of cloth, polyester-viscose rayon, produced by one manufacturer, in accordance with the same specification, or same specification revision, under one continuous set of operating conditions. Each batch shall consist of that quantity of cloth, polyester-viscose rayon that has been subjected to the same unit chemical or physical process intended to make the final product homogeneous.

4.2.2 **Examination.** Sampling plans and procedures for the following classification of defects shall be in accordance with MIL–STD–105. Continuous sampling plans, in accordance with MIL–STD–1235 may be used if approved by the procuring activity. Also, at the option of the procuring activity, AQL's and sampling plans may be applied to the individual characteristics listed using an AQL of 0.25 percent for each major defect and an AQL of 0.40 percent for each minor defect.

4.2.2.1 Cloth in bolts prior to packing (par. 3.1 and 3.4)

Categories	*Defects*	*Method of inspection*	*Code No. (see 6.3)*
Critical:	None defined		
Major.	None defined		
Minor:	AQL 1.50 percent		
201.	Width (when applicable) (see 4.3.1)	Scale	01001
202.	Weave improper	Visual	01002
203.	Holes, tears, dropped or loose threads	Visual	01003
204.	Evidence of poor workmanship (see 3.7)	Visual	01004

4.2.2.2 Open box (par. 5.2)

Categories	*Defects*	*Method of inspection*	*Code No.*
Critical.	None defined		
Major:	AQL 0.65 percent		
101	Bolts not individually wrapped	Visual	02001
102	Box liner material improper	Visual	02002
Minor:	AQL 1.50 percent		
201.	Liner not sealed	Visual	02003
202.	Liner torn or pierced	Visual	02004

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

4.2.2.3 Closed box (par. 5.2)

Categories	*Defects*	*Method of inspection*	*Code No*
Critical: None defined			
Major:	AQL 1 00 percent		
101	Gross weight, max	Approved scale	03001
102.	Marking misleading or unidentifiable	Visual	03002
103	Boxes improperly closed	Visual	03003
Minor: None defined			

4.2.3 Testing.

4.2.3.1 *Sampling.* The sample size shall be in accordance with MIL–STD–105, level L7 of table III B. A unit for inspection shall be a bolt From each bolt a sample two square yards shall be selected. If any sample fails to comply with any requirement the lot shall be rejected.

4.3 Test methods and procedures.

4.3.1 *Polyester fiber content Code No 04001*

4.3.1.1 *Desizing* The desizing shall be in accordance with Specification CCC–T–191 method 2611

4.3.1.2 *Determination of polyester fiber content Code No. 05001.* The desized, weighed cloth specimen (see paragraph 3 4) shall be placed in a 600 ml. beaker and 150 ml, of 70 percent sulfuric acid added. Allow to stand at room temperature for 15 minutes intermittently moving the fiber with a glass rod to ensure total immersion and wetting of the fiber The liquid shall be decanted and the residual fiber given two additional extractions, each with 75 ml of 70 percent sulfuric acid, decanting after each extraction. The decantate should be clear and, when added to 200 ml. of distilled water should also result in a clear solution. If turbidity is obtained in either the decantate or the distilled water to which the decantate has been added, repeat the above acid extractions until turbidity has been eliminated. The residual fiber shall be given repeated washes with distilled water until all the sulfuric acid has been removed The sulfuric acid shall be considered removed if a negative result is obtained when tested as follows:

(a) Wash the residual fiber with 200 ml, of distilled water and decant.

(b) Add three drops of 10 percent hydrochloric acid to the decantate and stir.

(c) Add 10 drops of 1 percent barium chloride.

If the solution remains clear after the barium chloride is added the absence of sulfate is indicated and the result is negative.

The specimens shall be transferred to a tared 250 ml. beaker. The beaker and contents shall be placed in an oven maintained at 100 degrees Centigrade (°C) to 105°C. for one hour, cooled in a desiccator and weighed The difference between the weight and that of the tared beaker represents the weight of the polyester fiber portion of the specimen. The polyester fiber content shall be calculated as follows:

$$\text{Percent polyester fiber} = \frac{B \times 100}{A}$$

Where:

A = weight of desized specimens.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

B = weight of desized specimens after extraction with 70 percent sulfuric acid.

4.3.1.3 *Identification of polyester fiber Code No. 06001.* A liquid of specific gravity 1.36 and liquid of specific gravity 1.40 shall be prepared by mixing the proper proportions of either xylene or benzene with either carbon tetrachloride or perchlorethylene and checking the specific gravity with a hydrometer. The residual fiber obtained from the polyester fiber content determination is loosely rolled into a ball between the thumb and forefinger and boiled for 5 minutes in either benzene or xylene. Remove specimen with a tweezer and place below the surface of the liquid of known specific gravity in a test tube. The polyester fiber will sink to the bottom of the tube when placed in a liquid of specific gravity 1.36 and float in the liquid of specific gravity of 1.40.

4.3.2 *Width Code No. 07001.* The width shall be determined in accordance with Specification CCC–T–191, method 5020.

4.3.3 *pH of water extract Code No. 08001.* Two specimens weighing approximately 0.5 gram each, shall be cut from each of the pieces comprising the sample. These specimens shall be combined, weighed, and transferred to a 250-ml. beaker. One hundred and fifty ml. of freshly boiled, distilled water shall be added to the beaker, the beaker covered with a watch glass, and the water boiled gently for 30 minutes. In case the volume of water becomes less than one-half the original amount during the boiling period, sufficient boiling distilled water shall be added to restore it to the original volume. At the end of 30 minutes the volume brought to 150 ml. by adding freshly boiled water. The covered beaker and contents shall be cooled to 25° to 30°C. without agitating the contents, to minimize the absorption of carbon dioxide from the atmosphere. The pH of the cooled liquid shall be determined, using a glass electrode pH electrometer, within one hour after removing the beaker from the source of heat. The distilled water used for this test shall be carried through the above operation as a blank, and must show a pH value in the range of 6.0 to 7.0.

4.3.4 *Ash Code No. 09001.* Sufficient specimens shall be cut from each of the pieces comprising the sample so as to obtain a total of approximately two grams, and transferred to a tared platinum or porcelain crucible and moistened with concentrated nitric acid. The crucible shall be heated on a steam bath for one hour and then heated carefully over a flame so as to avoid any loss. When the contents of the crucible have been charred, heat to dull redness until all carbonaceous matter has been burned off. The crucible shall be cooled in a desiccator and weighed. The gain in weight shall be calculated to percent ash in the sample as follows:

$$\text{Percent ash} = \frac{100\ (A - B)}{W}$$

Where:

A = weight of crucible and ignited residue

B = weight of crucible empty.

W = weight of specimens.

4.3.5 *Acidity or alkalinity Code No. 10001.* The solution used in the pH water extraction (see 4.3.3) shall be filtered If the pH of the solution is between 7.0 and 9.0, the solution shall be titrated with N/10 hydrochloric acid solution using methyl red as the indicator. If the pH of the solution is between 5.0 and 7.0, titrate with N/10 sodium hydroxide solution using phenophthalein as the indicator. Any acidity shall be calculated to percent acetic acid and any alkalinity shall be calculated to percent sodium carbonate.

4.3.6 *Ether soluble matter Code No. 11001.* Two specimens, weighing approxi-

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

mately 0.5 gram each, shall be cut from each of the pieces comprising the sample These specimens shall be weighed together and transferred to the extraction chamber of a Soxhlet extraction apparatus having ground-glass connections. The extraction chamber shall be assembled to a tared receiving flask and ether transferred to the extraction chamber until the specimens are covered and the ether siphons over into the flask. Approximately 25 ml. more of ether shall be added to the extraction chamber, a condenser shall be assembled to it and the assembled apparatus placed on a steam bath. The extraction shall be allowed to proceed for 15 hours. Heating shall be discontinued at a time when the ether content of the extraction chamber is nearly sufficient to cause the ether to siphon over into the receiving flask. The flask, containing the oily extract, shall be heated on a steam bath until the ether is removed. The flask and residue shall be dried in a vacuum desiccator, over concentrated sulfuric acid, until constant weight is obtained. The weight of residue shall be calculated to percent ether extract.

4.3.7 *Weight Code No 12001.* The weight shall be determined on each of the pieces comprising the sample in accordance with Specification CCC–T–191, method 5040.

4.3.8 *Thread count Code No. 13001.* The thread count shall be determined on each of the pieces comprising the sample in accordance with Specification CCC–T–191, method 5050.

4.3.9 *Breaking strength Code No. 14001.* The breaking strength shall be determined concurrently with the slippage value test and shall be read from the fabric-stretch curve of the graphic record The breaking strength is the point where there is no further increase in tension. The breaking strength of the warp yarns is taken as the max tension in pounds per inch recorded on the fabric-stretch curve for the filling slippage specimens The breaking strength of the filling yarns is taken as the max. tension in pounds per inch recorded on the fabric-stretch curve for the warp slippage specimens. The average of the five values obtained in each direction shall be reported as the breaking strength in that direction

4.3.10 *Slippage value Code No. 15001.*

4.3.10.1 *Apparatus.* A pendulum type testing machine as specified in Specification CCC–T–191, method 5100 with a suitable autographic recording device attached shall be used for determination of slippage value

4.3.10.2 *Preparation of specimens.* Specimens, four inches wide by 16.0 to 16.5 inches long, shall be selected for test. Five sets of two specimens each, one set from each of the five pieces comprising the sample, are required, one specimen of each set for warp slippage value, having the short dimension parallel to the warp yarns, and the other specimen of each set for the filling slippage value, having the short dimension parallel to the filling yarns Unless otherwise specified, no specimen shall be taken nearer the selvage than one-tenth the width of the material. The specimens shall be prepared by cutting strips of cloth of the number and in the directions specified above, approximately 4.5 inches wide and 17 inches long Any cut or broken threads shall then be raveled from the strip of cloth until only threads remain in the length-wise direction of the cloth which are approximately the same length as the cloth strip and only threads remain in the short direction which are approximately as long as the width of the cloth strip. Sufficient yarns shall then be raveled from both the long and short dimensions of the strip of cloth until the specimen is 4 inches wide by 16 to 16½ inches long. Any other convenient method of preparing the specimen may be used provided it does not effect the physical properties of the cloth. Fold a test specimen back on itself so that the distance from the fold to one edge,

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

parallel to the short dimension, measures approximately 5 inches and to the opposite edge at least 10 inches. The fold must be parallel to the crosswise yarns in the specimen. At 0.38 inch from the fold, sew a seam parallel to the crosswise yarns of the specimen. Use a seam of the type designated as 301–SSa–1 by Standard Fed Std–751. (Make the seam SSa–1 with one row of stitches, 12 stitches per inch, Type 301). In making the seam, use a needle and a thread sufficient strength so that it will not break when the seam is tested for elongation (A number 21 needle and both of the following threads have been found satisfactory: Commercial grade H (14 pound) waterproofed silk, finished line thread with a lefthand machine twist; or cotton thread with a left-hand machine twist having a minimum breaking strength of five pounds when tested in accordance with paragraph F–4E of MIL–T–13505 for a minimum thickness of 0.017 inch (16–4 Thread, Cranska Thread Co., Worcester, Mass.). Condition the specimens for at least 24 hours at 21° ± 2°C and 65 ± 2 per cent relative humidity.

4.3.10.3 *Procedure* The distance between the jaws of the test machine shall be adjusted to 3 inches. A 6-ounce clamp shall be attached to the specimen parallel to and at a distance of three inches from the seam described above. The clamp shall be attached to the 10-inch length of the specimen. The clamp can be assembled from a metallic photographic film clip approximately five inches long, a brass or steel rod six inches long and 3/16 inch in diameter, or brass or steel weights equal in weight to the 6-inch rod to bring the total weight of the assembly to six ounces. The 10-inch portion of the test specimen shall be placed symmetrically in the upper jaws of the test machine so that the long direction of the specimen is parallel to the direction of application of the load. The specimen shall be clamped in the upper jaw so that the 6-ounce clamp described above is approximately ¼ inch below the lower jaws of the test machine. The test machine shall be reset so that a zero load is shown on the graphic record. Make certain that the 6-ounce clamp is supported only by the test specimen so that a uniform tension of 6 ounces is supplied to the specimen. The lower jaws of the test machine shall be fastened to the specimen, taking care to grip the same yarns in the lower jaws as are gripped in the upper jaws. The apparatus shall be arranged to obtain a tension-stretch curve up to the breaking strength of the specimen, the stretch being indicated in inches by the vertical component of the curve and the tension being indicated in pounds by the horizontal component. The machine shall be started and allowed to apply tension until the specimen breaks. This graphic record shall be designated as the fabric-stretch curve. The same specimen shall be inserted in the jaws of the machine so that the seam is in a position parallel to the jaws and midway between the upper and lower jaws. The specimen shall be clamped in the jaws and tension applied by means of the 6-ounce clamp, as directed above, before tightening the lower jaws. The apparatus shall be arranged so that the graphic record of this test will be made on the same chart and will start at the same point as the fabric-stretch curve. The machine shall be started and tension allowed to be applied to the specimen until either the cloth breaks or the seam fails. This graphic record shall be designated as the seam-stretch curve. The tension shall be noted at which the vertical distance between the seam-stretch curve and the fabric-stretch curve is equal to the sum of (a) the vertical distance between these curves when the tension is one pound, and (b) a vertical distance on the chart equivalent to 0.25 inch on the cloth. The slippage shall be calculated as follows:

$$\text{Slippage value} = \frac{100A}{B}$$

Where:

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

A = tension at which the difference between the seam-stretch curve and the fabric-stretch curve is 0.25 inch plus the difference between these curves when the tension is one pound.

B = the minimum breaking strength for the class of cloth being tested as specified in table II.

The slippage value in the warp direction shall be considered as the average of five results obtained for the warp slippage specimens and the slippage value in the fill direction as the average of five results obtained for the fill slippage specimens.

4.3.11 *Stretch Code No. 16001* The percent of stretch shall be determined concurrently with the slippage value and shall be calculated as shown below for measurements of the fabric-stretch curve of the graphic record. The percent of stretch of the warp yarns is obtained from the fabric-stretch curve obtained when the slippage value of the filling yarns is determined The percent of stretch of the filling yarns is obtained from fabric-stretch curve obtained when the slippage value of the warp yarns is determined. The percent of stretch in each direction shall be considered as the average of five values determined in that direction calculated as follows:

$$\text{Percent of stretch} = \frac{100\ (A-B)}{3.00 + B}$$

Where:

A = elongation in inches of the portion of the specimen tested at the tension listed below for the class of cloth being tested.

Class	*Tension (pounds)*
1	40
2	50
3	50
4	60

B = elongation in inches of the portion of the specimen tested when the tension is one pound as read on the fabric-stretch curve (see note).

Note. The elongation of the specimen is represented by the vertical component of the fabric-stretch curve at the required tension).

5. PREPARATION FOR DELIVERY

5.1 Preservation and packaging (see 6.1)

5.1.1 *Level A.* The cartridge cloth shall be furnished in bolts wrapped in waxed paper.

5.1.2 *Level C.* The cartridge cloth shall be packaged in accordance with suppliers commercial practice Protection shall be such as to prevent deterioration during shipment and subsequent interval preliminary to use

5.2 Packing *(See 6.1.)*

5.2.1 *Level A.* The packages containing cartridge cloth shall be packed in cleated plywood boxes, or wirebound wood boxes conforming to the requirements of PPP–B–601 or MIL–B–107, respectively. Shipping containers shall be lined with a sealed waterproof case liner complying with MIL–L–10547, or equivalent Containers shall be strapped in accordance with the strapping requirements of the appendix of the applicable box specification. The gross weight shall not exceed 200 pounds.

5.2.2 *Level C.* The cartridge cloth shall be packed for shipment in conformance with consolidated Freight Classification rules and container specifications for rail shipments, or with National Motor Freight Classification rules and container specifications for truck shipment.

5.3 **Marking.** Exterior containers shall be marked in accordance with MIL-STD-129

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.

*5.3.1 Exterior containers enclosing packages prepared for level C shall be conspicuously marked MIN MIL PK. When specified, exterior containers for overseas shipment shall be marked with the Ordnance Corps symbol and the SM group of the item.

6. NOTES

6.1 Ordering data. Procurement documents should specify the following:

(a) Title, number and date of this Specification.

(b) Class of material required (see 1.2).

(c) Width of material required (see 3.3).

(d) Levels of protection (see 5.1).

(e) Special marking (see 5.3.1).

(f) Color (see 3.6).

6.2 Intended use. The polyester viscose rayon cloth is intended for use in the manufacture of cartridge bags for artillery ammunition.

6.3 Inspection Code numbers. The five digit code numbers assigned to the inspection herein are to facilitate future data collection and analysis by the Government.

Custodian:

ARMY-MU

Preparing activity:

ARMY-MU

Project No. 8305-A194Y

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T20:48Z
Check the source to verify that this is the current version before use.