[illegible]
NOTICE 1
10 [illegible] 198[illegible]

MILITARY STANDARD
UNIT LOAD
FOR UNDERWAY REPLENISHMENT
MISSILE BOOSTER FINS
IN MK 205 MOD 0 CONTAINERS

Make the following pen and ink change:

Page 2, [illegible], as shown is incorrect. Place the following note below [illegible]: "The steel straps, item 2, must loop under both end walls and not between them as shown."

DISTRIBUTION STATEMENT A
Approved for public release;
distribution is unlimited.

[illegible] N/A

[illegible]

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T23:56Z
Check the source to verify that this is the current version before use.