INCH POUND

MIL-F-24724(SH)
AMENDMENT 2
16 October 1992
SUPERSEDING
AMENDMENT 1
2 June 1992

MILITARY SPECIFICATION

FILTER HOUSINGS (HYDRAULIC) AND DIFFERENTIAL PRESSURE INDICATORS, GENERAL SPECIFICATION FOR

This amendment forms a part of MIL-F-24724(SH), dated 15 February 1990, and is approved for use by the Naval Sea Systems Command, Department of the Navy and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 3

2.2, under "NATIONAL FLUID POWER ASSOCIATION (NFPA)", delete the following:

"T2.6.1 - Method for Verifying the Fatigue and Static Pressure Ratings of the Pressure Containing Envelope of a Metal Fluid Power Component."

2.2, under "NFPA": Add the following:

"T2.6.1 R1 - Method for Verifying the Fatigue and Establishing the Burst Pressure Ratings of the Pressure Containing Envelope of a Metal Fluid Power Component."

PAGE 6

3.4.9.1, line 3: Delete "equal to or less" and substitute "not greater".

3.5.4: Delete and substitute:

"3.5.4 Fatigue impulse. Filter housings, bypass relief valves, and differential pressure indicators shall withstand, without failure, 1 million impulse pressure cycles in accordance with NFPA T2.6.1 R1."

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T01:20Z
Check the source to verify that this is the current version before use.

PAGE 8

4.3: Delete and substitute:

"4.3 Qualification inspection. Qualification inspection shall be conducted at a laboratory acceptable to the qualifying activity. Qualification inspection shall consist of the examination and tests specified in table I. For each housing, tests shall be performed in the general sequence shown in table I unless otherwise approved by the procuring activity. Failure of any test shall be cause for rejection."

PAGE 10

4.5.1: Add the following at the end of the sentence:

"or an equivalent petroleum base oil at 68 centistokes."

PAGE 11

4.7.1.4, Delete and substitute:

"4.7.1.4 Fatigue impulse test. The filter housings, bypass relief valves, and differential pressure indicators shall be tested in accordance with NFPA T2.6.1 R1 to obtain a 90 percent assurance level and a 90 percent verification level that the rated fatigue pressure is not less than the rated operating pressure. Seals may be replaced during the test. The replacing of seals during impulse testing shall not be considered as a test failure. Any evidence of damage or malfunction shall be cause for failure."

4.7.1.5.1, line 11: Delete "10" and substitute "25".

Preparing activity:
Navy - SH
(Project 4330-N098)

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T01:20Z
Check the source to verify that this is the current version before use.