MIL-C-43805(GL)
AMENDMENT-2

20 November 1975
SUPERSEDING
Amendment-1
26 March 1975

MILITARY SPECIFICATION

CLOTH, NETTING, PARACHUTE SKIRT EXTENSION, NYLON, RASCHEL KNIT

This amendment forms a part of Military Specification MIL-C-43805(GL), dated 10 August 1972, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 2

3.2 Delete in its entirety and substitute the following:

"3.2 Color. Unless otherwise specified (see 6.2) the color of the netting shall be natural. If other than natural color netting is specified, the color shall be obtained by yarn dyeing."

3.2.2, line 2. Delete the words "natural (North Sky) daylight."

3.3.2 Add the following sentence, "There shall be 5 mesh repeats in the overall width of the finished netting."

3.3.3 Delete the last sentence and substitute the following:

"When edges are cut, the extending tails of cut edges shall be 1/2 inch ± 1/8 inch."

PAGE 3

3.3.4 Delete the first three lines and substitute the following:

"3.3.4 Sewing of cut edge. One edge of the netting shall have either a knitted selvage or the edge shall be sewn so that there shall be no loose ends along the full length. (see 3.4) and the following sewing requirements shall apply:"

FSC 8305

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T22:23Z
Check the source to verify that this is the current version before use.

PAGE 3 (cont'd)

3.4 Delete the first sentence and substitute the following: "For net purchased directly by the Government, unless otherwise specified (see 6.2) the cloth netting shall be furnished on individual rolls in 500 feet -5 + 25 feet lengths."

3.5 Delete in its entirety and substitute the following:

"3.5 Mending and joining. Damages in the netting shall be mended by either of the following methods:

a. Damaged sections may be completely cut out across the full width of the net. The net shall be joined by sewing the legs or pillars together as specified in 3.3.4.

b. Damaged sections may be mended by the patch method. The damaged portion of the netting shall be cut out and replaced with a piece of undamaged netting (see 3.3.2). For mending and joining, a full leg (one side of square mesh) shall be overlapped with a full leg of the main piece of the cloth netting and secured with stitch type 304 (zig-zag) using the thread yarn specified in 3.3.4. Knots will not be permitted in the joining or repair of damaged sections.

PAGE 4

4.2.2.1, last sentence, after the word "roll(s)", add "or cartons," throughout the paragraph.

PAGE 5

4.2.2.1 Add the following defects;

"Knots
Sharp "glob" resulting from improper "hot knife" cutting
Incorrect number of mesh repeats in the finished width"

4.2.2.1 Add "3/" to the defect beginning with "thick or thin place"

Add the following new footnote to the bottom of the table:

"3/ Sections mended in accordance with paragraph 3.5 shall not be classified as defects (see 4.2.2.2)."

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T22:23Z
Check the source to verify that this is the current version before use.

PAGE 5 (cont'd)

4.2.2.2, after the word "roll(s)". Add "or carton(s)" throughout the paragraph and Table II.

Line 10. Delete the word "roll" and substitute "500 feet".

PAGE 6

4.2.4 Delete the third sentence in its entirety and substitute the following:

"The sample unit shall be five yards of netting and each sample unit shall come from a different roll or carton."

After the word "roll(s)" add "or carton(s)" throughout the paragraph.

Custodian:

Army - GL

Preparing activity:

Army - GL

Proj. No. 8305-A369

☆ U. S. GOVERNMENT PRINTING OFFICE: 1975-603-766/1773

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T22:23Z
Check the source to verify that this is the current version before use.