MIL-R-43825B
AMENDMENT-2
19 May 1982
SUPERSEDING
AMENDMENT-1
25 March 1980

MILITARY SPECIFICATION

RACKS, TRAY BUSSING, MOBILE

This amendment forms a part of Military Specification MIL-R-43825B, dated 25 July 1978, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 3

* 2.2: Delete

"U.S. DEPARTMENT OF COMMERCE

CS 245-62 - Vinyl-Metal Laminates

(Application for copies should be addressed to the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.)"

PAGE 4

* 3.3.1: Delete and substitute:

"3.3.1 Vinyl-metal laminates. Vinyl-metal laminates shall consist of a sheet metal base, either ferrous or nonferrous, with one or both sides completely covered with vinyl securely bonded to the metal. The laminate shall be self-extinguishing in nature. The vinyl shall be as free as is commercially practicable of visual defects such as streaks, blisters, pinholes, particles of foreign matter and undispersed raw materials. The vinyl shall be stain resistant to orange and lemon peels, 10% nitric, sulfuric or citric acids, mineral oils, sodium hypochlorite (clorox), colas, coffee or hot bacon grease. The metal finish and temper shall be suitable for good film adhesion. The adhesive shall be uniform in consistency and free of undispersed particles and foreign matter that would interfere with good bonding."

FSC 7320

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T22:29Z
Check the source to verify that this is the current version before use.

PAGE 4 (cont'd)

* 3.4, 1st sentence: Delete and substitute "All racks, except type IV, shall be of double compartment design, fully enclosed, consisting of an aluminum alloy frame, extruded aluminum tray slides, aluminum alloy panels, doors and four swivel casters. Unless otherwise specified (see 6.2), the type IV rack shall be of the open type frame construction. Type IV open racks shall be supplied with push handles as specified in 3.4.4."

After 1st sentence: Add "The basic frame of the rack shall be an all welded assembly including the plate or plates to which the casters are attached."

Line 17: Delete "side".

PAGE 5

* 3.4.2: Delete and substitute:

"3.4.2 Panels. All panels, except the bottom panel, shall have firmly assembled to them a decorative exterior coating. The coating shall be a vinyl laminate conforming to 3.3.1. Unless otherwise specified (see 6.2), the coating shall be a walnut wood grain. Panels shall be securely fastened on all four edges by threaded fasteners and shall not rattle or vibrate when tested as specified in 4.4.1 and 4.4.3."

* 3.4.3, line 1, after "casters": Add "at the corners".
Line 2: Delete "B or C" and substitute "b or c".

2nd sentence: Delete and substitute:

"The two casters on either side of types I, II and III racks shall be equipped with locking brakes. Type IV, open racks shall be equipped with two locking brakes on the same side as the handle."

* 3.4.4: Delete.

PAGE 6

* 3.4.6: Delete and substitute:

"3.4.6 Bumpers. Racks shall have perimeter bumpers mounted at the top and bottom of the unit. The bumpers shall be fabricated from rubber or rubber-like material capable of being easily replaced. Bumpers shall protrude 3/4 to 1-1/8 inches beyond any part of the rack."

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T22:29Z
Check the source to verify that this is the current version before use.

PAGE 6 (cont'd)

* 3.4.7: Delete and substitute:

"3.4.7 Doors. All racks except type IV shall be provided with two equally sized, full length vertical doors at one end, along the width dimension of the rack. Doors shall have a decorative exterior coating of vinyl laminate on the outside conforming to 3.3.1 and shall be reinforced for rigidity. Unless otherwise specified (see 6.2), the coating shall be a walnut wood grain matching that used on panels. Doors shall have means to facilitate opening and shall close tightly against the door jamb or rack frame and shall be supported by a minimum of three hinges or a full length hinge located at the corners of the rack. The rack shall have provisions for holding the doors open against the sides."

PAGES 7 and 8

* Table I, under "Design and construction": Delete and substitute the following defects.

Design and construction, all rack types	Not type and size specified Bumpers missing or not as specified Bumpers loosely attached On flat surface all four wheels not touching surface Base plate not integral part of rack Casters not attached to reinforcing channel or reinforcing plate not provided Basic frame not welded Plate or plates not welded to which the casters are attached
All rack types except type IV	Not fully inclosed Panels not secured along the entire bottom, top and vertical edges Doors not as specified Doors do not close tightly against the sides Doors not reinforced Hinges not as specified Locking brakes not on the side of the rack
Rack type IV only	Open type rack not supplied with handle Locking brakes not the same side as the handle

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T22:29Z
Check the source to verify that this is the current version before use.

PAGE 9

* 4.4.1, line 5: Delete "The side opposite the rack handle" and substitute "Each of the two sides".

Line 7: Delete "corner opposite the rack handle" and substitute "of the four corners".

Lines 9 and 10, 8th sentence: Delete.

PAGE 10

6.2: Add "(e) When fully inclosed type LV rack is required (see 3.4.1.5)."

The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in the notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodians:

Army - GL
Navy - SA
Air Force - 99

Preparing activity:

Army - GL

Project No. 7320-0713

Review activities:

Army - MD
Navy - MC

☆ U.S GOVERNMENT PRINTING OFFICE: 1982—605-022/2856 2-1

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T22:29Z
Check the source to verify that this is the current version before use.