MIL-S-10522K (PA)
15 May 1975
Superseding
MIL-S-20522J (MU)
09 June 1972

MILITARY SPECIFICATION

SIMULATOR, BOOBY TRAP, WHISTLING, M119
PARTS FOR AND LOADING, ASSEMBLING AND PACKING

This specification is approved for use by all Departments and Agencies of the Department of Defense,

1. SCOPE

1.1 This specification covers the parts for and the loading, assembling and packing for one type of simulating device designated as Simulator, Booby Trap, Whistling, M119.

2. APPLICABLE DOCUMENTS

*2.1 The following documents of' the issue In effect on date of invitation for bids or request for proposal, form a part of this specification to the-extent specified herein.

SPECIFICATIONS

FEDERAL

QQ-Z-325 - Zinc Plating (Electrodeposited)
QQ-P-416 - Plating, Cadmium (Electrodeposited)

MILITARY .

MIL-P-223 - Powder, Black
MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specification For

STANDARDS

FSC: 1370

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for "Inspection by Attributes (ABC-STD-105)
MIL-STD-286 - Propellants, Solid: Sampling, Inspection and Testing

DRAWINGS

U.S. ARMY PICATINNY ARSENAL

PRODUCT AND PACKAGING DRAWINGS

8848602 - Simulator, Booby Trap, Whistling, M119 Assembly
8799716 - Carton, Packing, Ammunition for Simulator, Booby Trap, Whistling, M119
3799717 - Box, Packing, Ammunition, Wirebound form Simulator, Booby Trap, Whistling, M119

(Copies of specifications, standards, drawings and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the Contracting Officer).

*2.2 Other Publications. - The following documents form a part of this specification to the extent specified herein. Unless otherwise indicated; the issue in effect on the date of invitation for bids or request for proposal shall apply.

CODE OF FEDERAL REGULATIONS

Title 49 - Transportation, Parts 100-199

(The Code of Federal Regulations Is available from the Superintendent of Documents, U.S. Government Printing Officer, Washington, D.C. 20402. Orders should specify, "49 CFR 100-199 (latest revision)").

*(For meaning of asterisk see paragraph 6.6).

3. REQUIREMENTS

3.1 Material. - Material and parts shall be in accordance with applicable drawings and specifications.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

3.2 Assembly. - The assembly shall comply with all requirements specified on Drawing (dwg.) 8848602 and with all requirements in applicable specifications.

3.3 Moisture content

3.3.1 Moisture content of match head and whistle compositions. - The moisture content of each composition at the loading station at the time of loading shall not exceed 0.1 percent.

3.3.2 Moisture content of fuze powder. - The moisture content of fuze powder, prior to the addition of the cellulose nitrate camphor at the loading station at the time of loading . shall not exceed 0.3 percent.

3.3.3 Felt, paper and chipboard. - The moisture content of the felt, paper, and chipboard components of the simulator assembly at the loading station at the time of loading shall not exceed 6 percent.

3.3.4 The moisture content of the black powder at the loading station at the time of loading shall not exceed 0.3 percent.

3.4 Embrittlement of extension spring. - The extension spring (see dwg. 8848592) shall not break when stretched to the minimum point of permanent distortion.

3.5 Functioning. - The assembly shall meet the following requirements.

3.5.1 Normal. - The assembly shall ignite and burn with an audible whistling sound for the required number of seconds (see dwg. 8848599).

3.5.2 Malfunction. - The assembly shall not explode or have any part rupture or become detached during Initiation or burning.

3.6 Quick Leak Test. - The packed carton sealed in the barrier bag shall show no evidence of air or water leakage.

*3.7 Workmanship. - All parts and assemblies shall be fabricated and loaded In a thorough workmanlike manner, and all manufacturing, processing, and assembly operations shall

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

be correctly performed. They shall be clean and free of burrs, sharp edges, unblended radii, surface defects, chips, dirt, grease and oil (except where specifically required), corrosion products and other foreign matter. The cleaning method used shall not be injurious to any part or assembly nor shall they be contaminated by the cleaning agent. Exterior surface coatings shall be continuous except for a few light scratches not exposing base material. All required markings shall be neat and sharply defined. (Required packing shall be dry).

*3.8 First Article Inspection. - This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

*4. QUALITY ASSURANCE PROVISIONS

*4.1 Responsibility for Inspection and Standard Quality Assurance Provisions. - Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

*4.2 Classification of inspections. - The following types of inspection shall be conducted on this item.

a. First Article Inspection

b. Quality Conformance Inspection

*4.3 First Article Inspection

*4.3.1 Submission. - The contractor shall submit a first article sample (see 6.2b) as designated by the Contracting Officer. The first article sample shall consist of 25 complete sets of parts, sub-assemblies (Le. 25 each of every component and sub-assembly) and 50 loaded simulators. The first article sample shall be evaluated in accordance with the provisions of 4.3.2 and 4.3.3. Unless otherwise directed by the Contracting Officer, loaded components shall not be submitted to a Proving Ground for any test until the inert components and inert sub-assemblies submitted in accordance with this paragraph have been accepted.

4.3.2 Inspections to be performed. - See MIL-A-48078 and paras 4. 4.2.1 thru 4.4.2.16, testing per para. 4.4.3, and Table I specified herein.

Source: https://assist.dla.mil -- Downloaded: 202610-17T14:12Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-S-10522K (PA)

PARAGRAPH #	TITLE: Simulator, Booby Trap, Whistling, M119, Inert Parts, Sub-assemblies, and Complete Assemblies		SHEET 1 OF 2		DRAWING NUMBER: See Below NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Inert Parts (Dwg. 8848602) Examination for Defects	25 (Note 1)		3.2	4.4.2.1 thru 4.4.2.10
	Sub-assemblies Lower Disc Assembly (Dwg. 8848585) Examination for Defects	25		3.2	4.4.2.11
	Upper Disc Assembly (Dwg. 8848584) Examination for Defects	25		3.2	4.4.2.12
	Spool Assembly (Dwg. 8848590) Examination for Defects	25		3.2	4.4.2.2
	Scratcher Assembly (Dwg. 8848587) Examination for Defects	25		3.2	4.4.2.13
	Whistle Assembly (Dwg. 8848599) Examination for Defects	25		3.2	4.4.2.14

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-S-10522K (PA)

PARAGRAPH *	TITLE Continuation Sheet		SHEET 2 OF 2		DRAWING NUMBER See Below / NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Assembly (Dwg. 8848602)				
	Examination for Defects	50 (Note 2)		3.2	4.4.2.15 thru 4.4.2.16
	Tests				
	Protective coating of extension spring (Dwg. 8848592)	25 (Note 3)		3.2	4.5.3
	Protective coating of bracket (Dwg. 8848603)	25 (Note 3)		3.2	4.5.3
	Embrittlement of extension spring (Dwg. 8848592)	25 (Note 4)		3.4	4.5.4
	Functioning (Dwg. 8848602)	50 (Note 5)		3.5	4.5.6
NOTES:	(1) Twenty-five (25) of each and every inert component (2) First fifty (50) complete assemblies (3) Performed on springs and brackets from (1) (4) Performed on additional twenty-five (25) springs (5) Performed on assemblies from (2)				

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

*4.3.3 Rejection. - (See MIL-A-48078)

*4.4 Quality conformance inspection,

*4.4.1 Inspection lot formation. - Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition inspection lots of-Simulator, Booby Trap, Whistling, M119 shall contain:

a. Parts from one lot interfix from one manufacturer.

b. Composition ingredients from not more than one lot from one manufacturer.

c. Fuze powder from not more than one lot.

d. Quickmatch from not more than one lot.

e. Match head composition, scratcher composition " and charge composition of' one or more batches produced under one continuous set of operating conditions, with each batch of the composition having been subjected to the same physical mixing process intended to make the batch homogeneous,

*4.4.2 Examination, - (See MIL-A-48078). Unless otherwise specified in the classification of defects and test tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II, Equipment necessary for the performance of the inspections listed shall be in accordance with 4.4.4.

Source: https://assist.dla.mil -- Downloaded: 202610-17T14:12Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-10522K (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
#4.4.2.1	Extension Spring		8848592
			NEXT HIGHER ASSEMBLY 8848602

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
101	Load at 2 times original length, min		0.40%	3.2	Gage
102	Load at 3 times original length, min		0.40%	3.2	Gage
Major B					
131	Spring takes a permanent set when extended a minimum of 26 inches inside hooks		0.40%	3.2	Manual Gage
	Note: The springs shall be tested in the order listed above				
Minor					
201	Unloaded length		0.65%	3.2	Gage
202	Protective coating missing or contains bare spot		0.65%	3.2	Visual
203	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-10522K (PA)

PARAGRAPH	TITLE			SHEET 1 OF 1	DRAWING NUMBER 8848590
*4.4.2.2	Spool Assembly				NEXT HIGHER ASSEMBLY 8848602
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined.				
Major B					
131	Protective coating missing or contains bare spot		0.40%	3.2	Visual
Minor					
201	Spool split or cracked		0.65%	3.2	Visual
202	Wire insecure		0.65%	3.2	Visual-Manual
203	Evidence of poor workmanship		0.65%	3.7	Visual-Manual
204	Protective coating not dry		0.65%	3.2	Visual-Manual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.3	Tube, Body	1 OF 1	8848586
			NEXT HIGHER ASSEMBLY 8848599

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Layers separated or tube damaged		0.40%	3.2	Visual
132	Location of hole		0.40%	3.2	Gage
Minor					
201	Length		0.65%	3.2	Gage
202	Thickness of wall, min.		0.65%	3.2	Gage
203	Inside diameter		0.65%	3.2	Gage
204	Crack		0.65%	3.2	Visual
205	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS MIL-S-10522K (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
*4.4.2.4	Tube, Outer				8848595
					NEXT HIGHER ASSEMBLY 8848602
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Layers separated or tube damaged		0.40%	3.2	Visual
Minor					
201	Length		0.65%	3.2	Gage
202	Inside diameter		0.65%	3.2	Gage
203	Wall thickness, min.		0.65%	3.2	Gage
204	Crack		0.65%	3.2	Visual
205	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8848603
*4.4.2.5	Bracket				NEXT HIGHER ASSEMBLY 8848602
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
101	Mounting hole missing		0.40%	3.2	Visual
Major B					
131	Thickness, min.		0.40%	3.2	Gage
Minor					
.201	Protective coating missing or contains bare spot		0.65%	3.2	Visual
202	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8848581
#4.4.2.6	Disc				NEXT HIGHER ASSEMBLY 8848584
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Thickness, min.		0.65%	3.2	Gage
202	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
#4.4.2.7	Disc, lower	1 OF 1	8848582
			NEXT HIGHER ASSEMBLY: 8848585

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Thickness, min.		0.65%	3.2	Gage
202	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8848583
*4.4.2.8	Disc, upper				NEXT HIGHER ASSEMBLY 8848584
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Thickness, min.		0.65%	3.2	Gage
202	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 20260-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
#4.4.2.9	Disc, top				8848593
					NEXT HIGHER ASSEMBLY 8848602
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Thickness , min.		0.65%	3.2	Gage
202	Diameter		0.65%	3.2	Gage
203	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-10522K (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8848588
*4.4.2.10	Cap				NEXT HIGHER ASSEMBLY 8848602
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Cap torn or punctured		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
#4.4.2.11	Lower Disc Assembly		8848585
			NEXT HIGHER ASSEMBLY 8848599

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Lower disc missing or insecure		0.65%	3.2	Visual-Manual
202	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS MIL-S-10522K (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8848584
*4.4.2.12	Upper disc assembly				NEXT HIGHER ASSEMBLY 8848602
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Upper disc missing or insecure		0.65%	3.2	Visual-Manual
202	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8848587
*4.4.2.13	Scratcher assembly				NEXT HIGHER ASSEMBLY 8848599
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
101	Scratcher composition coating missing or unevenly distributed		0.40%	3.2	Visual
102	Scratcher composition not dry		0.40%	3.2	Manual
Minor					
201	Length, min.		0.65%	3.2	Gage
202	Width, min.		0.65%	3.2	Gage
203	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
*4.4.2.14	Whistle Assembly				8848599
					NEXT HIGHER ASSEMBLY 8848602
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Whistle tube ruptured		100%	3.2	Visual
Major A					
101	Whistle charge missing		0.40%	3.2	Visual
102	Match head composition missing or length less than min		0.40%	3.2	Visual-Scale
103	Quick match insecure or missing		0.40%	3.2	Visual-Manual
104	Pull cord damaged to extent that function may be impaired or missing		0.40%	3.2	Visual
105	Starter paste coating incomplete or missing		0.40%	3.2	Visual
106	Scratcher assembly and igniter pads improperly assembled (not permitting free passage of pull cord), insecure, or missing		0.40%	3.2	Visual-Manual
107	Lower disc assembly missing		0.40%	3.2	Visual
108	Tape missing		0.40%	3.2	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET	DRAWING NUMBER
#4.4.2.14	Whistle assembly		2 OF 2	8848599
				NEXT HIGHER ASSEMBLY 8848602

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Lower disc assembly insecure or improperly assembled		0.65%	3.2	Visual-Manual
202	Tape insecure or improperly assembled		0.65%	3.2	Visual-Manual
203	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.15	Assembly, Prior to Assembling Cap				8848602
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Pull cord insecurely taped as evidenced by a slight pull parallel to longitudinal axis of assembly		100%	3.2	Visual-Manual
Major A					
101	Upper disc assembly missing		0.40%	3.2	Visual
102	Bracket missing, damaged or insecure		0.40%	3.2	Visual-Manual
103	Pull cord missing		0.40%	3.2	Visual
Major B					
131	Upper disc assembly insecure		0.40%	3.2	Visual-Manual
132	Glue on pull cord		0.40%	3.2	Visual
133	Tape missing		0.40%	3.2	Visual
Minor					
201	Part or sub-assembly can be removed by applying a slight finger pressure		0.65%	3.2	Visual-Manual
202	Tape not properly applied		0.65%	3.2	Visual
203	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
*4.4.2.16	Assembly				8848602
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Sufficient paint leakage under cap to bond pull cord to cap		100%	3.2	Visual (Note 1)
Major A					
101	Bracket missing, damaged or insecure		0.40%	3.2	Visual-Manual
Minor					
201	Cap not assembled properly		0.65%	3.2	Visual-Manual
202	Bracket not assembled properly		0.65%	3.2	Visual
203	Bare spot on any surface		0.65%	3.2	Visual
204	Marking misleading or unidentifiable		0.65%	3.2	Visual
205	Tape pull tab missing or inadequate		0.65%	3.2	Visual
206	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES: 1. Inspection for the presence of this defect need only be performed on those assemblies upon which the tape is insecure, applied less than 360 degrees, or has wrinkles extending from tape edge to beyond cap and outer tube joint.

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
*4.4.2.17	Unsealed Inner Carton				8799716
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
101	Simulator missing or damaged		0.40%	3.2	Visual
102	Any accessory component missing or damaged		0.40%	3.2	Visual
Minor					
201	Marking missing, incorrect or illegible		0.65%	3.2	Visual
202	Carton damaged to extent contents are endangered		0.65%	3.2	Visual
203	Contents loose within carton		0.65%	3.2	Visual
204	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
#4.4.2.18	Unsealed Outer Carton	1 OF 1	8799716
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Inner carton missing or improperly sealed		0.40%	3.2	Visual
132	Inner carton damaged to extent that contents are exposed		0.40%	3.2	Visual
133	Marking misleading or unidentifiable		0.40%	3.2	Visual
134	Instruction sheet missing		0.40%	3.2	Visual
135	Carton, filler, or simulator obviously damp or wet		0.40%	3.2	Visual-Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
*4.4.2.19	Sealed Outer Carton				8799716
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Carton damaged to extent that contents are exposed		0.40%	3.2	Visual
Minor					
201	Contents loose		0.65%	3.2	Manual
202	Marking misleading or unidentifiable		0.65%	3.2	Visual
203	Sealing strip improperly applied and fails to close carton completely		0.65%	3.2	Visual
204	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
*4.4.2.20	Sealed Packed Barrier Bag, Prior to Packing in Wooden Box				8799716
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Waterproofness of barrier bag destroyed by rupture, puncture, or separation of heat seal		0.40%	3.2	Visual
132	Evidence of crushed carton		0.40%	3.2	Visual (Note 1)
133	Excess air not exhausted from bag prior to sealing		0.40%	3.2	Visual
Minor					
201	Heat seal of barrier bag located so that one or more subsequent seals cannot be applied		0.65%	3.2	Visual
202	Marking of bag misleading or unidentifiable		0.65%	3.2	Visual
203	Carton corners not blunted prior to insertion into barrier bag		0.65%	3.2	Visual
204	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

1. Package should be opened for inspection if there is evidence of crushing.

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS MIL-S-10522K (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
*4.4.2.21	Packing box, Wirebound, Prior to Sealing				8799717
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Barrier bag missing or damaged		0.40%	3.2	Visual
132	Packing component (filler) missing or improperly positioned		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
*4.4.2.22	Sealed Wirebound Packing Box	1 OF 1	8799717
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Box damaged to the extent that contents are exposed or liable to become exposed		0.40%	3.2	Visual
132	Wirebinding missing, broken, or loose		0.40%	3.2	Visual
Minor					
201	Wirebinding mislocated or improperly engaged		0.65%	3.2	Visual
202	Contents loose		0.65%	3.2	Manual
203	Marking misleading or unidentifiable		0.65%	3.2	Visual
204	Metallic seal missing, unsealed or incorrectly positioned		0.65%	3.2	Visual
205	Cleats or battens split or broken		0.65%	3.2	Visual
206	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

*4.4.3 Testing.

4.4.3.1 Moisture content. -. Major A defects - The contractor shall provide adequate controls to insure that the materials used comply with the requirements (see Table II). For verification, the contractor shall select and subject to test, one sample of each material from each 8 hours production. A composite sample shall not be used. If the moisture content of' the sample exceeds the requirement, that quantity or sub-let of material represented by the sample shall not be used in production. If the quantity or sub-lot of material with excessive moisture has been used in loading and packing, the remaining unloaded and unpacked material shall not be used in production, and the loaded and packed simulators shall be rejected. Tests shall be performed as specified in 4.5.1.

TABLE II

Material	Reference
Whistle composition	3.3.1
Match head composition	3.3.1
Fuze powder	3.3.2
Felt	3.3.3
Paper	3.3.3
Chipboard	3.3.3
Carton and carton packing material	Dwg. 8799716
Black powder	3.3.4

4.4.3.2 Determination of' match head, scratcher, and whistle compositions. - Major A defects - A sample quantity of each composition shall be selected from each batch for these determinations. If the sample fails to meet the requirements specified (see Table III), the batch shall be rejected. The test shall be performed as specified In 4.5.2.

TABLE III

Composition	Reference
Match head	Dwg. 9269240
Scratcher	Dwg. 9269237
Whistle	Dwg. 9272250

4.4.3.3 Protective coating of extension spring (dwg. 88485 2) and bracket (dwg. 8848603) - Major B defects - Sampling, acceptance, and rejection shall be in accordance

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

with QQ-Z-325 or QQ-P-416 whichever is applicable, except that actual arts may be used in lieu of specimens. The test procedure shall be as specified in 4.5.3.

4.4.3.4 Embrittlement of extension spring. - Major A defect - Fifty (50) springs shall be selected from each heat treatment lot for test. If one or more springs fail to comply with the requirements (see 3.4), the heat treatment lot shall be rejected. The test procedure shall be as specified in 4.5.4. Springs used for this test shall not be returned to the lot.

4.4.3.5 Length of trip wire. - Major B defect - A sample of twenty (20) spool assemblies shall be selected from each lot for this test. The lot shall be rejected if one (1) or more trip wires fail to meet the specified requirement (see dwg. 8848590) when tested in accordance with 4.5.5.

*4.4.3.6 functioning. - The simulator assemblies shall be observed for any evidence of failure to comply with the requirements classified in Table IV, when tested as specified in 4.5.6.1.

TABLE IV

Defect	Defect Classification	Reference
Assembly explodes	Critical	3.5.2
Failure to ignite and burn	Major A	3.5.1
Failure to whistle	Major A	3.5.1
Whistle time too short	Major B	Dwg. 8848599
Whistle time too long	Minor	Dwg. 8848599
Any part ruptures or becomes detached	Major A	3.5.2
Spring breaks or fails to function	Major A	3.4

*4.4.3.6.1 Beginning with the first lot produced and continuing until three (3) consecutive lots have complied with the applicable requirements specified, one-hundred and twenty-five (125) simulator assemblies shall be selected from each let for testing. The lot shall be rejected if during the test, one (1) or more critical defects as listed

Source: https://assist.dla.mil -- Downloaded: 202610-17T14:12Z
Check the source to verify that this is the current version before use.

in Table IV occur, if four (4) or more assemblies exhibit any of the major A defects listed in Table IV, if six (6) or more assemblies exhibit the major B defect, listed in Table IV, if seven (7) or more assemblies exhibit a combination of the major A and major B defects in Table IV, if eight (8) or more assemblies exhibit the minor defect or a combination of the major and minor defects listed in Table IV.

*4.4.3.6.2 After three (3) consecutive lots have complied with the acceptance criteria of 4.4.3.6.1, fifty (50) assemblies shall be selected from each lot for test. The lot shall be rejected if, during the test, one (1) or more critical defects as listed in Table IV occur, if two (2) or more assemblies exhibit any of the major A defects in Table IV, if three (3) or more assemblies exhibit the major B defect, if four (4) or more assemblies exhibit the minor defect or a combination of minor and major defects defects listed in Table IV.

4.4.3.7 Quick Leak Test. - Major B defect - Ten (10) cartons in sealed barrier bags shall be selected from each lot for test. If' two (2) or more packsges show evidence of air leakage during testing or water leakage when package is opened, the lot shall be rejected. The test shall be performed as specified in 4.5.7.

*4.4.4 Inspection Equipment. - The inspection equipment required to perform the inspections and tests prescribed in this specification is identified in the 'paragraph Referance/ Inspection Method' column In the tables starting with paragraph 4.4.2.1, and the test method paragraphs (see 4.5). The contractor shall submit for approval, inspection equipment designs In accordance with the terms of the contract. See Section 6 of MIL-A-48078, and section 6.3 herein.

4.5 Test methods and procedures

4.5.1 Moisture content

4.5.1.1 Moisture content of whistle composition. - An accurately weighed portion of' approximately 5 gram of composition shall be transferred to a tared moisture dish. The moisture dish and contents shall be placed in a drying oven at 85 plus or minus 5 degrees C. for four (4) hours, cooled In a desiccator and weighed. The percentage of moisture in the sample shall be calculated as follows:

$$\text{Percentage moisture} = \frac{100A}{W}$$

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

where:
A = loss In weight in grams.
W = weight of the sample in grams.

4.5.1.2 Match head composition. - An accurately weighed portion Of approximately 5 grams of composition, prior to the addition of the lacquer, shall be transferred to a tared aluminum or glass dish approximately 60 millimeters (mm) in diameter. A tight fitting cover shall be fitted to the dish. The cover shall be removed, and the dish and contents placed in a desiccator containing a suitable desiccant such as calcium chloride, calcium sulfate or sulfuric acid. The desiccator shall be maintained at a temperature of 25 plus or minus 5 degrees Centigrade (C.). The dish and contents shall remain in the desiccator until the loss in weight between subsequent weighings does not exceed 1 milligram. The loss in weight shall be calculated as follows:

$$\text{Percentage moisture} = \frac{100A}{W}$$

where:
A = loss in weight in grams.
W = weight of the sample in grams.

4.5.1.3 Fuze powder. - Prior to adding the cellulose nitrate camphor binder, If used, an accurately weighed portion of approximately two (2) grams of the fuze powder shall be transferred to a tared weighing dish or watch glass. The container and contents shall be dried for four (4) hours in an oven at 70 plus or minus 5 degrees C. The dish and contents shall then be removed, covered, cooled in a desiccator and weighed. The loss In weight shall be calculated to the percentage of moisture in the sample.

4.5.1.4 Felt, paper, chipboard, carton and carton packing material. - Ten (10) grams of each material shall be “accurately weighed and, “placed in a tared weighing dish. Each dish and contents shall be weighed and placed In an oven and dried at 100 plus or minus 2 degrees C. for two (2) hours. Each dish and contents shall be cooled in a desiccator and weighed. The loss in weight shall be calculated as percent moisture in each sample.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

4.5.1.5 Black Powder. - The moisture content of the black powder shall be determined in accordance with MIL-P-223.

4.5.1.6 Alternate method. - The moisture content shall be determined in accordance with Method 101.4 of MIL-STD-286. The timer shall be set to the minimum time required to obtain constant readings and the drying temperature shall be as specified in 4.5.1.5.

4.5.2 Determination of compositions

4.5.2.1 Match head. - Prior to adding the lacquer, a one gram sample shall be selected and analyzed as follows:

4.5.2.1.1 Antimony sulfide. - An accurately weighed portion of approximately one gram shall be transferred to a 150 milliliter (ml.) beaker. Twenty-five (25) ml. of 12N hydrochloric acid shall be added to the beaker, and heated on a steam bath for 30 minutes with occasional stirring, and then filtered into a tared medium porosity glass crucible with suction. The beaker and contents of the crucible shall be washed with a two-percent solution of hydrochloric acid and finally with four 5 ml. portions of water.

The crucible and contents shall be dried in an oven maintained at 100 plus or minus 5 degrees C. for one hour, cooled in a desiccator for 1 hour and weighed. The residue shall be saved for the red phosphorous determination (paragraph 4.5.2.1.2). The percentage of antimony sulfide in the sample shall be calculated as follows:

$$\text{Percentage of antimony sulfide} = \frac{A-[(B-C)+(DE)]x100}{A}$$

where:

A = weight of sample
B = weight of glass crucible and residue.
C = weight of glass crucible.
D = loss In weight of crucible and contents after extraction with 15N nitric acid as determined In 4.5.2.1.3.
E = factor required by the volubility of red phosporus in hydrochloric acid (see 4.5.2.1.2).

4.5.2.1.1.1 Calculation of factor E. - From the lot of red phosphorus used in the manufacture of the match head

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

composition, 0.5300 plus or minus 0.0010 gm. shall be transferred to a 150 ml. beaker and 25 ml. of 12N hydrochloric acid added. The beaker and contents shall be heated on a steam bath for 30 minutes, stirred occasionally, and then filtered with the aid of a tared, medium porosity, glass crucible and suction. The beaker and contents of the crucible shall be washed with a two-percent solution of hydrochloric acid and finally with four 5 ml. portions of water. The crucible and residue shall be dried in an oven maintained at 100 plus or minus 5 degrees C. for one hour, cooled in a desiccator for 15 minutes, and weighed. The loss in weight of the crucible and contents shall be calculated to percentage of red phosphorus soluble in 12N hydrochloric acid, The factor represented by the letter E, given in the equation for calculating the percentage of' antimony sulfide, shall be calculated as follows:

$$E = \frac{F}{G}$$

where:

F = percent solubility of the red phosphorus used in the composition, expressed as a decimal fraction.

G = percent of volubility of the red phosphorus subtracted from 100 and the result expressed as a decimal fraction.

4.5.2.1.1.2 In the course of analysis of samples of match head composition, the volubility In hydrochloric acid of red phosphorus shall be recorded whenever practicable.

4.5.2.1.2 Red phosphorus. - The residue obtained in 4.5.2.1.1 shall be transferred from the glass crucible to a 150 ml. glass beaker with the aid of a stirring rod and five 5 ml. porti. ons of 15N nitric acid. The crucible shall be rinsed with four 5 ml. portions of distilled water, and the rinsings caught in the beaker. The contents of the beaker shall be heated on a steam bath for one hour and filtered into the previously used crucible using suction. The beaker and contents shall be washed with four 5 ml. portions of distilled water. The crucible and residue shall be dried in an oven maintained at 100 plus or minus 5 degrees C. for one hour, cooled In a desiccator for one hour and weighed. Percentage of red phosphorus In the sample shall be calculated as follows:

$$\text{Percentage of red phosphorus} = \frac{100D}{FA}$$

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

where:

D = loss in weight of crucible and contents due to extraction with 15N nitric acid.
F = factor obtained by subtracting the percent volubility of the red phosphorus from 100 and expressing the result as a decimal fraction
A = weight of sample.

4.5.2.1.3 Charcoal. - Percentage of charcoal in the sample shall be calculated as follows:

$$\text{Percentage of charcoal} = \frac{G-C}{A} \times 100$$

where:

G = weight of crucible and charcoal.
C = weight of crucible.
A = weight of sample.

4.5.2.2 Scratcher composition. - A one gram sample shall be selected from each batch of scratcher composition and analyzed as specified in the following paragraphs.

4.5.2.2.1 Antimony sulfide. - An accurately weighed portion of approximately one gram of the sample of scratcher composition which has been previously dried at 100 plus or minus 5 degrees C., shall be transferred to a 150 ml. beaker. Fifty (50) ml. of water shall be added to the beaker, the contents heated on a steam bath for one hour, and filtered using a tared, medium porosity sintered glass filtering crucible. The beaker and residue shall be washed five times with hot water, and the residue caught In the above mentioned crucible. The crucible" and contents shall be dried for one hour at 100 to 105 degrees C., cooled In a desiccator and weighed. The filtrate shall be retained for the determination of potassium chlorate and dextrin. The gain in weight of the crucible shall be calculated to percentage of antimony sulfide in the sample.

4.5.2.2.2 Potassium chlorate. - The filtrate obtained in 4.5.2.2.1 shall be diluted to 250 ml. in an accurately calibrated volumetric flask. A 25 ml. aliquot shall be transferred with a calibrated pipette to a 500 ml. Erlenmeyer flask, diluted to approximately 150 ml. and approximately 50 ml. of 18N sulfuric acid shall be added. The flask shall be stoppered with a rubber stopper equipped with a Bunsen valve and the contents heated

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

almost to boiling. Fifty (50) ml. of a standardized solution of approximately four Percent ferrous ammonium sulfate (Mohr's Salt) shall be added, using a calibrated pipette, and the solution boiled for two minutes, cooled, the valve loosened and the excess of Mohr's Salt titrated with a standardized 0.1N potassium permanganate. Concurrently conduct a blank determination using the same quantities of the reagents used for the analysis of the sample. The percentage of potassium chlorate in the sample shall be calculated as follows:

$$\text{Percentage of potassium chlorate} = \frac{0.2043(V-v)(N)(100)}{W}$$

where:

V = volume of potassium permangenate required for blank titration, ml.
v = volume of potassium permanganate required for sample titration, ml.
N = normality of potassium permanganate solution.
W = weight of original sample, gm.

4.5.2.2.3 Dextrin. - The percentage of dextrin in the sample shall be calculated by subtracting from 100 the combined percentages of antimony sulfide and potassium chlorate.

4.5.2.3 Whistle composition

4.5.2 .3.1 A ten (10) gram sample of the composition shall be selected and analyzed as follows:

4.5.2 .3.1.1 Red gum. - Quantitatively transfer an accurately weighed portion of approximately 5.0 gm. of the ground and blended sample to a tared medium porosity glass crucible of 30 ml. capacity containing a small stirring rod. Place the crucible on a tall form Fisher Filtrator containing a clean 200 ml. volumetric flask. To the crucible add 20 ml. of distilled water heated to 60-70 degrees C. Stir the contents of the crucible for approximately one minute and allow the water to , remain In contact with the aqueous extraction for at least three (3) minutes before applying suction. The water extraction shall be repeated four (4) times each time catching the wash in the volumetric flask. Aspirate the crucible and contents for approximately 10 minutes, and then place it In an oven maintained at 80 plus or minus 2 degrees C. for 3 hours. Reserve the filtrate for the potassium perchlorate determination. Remove

Source: https://assist.dla.mil -- Downloaded: 202610-17T14:12Z
Check the source to verify that this is the current version before use.

the crucible and contents from the oven after the three hour drying period, cool in a desiccator and weigh. Calculate the percentage of red gum as follows:

$$\text{Percentage of red gum} = \frac{A-B}{W} \times 100$$

where:

A = weight of crucible and contents after the water extraction.
B = weight of the empty crucible.
W = weight of the original sample.

4.5.2.3.1.2 Potassium perchlorate. - Carefully rinse the funnel of the filtrator in the above extraction with a stream of warm distilled water (50 to 60 degrees C.) collecting the washings in the volumetric flask. Cool the washings to room temperature then dilute the volumetric flask with distilled water to the mark and mix. With the aid of a 20 ml. pipette, quantitatively transfer a 20 ml. aliquot of the filtrate to a 50 ml. capacity platinum evaporating dish. Place the platinum dish and contents on a hot plate and carefully evaporate the contents to near dryness. Complete the evaporation to dryness on a steam bath. Place the platinum dish in a cold muffle furnace, heat to 600 degrees C. and maintain this temperature for 1-1/2 hours. Remove the dish from the muffle furnace, cool and quantitatively transfer the residue to a clean 400 ml. beaker, with the aid of a steam of hot distilled water. Dilute the filtrate to about 200-250 ml. with distilled water. Add 4 ml. of a 35 percent nitric acid solution and mix, with a stirring rod, during the addition of 50 ml. of a 10 percent silver nitrate solution. Heat the beaker and contents on a steam bath until the supernatent solution is clear. Collect the precipitate in a tared crucible and wash with four 15 ml. portions of a 1 percent nitric acid solution. Dry the crucible and contents In an oven at approximately 135 degrees C. for 1-1/2 hours. Cool in a desiccator and weigh. Calculate the percentage of potassium perchlorate in the sample as follows:

$$\text{Percentage potassium perchlorate} = \frac{966.6B}{W}$$

where:

B = gain In weight of the crucible.
W = weight of original sample.

Source: https://assist.dla.mil -- Downloaded: 202610-17T14:12Z
Check the source to verify that this is the current version before use.

4.5.2.3.1.3 Sodium Sallcylate. - Add the percentages of red gum and potassium perchlorate found and subtract from 100 percent.

4.5.3 Protective coating of extension spring and bracket. - The adequacy-of the protective coating shall be tested in accordance with the procedures specified in QQ-Z-325 or QQ-P-416 whichever is applicable. (Destructive tests)

4.5.4 Embrittlement of extension spring. - The spring shall be stretched-along its longitudinal axis until it no longer returns to its original position. When the spring no longer returns to its original length or profile it shall be considered permanently distorted. Any spring that breaks during the test shall be classed defective. Springs subjected to test shall not be returned to the lot. (Destructive test)

4.5.5 Length of trip wire. - The trip wire shall be unwound from-the spool assembly and its length measured to determine compliance with the specified requirement. (instructive test)

4.5.6 Functioning. - The following functioning test, in accordance with Acceptance Test Procedure, SIM-BTW- (latest revision) shall be performed at a Government proving ground. (Destructive test).

4.5.6.1 Functioning. - The simulator assemblies shall be mounted in accordance with instructions on dwg. 8848620. The assemblies shall be ignited by cutting the trip wire. Burning time shall be determined using equipment In accordance with 4.4.4.

4.5.6.2 Test validity. - If for any reason the proving ground considers that the test conditions have detrimentally affected the test results, the test shall be declared invalid and a new test performed with additional samples.

4.5.7 Quick leak test (Vacuum Differential Method). - The filled and sealed packages, after conditioning at ambient temperature (70 plus or minus 5 degrees F.) for at least four (4) hours, shall be tested for leakage by submerging In water contained In a vacuum vessel. A vacuum differential of 216mm (8 1/2 inches) of mercury from ambient conditions shall be drawn and held for 30 seconds (minimum) while observing for leakage of air. Repeat

Source: https://assist.dla.mil -- Downloaded: 202610-17T14:12Z
Check the source to verify that this is the current version before use.

the test after inverting the sample. A steady stream or recurring succession of bubbles from any surface or seam shall be cause for rejection. Where there is no emission of bubbles observed, the package shall be dried, opened and inspected. Evidence of water within the barrier, or on the carton shall also be cause for rejection. (Destructive test)

*5. PREPARATION FOR DELIVERY

5.1 Preservation and packaging

*5.1.1 Level A. - The simulator assemblies and accessories shall be preserved and packaged in accordance with dwg. 8799716.

5.2 Packing

*5.2.1 Level A. - The cartons shall be packed in accordance with dwg. 8799717.

*5.3 Marking. - Marking shall be in accordance with dwgs. 8799716 and 799717.

*6. NOTES

*6.1 Intended Use. - The whistling booby trap simulator M119 is designed to be used in training to simulate actual booby traps.

*6.2 Ordering Data. - Procurement documents shall specify the following:

a. Title, number and date of this specification.

b. Provisions for submission of first article samples. First article submission requirements should stipulate necessary conditions for the forwarding of samples to the proving grounds.

c. provisions of MIL-A-48078.

*6.3 Submission of Inspection Equipment Designs for Approval. - (See MIL-A-48078). Submit equipment designs as required, to Commander: Picatinny Arsenal, ATTN: SARPA-QA-T Dover, New Jersey 07801.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

*6.4 Distribution of ammunition data cards. - Distribution of data cards shall include the following: Commander, Picatinny Arsenal, ATTN: SARPA-QA-A-M, Dover, New Jersey 07801.

6.5 Proving Ground Functioning Test Summary

Test	Production Lots		Requirements
	First Article	First three Consecutive Acceptable"	Remaining	
Functioning	50	125	50	see 3.5 and Table IV

*6.6 The margins of this specification are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous issue were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous. issue.

Custodian:
Army-PA

Preparing Activity:
Army-PA

Project Number: 1370-A-044

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

INSTRUCTIONS: In a continuing effort to make our standardization documents better, the DoD provides this form for use in submitting comments and suggestions for improvements. All users of military standardization documents are invited to provide suggestions. This form may be detached, folded along the lines indicated, taped along the loose edge *(DO NOT STAPLE)*, and mailed. In block 5, be as specific as possible about particular problem areas such as wording which required interpretation, was too rigid, restrictive, loose, ambiguous, or was incompatible, and give proposed wording changes which would alleviate the problems. Enter in block 6 any remarks not related to a specific paragraph of the document. If block 7 is filled out, an acknowledgement will be mailed to you within 30 days to let you know that your comments were received and are being considered.

NOTE: This form may not be used to request copies of documents, nor to request waivers, deviations, or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document*(s)* or to amend contractual requirements.

(Fold along this line)

(Fold along this line)

DEPARTMENT OF THE ARMY

NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

BUSINESS REPLY MAIL
FIRST CLASS PERMIT NO. 12062 WASHINGTON D. C.
POSTAGE WILL BE PAID BY THE DEPARTMENT OF THE ARMY

Commander
US Army Armement Research and Development Command
ATTN: DRDAR-TST-S
Dover, NJ 07801

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

(See Instructions – Reverse Side)

1. DOCUMENT NUMBER	2. DOCUMENT TITLE

3a. NAME OF SUBMITTING ORGANIZATION	4. TYPE OF ORGANIZATION *(Mark one)*
	☐ VENDOR
b. ADDRESS *(Street, City, State, ZIP Code)*	☐ USER
	☐ MANUFACTURER
	☐ OTHER *(Specify)*: _____

5. PROBLEM AREAS

a. Paragraph Number and Wording:

b. Recommended Wording:

c. Reason/Rationale for Recommendation:

6. REMARKS

7a. NAME OF SUBMITTER *(Last, First, MI)* – Optional	b. WORK TELEPHONE NUMBER *(Include Area Code)* – Optional
c. MAILING ADDRESS *(Street, City, State, ZIP Code)* – Optional	8. DATE OF SUBMISSION *(YYMMDD)*

Source: https://assist.dla.mil -- Downloaded: 2026/10-17T14:12Z
Check the source to verify that this is the currentversion before use.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T14:12Z
Check the source to verify that this is the current version before use.