MIL-F-50983B (AR)
AMENDMENT 7
06 June 1983
SUPERSEDING
AMENDMENT 6
17 May 1983

MILITARY SPECIFICATION

FUZE, MT, SQ, M577
LOADING, ASSEMBLING, PACKING AND METAL PARTS
FUZE, MT, SQ, M582 METAL PARTS

This amendment forms a part of Military Specification MIL-F-50983B (AR), dated 30 June 1980, and is approved for use by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 3

3.7: Delete in its entirety.

PAGE 5

Add the following new paragraphs:

"3.19 Barrel housing static load. The barrel housing (dwg. 9236688) shall not fracture when a load as specified on the applicable drawing is applied.

3.20 Rotor, SSD (see dwg. 11786092). The rotor teeth shall not fracture when a load as specified on the applicable drawing is applied."

PAGE 6

4.3.1: To the group entitled 15 each, delete: "9236518".

To the group entitled 15 each, add: "9236729, 9236730 and 9236731".

To the group entitled 15 each, delete: "9236540" and add "11786095."

To the group entitled 50 each, delete: "9236528, 9236537, 9236604" and add "11786090, 11786093 and 9357827."

PAGE 7

4.3.1: To the group entitled 50 each, Add "9236712, 9236733".

FSC 1390

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

PAGE 22

4.4.2.13: Add the following major defects:

Major category:

"Major 103	Die casting defect	10	a	3.17	Visual w/aid C
Major 104	Static load test	10	a	3.19	4.5.22."

To the block entitled notes, add the following:

"a. Reject the lot if one (1) or more defective units are found."

PAGE 23

* 4.4.2.14: To the block entitled Drawing Number, delete: "9236685".

* Delete Major defect category "101" in its entirety.

PAGE 45

4.4.2.36: To the block entitled Drawing Number, add: "9236712 and 9236733".

To the block entitled Next Higher Assembly, add: "9236711 and 9236732".

PAGE 46

4.4.2.37: To the block entitled Drawing Number, add: "9236732".

Add:

Category	Examination	No. of Sample Units	AQL or 100%	Reqmt. Para.	Para. Ref. Insp Method
"112	91b. axial load	d	e	3.2	4.5.1ae".

Note b, add: "and 9236742".

Note c, add "and 9236732".

To block entitled Notes, add "d. Destructive. See paragraph 4.4.3.7 for applicable sample plan."

To block entitled Notes, add "e. Reject the Timer Assembly inspection lot if one (1) or more defective units are found."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

PAGE 54

4.4.2.45: In the block entitled drawing number, delete "9236619" and substitute "9357826."

PAGE 62

4.4.2.53, add the following Major defects:

"Major category:

Major 107: True position of safety plate pivot hole 0.40% 3.2 Gage

Major 108: Diameter of safety plate pivot hole, max 0.40% 3.2 Gage."

PAGE 63

4.4.2.54: Delete in its entirety and substitute the following new paragraph 4.4.2.54.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.54	Spacer, Trigger		9357827
			NEXT HIGHER ASSEMBLY
			9236603

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	True position of top pins		0.40%	3.2	Gage
102	True position of bottom pins		0.40%	3.2	Gage
103	25 lb. axial unseating load on bottom pins	80a	b	3.2	4.5.1.u
104	5 lb. axial unseating load on top pins	80a	b	3.2	4.5.1.v
105	Height of bottom pins above spacer surface		0.65%	3.2	Gage
106	Height of top pins above spacer surface		0.65%	3.2	Gage
107	True position of release lever pivot hole		0.40%	3.2	Gage
108	Diameter of release lever pivot hole max.		0.40%	3.2	Gage
109	Density incorrect	10c	d	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

a. Destructive.
b. Reject the lot if two (2) or more defective units are found.
c. Destructive.
d. ~~Reject the lot if one (1) or more defective units are found.~~
e. Alternative "Compressive Load Test" may be performed in lieu of Inspections 107 and 108. See para. 4.4.2.56 Trigger Assembly.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

PAGE 64

4.4.2.55: Delete in its entirety.

PAGE 73

4.4.2.64: To block entitled Drawing Number, delete "9236575" and substitute "9345286".

PAGE 75

* 4.4.2.66, Minor defect 108: Delete "9.0 + 4.0 in. lb." and substitute "10.0 + 4.0 in. lb."

PAGE 78

4.4.2.68: To block entitled Drawing Number, delete "9236562" and substitute "9345287".

Add the following:

Category	Examinations	No. of Sample Units	AQL or 100%	Req'mt Para.	Para Ref Insp. Method
"105	Height of ribs	-	0.40%	3.2	Gage".

PAGE 79

4.4.2.69: Delete in its entirety.

PAGE 80

4.4.2.70: Add the following:

Category	Examination	No. of Sample Units	AQL or 100%	Req'mt Para.	Para. Ref. Insp. Method
"103	Detonator(s) missing or inverted		0.40%	3.2	Visual
104	Crimp missing over detonator holder		0.40%	3.2	Visual
			0.40%	3.2	Visual
105	Tape missing		0.40%	3.2	Visual
106	Detonator(s) not positioned over MDF		0.65%	3.2	Visual"

PAGE 87

4.4.2.77: In the block entitled drawing number, delete "9236541" and substitute "11786096".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

In the block entitled next higher assembly, delete "9236540" and substitute "11786095".

Delete category 102 in its entirety.

PAGE 88

4.4.2.78: In the block entitled drawing number delete "9236540" and substitute "11786095".

Delete category 1 in its entirety.

After critical, in the examination or test column, add "None defined."

PAGE 89

4.4.2.79: IN the block entitled Next Higher Assembly delete "9236537" and substitute "11786093".

PAGE 90

4.4.2.80: In the block entitled drawing number delete "9236537" and substitute "11786093".

PAGE 93

4.4.2.83: In the block entitled drawing number delete "9236529" and substitute "11786091".

In the block Next Higher Assembly delete "9236528" and substitute "11786090".

PAGE 94

4.4.2.84: In the block entitled drawing number delete "9236528" and substitute "11786090".

Delete category 101, 102, and 104 and Note "c" in their entirety.

PAGE 97

4.4.2.87: To the block entitled Title, delete "Element, Crush" and substitute "Plug, Retainer".

To the block entitled Drawing Number, delete "9236518" and substitute "9236731".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

To the block entitled Next Higher Assembly, delete "9236516" and substitute "9236729".

To the block entitled Examination or Test, delete "Static Load Test" and substitute "Outside diameter".

To the block entitled No. of Sample Units: Delete "40a".

To the block entitled AQL or 100%, delete "b" and substitute "0.40%".

To the block entitled Paragraph Reference/Inspection Method, delete "4.5.1f" and substitute "Gage".

To the block entitled Notes: Delete Note a and Note b in their entirety.

PAGE 98

4.4.2.88, to the block entitled Drawing Number, delete "9236516" and substitute "9236729".

To the block entitled Examination or Test, delete "Crush retainer missing" and substitute "Plug retainer missing".

To the block entitled Examination or Test, delete "Crush element missing" and substitute "Axial static load test".

Major 102, to the block entitled No. of Sample Units, add "40a".

To the block entitled AQL or 100%, delete "0.40%" and substitute: "b".

To the block entitled Paragraph Reference/Inspection Method, delete "Manual" and substitute "4.5.1.f".

To the block entitled Notes: Add "a. Destructive".

To the block entitled Notes: Add "b. Reject the lot if one (1) or more defective units are found."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

4.4.2.96, delete category 101 in its entirety.

Add the following defect classification:

Category	Examination or Test	No. of Sample Units	AQL or 100%	Req. Para.	Para Ref./ Insp. Method
Info					
300	ICM Ballistic Mechanical Time Test	10	-	-	4.5.21.6

Add new paragraphs 4.4.2.100, 4.4.2.101, and 4.4.2.102.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.100	Spacer & Plate Assembly, SSD	1 OF 1	9236552
			NEXT HIGHER ASSEMBLY: 9236526

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Rotor lock does not return to dimension indicated after being depressed to surface "x".		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)
AMENDMENT 7

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.101	Lever, SSD		11786097
			NEXT HIGHER ASSEMBLY 11786095

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Profile incorrect		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:

10

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-50983B (AR)
AMENDMENT 7

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.102	Rotor, SSD	1 OF 1	11786092
			NEXT HIGHER ASSEMBLY: 11786090

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Die casting defect	10	a	3.17	Visual w/aid C
102	Torque on rotor teeth	10b	a	3.20	4.5.23
Minor					
201	Evidence of poor workmanship		1.0%	3.3	Visual

NOTES:
a. Reject the lot if one (1) or more defective units are found.
b. Non-destructive.

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

PAGE 110

4.4.3.3, delete in its entirety and substitute:

"4.4.3.3 Forty (40) foot drop. Beginning with the first article sample and continuing until three (3) additional consecutive production lots have complied with the acceptance criteria specified herein, a sample as specified in 4.4.2.96 shall be randomly selected from each lot and subjected to the tests as specified in 4.5.18. If one or more assemblies are found defective, the lot shall be rejected. After three consecutive lots are found acceptable, the test shall be discontinued. A first article sample shall be submitted, when necessary, as required by 4.3.1."

4.4.3.3.1, 4.4.3.3.2: Delete in their entirety.

PAGE 111

4.4.3.4, 4.4.3.4.1, 4.4.3.4.2: Delete in their entirety.

PAGE 112

Add: "4.4.3.7 Axial load test. The Timer Hair-spring and Timer Support and Pivot Assembly samples selected for the axial load test shall be randomly selected from each batch used to assemble the Timer Assembly inspection lot. One sample shall be welded at the beginning of the Timer Assembly inspection lot manufacturing period, two samples shall be welded at random times during the period and one sample at the end of the same period. The samples shall contain the number of welds specified on drawing 9236711 and shall be welded on the equipment used to manufacture the Timer Assembly inspection lot using the same equipment lot using the same equipment parameters (tip, frequency, pressure and energy). The equipment parameters used during an inspection lot manufacturing period shall be recorded. If prior to welding the required number of test samples, the inspection lot manufacturing period is interrupted and can not be continued on the same equipment with the same parameters. Timer Assemblies shall be selected from the inspection lot as test samples. The last Timer Assembly of the inspection lot manufacturing period shall be selected and, if necessary, Timer Assemblies shall be randomly selected from the same period. A Timer Assembly inspection lot shall consist of a maximum of two (2) hours production and manufactured on the same equipment and the same equipment parameters".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

PAGE 114

4.5.1, Table I, subparagraph f: Delete "Crush Element (Dwg. 9236518)" and substitute "Setting Key Assembly (Dwg. 9236729)".

Table I, subparagraph h. and j.: Delete in their entirety.

Table I, subparagraph i., delete, "dwg. 9236528" and substitute "dwg. 11786090".

PAGE 115

4.5.1, Table I, subparagraph l, delete "dwg. 9236537" and substitute "dwg. 11786093".

Table I, subparagraph m., delete "dwg. 9236540" and substitute "dwg. 11786095".

Table I, subparagraph q., delete in its entirety.

PAGE 116

4.5.1, Table I, subparagraph s: Delete in its entirety.

Table I, subparagraph u., delete "Pin, spacer assembly (dwg. 9236604)" and substitute "Pin, spacer trigger (dwg. 9357827)"

Under Load & Application column delete "35 lb." and substitute "25 lb.".

Table I, subparagraph v, delete "Pin, spacer assembly (dwg. 9236604)" and substitute "Pin, spacer trigger (dwg. 9357827)".

PAGE 117

4.5.1, Table I, subparagraph ab: Add "9236733".

Table I, subparagraph ac: Add "9236733".

Table I, subparagraph ad: Add "9236733".

Table I, subparagraph ae: Add "9236733".

Table I, subparagraph ae: Delete "9236712".

PAGE 121

4.5.2, Table II, subparagraph d: Add "9236733".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

* 4.5.2, Table II, subparagraph c, delete: "9.0 + 4.0 in. lb." and substitute "10.0 + 4.0 in. lb."

PAGE 122

* 4.5.3, Table III, delete: Subparagraph "d".

PAGE 127

4.5.19: Delete in its entirety.

PAGE 131

4.5.21.3.4, second and third line: Delete "and the suspect value falls outside the function time limits".

Add the following new paragraphs:

"4.5.21.6 Improved conventional munitions ballistic mechanical time test (information only). The fuzes shall be assembled to the M483A1 projectile. Five projectiles shall contain inert cargo and contain an expulsion charge. Five projectiles shall be inert loaded and contain a self registration charge. The projectiles shall be fired from the M185 cannon using the M119 series propelling charge. An 82 second fuze time setting shall be used and the fuze time of function or failure to function shall be recorded. The test method for measuring fuze time shall be the same as paragraph 4.5.21.3.

4.5.22 Static load test of barrel housing. The barrel housing shall be placed in a sleeve (dwg. 9236631). The load specified on the drawing shall be applied to the entire barrel housing shoulder at a deflection rate of less than 0.100 inches per second.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

4.5.23 Torque of rotor teeth. The rotor shall be placed in a suitable test fixture and the torque specified on the drawing shall be applied. After the test, the rotor teeth shall be examined for compliance with the requirements of 3.20."

The margins of this amendment are marked with an asterisk to indicate where changes from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army - AR

Preparing activity:
Army - AR

(Project 1390-A393)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.