MILITARY SPECIFICATION

CHARGE, PROPELLING, 8 INCH, M188A1 LOADING, ASSEMBLING, AND PACKING

This specification is approved for use by the US Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification covers the loading, assembling and packing for one type of propelling charge designated as Charge, Propelling, M188A1 for 8 Inch Howitzer, M110A2.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposals form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-P-223 - Powder, Black
MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specification For

DRAWINGS

ARRADCOM

PRODUCT AND PACKAGE DRAWINGS

FSC: 1320

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

9312720 - Packing and Marking for Container, Ammo, Metal PA66 for Charge Propelling 8 Inch, M188A1 for, How. SP, M110A2
9312712 - Charge, Propelling, 8 Inch, M188A1 for 8 Inch Howitzer, SP, M110A2

3. REQUIREMENTS

3.1 Materials.-Materials shall be in accordance with applicable drawings and specifications.

3.2 Propelling Charge.-The propelling charge shall comply with all requirements specified on drawing 9312712 and with all requirements specified in applicable specifications.

3.3 Moisture Content of Black Powder.-The moisture content of the black powder at the loading station at the time of loading shall not exceed the amount specified in MIL-P-223.

3.4 Weights

3.4.1 Weight of Propellant.-The propellant weight shall comply with the weight specified in the loading authorization within the following tolerance:

Increment Number	Tolerance Plus or Minus (±) Ounces
8	0.4
9	0.2

The propellant for Increment 8 may be determined by weighing 50 percent of the loading authorization of Increment 8 twice to a tolerance of 0.2 ounces.

3.4.2 Charge, Propelling Assembly Weight.-The weight of the propelling charge prior to packing shall not differ by more than 1.0 ounce from the total of the amount specified in the loading authorization plus actual or average weights of the empty increments, flash reducer, lacing cord, lacing jacket, and loaded base igniter and tube assembly. (See 6.8).

3.4.3 Base Igniter and Tube Assembly Weight.-(see 6.8).

3.4.3.1 Actual Weight of Tube.-The loaded base igniter and tube assembly weight shall not differ by more than 0.25

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

ounce from the nominal black powder weight plus the actual weight of the tube, actual weight or average weight of the base igniter assembly, and average weight of cap.

3.4.3.2 Average Weight of Tube.-The loaded base igniter and tube assembly weight shall not differ by more than 0.30 ounce from the nominal black powder and average tube weight plus the actual weight or average weight of the base igniter assembly and average weight of the cap.

3.4.4 Flash Reducer Assembly Weight.-The flash reducer assembly weight shall not differ by more than 0.55 ounce from the nominal black powder and potassium sulfate weights plus the average weight of the flash reducer body assembly.

3.5 Dimensional Gage

3.5.1 Maximum Length and Diameter.-The completed charge shall freely enter the prescribed gage. The gage shall be designed to inspect the maximum diameter and length. If the diameter feature is separate from the length feature, the diameter feature must extend approximately the full length of the charge.

3.5.2 Minimum Diameter.-The base end of the completed charge shall not freely enter the prescribed gage greater than two inches.

3.6 Workmanship.-All components shall be free of dirt, grease and other foreign material. There shall be no discoloration or deterioration of cloth and no evidence of rips, tears, or other cloth defects. All work performed shall be performed in a thorough workmanlike manner.

3.7 Proving Ground.-The muzzle velocity, pressure, and velocity standard deviation shall be as specified in Table I. (See 6.12).

TABLE I

Zone	Proj.	Temp	Velocity (feet per second) Minimum	Velocity (feet per second) Maximum	Velocity Standard Deviation FPS	Individual* Maximum Pressure PSI
Chg. 8	M106	70°F	2295	2365	6.5	34,500
Chg. 9	M106	70°F	2495	2565	6.5	42,100
Chg. 9	M106	145°F (Differential Pressure)				48,100
Chg. 9	M106	-50°F (Differential Pressure)				NA

*See 6.14

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

3.7.1 Differential Pressure

3.7.1.1 Hot Firings.-No individual differential pressure shall exceed 7000 psi. If the mean plus three (3) times the standard deviation exceeds 7000 psi, the lot will be referred (See 6.13).

3.7.1.2 Cold Firings.-No individual differential pressure shall exceed 3500 psi. If the mean plus three (3) times the standard deviation exceeds 3500 psi, the lot will be referred (See 6.13). In addition if any individual ignition delay exceeds 200 milliseconds, or if the mean plus three (3) times the standard deviation exceeds 200 milliseconds, the lot will be referred (see 6.13).

3.8 Complete Igniter Alignment.-An approved method of centering the complete igniter assembly in the increment assembly will be utilized for all charges.

3.9 Igniter Tubes.-All tubes shall be free of cracks, dents, creases, tears, flat areas, and softness greater than 0.25 square inch.

3.10 Assembly Torque.-The packing container test plug shall be assembled to withstand subsequent reapplication of the minimum assembly torque specified on the applicable drawing, without moving.

3.11 First Article Inspection.-This specification contains technical provisions for the first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for Inspection and Standard Quality Assurance Provisions.-Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of Inspections.-The following types of inspection shall be conducted on this item:

a. First Article Inspection

b. Quality Conformance Inspection

4.3 First Article Inspection

4.3.1 Submission.-The contractor shall submit a First Article Sample from the first weeks production as designated by the Contracting Officer for evaluation in accordance with the provisions of 4.3.2. The first article sample shall consist of the following:

Source: https://assist.dla.mil -- Downloaded: 202640-23T02:16Z
Check the source to verify that this is the current version before use.

Part Description	Drawing	Quantity
Strap Tying	9277188	5
Bag, Charge	9277277	5
Charge Bag Assembly	9277276	5
End, Base Igniter Marking	9277169	5
End, Base Igniter	9277171	5
Base Igniter End and Charge Bag Assembly	9281791	5
Base Igniter Assembly	9277167	5
Base Igniter and Charge Cap	9289130	5
Base Igniter and Tube Assembly	9285356	5
Increment 8 Body	9277179	5
Increment 8 Body and Liner Assembly	9277176	5
End, Increment 8	9277183	5
End Assembly, Increment 8	9277182	5
Increment 8 Body Assembly	9277178	5
Increment 8 Loading Assembly	9277175	5
Increment 9 Body	9312729	5
End, Increment 9	9312724	5
Increment 9 End Assembly	9312725	5
Increment 9 Assembly	9312726	5
Increment 9 Loading Assembly	9312727	5
Jacket, Lacing	9312731	5
Flash Reducer Body	9299190	5
Flash Reducer Body Assembly	9299189	5
Flash Reducer Assembly	9299188	5
Charge, Propelling, 8 Inch M188A1 for 8 Inch Howitzer, SP, M110A2, in Sealed Containers	9312712/ 9312720	10

4.3.2 Inspections to be Performed.-The First Article parts submitted in accordance with paragraph 4.3.1 will be subjected by the Government to any or all the requirements of the applicable drawings and specifications and to the inspections of Table I. All inspections listed in Table I shall be classified Major unless otherwise specified in referenced paragraphs and specifications.

4.3.3 Rejection.-See MIL-A-48078.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 5	DRAWING NUMBER
	Propelling Charge Components and Assemblies		NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Strap, Tying (Dwg. 9277188) Examination for Defects	5		3.2	4.4.2.1
	Bag, Charge (Dwg. 9277277) Examination for Defects	5		3.2	4.4.2.2
	Charge Bag Assembly (Dwg. 9277276) Examination for Defects	5		3.2	4.4.2.3
	End, Base Igniter Marking (Dwg. 9277169) Examination for Defects	5		3.2	4.4.2.4
	End, Base Igniter (Dwg. 9277171) Examination for Defects	5		3.2	4.4.2.5
	Base Igniter End and Charge Bag Assembly (Dwg. 9281791) Examination for Defects	5		3.2	4.4.2.6
	Base Igniter Assembly (Dwg. 9277167) Examination for Defects	5		3.2	4.4.2.7

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE		SHEET 2 OF 5		DRAWING NUMBER
	CONTINUATION SHEET				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Base Igniter and Charge Bag Loading Assembly (Dwg. 9281794) Examination for Defects	5		3.2	4.4.2.8
	Cap (Dwg. 9289130) Examination for Defects	5		3.2	4.4.2.9
	Base Igniter and Tube Assembly (Dwg. 9285356) Examination for Defects	5		3.2	4.4.2.10
	Increment 8 Body (Dwg. 9277179) Examination for Defects	5		3.2	4.4.2.11
	Increment 8 Body and Liner Assembly (Dwg. 9277176) Examination for Defects	5		3.2	4.4.2.12

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE		SHEET 3 OF 5		DRAWING NUMBER
	CONTINUATION SHEET				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	End, Increment 8 (Dwg. 9277183) Examination for Defects	5		3.2	4.4.2.13
	End Assembly, Increment 8 (Dwg. 9277182) Examination for Defects	5		3.2	4.4.2.14
	Increment 8 Body Assembly (Dwg. 9277178) Examination for Defects	5		3.2	4.4.2.15
	Increment 8 Loading Assembly (Dwg. 9277175) Examination for Defects	5		3.2	4.4.2.16
	Increment 9 Body (Dwg. 9312729) Examination for Defects	5		3.2	4.4.2.17
	End, Increment 9 (Dwg. 9312724) Examination for Defects	5		3.2	4.4.2.18

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-63125 (AR)

PARAGRAPH	TITLE			SHEET 4 OF 5	DRAWING NUMBER / NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	CONTINUATION SHEET				
	Increment 9 End Assembly (Dwg. 9312725) Examination for Defects	5		3.2	4.4.2.19
	Increment 9 Assembly (Dwg. 9312726) Examination for Defects	5		3.2	4.4.2.20
	Increment 9 Loading Assembly (Dwg. 9312727) Examination for Defects	5		3.2	4.4.2.21
	Jacket, Lacing (Dwg. 9312731) Examination for Defects	5		3.2	4.4.2.22
	Flash Reducer Body (Dwg. 9299190) Examination for Defects	5		3.2	4.4.2.23
	Flash Reducer Body Assembly (Dwg. 9299189) Examination for Defects	5		3.2	4.4.2.24
	Flash Reducer Assembly (Dwg. 9299188) Examination for Defects	5		3.2	4.4.2.25

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

TABLE I - FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE		SHEET 5 OF 5		DRAWING NUMBER / NEXT HIGHER ASSEMBLY
	CONTINUATION SHEET				
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
10	Charge, Propelling, 8 Inch, M188A1 for 8 Inch Howitzer, SP, M110A2 in Sealed Containers (Dwg. 9312712 and 9312720) Examination for Defects (except Proving Ground Test)	10		3.2	4.4.2.26/4.4.2.27/ 4.4.2.28/4.4.2.29/ 4.4.2.30/4.4.2.31

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

4.4 Quality Conformance Inspection

4.4.1 Inspection Lot Formation.-Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, inspection lots of propelling charge assemblies shall contain:

a. Propellant from not more than one lot number from one manufacturer.

b. Black powder from not more than one lot number from one manufacturer. (Base igniter and charge bag loading assembly).

c. Tubes from not more than one interfix number from one manufacturer.

d. Black powder from not more than one manufacturer (Flash Reducer Assembly).

4.4.2 Examination.-See MIL-A-48078.

a. Sampling Plans.-Unless otherwise specified in the Classification of Defects and Test tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.1	Strap, Tying				9277188
					NEXT HIGHER ASSEMBLY 9277178
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Cloth improper			3.1	4.5.5
Minor 201	Length		0.65%	3.2	Scale
202	Width	Note a	0.65%	3.2	Scale

NOTES: a. If a slitting machine is utilized, in lieu of the specified AQL, during the slitting process each roll will be inspected within the first 10 feet and the last 10 feet; i.e., two measurements per roll.

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9277277
4.4.2.2	Bag, Charge				NEXT HIGHER ASSEMBLY 9277276
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Width of cloth	Note a	0.40%	3.2	Scale
102	Cloth improper			3.1	4.5.5
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES: a. If a slitting machine is utilized, in lieu of the specified AQL, during the slitting process each roll will be inspected within the first 10 feet and the last 10 feet; i.e., two measurements per roll.

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.3	Charge Bag Assembly		9277276
			NEXT HIGHER ASSEMBLY 9281791

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Tape missing, insecure or improperly located		100%	3.2	Gage/Manual
102	Cloth Improper (tape)			3.1	4.5.5
103	Length		0.40%	3.2	Scale
104	Seam improper or improperly located		100%	3.2	Visual
Minor					
201	Length of tape after tack		0.65%	3.2	Scale
202	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.4	End, Base Igniter, Small		9277169
			NEXT HIGHER ASSEMBLY 9277167

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5
102	Diameter of base igniter end		0.40%	3.2	Gage
Minor					
201	Marking missing, misleading, or unidentifiable		0.65%	3.2	Visual
202	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9277171
4.4.2.5	End, Base Igniter, Large				NEXT HIGHER ASSEMBLY 9281791
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5
102	Diameter of base igniter end		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C- 63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9281791
4.4.2.6	Base Igniter End and Charge Bag Assembly				NEXT HIGHER ASSEMBLY 9277167
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of charge bag assembly		100%	3.2	Gage
102	Distance from end base igniter to first tape		0.40%	3.2	Gage
103	Seam improper		100%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.7	Base Igniter Assembly	1 OF 1	9277167
			NEXT HIGHER ASSEMBLY 9281794

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of seam circle		0.40%	3.2	Scale
102	Quilting missing or improper		0.40%	3.2	Visual/Manual
103	Quilting seam improper length		0.40%	3.2	Scale
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.8	Base Igniter and Charge Bag Loading Assembly		9281794
			NEXT HIGHER ASSEMBLY 9285356

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Assembly incorrect or damaged to the extent that black powder can escape (including any seams or openings incompletely stitched or broken stitching)		100%	3.2	Visual/Manual
Major					
101	Weight of black powder		100%	3.2	4.5.1
102	Moisture content of black powder	(a)		3.3	4.5.3
103	Minimum distance from tape to inner stitching at trimmed end		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual
202	Distance from trimmed end of charge bag to first seam		0.65%	3.2	Scale

NOTES: (a) See paragraph 4.4.3.2.

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.9	Cap				9289130
					NEXT HIGHER ASSEMBLY
					9285356
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Thickness		0.40%	3.2	Gage
Minor 201	Length		0.65%	3.2	Scale

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

20

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.10	Base Igniter and Tube Assembly		9285356
			NEXT HIGHER ASSEMBLY 9277175

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Base igniter and charge bag loading assembly damaged or improper		100%	3.2	Visual
Major					
101	Base igniter and charge bag loading assembly improperly tied to tube, i.e., tie missing, loose or incorrect (Note a) (excluding length of ties after tying)		100%	3.2	Visual
102	Base igniter and tube assembly weight		100%	3.4.3	4.5.9
103	Cap missing or insecure		100%	3.2	Visual/Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual
202	Charge bag twisted or folded in tube (to be checked prior to assembly of cap to tube)		0.65%	3.2	Visual

NOTES: a. Looseness will be allowed during teardown provided there is evidence the knot was tied.

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9277179
4.4.2.11	Increment 8, Body				NEXT HIGHER ASSEMBLY 9277176
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Cloth improper			3.1	4.5.5
Minor 201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9277176
4.4.2.12	Increment 8, Body and Liner Assembly				NEXT HIGHER ASSEMBLY 9277178
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Liner assembly improper, improperly assembled, missing or improperly located		0.40%	3.2	Visual/Scale
Minor 201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.13	End, Increment 8				9277183
					NEXT HIGHER ASSEMBLY 9277182
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5
Minor					
201	Established length		0.65%	3.2	Scale
202	Established width of straight section		0.65%	3.2	Scale

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9277182
4.4.2.14	End Assembly, Increment 8				NEXT HIGHER ASSEMBLY 9277178
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Seam improper		0.40%	3.2	Visual/Manual
Minor 201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9277178
4.4.2.15	Increment 8, Body Assembly				NEXT HIGHER ASSEMBLY 9277175
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	End assembly improperly assembled to body and liner assembly		0.40%	3.2	Visual
102	Any seam improper		0.40%	3.2	Visual/Manual
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9277175
4.4.2.16	Increment 8 Loading Assembly				NEXT HIGHER ASSEMBLY 9312712
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Base igniter and tube assembly improperly assembled to body assembly		100%	3.2	Visual/Manual
102	Base igniter and tube assembly improper or damaged (including condition of tube immediately prior to insertion into body and end assembly)		100%	3.2/3.9	Visual/Manual
103	Propellant weight			3.4.1	4.5.2
104	Any seam improper		100%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9312729
4.4.2.17	Increment 9 Body				NEXT HIGHER ASSEMBLY 9312726
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Cloth improper			3.1	4.5.5
Minor 201	Evidence of poor workmanship		0.65%	3.6	Visual
202	Marking missing, misleading, or unidentifiable		0.65%	3.2	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

28

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.18	End, Increment 9				9312724
					NEXT HIGHER ASSEMBLY
					9312725
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5
Minor					
201	Established length		0.65%	3.2	Scale
202	Established width of straight section		0.65%	3.2	Scale

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.19	Increment 9 End Assembly		9312725
			NEXT HIGHER ASSEMBLY 9312726

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Seam improper		0.40%	3.2	Visual/Manual
Minor 201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4910

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2, 20	Increment 9 Assembly		9312726
			NEXT HIGHER ASSEMBLY 9312727

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Increment 9 end assembly improperly assembled to body		0.40%	3.2	Visual
102	Any seam improper		0.40%	3.2	Visual/Manual
103	Liner assembly improper, improperly assembled, or missing		0.40%	3.2	Visual/Scale
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.21	Increment 9 Loading Assembly	1 OF 1	9312727
			NEXT HIGHER ASSEMBLY 9312712

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major				3.4.1	4.5.2
101	Propellant weight			3.2	Visual
102	Any seam improper		100%		
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.22	Jacket, Lacing		9312731
			NEXT HIGHER ASSEMBLY
			9312712

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5
102	Lacing cord missing or improperly assembled (2 locations)		0.40%	3.2	Visual/Manual
Minor					
201	Marking missing, misleading, or unidentifiable		0.65%	3.2	Visual
202	Evidence of poor workmanship		0.65%	3.6	Visual
203	Any seam improper or incompletely stitched		0.65%	3.2	Visual/Manual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.23	Flash Reducer Body		9299190
			NEXT HIGHER ASSEMBLY
			9299189

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Outer diameter		0.65%	3.2	Gage
202	Inner diameter		0.65%	3.2	Gage
203	Marking missing, misleading or unidentifiable		0.65%	3.2	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C- 63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.24	Flash Reducer Body Assembly				9299189
					NEXT HIGHER ASSEMBLY 9299188
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Any seam incompletely stitched		0.40%	3.2	Visual
102	Location of inner seam, minimum		0.40%	3.2	Gage
103	Location of outer seam, minimum		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.25	Flash Reducer Assembly		9299188
			NEXT HIGHER ASSEMBLY 9277173

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Any assembly damaged or improper to the extent black powder or potassium sulfate can escape		100%	3.2	Visual/Manual
102	Flash Reducer assembly weight		0.40%	3.4.4	4.5.12
103	Presence of black powder and potassium sulfate in flash reducer assembly		0.40%	3.2	Manual
104	Any seam incompletely stitched		0.40%	3.2	Visual
Minor					
201	Marking missing, misleading, or unidentifiable		0.65%	3.2	Visual
202	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2. 26	Charge, Propelling, 8 Inch, M188A1 for 8 Inch Howitzer, SP, M110A2	1 OF 2	9312712
			NEXT HIGHER ASSEMBLY --

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Assembly damaged or improper to the extent that black powder can escape		100%	3.2	Visual/Manual
2	Black powder missing in basepad		100%	3.2	Manual
	Proving Ground				
3	Pressure (see 6.14)	(a)		3.7	4.5.6
Major					
101	Basepad not in true position with respect to outer diameter of charge (to be determined after straps are securely tied and charge is laced)		100%	3.2	Gage
102	Dimensional gage failure		100%	3.5.1	Gage
103	Lacing missing, improper or insecure		100%	3.2	Visual/Manual
104	Igniter protector cap missing or improperly attached		0.40%	3.2	Visual
105	Propelling charge assembly weight		100%	3.4.1	4.5. 8
106	Assembly damaged to the extent that propellant or potassium sulfate can escape (includes any seams or openings incompletely stitched and broken stitches)		100%	3.2	Visual
107	Any component missing , improper, or improperly assembled (including flash reducer)		100%	3.2	Visual

NOTES: (a) Samples tested for Muzzle Velocity and Muzzle Velocity Standard Deviation and Differential Pressure will be monitored for pressure.

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026/10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C- 63125 (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2. 26	CONTINUATION SHEET	2 OF 2	9312712
			NEXT HIGHER ASSEMBLY
			--

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
108	Straps loose, broken or insecurely tied		0.40%	3.2	Visual/Manual
109	Condition of igniter tube protruding from Increment 8, prior to assembly of Increment 9		100%	3.9	Visual
110	Dimensional Gage failure		0.40%	3.5.2	Gage
	Proving Ground				
111	Muzzle velocity and muzzle velocity standard deviation (Zone 8)	15		3.7	4.5.6
112	Muzzle velocity and muzzle velocity standard deviation (Zone 9)	15		3.7	4.5.6
113	Differential pressure	20		3.7	4.5.6
Minor					
201	Evidence of poor workmanship (see 6.18)		0.65%	3.6	Visual
202	Location of lacing jacket		0.65%	3.2	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C- 63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9312720
4.4.2. 27	Charge, Prior to Insertion Into Container				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Charge not tightly wrapped immediately prior to insertion into container (i.e., all charge full diameter points should be in contact with the wrapper).		0.40%	3.2	Visual/Manual
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.28	Container, Prior to Insertion of Charge				9312720
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Foreign matter or rust in container		0.40%	3.2	Visual
102	Bottom cushion missing		100%	3.2	Visual
Minor					
201	Damaged container (to include dents protruding greater than 1/4" into container)		0.65%	3.2	Visual/Gage (see 6.4)

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

40

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C- 63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9312720
4.4.2.29	Container, Prior to Sealing				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Long filler or wrapper above top of charge (except for one allowable torn filler)		100%	3.2	Visual
102	Charge diametrically loose to the extent that a long filler may be completely inserted		100%	3.2	Manual
103	Any filler (if required) or top cushion missing or improper		100%	3.2	Visual
104	Dimension "X", minimum. (In lieu of measuring Dimension "X", the measurement of Dimension "Y" maximum may be taken)		100%	3.2	Gage
105	Filler inserted in container prior to inserting top cushion		0.40%	3.2	Visual
106	More than five long fillers present		0.40%	3.2	Visual
107	Overlap of one long filler with another at top of charge		0.40%	3.2	Visual
108	Charge cannot be removed by hand	(a)		3.2	4.5.10
Minor	None defined				

NOTES: (a) One sample from each eight (8) hours production.

SARPA-QA FORM 2567 FEB 74 4810

41

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.30	Container, Sealed				9312720
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Test plug missing		100%	3.2	Visual
102	DOD symbol missing, misleading or unidentifiable (if applicable)		0.40%	3.2	Visual
103	Test plug assembly torque		0.40%	3.10	Test (see 6.11)
104	Air pressure test		100%	3.2	4.5.4
Minor					
201	Test plug not greased (to be checked after air pressure test and prior to reassembly)		0.65%	3.2	Visual
202	Metallic seal missing or incorrectly applied		0.65%	3.2	Visual
203	Marking missing, misleading, or unidentifiable		0.65%	3.2	Visual
204	Cover incompletely engaged		0.65%	3.2	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C- 63125 (AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.31	Containerized Charge				9312720
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
NOTE (a)	Tear down Inspection	(b)		(c)	4.5.7 (d)

NOTES:

(a) Category is critical or major dependent upon category of the defect inspected.
(b) See paragraph 4.4.3.1.
(c) Requirement paragraph is dependent upon inspection performed.
(d) Allowance will be made for stretching of cloth when measuring dimensions that apply prior to loading or assembling. The allowance shall not exceed twice the original tolerance or one-half the minimum dimensions.

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

4.4.3 Testing

4.3.3.1 Teardown Inspection

4.3.3.1.1 Initial Production Lot Sampling.-In addition the samples of 4.4.3.1.2, three completely assembled charges shall be randomly selected from each days production until three consecutive days productions is found acceptable.

4.4.3.1.2 Lot Sampling.-Twenty completely assembled charges shall be randomly selected from each lot. If there is a lapse in production in excess of ninety (90) days, or the previous lot was waived or rejected due to this inspection, sampling will return to initial production lot sampling.

4.4.3.2 Moisture Content of Black Powder.-At least one sample of black powder from each eight hours loading of base igniter assemblies will be tested for moisture content.

4.4.4 Inspection Equipment.-The inspection equipment required to perform the examinations and tests prescribed herein is described in the 'Paragraph Reference/Inspection Method' column in the tables starting with paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and paragraph 6.3 of this specification.

4.5 Test Methods and Procedures

4.5.1 Weight of Black Powder in Base Igniter and Charge Bag Loading Assembly.-The inspections below are to be conducted by inspection personnel using equipment designated for inspection purposes and shall be clearly distinguished from production operations. The weight of black powder in the base igniter and charge bag will be inspected 100 percent. The weight of the black powder in the basepad will be determined by subtracting an average weight of the empty assembly or the actual weight as marked on the individual assembly from the loaded basepad, empty charge bag assembly weight. The weight of the black powder in the charge bag will be determined by subtracting the average or actual weight of the loaded basepad, empty charge bag assembly from the loaded base igniter and charge bag assembly weight. Any assembly which fails to comply with the applicable requirement shall be classed defective and removed from the lot. Inspection equipment shall be in accordance with 4.4.4.

Source: https://assist.dla.mil -- Downloaded: 202640-23T02:16Z
Check the source to verify that this is the currentversion before use.

4.5.2 Propellant Weight (see 3.4).-The inspections below are to be conducted by inspection personnel using equipment designated for inspection purposes and shall be clearly distinguished from production operations. Any increment which fails to comply with the applicable requirement shall be classed defective and removed from the lot. Inspection equipment shall be in accordance with 4.4.4.

4.5.2.1 Method 1.-The loaded increment will be inspected 100 percent. The weight of the propellant will be determined by subtracting an average weight of the empty increment bag or the actual weight as marked on the individual increment bag from the loaded increment weight.

4.5.2.2 Method 2.-The weight of the propellant will be inspected 100 percent prior to loading the increment on a different balance. In addition, the propellant weight of the loaded increment will be inspected using a sampling plan from MIL-STD-105 or MIL-STD-1235 with an AQL of 0.40 percent. The weight of the propellant will be determined by subtracting an average weight of the empty increment bag or the actual weight as marked on the individual increment bag from the loaded increment weight.

4.5.3 Moisture Content of Black Powder.-The moisture content of the black powder will be determined in accordance with MIL-P-223. If any sample fails to meet the specified requirement, the eight hours production represented by the sample shall be rejected.

4.5.4 Air Pressure Test.-Each container shall be tested as specified on the appropriate drawing. A pressure drop equivalent to or greater than the applicable requirement shall be cause for rejection and removal from the lot.

4.5.5 Cloth.-At the time cloth is introduced to the sewing or cutting operation, an identification will be made for each roll to verify that proper material is used. Any cloth failing to be identified as proper material in accordance with applicable drawings and specifications shall be rejected from the lot.

4.5.6 Proving Ground.-This test shall be conducted at a Government Proving Ground in accordance with the applicable acceptance test procedure using M106, HE projectiles inert loaded within 0.1 pound of an as fired weight of 200.0 pounds using Primer, M82 and fired in cannon M201A1 with 75 percent (minimum) remaining life. Firing shall be conducted with a spindle to charge base stand-off of 1 inch (plus or minus 1/4 inch). Prior to firing, all charges shall be temperature

Source: https://assist.dla.mil -- Downloaded: 202640-23T02:16Z
Check the source to verify that this is the current version before use.

conditioned in a large conditioning box with adequate air circulation at the required temperature for a minimum of 24 hours and assurance will be made that, when fired, the charges are at the conditioning temperature. The following tolerances shall apply to all -50°F, 145°F and 70°F conditioning: -50°F from -50°F to -45°F; 145°F from 140°F to 145°F; 70°F from 68°F to 72°F. Copper crusher gages (2) shall be used to measure the maximum chamber pressure of each charge. Velocity coils will be used to measure the muzzle velocity of each charge.

4.5.6.1 Muzzle-Velocity and Muzzle Velocity Standard Deviation.-Determination of acceptance will be in accordance with MIL-STD-414, Section B, Table B3, AQL of 0.65%. All muzzle velocity and muzzle velocity standard deviation samples will be ballistic tested at 70°F. Fifteen (15) charges will be fired for muzzle velocity and muzzle velocity standard deviation. If the sample is determined unacceptable the lot will be rejected. In addition, if the velocity standard deviation of the sample multiplied by the factor 0.76 exceeds the applicable lot requirement, the lot shall be rejected. Fifteen (15) calibration charges will be fired alternately with the test samples and the muzzle velocity and pressure of all the test charges will be corrected to standard conditions.

4.5.6.2 Pressure.-If any propelling charge individual corrected maximum pressure exceeds the applicable requirement, the lot shall be rejected.

4.5.6.3 Differential Pressure.-Two pressure-time gages at different locations (one in the spindle and one at the projectile base) will be used to record pressure-time traces. Differential pressure traces will be obtained by subtracting the projectile gage output from the spindle gage output. The maximum differential pressure of any charge will be defined as the maximum amplitude of the first negative wave of the differential pressure trace prior to peak pressure. Any trace which contains no amplitude in the negative direction will be considered to have a maximum differential pressure of zero. Any sample failing to meet the differential pressure requirements shall be cause for the lot to be referred or rejected (see 3.7.1). Ignition delay will be recorded on all differential pressure firings. Any sample failing to meet the ignition delay requirements shall be cause for the lot to be referred. Ten (10) charges will be conditioned to 145°F and ten (10) charges will be conditioned to -50°F for differential pressure firings. Ten (10) calibration charges will be fired intermixed (five (5) at each temperature) with the test samples and the muzzle velocity and pressure of all test charges corrected to standard conditions.

Source: https://assist.dla.mil -- Downloaded: 202640-23T02:16Z
Check the source to verify that this is the current version before use.

4.5.7 Teardown Inspection.-Each container and propelling charge will be subjected to each of the critical (except critical defect 3, paragraph 4.4.2.26) and 100 percent major (except major defect 101, paragraph 4.4.2.8; major defect 102, paragraph 4.4.2.10; major defect 103, paragraph 4.4.2.16; major defect 101, paragraph 4.4.2.21; major defects 101 and 105, paragraph 4.4.2.26; major defect 101, paragraph 4.4.2.27; major defect 104, paragraph 4.4.2.29) inspections defined in 4.4.2 of this specification. Samples may be accumulated or inspected upon selection providing the selection remains random and represents the lot. The inspections will be performed by the contractor and witnessed by the Government. The detection of any one of the above defects shall be cause for rejection of the lot represented by the sample.

4.5.8 Charge, Propelling, Assembly Weight.-The actual weights as marked on the individual assembled base igniter and tube assembly, and empty increment assemblies plus average or actual weight of the flash reducer plus the average or actual weights of the lacing cords and jacket together with the nominal propellant weights as specified in the loading authorization shall be subtracted from the assembled charge, propelling assembly weight. If the resulting weight deviation is greater than the requirement, the propelling charge will be classified defective and removed from the lot (see 6.9).

4.5.9 Base Igniter and Tube Assembly Weight

4.5.9.1 Method 1.-The actual weight of the tube along with the average weight of the empty base igniter assembly or the actual weight as marked on the individual empty base igniter assembly shall be recorded for each base igniter and tube assembly. These weights along with the nominal weights of black powder and average weight of the cap shall be subtracted from the assembled base igniter and tube assembly weight. If the resulting weight deviation is greater than the requirement, the base igniter and tube assembly will be classified defective and removed from the lot (see 6.10.1).

4.5.9.2 Method 2.-The average weight of the empty base igniter assembly or the actual weight as marked on the individual empty base igniter assembly shall be recorded for each base igniter and tube assembly. These weights along with the average weight of the cap and the nominal weights of the tube and black powder shall be subtracted from the assembled base igniter and tube assembly weight. If the resulting weight deviation is greater than the requirement, the base igniter and the tube assembly will be classified defective and removed from the lot (see 6.10.2).

Source: https://assist.dla.mil -- Downloaded: 202610-23T02:16Z
Check the source to verify that this is the current version before use.

4.5.10 Charge Removal from Container.-Each sample shall be tested for removal of the propelling charge from the container by hand. The charge may be pulled out by the tying straps or the container may be inverted and the charge either pulled out or slid out. Each charge tested shall be checked for damage to the tying straps (looseness, tears, etc.) and the charge will be repaired (retie the tying straps and relace the charge, if necessary). Each charge tested shall be rewrapped (may use the same wrapper if the wrapper is not badly damaged) and re-packed in accordance with this specification and the applicable drawings. Any charge that cannot be removed from the container using the above method shall be cause for rejection of the production represented by the sample.

4.5.11 Complete Igniter Alignment.-Each complete igniter assembly shall be assembled to the increment assembly utilizing an approved method of assuring alignment between the igniter tube and the outer diameter of the increment assembly. The method to be used during production is to be established by the contractor and approved by the government (see 6.17).

4.5.12 Flash Reducer Assembly Weight.-The inspection below is to be conducted by inspection personnel using equipment designated for inspection purposes and shall be clearly distinguished from production operations. The weight deviation will be determined by subtracting the average flash reducer body assembly weight plus the nominal black powder and potassium sulfate weights from the flash reducer assembly weight.

5. PREPARATION FOR DELIVERY

5.1 Packing and Marking.-The propelling charges shall be packed, sealed, tested and marked in accordance with the specified requirements of drawing 9312720.

6. NOTES

6.1 Intended Use.-The propelling charges covered by this specification are intended for use in M201A1 cannon.

6.2 Ordering Data.-See MIL-A-48078.

6.3 Submission of Designs for Approval.-See 6.2.3 of MIL-A-48078. Submit equipment designs, as required, to Commander, ARRADCOM, Attn: DRDAR-QAR-I, Dover, New Jersey 07801.

6.4 Visual Examination Qualification.-When compliance with the applicable requirement is in doubt as a result of visual examination the characteristic may be measured or gaged to determine acceptability.

Source: https://assist.dla.mil -- Downloaded: 202640-23T02:16Z
Check the source to verify that this is the current version before use.

6.5 Inspection Lot Size.-It is noted that the size of inspection lots of components, assemblies, or items of delivery may differ from the actual quantities contractually scheduled for delivery. However, in order to facilitate scheduling of tests or deliveries, inspection lots of items of delivery may be equivalent to such contract quantities provided all of the lot formation criteria and sampling provisions of this specification are maintained.

6.6 Proving Ground.-A copy of all proving ground data should be submitted to Commander, ARRADCOM, Attn: DRDAR-QAR-Q and DRDAR-LCA-G, Dover, New Jersey 07801 and PM M110E2, Attn: DRCPM-M110E2-LP, Rock Island, Illinois 61299.

6.7 Teardown Inspection.-A list of all defects found during teardown inspection shall be submitted to Commander, ARRADCOM, Attn: DRDAR-QAR-Q and DRDAR-LCA-G, Dover, New Jersey 07801 and PM M110E2, Attn: DRCPM-M110E2-LP, Rock Island, Illinois 61299.

6.8 Charge, Propelling Assembly Weight and Base Igniter and Tube Assembly Weight.-This requirement applies to the load plant at the time of loading only. Due to subsequent change in weight of the components because of variation in material and moisture content, this test cannot be repeated after initial manufacture to the degree of accuracy required.

6.9 Charge, Propelling, Assembly Weight.-

Weights To Be Determined		Assembly Drawing Number
Actual Weight of Base Igniter and Tube Assembly	-	9285356
Average/Actual Weight of Flash Reducer Assembly	-	9299188
Actual Weight of Increment 8 Body Assembly	-	9277178
Actual Weight of Increment 9 Assembly	-	9312726
Average Weight of Lacing Cord	-	9312712
Average Weight of Lacing Jacket	-	9312731
Propellant Weight	-	Loading Authorization
Component Weight (sum of above weights)		

Source: https://assist.dla.mil -- Downloaded: 202640-23T02:16Z
Check the source to verify that this is the current version before use.

The propelling charge assembly weight minus the component weight equals the "Weight Deviation".

6.10 Base Igniter and Tube Assembly Weight.-

6.10.1 Method 1.-

Weights To Be Determined		Assembly Drawing Number
Actual Weight of Tube	-	9285248
Average/Actual Weight of Base Igniter Assembly	-	9277167
Average Weight of Cap	-	9289130
Nominal Weight of Black Powder	-	9281794
Component Weight (sum of above weights)		

The base igniter and the tube assembly weight minus the component weight equals the "Weight Deviation".

6.10.2 Method 2.-

Weights To Be Determined		Assembly Drawing Number
Nominal Weight of Tube	-	MIL-I-48252
Average/Actual Weight of Base Igniter Assembly	-	9277167
Average Weight of Cap	-	9289130
Nominal Weight of Black Powder	-	9281794
Component Weight (sum of above weights)		

The base igniter and tube assembly weight minus the component weight equals the "Weight Deviation".

6.11 Test Plug Assembly Torque.-This requirement applies to the load plant at the time of loading only. Due to creep of the mechanical properties of the test plug washer, this test cannot be repeated after initial manufacture.

Source: https://assist.dla.mil -- Downloaded: 202610-23T02:16Z
Check the source to verify that this is the currentversion before use.

6.12 Proving Ground Summary (See 4.5.6).-

Test	Zone	Sample Size	Number of Ref Rounds	Velocity	Maximum Individual Pressure	Differential Pressure
70°F	8	15	15	*	34,500	NA
70°F	9	15	15	*	42,100	NA
145°F	9	10	5	INFO	48,100	**
-50°F	9	10	5	INFO	INFO	**

*See 4.5.6.1 and 3.7
**See 4.5.6.3 and 3.7.1

6.13 Differential Pressure.-If the differential pressure or ignition delay requires referral of the lot, the disposition of the lot shall be referred to PM M110E2, Attn: DRCPM-M110E2-LP, Rock Island, Illinois 61299 with an info copy to ARRADCOM, Attn: DRDAR-QAR-Q and DRDAR-LCA-G, Dover, New Jersey 07801.

6.14 Individual Maximun Pressure.-Individual Maximum Pressure specified in 3.7 is based on firing with an M106 Projectile loaded to an as fired weight of 200.0 lbs. Any change in weight or projectile will require an adjustment of this pressure requirement.

6.15 Muzzle Velocity and Muzzle Velocity Standard Deviation.-This requirement is based on obtaining a nominal velocity of 2510 fps and a standard deviation of 6.0 fps with the M650 HE RA projectile family.

6.16 Data Cards.-A copy of all data cards should be submitted to Commander, ARRADCOM, Attn: DRDAR-QAR-Q and DRDAR-LCA-G, Dover, New Jersey 07801 and PM M110E2, Attn: DRCPM-M110E2-LP, Rock Island, Illinois 61299.

6.17 Method of Assuring Alignment Submission.-The method for assuring alignment of the complete igniter assembly shall be submitted to Commander, ARRADCOM, Attn: DRDAR-QAR-Q, Dover, New Jersey 07801, for approval.

6.18 Workmanship.-Rips or tears in the eyelit area of the lacing jacket and stretching of cloth caused by lacing the charge is acceptable provided the lacing cord in the bead is not broken.

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project Number: 1320-A-399

☆U.S. GOVERNMENT PRINTING OFFICE: 1978-703-122/2889

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS: This form is provided to solicit beneficial comments which may improve this document and enhance its use. DoD contractors, government activities, manufacturers, vendors, or other prospective users of the document are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity. A response will be provided to the submitter, when name and address is provided, within 30 days indicating that the 1426 was received and when any appropriate action on it will be completed.
NOTE: This form shall not be used to submit requests for waivers, deviations or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

DOCUMENT IDENTIFIER *(Number)* AND TITLE

MIL-C-63125 Charge, Propelling, 8Inch, M188A1 LAP

NAME OF ORGANIZATION AND ADDRESS OF SUBMITTER

☐ VENDOR ☐ USER ☐ MANUFACTURER

1. ☐ HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE? ☐ IS ANY PART OF IT TOO RIGID, RESTRICTIVE, LOOSE OR AMBIGUOUS? PLEASE EXPLAIN BELOW.

A. GIVE PARAGRAPH NUMBER AND WORDING

B. RECOMMENDED WORDING CHANGE

C. REASON FOR RECOMMENDED CHANGE(S)

2. REMARKS

SUBMITTED BY *(Printed or typed name and address — Optional)*

TELEPHONE NO.

DATE

DD FORM 1 OCT 76 1426 EDITION OF 1 JAN 72 WILL BE USED UNTIL EXHAUSTED.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:16Z
Check the source to verify that this is the current version before use.