MIL-F-70620A (AR)
14 July 1987
SUPERSEDING
MIL-F-70620
29 September 1986

MILITARY SPECIFICATION

FUZE, MTSQ, M772
LOADING, ASSEMBLING AND PACKING

This Specification is approved for use within the U.S. Army Armament Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This specification covers the requirements and quality assurance provisions for the loading, assembling and packing of the M772 Mechanical Time Super Quick Fuze.

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Specifications and standards. The following specifications and standards form a part of this specification to the extent specified herein. Unless otherwise specified, the issues of these documents shall be those listed in the issue of the Department of Defense Index of Specifications and Standards (DoDISS) and supplement thereto, cited in the solicitation.

SPECIFICATIONS

MILITARY

MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specification for

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, U.S. Army Armament Munitions and Chemical Command, Attn. AMSMC-QA, Picatinny Arsenal, New Jersey 07806-5000 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

AMSC N/A
FSC 1390
DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:49Z
Check the source to verify that this is the current version before use.

MIL-STD-331 - Fuze and Fuze Components, Environmental and Performance Test for
MIL-STD-414 - Sampling Procedures and Tables for Inspection by Variables for Percent Defective

2.1.2 Other Government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this specification to the extent specified herein. Unless otherwise specified, the issues shall be those in effect on the date of the solicitation.

DRAWINGS

US ARMY ARMAMENT RESEARCH, DEVELOPMENT AND ENGINEERING CENTER (ARDEC)

PRODUCT DRAWINGS

12624567 - Fuze, MTSQ, M772

(Copies of specifications, standards, drawings, and publications required by manufacturers in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting officer.)

2.2 Order of precedence. In the event of a conflict between the text of this specification and the references cited herein, (except for associated detail specifications, specification sheets or MS standards), the text of this specification shall take precedence. Nothing in this specification, however, shall supersede applicable laws and regulations unless a specific exemption has been obtained.

3. REQUIREMENTS

3.1 Material. Materials and parts shall be in accordance with applicable drawings and specifications.

3.2 Fuze assembly. The M772 MTSQ fuze assemblies shall comply with all requirements specified on drawing (dwg.) 12624567 and with all requirements specified in applicable specifications.

3.3 Transportation vibration. The fuze assembly shall comply with the requirements of MIL-STD-331, Test 119, Procedure 2, and of 3.7.1, 3.7.3 and 3.7.6.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:49Z
Check the source to verify that this is the current version before use.

3.4 Jolt and jumble. The fuze assembly shall comply with the requirements of MIL-STD-331, Test 101.2, Procedure 2 and Test 102.1.

3.5 Drop test, 1.5 meter. The fuze assembly shall comply with the requirements of MIL-STD-331, Test 111.1.

3.6 Waterproofness. The fuze assembly shall comply with the MIL-STD-331A, Test 108, except that the duration of immersion shall be five (5) minutes and pressure shall be three (3) psi gauge (6896 Pa).

3.7 Ballistic performance (proving ground).

3.7.1 Premature bursts. There shall be no premature bursts or metal parts failure in the mortar or in the first 100 meters of flight.

3.7.2 Arming safety. The fuze shall not function on impact against a 1" (25.4mm) plywood screen positioned at a distance of 40 meters ± 1 meter.

3.7.3 Mechanical time functioning (70°F). The fuze, when set in the time mode, shall cause the projectile to function within the following upper (UL) and lower (LL) time limits.

Set Time (Sec)	Function Time Limits (Sec)	
16.5	LL = 15.88	UL = 17.12
28.0	LL = 27.16	UL = 28.84
44.0	LL = 43.00	UL = 45.00

3.7.4 Extreme temperatures mechanical time functioning. The fuze, when set in the time mode, and conditioned at -50°F or +145°F, shall cause the projectile to function within the following time limits.

Set Time (Sec)	Function Time Limits (Sec)	
28.0	LL = 27.00	UL = 29.00

3.7.5 Off time. The fuze when set in the time mode, at any temperature condition, shall function within the following off time limits:

Set Time (Sec)	Early Off Time (Sec)	Late Off Time (Sec)
16.5	15.00 or less	18.00 or more
28.0	26.25 or less	29.75 or more
44.0	42.00 or less	46.00 or more

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:49Z
Check the source to verify that this is the current version before use.

3.7.6 Fuze failures. When a fuze is set to function in the air and functions upon impact, it shall be considered a ground impact. When it fails to function on impact, it shall be considered a dud.

3.8 First article. When specified in the contract or purchase order, a sample shall be subjected to first article inspection in accordance with the technical provisions herein. (see 4.3 and 6.2)

3.9 Workmanship. All parts and assemblies shall be fabricated in a thorough, workmanlike manner. They shall be free of burrs, sharp edges, cracks, dirt, rust and other foreign matter. The cleaning methods shall not be injurious to any part, nor shall the parts be contaminated by the cleaning agent. Exterior surface coatings shall be uniform and continuous except for a few light scratches not exposing base material. All required markings shall be neat and sharply defined.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the specification where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.1.1 Responsibility for compliance. All items must meet all requirements of section 3 and 5. The inspection set forth in this specification shall become a part of the contractor's overall inspection system or quality program. The absence of any inspection requirements in the specification shall not relieve the contractor of the responsibility of assuring that all products or supplies submitted to the Government for acceptance comply with all requirements of the contract. Sampling in quality conformance does not authorize submission of known defective material, either indicated or actual, nor does it commit the Government to acceptance of defective material.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:49Z
Check the source to verify that this is the current version before use.

4.2 Classification of inspections. The following types of inspection shall be conducted on this item:

a. First Article Inspection

b. Quality Conformance Inspection

4.3 First article inspection

4.3.1 Submission The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated.

Part description	Drawings	Quantity
Screw, Clamp	507.00-00.84	10
Expelling Charge Assembly	507.00-81.00	10
Plug, Base	507.00-00.67	10
Fuze, MTSQ, M772	12624567	229

4.3.2 Inspections to be performed. See MIL-A-48078 and Table I specified herein.

4.3.3 Rejection. See MIL-A-48078.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:49Z
Check the source to verify that this is the current version before use.

TABLE I - First article inspection

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-70620A (AR)

PARAGRAPH	TITLE: Fuze, MTSQ, M772 and Components	SHEET 1 OF 2	DRAWING NUMBER: See Below
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Screw, Clamp (Dwg. 507.00-00.84)				
	Examination for Defects	10		3.2	4.4.2.1
	Assembly, Expelling Charge (Dwg. 507.00-81.00)				
	Examination for Defects	10		3.2	4.4.2.2
	Plug, Base (Dwg. 507.00-00.67)				
	Examination for Defects	10		3.2	4.4.2.3
	Fuze, MTSQ, M772 (Dwg. 12624567)				
	Examination for Defects	10		3.2	4.4.2.4
	Waterproofness Test	15	(a)	3.6	4.5.4
	Handling Safety Test				
	Jolt and Jumble Test	12	(a)	3.4	4.5.2
	1.5 Meter Drop Test	10	(a)	3.5	4.5.3

NOTES: (a) One (1) or more defectives shall be cause for rejection. (b) Two (2) early off times or three (3) or more late off times shall be cause for rejection. (c) Two (2) or more ground impacts shall be cause for rejection. (d) Two (2) or more duds shall be cause for rejection. (e) One (1) or more groups exceeding the lot percent defective shall be cause for rejection. (f) Two (2) or more fuze failures shall be cause for rejection.

Source: https://assist.dla.mil - Downloaded: 2026-10-29T03:49Z
Check the source to verify that this is the current version before use.

TABLE I - First article inspection

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-70620A (AR)

PARAGRAPH	TITLE: Fuze, MTSQ, M772 and Components		SHEET 2 OF 2		DRAWING NUMBER: See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Performance Test (Proving Ground)				
	Transportation vibration test samples premature during MIL-STD-331A test no. 119, procedure 2 and ballistic test	20	(a)	3.3	4.5.1
	Transportation vibration ballistic test fuze failures	20	(f)	3.3	4.5.1
	Premature Bursts	150	(a)	3.7.1	4.5.5.2
	Function in arming safety test	12	(a)	3.7.2	4.5.5.1
	Estimated lot percent defective	170	(e)	3.7.3& 3.7.4	4.5.5.2
	Off Times	170	(b)	3.7.5	4.5.5.2
	Ground impact	150	(c)	3.7.6	4.5.5.2
	Duds	150	(d)	3.7.6	4.5.5.2

NOTES:

AMSMC Form 1570, 1 Feb 85

Replaces DRSMC-QA (D) Form 160, 1 Aug 83, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:49Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection

4.4.1 Inspection lot formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, each inspection lot of fuzes shall contain:

a. Fuze components of one lot interfix number from one manufacturer.

b. Expelling charges of one lot interfix number from one manufacturer.

4.4.2 Examination. See MIL-A-48078. Unless otherwise specified in the Classification of Defects and Test Tables, sampling plans and procedures for major and minor defects shall be in accordance with MIL-STD-105 (DIN 40080), Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:49Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.1	Screw, Clamp				507.00 - 00.84
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Major diameter		0.40%	3.2	Gage
102	Pitch diameter		0.40%	3.2	Gage
103	Inside diameter		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.9	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:49Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.2	Expelling Charge Assembly				507.00-81.00
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outer diameter of cup		0.40%	3.2	Gage
102	Height of cup		0.40%	3.2	Gage
103	Bonding missing or improperly applied		0.40%	3.2	Visual
104	Total weight		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.9	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2025-10-15T03:49:52Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.3	Plug, Base				507.00 - 00.67
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Pitch diameter		0.40%	3.2	Gage
102	Major diameter		0.40%	3.2	Gage
103	Small diameter of rotor cavity		0.40%	3.2	Gage
104	Large diameter of rotor cavity		0.40%	3.2	Gage
105	Thickness between rotor cavity and blind hole		0.40%	3.2	Gage
Minor					
201	Length of base plug		0.65%	3.2	Gage
202	Evidence of poor workmanship		0.65%	3.9	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:49Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.4	Fuze, MTSQ, M772 (Prior to Assembly of Base Plug and After Assembly of Clamp Screw)	1	1	12624567
				NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Rotor not engaged to set back pins		100%	3.2	Visual
2	Safety arbor not engaged to rotor slot		100%	3.2	Visual
Major					
101	Detonator missing or improperly assembled		100%	3.2	Visual
102	External threads improper		0.40%	3.2	Gage
103	Length of external threads protrusion		0.40%	3.2	Gage
104	Width of time setting slot		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.9	Visual

NOTES:

12

Source: https://assist.dla.mil -- Downloaded: 2025-10-03 04:02

Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-70620A (AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.5	Fuze, MTSO, M772, Destructive Lot Acceptance Testing	1 OF 1	12624567
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Transportation vibration test samples prematures during MIL-STD-331A, test no. 119, procedure 2	10	(a)	3.3	4.5.1
2	Jolt and jumble test	12	(a)	3.4	4.5.2
3	1.5 meter drop test	10	(a)	3.5	4.5.3
4	Proving ground test				
	a. Premature burst in ballistic test	110	(a)	3.7.1	4.5.5.2
	b. Function in arming safety test	12	(a)	3.7.2	4.5.5.1
Major					
101	Complete fuze waterproofness test	5	(a)	3.6	4.5.4
102	Proving ground test				
	c. Transportation vibration ballistic test fuze failure	10	(f)	3.3	4.5.5.2
	d. Estimate lot percent defective	110	(e)	3.7.3 & 3.7.4	4.5.5.2
	e. Off times	100	(b)	3.7.5	4.5.5.2
	f. Ground impact	100	(c)	3.7.6	4.5.5.2
	g. Duds	100	(d)	3.7.6	4.5.5.2
Minor	None defined				

NOTES: (a) One (1) or more defective(s) shall cause the lot to be rejected. (b) Two (2) early off times or two (2) or more late off time shall cause the lot to be rejected. (c) Two (2) or more ground impacts shall cause the lot to be rejected. (d) Two (2) or more duds shall cause the lot to be rejected. (e) One (1) or more groups exceeding the lot percent defective shall cause the lot to be rejected. (f) Two (2) or more fuze failures shall cause the lot to be rejected.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:49Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.6	Packing, assembly	1 OF 1	42.700-0540a
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Bottom perforated board missing		0.40%	5.1	Visual
102	Fuze can assembly not properly coupled		0.40%	5.1	Visual
103	Top perforated board missing		0.40%	5.1	Visual
104	Incorrect number of fuzes		0.40%	5.1	Visual
105	Spacer missing		0.40%	5.1	Visual
106	Liner missing		0.40%	5.1	Visual
107	Wood box improperly sealed		0.40%	5.1	Visual
Minor					
201	Marking missing or unidentfiable		0.65%	5.1	Visual
202	Evidence of poor workmanship		0.65%	3.9	Visual

NOTES:

Check the source to verify that this is the current version before use.
Source: http://assist.dla.mil -- Downloaded: 2020-10-23T01:40Z

3. Inspection equipment. The inspection equipment required to perform the examination and tests prescribed herein is described in the Paragraph Reference/Inspection Method column in the tables starting with 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and 6.3 of this specification.

4.5 Methods of inspection

4.5.1 Transportation vibration. The test shall be performed on complete fuze assemblies (dwg. 12624567) set "S". The test shall be conducted in accordance with the procedures outlined in MIL-STD-331, Test 119, Procedure 2. The sampled fuzes shall then be fired as detailed in 4.5.5.2. If the fuzes do not comply with the requirements of 3.7.1 and 3.7.3, the first article or the lot shall be rejected.

4.5.2 Jolt and jumble. The test shall be performed on complete fuze assemblies (dwg. 12624567) set "S". The test shall be conducted in accordance with the procedures outlined in MIL-STD-331, Test 101.2, Procedure II. Immediately after the completion of the jolt test, the fuzes shall be subjected to the jumble test in accordance with MIL-STD-331, Test 102.1. After the jumble test, the fuzes shall be disassembled to determine if the fuzes have been armed or become unsafe in any way. If so, the conditions shall be classed as defective. If one or more fuzes are classed defective, the lot shall be rejected.

4.5.3 Drop test, 1.5 meter. The complete fuze assemblies without the pull wire set "s" shall be assembled to inert loaded projectiles as specified in the contract and subjected to the 1.5 meter drop test in accordance with MIL-STD-331, Test 111.1, Procedure 1. After this test, the fuzes shall be disassembled to determine if the fuzes have been armed or become unsafe in any way. If so, the condition shall be classed defective. If one or more fuzes are classed defective, the lot shall be rejected.

4.5.4 Waterproofness. The loaded fuze assemblies shall be subjected to the waterproofness test in accordance with MIL-STD-331, Test 108, except as provided in 3.6. After this test, the fuzes shall be disassembled and examined under the ultra-violet light to determine compliance with 3.6. Any assembly that does not comply with the requirements specified in 3.6 shall be classed defective.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:49Z
Check the source to verify that this is the current version before use.

4.5.5 Performance test (proving ground ballistic) (see 6.4).

4.5.5.1 Arming safety. The fuze shall be assembled to the inert filled 81mm cartridge set "s" and fired at charge 1 from an 81mm mortar. They shall be fired against an one inch plywood screen set a distance of 40 meter ± 1 meter. If any fuze functions during the test, the lot shall be rejected. If any fuze does not function and the velocity is less than the requirement, the sample shall be classed a "no test" and a new sample shall be selected and tested.

4.5.5.2 Mechanical time functioning. The sample fuzes shall be assembled to 81mm, M819 cartridges, or M853A1 cartridges and fired from an M252 mortar between 45° and 85° elevation for air burst functioning. All fuze settings shall be photographed utilizing an instant, self processing camera. Three independent infrared sensing chronograph systems will be used to measure time of burst. The times shall be recorded from the chronograph counters to three decimal places. The three recorded time values for each round are averaged and the average is rounded to the nearest 0.01 second. When the first digit removed is 5, the last digit retained should increase by one unit if it is an odd number and it should not be changed if it is an even number. If one time value is lost or is determined to be invalid, (see 6.5) the remaining two values are used. The time values obtained by the chronograph systems shall be used to calculate the estimate of lot percent defectives. Where at least two chronograph systems provide a time value, the average shall be taken as the individual fuze value. The estimate of the lot percent defective shall be calculated using the methods prescribed in MIL-STD-414, Example B3. Any group which does not meet the time limits in 3.7.3 and 3.7.4 by an estimated lot percent defective greater than the appropriate values given below shall cause the lot to be rejected.

Sample Size (See 6.6)	Maximum Allowable Percent Defect
26-30	1.29
20	1.29
17-19	1.31
8-10	1.31

5. PACKAGING

5.1 Packaging, packing and marking. Packaging, packing and marking shall be in accordance with 42.700-0540.0a

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:49Z
Check the source to verify that this is the current version before use.

6. NOTES

6.1 Intended use. The M772 MTSQ Fuze is intended for use on 81mm mortar ammunition.

6.2 Ordering data. See MIL-A-48078 (PA).

6.3 Submission of designs for approval. See 6.2.3 of MIL-A-48078 . Submit equipment designs, as required, to Commander, AMCCOM, ATTN: AMSMC-QAT-I, Picatinny Arsenal, NJ, 07806-5000. This address will be specified on the Contract Requirement List DD Form 1423 in the contract. Unless otherwise specified, data item DI-R-1714 will apply.

6.4 Performance test summary (proving ground ballistic).

6.4.1 First article inspection test.

6.4.1.1 ARMING SAFETY

Cartridge	Charge	QE (mils)	Set	Quantity
Inert 81MM	1	0	"S"	12

6.4.1.2 Mechanical time function at 70°F

Cartridge	Charge	QE (mils)	Set Time	Quantity
M819/M853	1	800/1000	16.5 Sec	20 (a)
M819/M853	1	800/1000	16.5 Sec	30
M819/M853	2	1156	28.0 Sec	30
M819/M853	4	1400	44.0 Sec	30

Note: The fuzes shall be conditioned at 70°F for a minimum of 4 hours

6.4.1.3 Extreme temperatures mechanical time function

Cartridge	Charge	QE (mils)	Set Time	Quantity
M819/M853	2	1156	28.0 Sec	30 (b)

(a) Transportation vibration samples

(b) Thirty fuzes each shall be conditioned at -50°F and 145°F for a minimum of 4 hours.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:49Z
Check the source to verify that this is the current version before use.

6.4.2 Quality conformance test.

6.4.2.1 ARMING SAFETY

Cartridge	Charge	QE (mils)	Set	Quantity
Inert 81MM	1	0	"s"	12

6.4.2.2 Mechanical time function at 70°F

Cartridge	Charge	QE (mils)	Set Time	Quantity
M819/M853A1	1	800/1000	16.5	10 (a)
M819/M853A1	1	800/1000	16.5 Sec	20
M819/M853A1	2	1156	28.0 Sec	20
M819/M853A1	4	1400	44.0 Sec	20

Note: The fuzes shall be conditioned at 70°F for a minimum of 4 hours

6.4.2.3 Extreme temperatures mechanical time function

Cartridge	Charge	QE (mils)	Set Time	Quantity
M819/M853	2	1156	28.0 Sec	20 (b)

(a) Transportation vibration samples.
(b) Twenty fuzes each shall be conditioned at -50°F and 145°F for a minimum of 4 hours.

6.5 Lost times. When a fuze is fired for an airburst function and is observed to have functioned, but a chronograph system used to determine the elapsed time to function fails for any reason to record the appropriate value, then an entry of lost time shall be used instead of any recorded value. The round shall be considered lost when the above occurs for two or more chronograph systems.

6.6 Required number of data points. The number of readings (n) to be used for the estimated percent defective shall be no less than eight (8) for a sample group of ten (10), seventeen (17) for a sample group of twenty (20) or twenty-six (26) for a sample group of thirty (30). The number of readings used as a basis shall exclude duds, off times and lost times. If there are insufficient rounds in any group, it is the Government's option to require additional rounds to be fired under the conditions of the group, until sufficient in accordance with the above.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:49Z
Check the source to verify that this is the current version before use.

6.7 Subject term (key word) listing.

Cartridge, Illuminating, M853
Cartridge, Smoke, RP, M819
Fuze, Mechanical Time Super Quick, M772
I81MM Mortar
Testing, Arming Safety

6.8 Changes from previous issue. Vertical lines are not use in this version to identify changes with respect to the previous issue, due to extensiveness of changes.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1390-A560)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:49Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

(See Instructions – Reverse Side)

1. DOCUMENT NUMBER	2. DOCUMENT TITLE
MIL-F-70620A	FUZE, MTSQ, M772 LOADING, ASSEMBLING AND PACKING

3a. NAME OF SUBMITTING ORGANIZATION	4. TYPE OF ORGANIZATION *(Mark one)*
	☐ VENDOR
	☐ USER
b. ADDRESS *(Street, City, State, ZIP Code)*	☐ MANUFACTURER
	☐ OTHER *(Specify)*: _____

5. PROBLEM AREAS

a. Paragraph Number and Wording:

b. Recommended Wording:

c. Reason/Rationale for Recommendation:

6. REMARKS

7a. NAME OF SUBMITTER *(Last, First, MI)* – Optional	b. WORK TELEPHONE NUMBER *(Include Area Code)* – Optional
c. MAILING ADDRESS *(Street, City, State, ZIP Code)* – Optional	8. DATE OF SUBMISSION *(YYMMDD)*

DD FORM 82 MAR 1426 PREVIOUS EDITION IS OBSOLETE.

(TO DETACH THIS FORM, CUT ALONG THIS LINE.)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:49Z
Check the source to verify that this is the current version before use.