QUALIFICATION VALIDATED
EVERY 12 MONTHS

QPL-AS604-4
1 June 00
SUPERSEDING
QPL-AS604-3
26 Jun 98

QUALIFIED PRODUCTS LIST

OF

PRODUCTS QUALIFIED UNDER SAE AEROSPACE STANDARD

SAE-AS-604

HOSE ASSEMBLY, POLYTETRAFLUORETHYLENE, METALLIC REINFORCED,

3000 psi, 400°F, HEAVYWEIGHT, HYDRAULIC AND PNEUMATIC

This list has been prepared for use by or for the Government in the acquisition of products covered by Specification SAE-AS-604. Listing of a product is not intended to and does not connote endorsement of the product by the Department of Defense. All products listed herein have been qualified under the requirements for the product as specified in the latest effective issue of the applicable specification. This list is subject to change without notice; revision or amendment of this list will be issued as necessary. The listing of a product does not release the supplier from compliance with the specification requirements.

The activity responsible for this QPL is the Defense Supply Center Columbus (DSCC-VQ), Columbus, OH 43216-5000.

* X = size or size code

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER *	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
AS621			
-4,-6,-8,-10,-12,-16	AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X	19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98	Aeroquip Corporation
-4,-6,-8,-10,-12,-16	R736CC41-X	14 Oct 68,16 Jan 90, 23 Apr 73	Crane Resistoflex Company

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:28Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER *	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
AS621			
-4,-6,-8,-10,-12,-16	170141-X	26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89	Parker Hannifin Corporation
-4,-6,-8,-10,-12	514551X	21 Aug 92, 8 Mar 93	Teleflex, Inc.
-4,-6,-8,-10,-12,-16,-20	660606X, 240606X	12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76	Titeflex Corporation
AS622			
-4,-6,-8,-10,-12,-16	AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X	19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98	Aeroquip Corporation
-4,-6,-8,-10,-12,-16	R736CC42-X	14 Oct 68,16 Jan 90, 23 Apr 73	Crane Resistoflex Company
-4,-6,-8,-10,-12,-16	170143-X	26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89	Parker Hannifin Corporation
-4,-6,-8,-10,-12	514552X	21 Aug 92, 8 Mar 93	Teleflex, Inc.
-4,-6,-8,-10,-12,-16,-20	660614X, 240614X	12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76	Titeflex Corporation
AS623			
-4,-6,-8,-10,-12,-16	AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X	19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98	Aeroquip Corporation
-4,-6,-8,-10,-12,-16	R736CC43-X	14 Oct 68,16 Jan 90, 23 Apr 73	Crane Resistoflex Company
-4,-6,-8,-10,-12,-16	170145-X	26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89	Parker Hannifin Corporation
-4,-6,-8,-10,-12	514553X	21 Aug 92, 8 Mar 93	Teleflex, Inc.
-4,-6,-8,-10,-12,-16,-20	660615X, 240615X	12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76	Titeflex Corporation

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:28Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER *	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
AS624			
-4,-6,-8,-10,-12,-16	AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X	19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98	Aeroquip Corporation
-4,-6,-8,-10,-12,-16	R736CC44-X	14 Oct 68,16 Jan 90, 23 Apr 73	Crane Resistoflex Company
-4,-6,-8,-10,-12,-16	170190-X	26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89	Parker Hannifin Corporation
-4,-6,-8,-10,-12	524552X	21 Aug 92, 8 Mar 93	Teleflex, Inc.
-4,-6,-8,-10,-12,-16,-20	661414X, 241414X	12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76	Titeflex Corporation
AS625			
-4,-6,-8,-10,-12,-16	AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X	19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98	Aeroquip Corporation
-4,-6,-8,-10,-12,-16	R736CC45-X	14 Oct 68,16 Jan 90, 23 Apr 73	Crane Resistoflex Company
-4,-6,-8,-10,-12,-16	170192-X	26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89	Parker Hannifin Corporation
-4,-6,-8,-10,-12	524553X	21 Aug 92, 8 Mar 93	Teleflex, Inc.
-4,-6,-8,-10,-12,-16,-20	661415X, 241415X	12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76	Titeflex Corporation
AS626			
-4,-6,-8,-10,-12,-16	AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X	19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98	Aeroquip Corporation
-4,-6,-8,-10,-12,-16	R736CC46-X	14 Oct 68,16 Jan 90, 23 Apr 73	Crane Resistoflex Company

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:28Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER *	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
AS626			
-4,-6,-8,-10,-12,-16	170235-X	26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89	Parker Hannifin Corporation
-4,-6,-8,-10,-12	534553X	21 Aug 92, 8 Mar 93	Teleflex, Inc.
-4,-6,-8,-10,-12,-16,-20	661515X, 241515X	12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76	Titeflex Corporation
AS627			
-4,-6,-8,-10,-12,-16	AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X	19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98	Aeroquip Corporation
-4,-6,-8,-10,-12,-16	R736CC31-X	14 Oct 68,16 Jan 90, 23 Apr 73	Crane Resistoflex Company
-4,-6,-8,-10,-12,-16	170001-X	26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89	Parker Hannifin Corporation
-4,-6,-8,-10,-12	544554X	21 Aug 92, 8 Mar 93	Teleflex, Inc.
-4,-6,-8,-10,-12,-16,-20	660000X, 240000X	12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76	Titeflex Corporation
AS628			
-4,-6,-8,-10,-12,-16	AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X	19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98	Aeroquip Corporation
-4,-6,-8,-10,-12,-16	R736CC32-X	14 Oct 68,16 Jan 90, 23 Apr 73	Crane Resistoflex Company
-4,-6,-8,-10,-12,-16	170003-X	26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89	Parker Hannifin Corporation
-4,-6,-8,-10,-12	544555X	21 Aug 92, 8 Mar 93	Teleflex, Inc.
-4,-6,-8,-10,-12,-16,-20	660001X, 240001X	12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76	Titeflex Corporation

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:28Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER *	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
AS629			
-4,-6,-8,-10,-12,-16	AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X	19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98	Aeroquip Corporation
-4,-6,-8,-10,-12,-16	R736CC33-X	14 Oct 68,16 Jan 90, 23 Apr 73	Crane Resistoflex Company
-4,-6,-8,-10,-12,-16	170005-X	26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89	Parker Hannifin Corporation
-4,-6,-8,-10,-12	544556X	21 Aug 92, 8 Mar 93	Teleflex, Inc.
-4,-6,-8,-10,-12,-16,-20	660002X, 240002X	12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76	Titeflex Corporation
AS630			
-4,-6,-8,-10,-12,-16	AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X	19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98	Aeroquip Corporation
-4,-6,-8,-10,-12,-16	R736CC34-X	14 Oct 68,16 Jan 90, 23 Apr 73	Crane Resistoflex Company
-4,-6,-8,-10,-12,-16	170060-X	26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89	Parker Hannifin Corporation
-4,-6,-8,-10,-12	554555X	21 Aug 92, 8 Mar 93	Teleflex, Inc.
-4,-6,-8,-10,-12,-16,-20	660101X, 240101X	12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76	Titeflex Corporation

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:28Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER *	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
AS631			
-4,-6,-8,-10,-12,-16	AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X	19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98	Aeroquip Corporation
-4,-6,-8,-10,-12,-16	R736CC35-X	14 Oct 68,16 Jan 90, 23 Apr 73	Crane Resistoflex Company
-4,-6,-8,-10,-12,-16	170062-X	26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89	Parker Hannifin Corporation
-4,-6,-8,-10,-12	554556X	21 Aug 92, 8 Mar 93	Teleflex, Inc.
-4,-6,-8,-10,-12,-16,-20	660102X, 240102X	12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76	Titeflex Corporation
AS632			
-4,-6,-8,-10,-12,-16	AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X	19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98	Aeroquip Corporation
-4,-6,-8,-10,-12,-16	R736CC36-X	14 Oct 68,16 Jan 90, 23 Apr 73	Crane Resistoflex Company
-4,-6,-8,-10,-12,-16	170115-X	26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89	Parker Hannifin Corporation
-4,-6,-8,-10,-12	564556X	21 Aug 92, 8 Mar 93	Teleflex, Inc.
-4,-6,-8,-10,-12,-16,-20	660202X, 240202X	12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76	Titeflex Corporation

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:28Z
Check the source to verify that this is the current version before use.

MANUFACTURER and SUPPLIER LOCATION INFORMATION

Manufacturer: Aeroquip Corporation (CAGE Code: 00624)
Location: 300 S. East Avenue, Jackson, MI 49203-1972, US
Plant Location: Same address as manufacturer

Manufacturer: Crane Resistoflex Company (CAGE Code: 50599)
Location: 2575 West 5th Street, Jacksonville, FL 32254, US
Plant Location: Same address as manufacturer

Manufacturer: Parker Hannifin Corporation (CAGE Code: 98441)
Location: 220 Roberts Cut-Off Road, Fort Worth, TX 76114-0398, US
Plant Location: Same address as manufacturer

Manufacturer: Teleflex, Inc. (CAGE Code: 40223)
Location: One Firestone Drive, Suffield, CT 06078 US
Plant Location: 2615 Lantana Road – Suite A, Lantana, FL 33262, US

Manufacturer: Titeflex Corporation (CAGE Code: 78570)
Location: 603 Hendee Street, Springfield, MA 01109, US
Plant Location: Same address as manufacturer

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:28Z
Check the source to verify that this is the current version before use.