QUALIFICATION VALIDATED
EVERY 12 MONTHS

QPL-AS604-5
2 October 2001
SUPERSEDING
QPL-AS604-4
1 June 2000

# QUALIFIED PRODUCTS LIST

OF

PRODUCTS QUALIFIED UNDER SAE AEROSPACE STANDARD

SAE-AS-604

HOSE ASSEMBLY, POLYTETRAFLUORETHYLENE, METALLIC REINFORCED,

3000 psi, 400°F, HEAVYWEIGHT, HYDRAULIC

This list has been prepared for use by or for the Government in the acquisition of products covered by Specification SAE-AS-604. Listing of a product is not intended to and does not connote endorsement of the product by the Department of Defense. All products listed herein have been qualified under the requirements for the product as specified in the latest effective issue of the applicable specification. This list is subject to change without notice; revision or amendment of this list will be issued as necessary. The listing of a product does not release the supplier from compliance with the specification requirements.

The activity responsible for this QPL is the Defense Supply Center Columbus (DSCC-VQ), Columbus, OH 43216-5000.

* X = size or size code

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER * | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| **AS621** | | | |
| -4,-6,-8,-10,-12,-16 | AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X | 19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98 | Aeroquip Corp. |
| -4,-6,-8,-10,-12,-16 | R736CC41-X | 14 Oct 68,16 Jan 90, 23 Apr 73 | Crane Resistoflex Co. (1) |
| -4,-6,-8,-10,-12 | 514551X | 21 Aug 92, 8 Mar 93 | Crane Resistoflex Co. (2) |
| -4,-6,-8,-10,-12,-16 | 170141-X | 26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89 | Parker Hannifin Corp. |
| -4,-6,-8,-10,-12,-16,-20 | 660606X, 240606X | 12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76 | Titeflex Corp. |



DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:28Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER * | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| **AS622** | | | |
| -4,-6,-8,-10,-12,-16 | AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X | 19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98 | Aeroquip Corp. |
| -4,-6,-8,-10,-12,-16 | R736CC42-X | 14 Oct 68,16 Jan 90, 23 Apr 73 | Crane Resistoflex Co. (1) |
| -4,-6,-8,-10,-12 | 514552X | 21 Aug 92, 8 Mar 93 | Crane Resistoflex Co. (2) |
| -4,-6,-8,-10,-12,-16 | 170143-X | 26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89 | Parker Hannifin Corp. |
| -4,-6,-8,-10,-12,-16,-20 | 660614X, 240614X | 12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76 | Titeflex Corp. |
| **AS623** | | | |
| -4,-6,-8,-10,-12,-16 | AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X | 19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98 | Aeroquip Corp. |
| -4,-6,-8,-10,-12,-16 | R736CC43-X | 14 Oct 68,16 Jan 90, 23 Apr 73 | Crane Resistoflex Co. (1) |
| -4,-6,-8,-10,-12 | 514553X | 21 Aug 92, 8 Mar 93 | Crane Resistoflex Co. (2) |
| -4,-6,-8,-10,-12,-16 | 170145-X | 26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89 | Parker Hannifin Corp. |
| -4,-6,-8,-10,-12,-16,-20 | 660615X, 240615X | 12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76 | Titeflex Corp. |
| **AS624** | | | |
| -4,-6,-8,-10,-12,-16 | AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X | 19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98 | Aeroquip Corp. |
| -4,-6,-8,-10,-12,-16 | R736CC44-X | 14 Oct 68,16 Jan 90, 23 Apr 73 | Crane Resistoflex Co. (1) |
| -4,-6,-8,-10,-12 | 524552X | 21 Aug 92, 8 Mar 93 | Crane Resistoflex Co. (2) |


Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:28Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER * | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| -4,-6,-8,-10,-12,-16 | 170190-X | 26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89 | Parker Hannifin Corp. |
| -4,-6,-8,-10,-12,-16,-20 | 661414X, 241414X | 12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76 | Titeflex Corp. |
| **AS625** | | | |
| -4,-6,-8,-10,-12,-16 | AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X | 19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98 | Aeroquip Corp. |
| -4,-6,-8,-10,-12,-16 | R736CC45-X | 14 Oct 68,16 Jan 90, 23 Apr 73 | Crane Resistoflex Co. (1) |
| -4,-6,-8,-10,-12 | 524553X | 21 Aug 92, 8 Mar 93 | Crane Resistoflex Co. (2) |
| -4,-6,-8,-10,-12,-16 | 170192-X | 26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89 | Parker Hannifin Corp. |
| -4,-6,-8,-10,-12,-16,-20 | 661415X, 241415X | 12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76 | Titeflex Corp. |
| **AS626** | | | |
| -4,-6,-8,-10,-12,-16 | AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X | 19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98 | Aeroquip Corp. |
| -4,-6,-8,-10,-12,-16 | R736CC46-X | 14 Oct 68,16 Jan 90, 23 Apr 73 | Crane Resistoflex Co. (1) |
| -4,-6,-8,-10,-12 | 534553X | 21 Aug 92, 8 Mar 93 | Crane Resistoflex Co. (2) |
| -4,-6,-8,-10,-12,-16 | 170235-X | 26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89 | Parker Hannifin Corp. |
| -4,-6,-8,-10,-12,-16,-20 | 661515X, 241515X | 12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76 | Titeflex Corp. |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:28Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER * | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| **AS627** | | | |
| -4,-6,-8,-10,-12,-16 | AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X | 19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98 | Aeroquip Corp. |
| -4,-6,-8,-10,-12,-16 | R736CC31-X | 14 Oct 68,16 Jan 90, 23 Apr 73 | Crane Resistoflex Co. (1) |
| -4,-6,-8,-10,-12 | 544554X | 21 Aug 92, 8 Mar 93 | Crane Resistoflex Co. (2) |
| -4,-6,-8,-10,-12,-16 | 170001-X | 26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89 | Parker Hannifin Corp. |
| -4,-6,-8,-10,-12,-16,-20 | 660000X, 240000X | 12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76 | Titeflex Corp. |
| **AS628** | | | |
| -4,-6,-8,-10,-12,-16 | AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X | 19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98 | Aeroquip Corp. |
| -4,-6,-8,-10,-12,-16 | R736CC32-X | 14 Oct 68,16 Jan 90, 23 Apr 73 | Crane Resistoflex Co. (1) |
| -4,-6,-8,-10,-12 | 544555X | 21 Aug 92, 8 Mar 93 | Crane Resistoflex Co. (2) |
| -4,-6,-8,-10,-12,-16 | 170003-X | 26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89 | Parker Hannifin Corp. |
| -4,-6,-8,-10,-12,-16,-20 | 660001X, 240001X | 12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76 | Titeflex Corp. |


Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:28Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER * | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| **AS629** | | | |
| -4,-6,-8,-10,-12,-16 | AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X | 19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98 | Aeroquip Corp. |
| -4,-6,-8,-10,-12,-16 | R736CC33-X | 14 Oct 68,16 Jan 90, 23 Apr 73 | Crane Resistoflex Co. (1) |
| -4,-6,-8,-10,-12 | 544556X | 21 Aug 92, 8 Mar 93 | Crane Resistoflex Co. (2) |
| -4,-6,-8,-10,-12,-16 | 170005-X | 26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89 | Parker Hannifin Corp. |
| -4,-6,-8,-10,-12,-16,-20 | 660002X, 240002X | 12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76 | Titeflex Corp. |
| **AS630** | | | |
| -4,-6,-8,-10,-12,-16 | AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X | 19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98 | Aeroquip Corp. |
| -4,-6,-8,-10,-12,-16 | R736CC34-X | 14 Oct 68,16 Jan 90, 23 Apr 73 | Crane Resistoflex Co. (1) |
| -4,-6,-8,-10,-12 | 554555X | 21 Aug 92, 8 Mar 93 | Crane Resistoflex Co. (2) |
| -4,-6,-8,-10,-12,-16 | 170060-X | 26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89 | Parker Hannifin Corp. |
| -4,-6,-8,-10,-12,-16,-20 | 660101X, 240101X | 12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76 | Titeflex Corp. |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:28Z
Check the source to verify that this is the current version before use.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER * | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| **AS631** | | | |
| -4,-6,-8,-10,-12,-16 | AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X | 19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98 | Aeroquip Corp. |
| -4,-6,-8,-10,-12,-16 | R736CC35-X | 14 Oct 68,16 Jan 90, 23 Apr 73 | Crane Resistoflex Co. (1) |
| -4,-6,-8,-10,-12 | 554556X | 21 Aug 92, 8 Mar 93 | Crane Resistoflex Co. (2) |
| -4,-6,-8,-10,-12,-16 | 170062-X | 26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89 | Parker Hannifin Corp. |
| -4,-6,-8,-10,-12,-16,-20 | 660102X, 240102X | 12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76 | Titeflex Corp. |
| **AS632** | | | |
| -4,-6,-8,-10,-12,-16 | AR1411-X, AR1413-X, AR1414-X, AR1430-X, AR1432-X, AR1433-X | 19 Apr 68, 30 Mar 70, 29 May 73, 30 Aug 77, 17 Jul 78, 14 Sep 78, 12 Oct 78, 15 Nov 87, 3 Aug 98 | Aeroquip Corp. |
| -4,-6,-8,-10,-12,-16 | R736CC36-X | 14 Oct 68,16 Jan 90, 23 Apr 73 | Crane Resistoflex Co. (1) |
| -4,-6,-8,-10,-12 | 564556X | 21 Aug 92, 8 Mar 93 | Crane Resistoflex Co. (2) |
| -4,-6,-8,-10,-12,-16 | 170115-X | 26 Jan 71, 1 May 73, 26 Feb 80, 22 Jan 81, 20 Feb 81, 10 Dec 81, 23 Jan 89 | Parker Hannifin Corp. |
| -4,-6,-8,-10,-12,-16,-20 | 660202X, 240202X | 12 Mar 68, 9 Aug 68, 24 May 73, 9 Jul 76 | Titeflex Corp. |



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:28Z
Check the source to verify that this is the current version before use.

## MANUFACTURER and SUPPLIER LOCATION INFORMATION

**Manufacturer:** Aeroquip Corp. (CAGE Code: 00624)
Location: 300 S. East Avenue, Jackson, MI 49203-1972, US
Plant Location: Same address as manufacturer

**Manufacturer:** Crane Resistoflex Co. (CAGE Code: 50599)
Location: 2575 West 5th Street, Jacksonville, FL 32254, US
Plant Location: 1. Same address as manufacturer
2. 2615 Lantana Road, Suite A, Lantana, FL 33262, US

**Manufacturer:** Parker Hannifin Corp. (CAGE Code: 98441)
Location: 220 Roberts Cut-Off Road, Fort Worth, TX 76114-0398, US
Plant Location: Same address as manufacturer

**Manufacturer:** Titeflex Corp. (CAGE Code: 78570)
Location: 603 Hendee Street, Springfield, MA 01109, US
Plant Location: Same address as manufacturer



Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:28Z
Check the source to verify that this is the current version before use.