A-A-1965
October 15, 1982

COMMERCIAL ITEM DESCRIPTION

JACKET, FILING, WALLET

The General Services Administration has authorized the use of this commercial item description in preference to Jacket, Filing, Wallet as specified in Federal Specification UU-J-390C.

Salient characteristics:
Filing jackets shall be without flaps and shall have at least half-height gussets and plain, untabbed edges. Filing jackets shall be supplied in sizes as specified. The 9-1/2 (±1/16) inch x 18 (±1/16) inch filing jacket shall have full gussets. The leaves of the jackets shall be two-ply with rounded corners. The color of the outer ply shall be red; the color of the inner ply shall be red, salmon, or manila as specified. The front leaf shall be 1/2 inch (± 1/8 inch) lower than the top of the back leaf. The gusset shall be one ply, single piece construction with a reinforcing strip of cloth, polymeric nonwovern material, or latex impregnated fiber not less than 5/8 inch wide completely and securely glued to the top of the gusset on the inside face. The gusset shall be the same color as the outer ply of the leaves. The number of gusset folds for each expansion shall be as follows:

Sizes	Expansions
9-1/2 x 11-3/4	7/8 inch expansion - 1 fold
9-1/2 x 14-3/4	1-3/4 inch expansion - 2 folds
9-1/2 x 18	3-1/2 inch expansion - 4 folds

The leaves and gussets shall be made of red material conforming to the following requirements:

Characteristic	Requirement		TAPPI*
	Gusset	Leaves (2-ply)	Test Method
Basis weight (24 x 36-500), pounds	120 min.	240 min.	T-410
Thickness (inch)	0.009 min.	0.018 min.	T-411
Bursting strength (p.s.i.)	95 min.	190 min.	T-403
Tearing strength (grams, average both directions)	280 min.	550 min.	T-414
Fold endurance			
Machine direction	600 min.	---	T-511
Cross direction	375 min.	---	T-511

*The issue of the TAPPI test method in effect on the day of the solicitation shall be used to determine compliance with the requirements.

The plies of the leaves shall be completely and securely bonded together. When the plies are pulled apart, failure shall be entirely in the paper stock and not the adhesive bonds. The gusset shall be completely and securely bonded in place between the plies of the leaves. When the gusset is pulled from the leaves, failure shall be entirely in the paper stock and not the adhesive bond.

Workmanship. The filing jackets shall be free from holes, tears, creases, wrinkles, blisters, lumps and ply separations. The filing jackets shall lie flat and shall not warp or buckle. The jackets shall be clean and free of discoloration. There shall be no adhesive on any exposed surface. The top edges of the front and back leaves shall be parallel. The side edges of the front and back leaves shall be flush.

Source: https://assist.dla.mil -- Downloaded: 202610-26T08:18Z
Check the source to verify that this is the currentversion before use.

Regulatory requirements. The offeror/contractor is encouraged to use recovered materials in accordance with Public Law 94-580 to the maximum extent practicable.

Preservation, packaging, packing, labeling and marking. Preservation, packaging, packing, labeling and marking shall be as specified in the contract or order.

Note: TAPPI test methods are available from the Technical Association of the Pulp and Paper Industry, One Dunwoody Park, Atlanta, GA 30341.

Preparing Activity

GSA - OPP

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T08:18Z
Check the source to verify that this is the current version before use.