MIL-F-48388A (AR)
AMENDMENT 1
27 January 1989

MILITARY SPECIFICATION

FUZE, M934E6, LAUNCH SENSING SWITCH FOR

This Amendment forms part of Military Specification MIL-F-48388A (AR), dated 1 July 1985, and is approved for use within the U.S. Army Armament Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 3

Delete paragraph 3.2.5 in its entirety.

Add new paragraph 3.2.5 as follows:

"3.2.5 Solderability. The solderability shall meet the requirements of MIL-STD-202, Method 208."

Delete page 6 in its entirety.

Add new page 6A.

Add new page 6B.

PAGE 18

Paragraph 4.4.2.9 Major category:

Major 101: In column labeled "Para. Ref. / Insp. Meth.", delete "Gage" and substitute "Visual".

Delete page 20 in its entirety.

Add new page 20.

Delete page 21 in its entirety.

Add new page 21.

PAGE 22

Delete paragraph 4.5.2 in its entirety and substitute the following:

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:24Z
Check the source to verify that this is the current version before use.

"4.5.2 Closing time. The switch shall be mounted on a shock machine capable of producing a 30 g minimum square wave pulse of 17 milliseconds minimum duration. An accelerometer shall be mounted on the drop fixture to measure the shock pulse. The accelerometer's wave form may be low-pass filtered with a minimum band width of 200 Hz. Data shall be recorded showing the shock pulse and closure time of the launch switch using a storage oscilloscope. The wave form shall be recorded (eg. photograph, plotter trace) to provide a permanent record of the test. To verify switch closing time, the launch switch shall be subjected to an acceleration in a direction to move the switch weight towards contact along the longitudinal M-N axis of figure 1."

PAGE 23

Delete paragraph 4.5.5 in its entirety.

Add new paragraph as follows.

"4.5.5 Solderability. The solderability shall be performed as specified in MIL-STD-202, Method 208, with the exception that the aging requirement shall be one hour."

4.5.10 Shock, operating.

Delete "free-fall".

Delete "Parallel to the M-N axis in an M to N direction" and substitute "Parallel to the M-N axis in a direction to move the switch weight towards contact".

6.4 Submission of designs for approval.

Delete "Dover, NJ 07801-5000." and substitute "Picatinny Arsenal, NJ 07806-5000.".

Custodian:
Army-AR

Preparing Activity:
Army-AR:
(Project 1336-A569)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:24Z
Check the source to verify that this is the current version before use.

TABLE I FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET OF		DRAWING NUMBER
	SWITCH ASSEMBLY, LAUNCH, AND COMPONENTS		1 2		9297015
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	SWITCH ASSEMBLY, LAUNCH Group A 1/	6			
	Marking			3.1	Visual
	Workmanship			3.5	Visual
	Launch Acceleration Sensing			3.2.1	4.5.1/Gage
	Lead Resistance			3.2.3	4.5.3/Gage
	Insulation Resistance			3.2.4	4.5.4/Gage
	Solderability			3.2.5	4.5.5

NOTES:

1/ Destructive Test

2/ 1/2 Hot 1/2 Cold. The units subjected to hot temperature shall be subjected to hot operating temperature. The units subjected to cold temperature shall be subjected to cold operating temperature.

3/ Initiate test within 5 minutes of removal from temperature chamber, with temperatures per note 2.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:24Z
Check the source to verify that this is the current version before use.

TABLE I FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
	SWITCH ASSEMBLY, LAUNCH, AND COMPONENTS	2	2	9297015
				NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Group B 1/ Environmental Sequence	12			
	Marking			3.1	Visual
	Workmanship			3.5	Visual
	Temperature 2/			3.2.8	4.5.8
	Transportation Vibration 2/			3.2.6	4.5.6
	Vibration-Acceleration Operating 2/			3.2.9	4.5.9
	Handling Shock 3/			3.2.7	4.5.7
	Shock, Operating 3/			3.2.10	4.5.10
	Launch Acceleration Sensing 3/			3.2.1	4.5.1
	Lead Resistance 3/			3.2.3	4.5.3/Gage
	Closing Time			3.2.2	4.5.2/Gage
	Insulation Resistance			3.2.4	4.5.4/Gage

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:24:22Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.11	SWITCH ASSEMBLY - LAUNCH	1 OF 2	9297015
			NEXT HIGHER ASSEMBLY 9297030

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	SWITCH ASSEMBLY, LAUNCH Group A				
Major					
101	Launch Acceleration Sensing		100%	3.2.1	4.5.1/Gage
102	Lead Resistance		100%	3.2.3	4.5.3/Gage
103	Insulation Resistance		100%	3.2.4	4.5.4/Gage
Minor					
201	Marking		0.40%	3.1	Visual
202	Workmanship		0.40%	3.5	Visual

NOTES:

1/ Destructive Test

2/ 1/2 Hot 1/2 Cold. The units subjected to hot temperature shall be subjected to hot operating temperature. The units subjected to cold temperature shall be subjected to cold operating temperature.

3/ Initiate test within 5 minutes of removal from temperature chamber, with temperatures per note 2 (above).

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:24Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.11	SWITCH ASSEMBLY - LAUNCH		2 2	9297015
				NEXT HIGHER ASSEMBLY: 9297030

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Group B 1/ Environmental Sequence		4/		
Major					
104	Temperature 2/			3.2.8	4.5.8
105	Transportation Vibration 2/			3.2.6	4.5.6
106	Vibration-Acceleration Operating 2/			3.2.9	4.5.9
107	Handling Shock 3/			3.2.7	4.5.7
108	Shock Operating 3			3.2.10	4.5.10
109	Launch Acceleration Sensing 3/			3.2.1	4.5.1/Gage
110	Lead Resistance 3/			3.2.3	4.5.3/Gage
111	Closing Time			3.2.2	4.5.2/Gage
112	Insulation Resistance			3.2.4	4.5.4/Gage
Minor					
203	Marking			3.1	Visual
204	Workmanship			3.5	Visual
205	Solderability			3.5.2	4.5.5

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T19:24Z
Check the source to verify that this is the current version before use.