ADOPTION NOTICE

EIA364.45, "Firewall Flame Test Procedure for Electrical Connectors (S/S by EIA-364-45)", was adopted on 13-SEP-2011 for use by the Department of Defense (DoD). Proposed changes by DoD activities must be submitted to the DoD Adopting Activity: Defense Supply Center Columbus, P.O. Box 3990, Attn: DSCC-VAC, Columbus, OH 43216-5000. Copies of this document may be purchased from the Electronic Components Association, 2500 Wilson Boulevard, Suite 310, Arlington, Virginia 22201.

EIA364.45 has been superseded by EIA-364-45.

Custodians:
Army - CR
Navy - AS
Air Force - 85
DLA - CC

Adopting Activity:
DLA - CC

Reviewer Activities:
Army - AV, MI

NOTE: The activities above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.dla.mil.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T15:46Z
Check the source to verify that this is the current version before use.