INCH-POUND
A-A-59876
30 Nov 2010

COMMERCIAL ITEM DESCRIPTION

Calibrator, Torque Wrench
5 in-lbs – 2000 ft-lbs

The General Services Administration has authorized the use of this commercial item description for all federal agencies.

1. SCOPE. This document describes performance requirements for a Torque Wrench Calibrator, and associated dead-weight calibration equipment. The Torque Wrench Calibrator consists of two separate "stations". The two stations of the Torque Wrench Calibrator must be capable of being operated at the same time. These systems are intended for use by civilian and military personnel to perform calibration of torque setting and indicating instruments, force gages, dynamometers, and cable testers.

2. SALIENT CHARACTERISTICS

2.1 Torque Wrench Calibrator description. There shall be one low torque (manual) station for calibrating torque wrenches and screwdrivers, having a range of 5 in-lb to 250 ft-lb and one high torque station for mechanically generated torque, tension, and force calibrator having a range of 30 in-lb to 2000 ft-lb. The design of the torque loader shall be inherently safe, upon failure of the drive bar and adapter plates; for example, fragments and broken parts shall be contained within the framework of the machine. Any reaction posts or similar structures attached to the frame shall be designed to a safety factor of five or better on ultimate material strength. A method shall be provided for restraining torque wrench handles. Reaction bars, and tension cables, in the event that the test item or tension cable disengages from the machine or breaks. The safety restraint shall provide complete protection to the operator during calibration of force gauges, and cable testers.

2.2 Design and construction. The Torque Wrench Calibrator shall be designed and constructed so that no parts will work loose in service. It shall be built to withstand the strains, jars, vibrations, and other conditions incident to shipping, storage, installation, and service. It shall be weatherproof and designed to prevent the intrusion of water and sand into critical operating components.

2.2.1 Markings. All external devices which require an operational or maintenance interface shall be marked in accordance with MIL-STD-130.

Beneficial comments, recommendations, additions, deletions, clarifications, etc. and any data that may improve this document should be sent to: WR-ALC/GRVEC, Robins AFB GA 31098-1813. Since contact information can change, you may want to verify the currency of this address information using the ASSIST Online database at https://assist.daps.dla.mil/online .

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:29Z
Check the source to verify that this is the current version before use.

2.2.2 Identification and information plates. An identification plate in accordance with MIL-STD-130 shall be securely attached to the Torque Wrench Calibrator in a readily accessible location. The identification plate shall contain the following information: nomenclature, part number, serial number, date of manufacture, manufacturer's name, Commercial and Government Entity (CAGE) code, date of warranty expiration, and National Stock Number (NSN). In accordance with MIL-STD-130, the Torque Wrench Calibrator and any components meeting Unique Identification (UID) criteria shall have UID information permanently affixed near the respective identification plate(s). UID information shall be included as both a bar code and human readable markings.

2.2.3 Fastening devices. All screws, bolts, nuts, pins, and other fastening devices shall be properly designed, manufactured, and installed with adequate means of preventing loss of torque or adjustment. Cotter pins, lock washers, or nylon patches shall not be used for this purpose, except for the attachment of trim items or as provided in commercial components. Tapped aluminum threads shall have a minimum thread engagement of at least two times the nominal fastener diameter.

2.2.4 Welders and welding. Welding procedures shall be in accordance with a nationally recognized welding code. The surface parts to be welded shall be free from rust, scale, paint, grease, and other foreign matter. Welds shall be of sufficient size and shape to develop the full strength of the welded parts. Welds shall transmit stress without cracking or permanent distortion when the parts connected by the welds are subjected to test, proof, and service loadings.

2.2.5 Foolproofness. Where improper installation of an item causes a malfunction, an asymmetric mounting system shall be provided, where practical, to ensure proper mounting of the item.

2.3 Environmental conditions.

2.3.1 Operating temperature range. The Torque Wrench Calibrator shall be capable of operating in ambient temperatures ranging from 67 degrees F to 79 degrees F, with a relative humidity of 20% to 50% (non-condensing). The temperature and relative humidity shall be continuously monitored and recorded by a monitor located in each room where calibration activities are being conducted.

2.3.2 Storage temperature range. The Torque Wrench Calibrator shall be capable of being stored in ambient temperatures ranging from -40 degrees F to +160 degrees F, with a relative humidity of up to 95% (non-condensing), with no degradation to performance or requirement for maintenance.

2.4 System dimensions. The high torque station Torque Wrench Calibrator dimensions, excluding the digital indicator, shall not exceed 45 inches in width, 24 inches in depth, and 50 inches in height, when the slides and other accessories are retracted

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:29Z
Check the source to verify that this is the current version before use.

2.5 Performance. The Torque Wrench Calibrator shall meet the following capabilities, unless otherwise specified, following a warm-up period of no greater than thirty minutes. The Torque Wrench Calibrator maximum non-repeatability shall be +/- 0.15% indicated value of the average of five replications, or +/- 0.1 in-oz, whichever is greater, throughout the specified range of 0.5 in-oz to 2000 ft-lb. The Torque Wrench Calibrator's maximum creep, measured from the initial reading on loading to the reading after five minutes, must not exceed 0.15% of full scale for each transducer. Torque ranges shall be provided such that the following outputs are obtained at the test interfaces: low torque (bidirectional) 5 in-lb to 250 ft-lb; high torque (bidirectional) 30 in-lb to 2000 ft-lb and force from 5 lb to 2000 lb. The total uncertainty shall not exceed +/- 0.5% indicated value for either. Total uncertainty refers to the combined effects of linearity, hysteresis, zero drift, creep, temperature coefficient, and any other error contributions, added to the systematic uncertainty contributed by the calibration standard.

2.5.1 Low torque. The low torque section shall be a bench-top instrument for manual torque testing from 5 in-lb to 250 ft-lb. All transducers shall be mounted in the same plane of a common fixture. The fixture shall be designed to be turned on its side so that any torque wrench may be oriented with its handle parallel or perpendicular to the floor. This fixture shall be sturdy enough to allow a wrench to be torqued to 250 ft-lb without sliding or reacting on any type of bench-top surface. Clamping mechanisms are permitted; bolting or holding devices which require modification to the bench-top surface are not permitted. The low torque section shall accommodate all instruments which are in torque range. The low torque section shall have a dedicated digital indicator. The digital indicator's front panel must be easily viewed and accessed by the operator, when the indicator is placed on a bench-top with a height between 34 and 44 inches and a depth not to exceed 36 inches. All transducers in the low torque section shall be capable of being connected to the digital indicator at all times by cables which are detachable at each end with cannon-plug type connectors. A selector switch on the front panel of the digital indicator shall show the range of each transducer. An indicator shall also be illuminated next to the active transducer. Since this section of the torque calibrator shall not have a torque generation system, a visual and audible overload indicator shall be provided to alert the operator before the torque cell is overloaded to the point of permanent deformation.

2.5.2 High torque. The high torque section shall be a versatile, operator-friendly calibrator for calibrating torque wrenches, multipliers and force gages. The high torque section shall be equipped with a protective mechanism which shall automatically actuate when the load limit of the torque cell is exceeded (whether the torque is loaded automatically or manually). The operator shall not be required to interact with the calibrator to distinguish which load cell is in use or what the maximum load limit is. The calibrator shall also be equipped with "dummy" drive sockets, for the operator to exercise torque wrenches prior to mounting on the calibrator. The "dummy" drive sockets (sizes ¼, $^{3}/_{8}$, ½, ¾ and 1 inch female square) shall be positioned in a location convenient to the operator.

2.5.2.1 Torque generator. The high torque portion of the Torque Wrench Calibrator shall contain a manual or automatic mechanical loader. The mechanical loader's sensitivity must be commensurate with the resolution of the indicator. If a manual loader is used then no more than 30 revolutions shall be required to test the full range of any one test item. Multiple loading mechanisms may be used. Maximum input torque for manual operation is 8 ft-lb.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:29Z
Check the source to verify that this is the current version before use.

2.5.2.2 Torque instrument fixturing. The reaction post must ride on a stable horizontal slider with quick-adjust settings. All reaction posts, fixturing, and adapters must accommodate at least the instruments listed in this document within its torque range, such that the maximum possible misalignment, measured from the transducer platform to the free-standing instrument, is 3° in any plane.

2.5.3 Torque transducers. Multiple torque transducers may be used to cover the range of the instrument. Torque transducers shall overlap the range of the next lower capacity by at least 10%. Transducers shall be easily interchangeable within the instrument fixturing and shall all connect via the same quick connect (canon-type plug) output cable to the digital indicator. The indicator shall identify the transducer selected without operator input.

2.5.4. Digital indicator. Each section of the Torque Wrench Calibrator shall contain an electronic digital readout display capable of displaying the measured torque. At a minimum, the characters shall be at least 0.5 inch in height. A cathode ray tube monitor shall not be used for this display.

2.5.5 Indications.

2.5.5.1 Visual indications. Visual indication shall be provided on the front panel of the digital indicator to indicate, at a minimum, the following conditions: power on/off, applicable engineering units, transducer in use range, torque over-range (greater than 100% of transducer range), first Peak-of-Torque, peak, track, and clockwise or counterclockwise operation.

2.5.5.2 Audible indications. Audible indication shall be provided to indicate torque over-range greater than 120% of transducer range. First Peak-of-Torque is defined as the first peak torque value just prior to the torque drop-off which occurs as the wrench begins its “camming action.” This value shall be displayed on the digital indicator for 3 seconds, then automatically rezero.

2.5.6 Calibration. The indicator shall have a zero adjustment available to the operator and separate calibration adjustments (either electronic or mechanical) available to the calibrating technician through the use of a “password” or “calibration void” sticker. The indicator shall permit interchangeability of transducers within the same range, without requiring hardware changes in the digital indicator. The range of the output millivolt or volt (mV or V) of all transducers delivered shall not exceed 50% of adjustment range of the digital indicator. All fixtures required to calibrate the torque cells using the dead-weight method shall be provided. All moment arms (bipolar), cables, weight pans, weights, etc., shall be supplied for on-site calibration of the Torque Wrench Calibrator. Each calibration arm shall overlap at least 10% of the useable range of the next lower capacity arm. Total uncertainty of the generated torque shall be documented and shall not exceed +/- 0.05% indicated value or +/- 0.1 in-oz, whichever is greater. No single piece of the calibration fixturing shall exceed 5 ft in length, or 50 lb in weight.

2.5.7 Diagnostics. The indicator shall employ the following functional self-tests. These self-tests shall, whenever possible, provide an internal verification of the equipment’s modes of operation. These self-tests shall require no external standards or devices. A means shall be provided to change any calibration factor or other correction data stored in the memory of the equipment, if available. The high-torque indicator shall be capable of displaying torque and

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:29Z
Check the source to verify that this is the current version before use.

force units; the item shall be capable of displaying torque in units of ft-lb, in-lb, in-oz, Newton-meters and meter-kilograms; the item shall be capable of displaying force in Newtons and pounds. The default shall be torque indicated in units of in-lb. The low torque indicator shall not require force or tension.

2.6 Electrical.

2.6.1 Power requirements. The Torque Wrench Calibrator shall have 120/220 VAC +/- 10%, 50/60 Hz nominal power requirements. A detachable power connector(s) shall be provided with the system. These connectors shall be a NEMA 5-15 style standard plug.

2.6.1.1 Power switch. There shall be an input power on-off switch located on the front panel. A visible light shall indicate when the equipment main power is on.

2.6.1.2 Power connections. A minimum 5 foot power cord shall be provided with the digital indicator.

2.6.1.3 Torque transducer power connections. A minimum 5 foot detachable cable shall be provided with the indicator for each torque transducer in the low torque section. At least one 5 foot minimum detachable cable shall be provided with high torque section. Each section shall include one spare cable.

2.6.1.4 Cable polarization. The polarization of all cable connectors shall be accomplished by a mechanical method that prevents inadvertent mating in more than one position. The polarization shall be accomplished prior to the electrical engagement of the contacts. All plug-in cabling shall be capable of being disconnected without major disassembly or removal of adjacent components.

2.6.2 Transient response. Permanent alteration of Torque Wrench Calibrator characteristics shall not occur for transients which recover within a steady state tolerance band within 500 milliseconds. Transient values are derived from and referenced to the nominal values specified for voltage and frequency.

2.6.3 Voltage transient. Voltage transients of 10% to 30% may impair the equipment performance momentarily, but the transient shall not interrupt normal operation for longer than 30 seconds.

2.6.4 Frequency transient. Frequency transient of 5% to 10% may impair the equipment performance momentarily, but the transient shall not interrupt normal operation for longer than 30 seconds.

2.6.5 Fuses or circuit breakers. Fuses or circuit breakers shall protect the internal circuitry and be easily accessible for all operators.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:29Z
Check the source to verify that this is the current version before use.

2.7 Printer. A printer with the following requirements shall be provided: a minimum 16-character width and two line per second speed which shall be provided for use with the high torque portion of the calibrator. The printer may be either internal to the digital indicator or in a separate enclosure physically and electrically attached to the digital indicator. The printer shall be capable of printing torque readings and units directly from the digital indicator. A "PRINT" button shall be provided for on either the indicator or printer. A paper feed button shall also be provided. The printer shall be provided with a device for allowing the operator to easily tear off a length of paper. At least six rolls of printer paper shall be provided, as well as 3 spare ink sources (the ribbon, toner cartridge, ink cartridge or other technology). The original manufacturer's part number for the printer shall be noted in the equipment manual. The paper and ink source shall be of a type available commercially. The paper size and ink cartridge manufacturer and part number shall be noted in the equipment manual.

2.8 Other requirements.

2.8.1 Front panel controls. All modes and functions shall be operable using front panel controls. The locations and labeling of indicators, controls, and switches shall provide for maximum clarity and easily understood operation without reference to tables, charts or flow diagrams.

2.8.2 Storage cabinet. A heavy-duty storage cabinet shall be supplied with the Torque Wrench Calibrator. The Torque Wrench Calibrator shall require minimal mounting to be stable on the storage cabinet. The cabinet shall accommodate all adapters and fixturing (with the exception of calibration weights and moment arms) in an orderly and accessible manner. Color and finish of the storage cabinet shall be identical to that of the main instrument. Knobs or handles on the cabinet shall not interfere with the operation of the mechanical loader. The storage cabinet shall store the low torque calibration section when those instruments are not in use. The cabinet shall have casters for mobility that can be locked during use or storage.

2.8.3 Drive adapters. Drive adapters shall be provided to accommodate ¼ in., $^{5}/_{16}$ in., $^{3}/_{8}$ in., ½ in., ¾ in., and 1 in. square torque wrenches, hex drive torque screwdrivers, and any other adapters which shall be required to calibrate the test item. These adapters shall not, when placed in the system, have free rotational play greater than 1^{O}. A means of compensation shall be provided to keep the moment arm at 90° +/- 1^{O} with any applied weight, i.e., the calibration method must ensure no cosine error is introduced to the transducer during calibration. All drive adapters shall conform to specifications of ANSI B107.4-1982. All other accessories necessary for normal operation and calibration of the equipment shall be supplied.

2.9 Workmanship. The Torque Wrench Calibrator, including all parts and accessories, shall be constructed and finished in a thoroughly workmanlike manner. Workmanship objectives shall include freedom from blemishes, defects, burrs and sharp corners and edges; accuracy of dimensions, surface finish, and radii of fillets; thoroughness of welding, painting, and riveting; marking of parts and assemblies; and proper alignment of parts and tightness of assembly fasteners.

2.9.1 Bolted connections. Bolt holes shall be accurately punched or drilled and shall be deburred. Threaded fasteners shall be tight and shall not work loose during testing or service usage.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:29Z
Check the source to verify that this is the current version before use.

2.9.2 Riveted connections. Rivet holes shall be accurately punched or drilled and shall be deburred. Rivets shall be driven with pressure tools and shall completely fill the holes. Rivet heads shall be full, neatly made, concentric with the rivet holes, and in full contact with the surface of the component.

2.9.3 Gear and lever assemblies. Gear and lever assemblies shall be properly aligned and meshed and shall be operable without interference, tight spots, loose spots, or other irregularities. Where required for accurate adjustment, gear assemblies shall be free of excessive backlash.

2.9.4 Cleaning. The Torque Wrench Calibrator shall be thoroughly cleaned. Loose, spattered, or excess solder; welding slag; stray bolts, nuts, and washers; rust; metal particles; pipe compound; and other foreign matter shall be removed during and after final assembly.

2.10 Installation and demonstration. For laboratories in the United States only, the contractor shall be responsible for installation and set-up of the equipment at the designated location and demonstrate the equipment is ready for use. Installation and demonstration is projected to take two days. The cost for installation and demonstration shall be included in the unit price of the Torque Wrench Calibrator.

3. REGULATORY REQUIREMENTS.

3.1 Recycled, recovered, or environmentally preferable materials. Recycled, recovered, or environmentally preferable materials should be used to the maximum extent possible provided that the material meets or exceeds the operational and maintenance requirements, and promotes economically advantageous life cycle costs. The offeror/contractor is encouraged to use recovered materials to the maximum extent practicable, in accordance with 23.403 of the Federal Acquisition Regulation (FAR). However, used, rebuilt, or refurbished items shall not be provided.

3.2 Green Procurement Program. Green Procurement Program (GPP) is a mandatory federal acquisition program that focuses on the purchase and use of environmentally preferable products and services. GPP requirements apply to all acquisitions using appropriated funds, including services and new requirements. FAR 23.404(b) applies and states the GPP requires 100% of Environmental Protection Agency designated product purchase that are included in the Comprehensive Procurement Guidelines list that contains recovered materials, unless the item cannot be acquired: a) competitively within a reasonable timeframe; b) meet appropriate performance standards, or c) at a reasonable price. The prime contractor is responsible for ensuring that all subcontractors comply with this requirement.

4. PRODUCT CONFORMANCE PROVISIONS.

The products provided shall meet the salient characteristics of this Commercial Item Description, conform to the producer’s own drawings, specifications, standards, and quality assurance practices, and be the same product offered for sale in the commercial marketplace. The government reserves the right to require proof of such conformance. Minor changes to the commercial product, with respect to ruggedizing and environmental suitability and protection

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:29Z
Check the source to verify that this is the current version before use.

shall be permitted, subject to the approval of the procurement office, to satisfy the requirements of this commercial item description.

4.1 Classification of inspections. The inspection requirements specified herein are classified as follows:

a. First production inspection (see 4.2).

b. Conformance inspection (see 4.3).

4.2 First production inspection. The first production Torque Wrench Calibrator shall be subjected to the examinations, tests, and analyses described in 4.5.1 through 4.5.7. The contractor shall provide or arrange for all test equipment and facilities.

4.3 Conformance inspection. Each production Torque Wrench Calibrator shall be subjected to the examinations and tests described in 4.5.1.

4.4 Inspection requirements.

4.4.1 General inspection requirements. Apparatus used in conjunction with the inspections specified herein shall be laboratory precision type, calibrated at proper intervals to ensure laboratory accuracy.

4.4.2 Data. During all testing specified herein, at least the following data, unless not applicable, shall be recorded at intervals not to exceed 30 minutes. Additional data or shorter intervals shall be provided as appropriate for any specific test.

a. Date.

b. Time started.

c. Time finished.

d. Ambient temperature.

e. Ambient humidity.

4.4.3 Test rejection criteria. Throughout all tests specified herein, the Torque Wrench Calibrator shall be closely observed for the following conditions, which shall be cause for rejection:

a. Failure to conform to design or performance requirements specified herein or in the contractor's technical proposal.

b. Structural failure of any component, including permanent deformation, or evidence of impending failure.

c. Evidence of excessive wear.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:29Z
Check the source to verify that this is the current version before use.

d. Misalignment of components.

e. Conditions that present a safety hazard to personnel during operation, servicing, or maintenance.

f. Evidence of corrosion or deterioration.

4.5 Test methods.

4.5.1 Examination of product. Each Torque Wrench Calibrator shall be examined to verify compliance with the requirements herein prior to accomplishing any other tests listed in 4.5. A contractor-generated, Government-approved checklist shall be used to identify each requirement not verified by a test or analysis, and shall be used to document the inspection results. Particular attention shall be given to materials, workmanship, dimensions, surface finishes, protective coatings and sealants and their application, welding, fastening, and markings. Proper operation of each Torque Wrench Calibrator function shall be verified. Certifications and analyses shall be provided in accordance with Table I. Each production Torque Wrench Calibrator shall be inspected to a Government-approved reduced version of the checklist.

TABLE I. Certifications and analyses.

Paragraph	Required Certifications and Analyses
2.6.1 Power requirements	The contractor shall certify that the Torque Wrench Calibrator has been built to meet the power specifications set forth in 2.6.1
2.6.2 Transient response	The contractor shall analyze the Torque Wrench Calibrator to verify the transient response time to be less than or equal to 500 milliseconds.
2.6.3 Voltage Transient	The contractor shall analyze the Torque Wrench Calibrator to verify that voltage transients do not interrupt normal operation for greater than 30 seconds as specified in 2.6.3.
2.6.4 Frequency Transient	The contractor shall analyze the Torque Wrench Calibrator to verify that frequency transients do not interrupt normal operation for greater than 30 seconds as specified in 2.6.4.
2.6.5 Fuses or circuit breakers	The contractor shall analyze and certify all internal circuitry to be protected by fuses or circuit breakers.

4.5.2 Environmental testing.

4.5.2.1 High temperature storage and operation test. A first production Torque Wrench Calibrator shall be tested in accordance with MIL-STD-810, Method 501.5, Procedures I and II, to demonstrate compliance with the high temperature storage and operating requirements of 2.3.1 and 2.3.2. Test duration shall be one 24-hour cycle for each procedure.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:29Z
Check the source to verify that this is the current version before use.

4.5.2.2 Low temperature storage and operation test. A first production Torque Wrench Calibrator shall be tested in accordance with MIL-STD-810, Method 502.5, Procedures I and II, to demonstrate compliance with the low temperature storage and operating requirements of 2.3.1 and 2.3.2. Test duration shall be one 24-hour cycle for each procedure.

4.5.3 Dimension measurement. A first production Torque Wrench Calibrator shall be measured to demonstrate compliance with the dimensional requirements of 2.4.

4.5.4 Performance demonstration. A first production Torque Wrench Calibrator shall be demonstrated to meet the performance criteria set forth in 2.5 to 2.5.7.

4.5.5 Transient response test. A first production Torque Wrench Calibrator shall be tested to be in compliance with the transient response requirements set forth in 2.6.2.

4.5.6 Voltage transient test. A first production Torque Wrench Calibrator shall be tested to be in compliance with the voltage transient requirements set forth in 2.6.3.

4.5.7 Frequency transient test. A first production Torque Wrench Calibrator shall be tested to be in compliance with the frequency transient requirements set forth in 2.6.4.

4.5.8 Inspection. All requirements set forth in 2.1 to 2.9.4 shall be verified by inspection in accordance with the contractor-generated, Government-approved checklist set forth in 4.5.1.

4.6 Verification of calibration. The Torque Wrench Calibrator shall be calibrated by a method traceable to the National Institute of Standards and Technology and shall be delivered with a calibration certificate or report.

5. PACKAGING.

5.1 Preservation, packing, and marking shall be as specified in the contract or order.

6. NOTES.

6.1 Source of documents.

6.1.1 Department of Defense and Federal documents may be obtained at https://assist.daps.dla.mil/online or from the Document Automation and Production Service, Bldg 4D (DPM-DODSSP), 700 Robbins Avenue, Philadelphia PA 19111-5094.

6.1.2 National Electrical Manufacturers Association (NEMA) standards may be obtained from National Electrical Manufacturers Association, 1300 North 17th Street, Suite 1752, Rosslyn, Virginia 22209. Electronic copies of NEMA standards may be obtained from http://www.nema.org/stds/ .

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:29Z
Check the source to verify that this is the current version before use.

6.1.3 FAR and DFARS may be obtained from the Superintendent of Documents, P.O. Box 371954, Pittsburgh, PA 15250-7954. Electronic copies of the FAR may be obtained from http://www.arnet.gov/far Electronic copies of the DFARS may be obtained from http://www.acq.osd.mil/dpap/dars/dfars/index.htm .

6.1.4 ANSI/EIA standards may be obtained at http://www.ansi.org or http://www.eia.org or available from the Electronics Industry Association, Engineering Department, 2001 Pennsylvania Ave., N.W., Washington, D.C., 20006. Phone: 1-800-854-7179 (USA and Canada).

6.2 Ordering data. Acquisition documents should specify the following:

a. Title, number, and date of this CID.

6.3 Key words.

Dual station usage
Dynamometers
Force gages

Custodian:
Air Force - 84

Preparing activity:
Air Force - 84

Review activity:
DLA - IS

Agent:
Air Force - 99

Project 6635-2010-004

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.daps.dla.mil/online .

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:29Z
Check the source to verify that this is the current version before use.